

Tay 650–15, Tay 650–15/10, and Tay 651–54 engines with ice-impact panels if:

(1) Those ice-impact panels incorporate the RR SB No. TAY–72–1326 standard; and

(2) Ice-impact panels were repaired using RR repair scheme TV5451R, HRS3491, or HRS3615 and bonding material other than polysulfide; unless

(3) The panels and the surrounding fillers are inspected for condition using 3.B. through 3.D.(3) (in-service) or 3.K.(1) through 3.(M)(3) (at overhaul or shop visit) of the Accomplishment Instructions of RRD SB No. TAY–72–1638, Revision 2, dated September 21, 2004.

(u) Perform repetitive inspections as specified in paragraph (n) of this AD.

(v) After the effective date of this AD, do not install any Tay 611–8 engine with ice-impact panels if:

(1) Those ice-impact panels incorporate the RR SB No. TAY–72–1326 standard; and

(2) Ice-impact panels were repaired using RR repair scheme TV5451R, HRS3491, or HRS3615 and bonding material other than polysulfide, unless

(3) The panels and the surrounding fillers are inspected for condition using 3.B. through 3.D.(2) (in-service) or 3.K.(1) through 3.M.(3) (at overhaul or shop visit) of the Accomplishment Instructions of RRD SB No. TAY–72–1639, Revision 2, dated September 21, 2004.

(w) Perform repetitive inspections as specified in paragraph (s) of this AD.

Alternative Methods of Compliance

(x) The Manager, Engine Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

Material Incorporated by Reference

(y) You must use the Rolls-Royce service information specified in Table 2 to perform the inspections required by this AD. The Director of the Federal Register approved the incorporation by reference of the documents listed in Table 2 of this AD in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. You can get a copy from Rolls-Royce Deutschland Ltd & Co KG, Eschenweg 11, D–15827 Dahlewitz, Germany; telephone 49 (0) 33–7086–1768; fax 49 (0) 33–7086–3356. You may review copies at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html. Table 2 follows:

TABLE 2.—INCORPORATION BY REFERENCE

Service information No.	Page	Revision	Date
SB No. TAY–72–1638 Total Pages: 35	ALL	2	Sept. 21, 2004.
SB No. TAY–72–1639 Total Pages: 28	ALL	2	Sept. 21, 2004.
Repair Scheme No. HRS3648 Front Sheet Total Pages: 1	ALL	2	Jan. 28, 2004.
Repair Scheme No. HRS3648 History Sheet Total Pages: 3	ALL	2	Jan. 28, 2004.
Repair Scheme No. HRS3648 Total Pages: 30	ALL	2	Jan. 27, 2004.
Repair Scheme No. HRS3649 Front Sheet Total Pages: 1	ALL	2	Sept. 1, 2004.
Repair Scheme No. HRS3649 History Sheet Total Pages: 3	ALL	2	Sept. 7, 2004.
Repair Scheme No. HRS3649 Total Pages: 24	ALL	2	June 17, 2004.

Related Information

(z) LBA AD D2004–313R2, dated September 21, 2004, also addresses the subject of this AD.

Issued in Burlington, Massachusetts, on December 22, 2004.

Jay J. Pardee,

Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 05–40 Filed 1–5–05; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2004–19494; Directorate Identifier 2004–NM–135–AD; Amendment 39–13919; AD 2004–26–07]

RIN 2120–AA64

Airworthiness Directives; Airbus Model A318, A319, A320, and A321 Series Airplanes Equipped With Air Cruisers/ Aerazur Forward and Aft Passenger Door Emergency Escape Slides

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Airbus Model A318, A319, A320, and A321 series airplanes equipped with certain forward and aft passenger door emergency escape slides. This AD requires modifying the forward and aft

door slides. This AD is prompted by manufacturer testing that has shown contact between the inflation hose and fabric roll, within a short period of time after inflation of the emergency escape slides, can rupture the inflation hose at its end fittings. We are issuing this AD to prevent interference between the inflation hose and slide fabric and rupture of the inflation hose, which could result in incomplete inflation of the emergency escape slides and consequent unavailability of those slides during an emergency evacuation.

DATES: This AD becomes effective February 10, 2005.

The incorporation by reference of a certain publication listed in the AD is approved by the Director of the Federal Register as of February 10, 2005.

ADDRESSES: For service information identified in this AD, contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. You can examine this information at the National Archives and Records Administration

(NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

You can examine the contents of this AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., room PL-401, on the plaza level of the Nassif Building, Washington, DC. This docket number is FAA-2004-19494; the directorate identifier for this docket is 2004-NM-135-AD.

FOR FURTHER INFORMATION CONTACT: Tim Dulin, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2141; fax (425) 227-1149.

Examining the Docket

The AD docket contains the proposed AD, comments, and any final disposition. You can examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the DOT street address stated in the **ADDRESSES** section.

SUPPLEMENTARY INFORMATION: The FAA proposed to amend 14 CFR Part 39 with an AD for certain Airbus Model A318, A319, A320, and A321 series airplanes equipped with certain forward and aft passenger door emergency escape slides. That action, published in the **Federal Register** on November 3, 2004 (69 FR

63960), proposed to require modifying the forward and aft door slides.

Comments

We provided the public the opportunity to participate in the development of this AD. No comments have been submitted on the proposed AD or on the determination of the cost to the public.

Conclusion

We have carefully reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

Costs of Compliance

The following table provides the estimated costs for U.S. operators to comply with this AD, at an average labor rate of \$65 per work hour.

ESTIMATED COSTS

Action	Work hours per slide	Slides per airplane	Parts	Cost per airplane	Number of U.S. registered airplanes	Fleet cost
Modification	1	2	Free	\$130	648	\$84,240

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2004-26-07 Airbus: Amendment 39-13919. Docket No. FAA-2004-19494; Directorate Identifier 2004-NM-135-AD.

Effective Date

(a) This AD becomes effective February 10, 2005.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Airbus Model A318-111 and -112 series airplanes; Model A319-111, -112, -113, -114, -115, -131, -132, and -133 series airplanes; Model A320-111, -211, -212, -214, -231, -232, and -233 series airplanes; and Model A321-111, -112, -131, -211, and -231 series airplanes; certificated in any category; equipped with Air Cruisers/Aerazur forward passenger door emergency escape slides, part number (P/N) D31516-111, -113, -115, -117, -311, or -313, and aft passenger door emergency escape slides, P/N D31517-111, -113, -115, -117, -311, or -313; except those airplanes on which Airbus Modification 33429 has been accomplished in production.

Unsafe Condition

(d) This AD was prompted by manufacturer testing that has shown contact between the inflation hose and fabric roll, within a short period of time after inflation of the emergency escape slides, can rupture

the inflation hose at its end fittings. We are issuing this AD to prevent interference between the inflation hose and slide fabric and rupture of the inflation hose, which could result in incomplete inflation of the emergency escape slides and consequent unavailability of those slides during an emergency evacuation.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Modification

(f) Within 37 months after the effective date of this AD, modify the forward and aft door slides, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-25-1338, dated February 9, 2004.

Note 1: Airbus Service Bulletin A320-25-1338, dated February 9, 2004, refers to Air Cruisers/Aerazur Service Bulletin A320 004-25-72, dated October 28, 2003, as an additional source of service information for modifying the forward and aft door slides.

Alternative Methods of Compliance (AMOCs)

(g) The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

Related Information

(h) French airworthiness directive F-2004-072, dated May 26, 2004, also addresses the subject of this AD.

Material Incorporated by Reference

(i) You must use Airbus Service Bulletin A320-25-1338, dated February 9, 2004, to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approves the incorporation by reference of these documents in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. For copies of the service information, contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. For information on the availability of this material at the National Archives and Records Administration (NARA), call (202) 741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html. You may view the AD docket at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., room PL-401, Nassif Building, Washington, DC.

Issued in Renton, Washington, on December 20, 2004.

Kevin M. Mullin,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 05-107 Filed 1-5-05; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003-NM-186-AD; Amendment 39-13918; AD 2004-26-06]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 767-300 and 767-300F Series Airplanes Equipped With General Electric or Pratt & Whitney Engines

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), that is applicable to certain Boeing Model 767-300 and 767-300F series airplanes equipped with General Electric or Pratt & Whitney engines. This AD requires reworking the wing-to-strut diagonal braces and the aft pitch load fittings of the wings, and reinstalling the diagonal braces with new fuse pins and associated hardware. This action is necessary to prevent undetected loss of the diagonal brace fuse pins of the wings and consequent increased loads in other wing-to-strut joints, which could result in separation of the struts and engines from the wings. This action is intended to address the identified unsafe condition.

DATES: Effective February 10, 2005.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of February 10, 2005.

ADDRESSES: The service information referenced in this AD may be obtained from Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

FOR FURTHER INFORMATION CONTACT:

Suzanne Masterson, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 917-6441; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain Boeing Model 767-300 and 767-300F series airplanes equipped with General Electric or Pratt & Whitney engines was published in the **Federal Register** on April 1, 2004 (69 FR 17080). That action proposed to require reworking the wing-to-strut diagonal braces and the aft pitch load fittings of the wings, and reinstalling the diagonal braces with new fuse pins and associated hardware. For certain airplanes, that proposal would require replacing the bushings of the aft pitch load fittings, installing new fuse pins, and reworking the fittings, as applicable.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the comments received.

Request for Credit for Actions Accomplished per Revision 1 of the Service Bulletin

Two commenters, the manufacturer and one operator, request that the FAA give credit for actions accomplished in accordance with Boeing Alert Service Bulletin 767-54A0096, Revision 1, dated July 12, 2001. The commenters indicate that the proposed AD references Boeing Alert Service Bulletin 767-54A0096, Revision 2, dated December 18, 2003, as the appropriate source of information, and point out that Revision 2 states that no more work is necessary on airplanes modified in accordance with Revision 1.

We do not agree with the commenters' request. The statement in Revision 2 of the service bulletin that "No more work is necessary on airplanes changed as shown in Revision 1 of this service bulletin," is incorrect. Revision 2 of the service bulletin revises, among other changes, the bushing swage lip dimension in Figures 3 and 6 of Revision 1 of the service bulletin. Therefore, we have determined that accomplishing the rework specified in Revision 1 does not adequately address the identified unsafe condition.

In addition, since we issued the proposed AD, Boeing has issued and we have reviewed Service Bulletin Information Notice (IN) 767-54A0096 IN 03, dated April 15, 2004, which corrects an additional dimension (*i.e.*, the bushing swage groove radius dimension) in Figures 3 and 6 of Revision 2. We have reworded paragraphs (a) and (b) of this AD to