

section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Boeing: Docket No. FAA-2005-20347; Directorate Identifier 2004-NM-226-AD.

Comments Due Date

(a) The Federal Aviation Administration (FAA) must receive comments on this AD action by April 1, 2005.

Affected ADs

(b) None.

Applicability

(c) This AD applies to the airplanes listed in Table 1 of this AD, certificated in any category:

TABLE 1.—APPLICABILITY

Boeing models	As listed in
737-300, -400, and -500 series airplanes	Boeing Alert Service Bulletin 737-34A1821, dated July 15, 2004.
737-600, -700, -700C, -800 and -900 series airplanes	Boeing Alert Service Bulletin 737-34A1801, dated July 15, 2004.

Unsafe Condition

(d) This AD was prompted by one operator reporting flight management computer (FMC) map shifts on several Model 737-400 series airplanes with dual FMCs, using operational program software (OPS) version U10.4A. We are issuing this AD to prevent the FMC from displaying the incorrect actual navigation performance value to the flightcrew, which could prevent adequate alerting of a potential navigation error. This condition could result in a near miss with other airplanes or terrain, or collision if other warning systems also fail.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Install Updated Version of OPS

(f) Within 180 days after the effective date of this AD, install the updated version of the OPS in the left and right FMCs; and, before further flight, do all the other specified actions. Do the installation and other specified actions by accomplishing all of the actions in the Accomplishment Instructions of the applicable service bulletin, as listed in Table 1 of this AD. Where the service bulletin specifies a configuration check, certificated maintenance personnel must perform the configuration check.

Reinstall Software, If Necessary

(g) If the incorrect software version of the OPS, model/engine database if applicable, or software options database is found installed on any FMC during any configuration check required by paragraph (f) of this AD: Before further flight, reinstall the software, as applicable. Do the reinstallation of any software in accordance with the Accomplishment Instructions of the applicable service bulletin, as listed in Table 1 of this AD.

Alternative Methods of Compliance (AMOCs)

(h) The Manager, Seattle Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in

accordance with the procedures found in 14 CFR 39.19.

Issued in Renton, Washington, on February 2, 2005.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 05-2827 Filed 2-14-05; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2005-20345; Directorate Identifier 2004-NM-101-AD]

RIN 2120-AA64

Airworthiness Directives; Dornier Model 328-300 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Dornier Model 328-300 series airplanes. This proposed AD would require installing a drain hole in the lower skin of the left- and right-hand elevator horns. This proposed AD is prompted by reports of water found in the elevator assembly. We are proposing this AD to prevent water or ice accumulating in the elevator assembly, which could result in possible corrosion that reduces the structural integrity of the flight control surface, or in an unbalanced flight control surface. These conditions could result in reduced controllability of the airplane.

DATES: We must receive comments on this proposed AD by March 17, 2005.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

- DOT Docket Web site: Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- Government-wide rulemaking Web site: Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- Mail: Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., Nassif Building, room PL-401, Washington, DC 20590.

- By fax: (202) 493-2251.

- Hand Delivery: Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact AvCraft Aerospace GmbH, PO Box 1103, D-82230 Wessling, Germany.

You can examine the contents of this AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., room PL-401, on the plaza level of the Nassif Building, Washington, DC. This docket number is FAA-2005-20345; the directorate identifier for this docket is 2004-NM-101-AD.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2125; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to submit any relevant written data, views, or arguments regarding this proposed AD. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2005-20345; Directorate Identifier 2004-NM-101-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments submitted by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of our docket Web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You can review the DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you can visit <http://dms.dot.gov>.

Examining the Docket

You can examine the AD docket on the Internet at <http://dms.dot.gov>, or in

person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the DOT street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the DMS receives them.

Discussion

The Luftfahrt-Bundesamt (LBA), which is the airworthiness authority for Germany, notified us that an unsafe condition may exist on certain Dornier Model 328-300 series airplanes. The LBA advises that there have been reports that, during maintenance, water (from rain or condensation) was found in the elevator assembly. The water accumulates in the elevator due to the lack of a drain hole and could freeze in a cold environment (e.g., due to high altitude or winter weather). Accumulated water or ice in the elevator assembly, if not corrected, could result in possible corrosion that reduces the structural integrity of the flight control surface, or in an unbalanced flight control surface. These conditions could result in reduced controllability of the airplane.

Relevant Service Information

AvCraft Aerospace GmbH has issued Dornier Service Bulletin SB-328J-55-203, Revision 1, dated November 19, 2003. The service bulletin describes

procedures for installing a drain hole in the lower skin of the left- and right-hand elevator horns. Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition. The LBA mandated the service information and issued German airworthiness directive D-2004-005, dated January 8, 2004, to ensure the continued airworthiness of these airplanes in Germany.

FAA's Determination and Requirements of the Proposed AD

This airplane model is manufactured in Germany and is type certificated for operation in the United States under the provisions of § 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the LBA has kept the FAA informed of the situation described above. We have examined the LBA's findings, evaluated all pertinent information, and determined that we need to issue an AD for products of this type design that are certificated for operation in the United States. Therefore, we are proposing this AD, which would require accomplishing the actions specified in the service information described previously.

Costs of Compliance

The following table provides the estimated costs for U.S. operators to comply with this proposed AD.

ESTIMATED COSTS

Action	Work hours	Average labor rate per hour	Parts	Cost per airplane	Number of U.S.-registered airplanes	Fleet cost
Installing drain hole	1	\$65	\$100	\$165	49	\$8,085

Authority of This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation

is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Fairchild Dornier GMBH (Formerly Dornier Luftfahrt GmbH): Docket No. FAA–2005–20345; Directorate Identifier 2004–NM–101–AD.

Comments Due Date

(a) The Federal Aviation Administration must receive comments on this AD action by March 17, 2005.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Dornier Model 328–300 series airplanes, serial numbers 3105 through 3219 inclusive, certificated in any category.

Unsafe Condition

(d) This AD was prompted by reports of water found in the elevator assembly. We are issuing this AD to prevent water accumulating in the elevator assembly, which could result in possible corrosion that reduces the structural integrity of the flight control surface, or in an unbalanced flight control surface. These conditions could result in reduced controllability of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Installation

(f) Which 90 days after the effective date of this AD, install a drain hole in the lower skin of the left- and right-hand elevator horns in accordance with the Accomplishment Instructions of Dornier Service Bulletin SB–328J–55–203, Revision 1, dated November 19, 2003.

Alternative Methods of Compliance (AMOCs)

(g) The Manager, International Branch, ANM–116, FAA, Transport Airplane Directorate, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

Related Information

(h) German airworthiness directive D–2004–005, dated January 8, 2004, also addresses the subject of this AD.

Issued in Renton, Washington, on January 31, 2005.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 05–2828 Filed 2–14–05; 8:45 am]

BILLING CODE 4910–13–M

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2005–20357; Directorate Identifier 2004–NM–120–AD]

RIN 2120–AA64

Airworthiness Directives; Boeing Model 767 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Boeing Model 767 series airplanes. This proposed AD would require replacing hinge assemblies with new hinge assemblies in the outboard overhead stowage bins and reworking hinge assemblies in the outboard overhead stowage bins that are adjacent to curtain tracks. This proposed AD is prompted by reports of hinge assemblies of outboard overhead stowage bins breaking or the stowage bin doors not latching properly. We are proposing this AD to prevent the outboard overhead stowage bins opening during flight and releasing baggage, and consequently cause passenger injury and blockage of the aisles during emergency egress.

DATES: We must receive comments on this proposed AD by April 1, 2005.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

- DOT Docket Web site: Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- Government-wide rulemaking Web site: Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- Mail: Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, room PL–401, Washington, DC 20590.

- By fax: (202) 493–2251.

- Hand Delivery: Room PL–401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124–2207.

You can examine the contents of this AD docket on the Internet at <http://dms.dot.gov>, or at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., room PL–401, on the plaza level of the Nassif Building, Washington, DC. This docket number is FAA–2005–20357; the directorate identifier for this docket is 2004–NM–120–AD.

FOR FURTHER INFORMATION CONTACT:

Susan Rosanske, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM–150S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055–4056; telephone (425) 917–6448; fax (425) 917–6590.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to submit any written relevant data, views, or arguments regarding this proposed AD. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA–2005–20357; Directorate Identifier 2004–NM–120–AD” in the subject line of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments submitted by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of that Web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You can review DOT’s complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477–78), or you can visit <http://dms.dot.gov>.

Examining the Docket

You can examine the AD docket on the Internet at <http://dms.dot.gov>, or in