

Inspection of Wire Bundles and Corrective Actions

(f) Within 60 months after the effective date of this AD: Perform a detailed inspection for chafing of the wire bundles located below the passenger compartment, above the center fuel tank, aft of station 540 to approximately station 663.75, right buttock line and left buttock line 24.50, and any applicable corrective actions, by accomplishing all of the applicable actions specified in the Accomplishment Instructions of Boeing Service Bulletin 737-28-1208, dated July 8, 2004. Any corrective actions must be done before further flight. Where the service bulletin states that repair of wire damage may be done in accordance with an "approved equivalent procedure," the repair must be accomplished according to the chapter of the Boeing Standard Wiring Practices Manual specified in the service bulletin. Approved equivalent procedures may be used for removing and re-installing passenger cabin furnishings, and removing and returning power to the airplane.

Note 1: For the purposes of this AD, a detailed inspection is: "An intensive examination of a specific item, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at an intensity deemed appropriate. Inspection aids such as mirror, magnifying lenses, etc., may be necessary. Surface cleaning and elaborate procedures may be required."

Adjustment/Replacement of Wire Bundle Clamps

(g) After performing the actions required by paragraph (f) of this AD: Before further flight, adjust and replace, as applicable, the wire bundle clamps located aft of station 540, by accomplishing all of the applicable actions specified in the Accomplishment Instructions of Boeing Service Bulletin 737-28-1208, dated July 8, 2004.

Alternative Methods of Compliance

(h) The Manager, Seattle Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

Issued in Renton, Washington, on February 6, 2005.

Ali Bahrami,

Manager, Transport Airplane Directorate,
Aircraft Certification Service.

[FR Doc. 05-2836 Filed 2-14-05; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2005-20379; Directorate Identifier 2004-NM-174-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A310 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all Airbus Model A310 series airplanes. This proposed AD would require measuring the clearance between the compensator and the guide assembly of probe no. 1 on the outboard fuel tanks, and performing corrective actions if necessary. This proposed AD is prompted by the results of fuel system reviews conducted by the manufacturer. We are proposing this AD to prevent interference between the compensator and the guide assembly of probe no. 1, which could create an ignition source that could result in a fire or explosion.

DATES: We must receive comments on this proposed AD by March 17, 2005.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

- DOT Docket Web site: Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.
- Government-wide rulemaking Web site: Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.
- Mail: Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, room PL-401, Washington, DC 20590.
- By fax: (202) 493-2251.
- Hand Delivery: Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France.

You can examine the contents of this AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., room PL-401, on the plaza level of the Nassif Building, Washington, DC.

You can examine the contents of this AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., room PL-401, on the plaza level of the Nassif Building, Washington, DC.

This docket number is FAA-2005-20379; the directorate identifier for this docket is 2004-NM-174-AD.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2125; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to submit any relevant written data, views, or arguments regarding this proposed AD. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2005-20379; Directorate Identifier 2004-NM-174-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments submitted by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of our docket website, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You can review the DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you can visit <http://dms.dot.gov>.

Examining the Docket

You can examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the DOT street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the DMS receives them.

Discussion

The FAA has examined the underlying safety issues involved in recent fuel tank explosions on several large transport airplanes, including the adequacy of existing regulations, the

service history of airplanes subject to those regulations, and existing maintenance practices for fuel tank systems. As a result of those findings, we issued a regulation titled “Transport Airplane Fuel Tank System Design Review, Flammability Reduction and Maintenance and Inspection Requirements” (67 FR 23086, May 7, 2001). In addition to new airworthiness standards for transport airplanes and new maintenance requirements, this rule included Special Federal Aviation Regulation No. 88 (“SFAR 88,” Amendment 21–78, and subsequent Amendments 21–82 and 21–83).

Among other actions, SFAR 88 requires certain type design (*i.e.*, type certificate (TC) and supplemental type certificate (STC)) holders to substantiate that their fuel tank systems can prevent ignition sources in the fuel tanks. This requirement applies to type design holders for large turbine-powered transport airplanes and for subsequent modifications to those airplanes. It requires them to perform design reviews and to develop design changes and maintenance procedures if their designs do not meet the new fuel tank safety standards. As explained in the preamble to the rule, we intended to adopt airworthiness directives to mandate any changes found necessary to address unsafe conditions identified as a result of these reviews.

In evaluating these design reviews, we have established four criteria intended to define the unsafe conditions associated with fuel tank systems that require corrective actions. The percentage of operating time during which fuel tanks are exposed to flammable conditions is one of these criteria. The other three criteria address the failure types under evaluation: Single failures, single failures in combination with another latent condition(s), and in-service failure

experience. For all four criteria, the evaluations included consideration of previous actions taken that may mitigate the need for further action.

The Joint Aviation Authorities (JAA) has issued a regulation that is similar to SFAR 88. (The JAA is an associated body of the European Civil Aviation Conference (ECAC) representing the civil aviation regulatory authorities of a number of European States who have agreed to cooperate in developing and implementing common safety regulatory standards and procedures.) Under this regulation, the JAA stated that all members of the ECAC that hold type certificates for transport category airplanes are required to conduct a design review against explosion risks.

We have determined that the actions identified in this AD are necessary to reduce the potential of ignition sources inside fuel tanks, which, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane.

The Direction Générale de l’Aviation Civile (DGAC), which is the airworthiness authority for France, notified us that an unsafe condition may exist on all Airbus Model A310 series airplanes. The DGAC advises that a design review has revealed the potential for insufficient clearance between the compensator and the guide assembly of probe no. 1 on the outboard fuel tanks. Also, the clearance on probe no. 1 of the left-hand outboard fuel tank may be different than on probe no. 1 of the right-hand outboard fuel tanks. This condition, if not corrected, could cause interference between the compensator and the guide assembly of probe no. 1, which could create an ignition source that could result in a fire or explosion.

Relevant Service Information

Airbus has issued Service Bulletin A310–28–2152, dated January 12, 2004.

The service bulletin describes procedures for measuring the clearance between the compensator and the guide assembly of probe no. 1 on the left- and right-hand outboard fuel tanks, and performing corrective action if the clearance is less than 3 mm. The corrective action consists of modifying the guide assembly of probe no. 1 to ensure that there is 3 mm of clearance or more between the compensator and the guide assembly. Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition. The DGAC mandated the service information and issued French airworthiness directive F–2004–125, dated July 21, 2004, to ensure the continued airworthiness of these airplanes in France.

FAA’s Determination and Requirements of the Proposed AD

This airplane model is manufactured in France and is type certificated for operation in the United States under the provisions of § 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the DGAC has kept the FAA informed of the situation described above. We have examined the DGAC’s findings, evaluated all pertinent information, and determined that we need to issue an AD for products of this type design that are certificated for operation in the United States.

Therefore, we are proposing this AD, which would require accomplishing the actions specified in the service information described previously.

Costs of Compliance

The following table provides the estimated costs for U.S. operators to comply with this proposed AD.

ESTIMATED COSTS

Action	Work hours	Average labor rate per hour	Parts	Cost per air-plane	Number of U.S.-registered airplanes	Fleet cost
Inspection	2	\$65	None	\$130	59	\$7,670

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation

is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order

13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Airbus: Docket No. FAA-2005-20379; Directorate Identifier 2004-NM-174-AD.

Comments Due Date

(a) The Federal Aviation Administration must receive comments on this AD action by March 17, 2005.

Affected ADs

(b) None.

Applicability

(c) This AD applies to all Airbus Model 310 series airplanes, certificated in any category.

Unsafe Condition

(d) This AD was prompted by the results of fuel system reviews conducted by the manufacturer. We are issuing this AD to prevent interference between the compensator and the guide assembly of probe no. 1, which could create an ignition source that could result in a fire or explosion.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Measurement

(f) Within 4,000 flight hours after the effective date of this AD, measure the clearance between the compensator and the guide assembly of probe no. 1 on the left- and right-hand outboard fuel tanks, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A310-28-2152, dated January 12, 2004. If the clearance between the compensator and the guide assembly is less than 3 mm, before further flight, modify the guide assembly of probe no. 1 to provide clearance of 3 mm or more between the compensator and the guide assembly, in accordance with the Accomplishment Instructions of the service bulletin.

Parts Installation

(g) As of the effective date of this AD, no person may install probe no. 1 on the left- or right-hand outboard fuel tank unless the requirements of paragraph (f) of this AD have been accomplished.

Alternative Methods of Compliance (AMOCs)

(h) The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

Related Information

(i) French airworthiness directive F-2004-125, dated July 21, 2004, also addresses the subject of this AD.

Issued in Renton, Washington, on February 9, 2005.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 05-2886 Filed 2-14-05; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF HOMELAND SECURITY

Coast Guard

33 CFR Part 100

[CGD01-05-005]

RIN 1625-AA08

Special Local Regulations for Marine Event; Manhattan College Invitational Regatta, Harlem River, New York, NY

AGENCY: Coast Guard, DHS.

ACTION: Notice of proposed rulemaking.

SUMMARY: The Coast Guard proposes to establish a temporary special local regulation for a regatta located on the Harlem River. This proposed action

would protect life and property on the navigable waters of the United States during the event. This action would restrict vessel traffic in a portion of the Harlem River, New York, NY, during the event.

DATES: Comments and related material must reach the Coast Guard on or before March 17, 2005.

ADDRESSES: You may mail comments and related material to Waterways Oversight Branch, Coast Guard Activities New York, 212 Coast Guard Drive, Room 203, Staten Island, NY 10305, or hand deliver them between the hours of 8 a.m. and 3 p.m., at the same address above, Monday through Friday, except Federal holidays. Comments and material received from the public, as well as documents indicated in this preamble as being available in the docket, are part of docket CGD01-05-005 and are available for inspection or copying at the address indicated above between 8 a.m. and 3 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: Lieutenant Commander W. Morton, Waterways Oversight Branch, Coast Guard Activities New York (718) 354-4191.

SUPPLEMENTARY INFORMATION:

Request for Comments

We encourage you to participate in this rulemaking by submitting comments and related material. If you do so, please include your name and address, identify the docket number for this rulemaking (CGD01-05-005), indicate the specific section of this document to which each comment applies, and give the reason for each comment. Please submit all comments and related material in an unbound format, no larger than 8½ by 11 inches, suitable for copying. If you would like to know they reached us, please enclose a stamped, self-addressed postcard or envelope. We will consider all comments and material received during the comment period. We may change this proposed rule in view of them.

If, as we anticipate, we make this temporary final rule effective less than 30 days after publication in the **Federal Register**, we will explain in that publication, as required by 5 U.S.C. (d)(3), our good cause for doing so.

Public Meeting

We do not now plan to hold a public meeting. But you may submit a request for a meeting by writing to the Waterways Management Division at the address under **ADDRESSES** explaining why one would be beneficial. If we