ADDRESSES: You can examine the contents of this AD docket on the Internet at http://dms.dot.gov, or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., room PL-401, on the plaza level of the Nassif Building, Washington, DC. This docket number is FAA-2004-19563; the directorate identifier for this docket is 2003–NM-10-AD.

FOR FURTHER INFORMATION CONTACT:

Serge Napoleon, Aerospace Engineer, Airframe and Propulsion Branch, ANE– 171, FAA, New York Aircraft Certification Office, 1600 Stewart Avenue, suite 410, Westbury, New York 11590; telephone (516) 228–7312; fax (516) 794–5531.

SUPPLEMENTARY INFORMATION:

Discussion

We proposed to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) with a notice of proposed rulemaking (NPRM) for a new AD for certain Bombardier Model CL-600-2B16 (CL-604) series airplanes. That NPRM was published in the Federal Register on November 9, 2004 (69 FR 64869). The NPRM would have required replacing the side-brace fitting shafts of the main landing gear (MLG) with new, improved side-brace fitting shafts; inspecting for corrosion of the MLG side-brace fitting shafts; and replacing the nut, washer, and cotter pin of the MLG side-brace fitting shafts with new parts; as applicable. The NPRM was prompted by the discovery of fractures of the MLG side-brace fitting shafts caused by corrosion on the forward side of the side-brace fitting shafts. The proposed actions were intended to prevent fracture of the MLG side-brace fitting shafts, which could result in collapse of the MLG.

Actions Since NPRM Was Issued

Since we issued the NPRM, the airplane manufacturer has informed us that all airplanes identified in the applicability section of the NPRM have already accomplished the actions specified in Bombardier Alert Service Bulletin A604–32–018, Revision 01, dated February 22, 2002, which would have been required by the proposed AD. Transport Canada Civil Aviation (TCCA), which is the airworthiness authority for Canada, has also confirmed that the proposed requirements have already been accomplished on all affected airplanes.

FAA's Conclusions

Upon further consideration, we have determined that it is unnecessary to

issue the proposed AD. Accordingly, the NPRM is withdrawn.

Withdrawal of the NPRM does not preclude the FAA from issuing another related action or commit the FAA to any course of action in the future.

Regulatory Impact

Since this action only withdraws an NPRM, it is neither a proposed nor a final rule and therefore is not covered under Executive Order 12866, the Regulatory Flexibility Act, or DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979).

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Withdrawal

Accordingly, we withdraw the NPRM, Docket No. FAA–2004–19563, Directorate Identifier 2003–NM–10–AD, which was published in the **Federal Register** on November 9, 2004 (69 FR 64869).

Issued in Renton, Washington, on March 31, 2005.

Kalene C. Yanamura.

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service. [FR Doc. 05–6916 Filed 4–6–05; 8:45 am] BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2005-20863; Directorate Identifier 2004-SW-36-AD]

RIN 2120-AA64

Airworthiness Directives; Eurocopter France Model AS350B, BA, B1, B2, B3, D, and AS355E Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes adopting a new airworthiness directive (AD) for the specified Eurocopter France (ECF) model helicopters. This proposal would require replacing the hydraulic fluid at a specified time interval when operating in cold weather. This proposal is prompted by reports of ice forming due to condensation in some parts of the hydraulic system during cold weather operation. The actions specified by this proposed AD are intended to prevent ice from forming in the hydraulic system resulting in an unintended movement of

the flight controls and subsequent loss of control of the helicopter.

DATES: Comments must be received on or before June 6, 2005.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD:

- DOT Docket Web site: Go to http://dms.dot.gov and follow the instructions for sending your comments electronically;
- Government-wide rulemaking Web site: Go to http://www.regulations.gov and follow the instructions for sending your comments electronically;
- Mail: Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590;
 - Fax: 202-493-2251; or
- Hand Delivery: Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

You may get the service information identified in this proposed AD from American Eurocopter Corporation, 2701 Forum Drive, Grand Prairie, Texas 75053–4005, telephone (972) 641–3460, fax (972) 641–3527.

You may examine the comments to this proposed AD in the AD docket on the Internet at http://dms.dot.gov.

FOR FURTHER INFORMATION CONTACT: Ed Cuevas, Aviation Safety Engineer, FAA, Rotorcraft Directorate, Safety Management Group, Fort Worth, Texas 76193–0111, telephone (817) 222–5355, fax (817) 222–5961.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to submit any written data, views, or arguments regarding this proposed AD. Send your comments to the address listed under the caption ADDRESSES. Include the docket number "FAA—2005—20863, Directorate Identifier 2004—SW—36—AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to http://dms.dot.gov, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed rulemaking. Using the search function of our docket Web site, you can find and read the comments to any of our

dockets, including the name of the individual who sent or signed the comment. You may review the DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477–78) or you may visit http://dms.dot.gov.

Examining the Docket

You may examine the docket that contains the proposed AD, any comments, and other information in person at the Docket Management System (DMS) Docket Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone 1–800–647–5227) is located at the plaza level of the Department of Transportation NASSIF Building in Room PL–401 at 400 Seventh Street, S.W., Washington, DC. Comments will be available in the AD docket shortly after the DMS receives them

Discussion

The Direction Generale de l'Aviation Civile (DGAC), the airworthiness authority for France, notified the FAA that an unsafe condition may exist on the specified ECF Model AS350 and AS355 helicopters. The DGAC advises of the formation of ice in some parts of the hydraulic system during flights in cold weather and when the hydraulic fluid is highly contaminated by water.

ECF has issued Alert Service Bulletin Nos. 05.00.43 and 05.00.45, both dated April 8, 2004, which specify provisions for replacing hydraulic fluid in cold weather. The DGAC classified these service bulletins as mandatory and issued AD Nos. F–2004–055 and F–2004–056, both dated April 28, 2004, to ensure the continued airworthiness of these helicopters in France.

These helicopter models are manufactured in France and are type certificated for operation in the United States under the provisions of 14 CFR 21.29 and the applicable bilateral agreement. Pursuant to the applicable bilateral agreement, the DGAC has kept us informed of the situation described above. We have examined the findings of the DGAC, reviewed all available information, and determined that AD action is necessary for products of these type designs that are certificated for operation in the United States.

The previously described unsafe condition is likely to exist or develop on other helicopters of the same type designs registered in the United States. Therefore, the proposed AD would require, if the outside air temperature in an FAA weather briefing is forecast to be below negative 15 degrees Celsius (5 degrees Fahrenheit) at or below your

planned flight altitude and the hydraulic fluid has not been replaced within the past 100 hours time-inservice or within the past 30 days, whichever occurred first, before further flight, replace the hydraulic fluid. The actions would be required to be accomplished following the service bulletins described previously.

We estimate that this proposed AD would affect 556 helicopters of U.S. registry, and the proposed actions would take about:

- 2 work hours to replace the hydraulic fluid per helicopter at an average labor rate of \$65 per work hour; and
- \$6 for hydraulic fluid each time it is changed.

Based on these figures, we estimate the total cost impact of the proposed AD to be \$75,616, assuming two fluid replacements per year for 50 percent of the helicopter fleet.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. Additionally, this proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

- 1. Is not a "significant regulatory action" under Executive Order 12866;
- 2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- 3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a draft economic evaluation of the estimated costs to comply with this proposed AD. See the DMS to examine the draft economic evaluation.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

Eurocopter France: Docket No. FAA-2005–20863; Directorate Identifier 2004–SW-36–AD.

Applicability: Model AS350B, BA, B1, B2, B3, D and AS355E helicopters, certificated in any category.

Compliance: Required as indicated.
To prevent ice from forming in the hydraulic system resulting in an unintended movement of the flight controls and subsequent loss of control of the helicopter, do the following:

(a) If the outside air temperature in an FAA weather briefing is forecast to be below negative 15 degrees Celsius (5 degrees Fahrenheit) at or below your planned flight altitude and the hydraulic fluid has not been replaced within the past 100 hours time-inservice or within the past 30 days, whichever occurred first, before further flight, replace the hydraulic fluid. Replace the hydraulic fluid by following the Accomplishment Instructions, paragraphs 2.A. and 2.B., of Eurocopter Alert Service Bulletin Nos. 05.00.43 or 05.00.45, both dated April 8, 2004, as applicable.

(b) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Contact the Safety Management Group, Rotorcraft Directorate, FAA, for information about previously approved alternative methods of compliance.

(c) Special flight permits will not be

Note: The subject of this AD is addressed in Direction Generale de l'Aviation Civile (France) AD Nos. F-2004-055 and F-2004-056, both dated April 28, 2004.

Issued in Fort Worth, Texas, on March 31, 2005.

David A. Downey,

Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 05–6917 Filed 4–6–05; 8:45 am]

BILLING CODE 4910-13-P

FEDERAL TRADE COMMISSION

16 CFR Part 410

Deceptive Advertising as to Sizes of Viewable Pictures Shown by Television Receiving Sets

AGENCY: Federal Trade Commission. **ACTION:** Request for public comments.

SUMMARY: The Federal Trade Commission ("FTC" or "Commission") requests public comment on the overall costs, benefits, and regulatory and economic impact of its Rule concerning Deceptive Advertising as to Sizes of Viewable Pictures Shown by Television Receiving Sets ("Rule" or "Picture Tube Rule"), as part of the Commission's systematic review of all current Commission regulations and guides. DATES: Written comments will be accepted until Monday, June 6, 2005. **ADDRESSES:** Interested parties are invited to submit written comments. Comments should refer to "Picture Tube Rule Regulatory Review, Matter No. P924214" to facilitate the organization of comments. A comment filed in paper form should include this reference both in the text and on the envelope, and should be mailed or delivered to the following address: Federal Trade Commission/Office of the Secretary, Room H-159 (Annex B), 600 Pennsylvania Avenue, NW., Washington, DC 20580. Comments containing confidential material must be filed in paper form and the first page of the document must be clearly labeled "Confidential." The FTC is requesting that any comment filed in paper form be sent by courier or overnight service, if possible, because postal mail in the Washington area and at the Commission is subject to delay due to heightened security precautions. Comments filed in electronic form should be submitted by clicking on the following: https:// secure.commentworks.com/ftc-picture and following the instructions on the Web-based form. To ensure that the Commission considers an electronic comment, you must file it on the Webbased form at https://

secure.commentworks.com/ftc-picture.
The FTC Act and other laws the
Commission administers permit the
collection of public comments to

consider and use in this proceeding as appropriate. The Commission will consider all timely and responsive public comments that it receives, whether filed in paper or electronic form. Comments received will be available to the public on the FTC Web site, to the extent practicable, at http:/ /www.ftc.gov. As a matter of discretion, the FTC makes every effort to remove home contact information for individuals from the public comments it receives before placing those comments on the FTC Web site. More information, including routine uses permitted by the Privacy Act, may be found in the FTC's privacy policy, at http://www.ftc.gov/ ftc/privacy.htm.

FOR FURTHER INFORMATION CONTACT: Neil Blickman, (202) 326–3038, Attorney, Division of Enforcement, Bureau of Consumer Protection, Federal Trade Commission, 600 Pennsylvania Avenue, NW., Washington, DC 20580.

SUPPLEMENTARY INFORMATION:

I. Background

The Commission's Picture Tube Rule, like the other trade regulation rules issued by the Commission, "define[s] with specificity acts or practices which are unfair or deceptive acts or practices in or affecting commerce. Such rules may include requirements prescribed for the purpose of preventing such acts or practices. A violation of a rule shall constitute an unfair or deceptive act or practice in violation of section 5(a)(1) of the [Federal Trade Commission] Act, unless the Commission otherwise expressly provides in its rule." 16 CFR 1.8.

The Picture Tube Rule, promulgated in 1966, sets forth the appropriate means for disclosing the method by which the dimensions of television screens are measured, when this measurement is included in any advertisement or promotional material for the television set. The purpose of the Rule is to establish uniformity in measuring television screens, and advise consumers of this method, thereby aiding comparison shopping for televisions. Under the Rule, any representation of the screen size must be based on the horizontal dimension of the actual, viewable picture area. Using any other measurement is unfair and deceptive, unless the method of measurement is clearly and conspicuously disclosed in close proximity to the size designation. The Rule notes that the horizontal measurement must not take into account any curvature of the tube. Further, disclosing the method of measurement in a footnote rather than in the body of

the advertisement does not constitute a disclosure in close proximity to the measurement. The Rule includes examples of both proper and improper representations of size descriptions.

In 1994, the Rule was amended to clarify some of the Rule's compliance illustrations, provide metric equivalents for the measurements stated in inches in the Rule's examples, and add a new Note 3 to the Rule to explain that the inclusion of metric figures is for information purposes only and does not impose a requirement on the industry to use metric measurements. 59 FR 54809 (Nov. 2, 1994).

Since the Rule was last subject to regulatory review and amended in 1994, broadcasting and television technology have advanced significantly, and an array of new types of televisions are available in the marketplace for consumers. The technological change with the closest nexus to the Rule is the introduction of digital television, including high definition television, and the advent of new wider screen televisions to display these enhanced digital pictures. New television display technologies available today include thin, flat panel televisions with either liquid crystal displays or plasma display panels. In addition, there have been advances in the quality and popularity of front and rear, big screen, projection televisions. Accordingly, the Commission seeks comment on the effect, if any, that advances in television technology have had on the Rule.

II. Regulatory Review Program

The Commission has determined to review all Commission rules and guides periodically. These reviews seek information about the costs and benefits of the Commission's rules and guides and their regulatory and economic impact. The information obtained assists the Commission in identifying rules and guides that warrant modification or rescission. Therefore, the Commission solicits comment on, among other things, the economic impact of its Picture Tube Rule; possible conflict between the Rule and state, local, or other federal laws; and the effect on the Rule of any technological, economic, or other industry changes.

III. Request for Comment

The Commission solicits written public comment on the following questions:

(1) Is there a continuing need for the Rule as currently promulgated?

(2) Has the television industry adopted the Rule's disclosure requirements as part of its routine business practice? If so, how, and what