

Adoption of the Amendment

■ Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

2005-09-07 Agusta S.p.A.: Amendment 39-14075. Docket No. FAA-2005-20292; Directorate Identifier 2004-SW-26-AD.

Applicability: Model A109E helicopters, certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To detect a fracture, a crack, or looseness of a main transmission support fitting (fitting) attachment bolt (bolt), and prevent fatigue failure of a fitting bolt and subsequent loss of control of the helicopter, accomplish the following:

(a) Within 5 hours time-in-service (TIS), and then at intervals not to exceed 10 hours TIS until a torque inspection of each fitting bolt is accomplished in accordance with paragraph (b) of this AD, inspect each fitting bolt, part number NAS625-14, for a fracture, a crack, or looseness using a light and a mirror in accordance with Part I, steps 1. through 4., of Agusta Bollettino Tecnico No. 109EP-43, dated March 25, 2004 (BT).

(1) On each of the 4 fittings, if a fracture or a crack is found in any bolt, replace all 4 bolts in the fitting with airworthy fitting bolts before further flight.

(2) If looseness is found in any bolt in any fitting, inspect each of the 4 bolts on each of the 4 fittings (16 bolts total) to determine if the torque is between 11.3-15.8 Nm (100-140 inch-pounds). If the indicated torque is not within the acceptable range on any bolt in a fitting, before further flight, remove all 4 bolts in the fitting and replace them with airworthy fitting bolts in accordance with Part II, steps 5.1 through 9. of the BT.

(b) Within 25 hours TIS, inspect each bolt in each fitting to determine if the torque is between 11.3-15.8 Nm (100-140 inch-pounds). If the indicated torque is not within the acceptable range on any bolt, before further flight, remove all 4 bolts in the fitting and replace them with airworthy fitting bolts in accordance with Part II, steps 5.1 through 9., of the BT.

(c) Accomplishing the inspections specified in paragraphs (a) and (b) constitute terminating actions for the requirements of this AD.

(d) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Contact the Safety Management Group, Rotorcraft Directorate, FAA, for information

about previously approved alternative methods of compliance.

(e) Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199 to operate the helicopter to a location where the requirements of this AD can be accomplished, provided that no fracture or crack or looseness was found during the inspections required by this AD.

(f) The inspections and replacements shall be done in accordance with Agusta Bollettino Tecnico No. 109EP-43, dated March 25, 2004. The Director of the Federal Register approved this incorporation by reference in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Agusta, 21017 Cascina Costa di Samarate (VA) Italy, Via Giovanni Agusta 520, telephone 39 (0331) 229111, fax 39 (0331) 229605-222595. Copies may be inspected at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

(g) This amendment becomes effective on June 13, 2005.

Note: The subject of this AD is addressed in Ente Nazionale per l'Aviazione Civile (Italy) AD No. 2004-099, dated March 29, 2004.

Issued in Fort Worth, Texas, on April 27, 2005.

Carl F. Mittag,

Acting Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 05-8952 Filed 5-6-05; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2005-20291; Directorate Identifier 2004-SW-25-AD; Amendment 39-14074; AD 2005-09-06]

RIN 2120-AA64

Airworthiness Directives; Agusta S.p.A. Model A119 Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD) for Agusta S.p.A. (Agusta) Model A119 helicopters that requires visually inspecting each main transmission support fitting (fitting) attachment bolt (bolt) for a fracture, a crack, or looseness, and verifying the torque on each fitting bolt. This amendment is prompted by two incidents of fatigue failure of the bolts that secure the transmission rear support fittings to the helicopter. The actions specified by this

AD are intended to detect a fracture, a crack, or looseness of a fitting bolt, and prevent fatigue failure of a fitting bolt and subsequent loss of control of the helicopter.

DATES: Effective June 13, 2005.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of June 13, 2005.

ADDRESSES: You may get the service information identified in this AD from Agusta, 21017 Cascina Costa di Samarate (VA) Italy, Via Giovanni Agusta 520, telephone 39 (0331) 229111, fax 39 (0331) 229605-222595.

Examining the Docket: You may examine the docket that contains this AD, any comments, and other information on the Internet at <http://dms.dot.gov>, or at the Docket Management System (DMS), U.S. Department of Transportation, 400 Seventh Street SW., Room PL-401, on the plaza level of the Nassif Building, Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Sharon Miles, Aviation Safety Engineer, FAA, Rotorcraft Directorate, Regulations and Guidance Group, Fort Worth, Texas 76193-0111, telephone (817) 222-5122, fax (817) 222-5961.

SUPPLEMENTARY INFORMATION: A proposal to amend 14 CFR part 39 to include an AD for Agusta Model A119 helicopters was published in the **Federal Register** on February 10, 2005 (70 FR 7057). That action proposed to require inspecting each fitting bolt, part number (P/N) NAS625-14 and P/N NAS625-18, for a fracture, a crack, or looseness, within 5 hours time-in-service (TIS) and then at intervals not to exceed 10 hours TIS until accomplishing a torque inspection of each fitting bolt. The torque inspection would have to be accomplished before further flight if looseness is found, or within 25 hours TIS if looseness is not found. If a fracture or a crack is found on any bolt in a fitting, replacing all 4 of the bolts in the fitting would be required. If looseness is detected on any fitting bolt, a torque inspection would be required. If any torque inspection reveals that the torque of any bolt in a fitting is not between 11.3-15.8 Nm (100-140 inch-pounds), all 4 of the bolts in the fitting would have to be replaced with airworthy fitting bolts before further flight.

The Ente Nazionale per l'Aviazione Civile (ENAC), the airworthiness authority for Italy, notified the FAA that an unsafe condition may exist on Agusta Model A119 helicopters. ENAC advises

of the need to check the bolts that secure the transmission support fittings to the structure by following the manufacturer's Bollettino Tecnico 119-8, dated April 7, 2004.

Agusta has issued Bollettino Tecnico No. 119-8, dated April 7, 2004, which specifies a periodic visual inspection to verify the condition (visible damage) of the airframe mounted main transmission fittings attaching hardware, and successively checking the torque of the bolts to exclude the possible presence of looseness and/or a fracture or a crack. ENAC classified this bollettino tecnico as mandatory and issued AD No. 2004-108, dated April 8, 2004, to ensure the continued airworthiness of these helicopters in Italy.

This helicopter model is manufactured in Italy and is type certificated for operation in the United States under the provisions of 14 CFR 21.29 and the applicable bilateral agreement. Pursuant to the applicable bilateral agreement, ENAC has kept the FAA informed of the situation described above. The FAA has examined the findings of ENAC, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were received on the proposal or the FAA's determination of the cost to the public. The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

We estimate that this AD will affect 21 helicopters of U.S. registry. The three inspections (one initial, one repetitive, and the torque inspection) will take approximately 4 work hours to accomplish at an average labor rate of \$65 per work hour. (The manufacturer states that it shall recognize a reimbursement of \$120 per helicopter for the labor.) Required parts will cost approximately \$1,600 per helicopter (\$100 per fitting bolt for 16 fitting bolts). Based on these figures, we estimate the total cost impact of the AD on U.S. operators to be \$39,060, assuming that no warranty credit is available and that all affected fitting bolts are replaced.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and

responsibilities among the various levels of government.

For the reasons discussed above, I certify that the regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared an economic evaluation of the estimated costs to comply with this AD. See the DMS to examine the economic evaluation.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

2005-09-06 Agusta S.p.A.: Amendment 39-14074. Docket No. FAA-2005-20291; Directorate Identifier 2004-SW-25-AD.

Applicability: Model A119 helicopters, serial numbers 14001 through 14037, except serial number 14036, certificated in any category.

Compliance: Required as indicated, unless accomplished previously. To detect a fracture, a crack, or looseness of a main transmission support fitting (fitting) attachment bolt (bolt) and prevent fatigue failure of a fitting bolt and subsequent loss of control of the helicopter, accomplish the following:

(a) Within 5 hours time-in-service (TIS), and then at intervals not to exceed 10 hours TIS until a torque inspection of each fitting bolt is accomplished in accordance with paragraph (b) of this AD, inspect each fitting bolt, part number NAS625-14 and NAS625-18, for a fracture, a crack, or looseness, using a light and a mirror.

(1) On each of the 4 fittings, if a fracture or a crack is found in any bolt, replace all 4 bolts in the fitting with airworthy fitting bolts before further flight.

(2) If looseness is found in any bolt in any fitting, inspect each of the 4 bolts on each of the 4 fittings (16 bolts total) to determine if the torque is between 11.3-15.8 Nm (100-140 inch-pounds). If the indicated torque is not within the acceptable range on any bolt in a fitting, before further flight, remove all 4 bolts in the fitting and replace them with airworthy fitting bolts in accordance with Part II, steps 4.1 through 5., of Agusta Bollettino Tecnico No. 119-8, dated April 7, 2004 (BT).

(b) Within 25 hours TIS, inspect each bolt in each fitting to determine if the torque is between 11.3-15.8 Nm (100-140 inch-pounds). If the indicated torque is not within the acceptable range on any bolt, before further flight, remove all 4 bolts in the fitting and replace them with airworthy fitting bolts in accordance with Part II, steps 4.1 through 5., of the BT.

(c) Accomplishing the inspections specified in paragraphs (a) and (b) constitute terminating actions for the requirements of this AD.

(d) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Contact the Safety Management Group, Rotorcraft Directorate, FAA, for information about previously approved alternative methods of compliance.

(e) Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199 to operate the helicopter to a location where the requirements of this AD can be accomplished, provided that no fracture, crack, or looseness was found during the inspections required by this AD.

(f) The inspections and replacements shall be done in accordance with Agusta Bollettino Tecnico No. 119-8, dated April 7, 2004. The Director of the Federal Register approved this incorporation by reference in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Agusta, 21017 Cascina Costa di Samarate (VA) Italy, Via Giovanni Agusta 520, telephone 39 (0331) 229111, fax 39 (0331) 229605-222595. Copies may be inspected at the National Archives and Records Administration (NARA). For information on the availability of this

material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

(g) This amendment becomes effective on June 13, 2005.

Note: The subject of this AD is addressed in Ente Nazionale per l'Aviazione Civile (Italy) AD No. 2004-108, dated April 8, 2004.

Issued in Fort Worth, Texas, on April 27, 2005.

Carl Mittag,

Acting Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 05-8953 Filed 5-6-05; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF HOMELAND SECURITY

Coast Guard

33 CFR Part 165

[CGD13-05-013]

RIN 1625-AA87

Security Zone; Protection of Military Cargo, Captain of the Port Zone Puget Sound, WA

AGENCY: Coast Guard, DHS.

ACTION: Notice of enforcement.

SUMMARY: The Captain of the Port Puget Sound will begin enforcing the Budd Inlet security zone in West Bay, Olympia, WA on Monday, May 9, 2005, at 8 a.m. Pacific daylight time. The security zone provides for the security of Department of Defense assets and military cargo in the navigable waters of Puget Sound and adjacent waters. The security zone will be enforced until Friday, May 13, 2005, at 11:59 p.m. Pacific daylight time.

DATES: The Budd Inlet security zone set forth in 33 CFR 165.1321 will be enforced from Monday, May 9, 2005, at 8 a.m. to Friday, May 13, 2005, at 11:59 p.m. Pacific daylight time, at which time enforcement will be suspended.

FOR FURTHER INFORMATION CONTACT: Captain of the Port Puget Sound, 1519 Alaskan Way South, Seattle, WA 98134 at (206) 217-6200 or (800) 688-6664 to obtain information concerning enforcement of 33 CFR 165.1321.

SUPPLEMENTARY INFORMATION: On August 27, 2004, the Coast Guard published a final rule (69 FR 52603) establishing regulations, in 33 CFR 165.1321, for the security of Department of Defense assets and military cargo in the navigable waters of Puget Sound and adjacent waters. On December 10, 2004, the Coast Guard published a final rule (69 FR 71709), which amended 33 CFR

165.1321 by adding Budd Inlet, Olympia, WA as a permanent security zone. These security zones provide for the regulation of vessel traffic in the vicinity of military cargo loading facilities in the navigable waters of the United States. These security zones also exclude persons and vessels from the immediate vicinity of these facilities during military cargo loading and unloading operations. In addition, the regulation establishes requirements for all vessels to obtain permission of the COTP or the COTP's designated representative, including the Vessel Traffic Service Puget Sound (VTS) to enter, move within, or exit these security zones when they are enforced. Entry into these zones is prohibited unless otherwise exempted or excluded under 33 CFR 165.1321 or unless authorized by the Captain of the Port or his designee.

The Captain of the Port Puget Sound will begin enforcing the Budd Inlet security zone established by 33 CFR 165.1321 on Monday, May 9, 2005, at 8 a.m. Pacific daylight time. The security zone will be enforced until Friday, May 13, 2005, at 11:59 p.m. Pacific daylight time. All persons and vessels are authorized to enter, move within, and exit the security zone on or after Friday, May 13, 2005, at 11:59 p.m. Pacific daylight time unless a new notice of enforcement is issued before then.

Dated: May 3, 2005.

Danny Ellis,

Captain, U.S. Coast Guard, Captain of the Port, Puget Sound.

[FR Doc. 05-9208 Filed 5-6-05; 8:45 am]

BILLING CODE 4910-15-P

LIBRARY OF CONGRESS

Copyright Office

37 CFR Part 270

[Docket No. RM 2005-2A]

Reports of Use of Sound Recordings Under Statutory License

AGENCY: Copyright Office, Library of Congress.

ACTION: Final rule.

SUMMARY: The Copyright Office of the Library of Congress is adopting amendments to the rules governing reports of use of sound recordings under the statutory license for preexisting subscription services.

DATES: June 8, 2005.

FOR FURTHER INFORMATION CONTACT: David O. Carson, General Counsel, or

William J. Roberts, Jr. Telephone: (202) 707-8380. Telefax: (202) 252-3423.

SUPPLEMENTARY INFORMATION: Digital audio services provide copyrighted sound recordings of music for the listening enjoyment of the users of those services. In order to provide these sound recordings, however, a digital audio service must license the copyrights to each musical work, as well as the sound recording of the musical work. There are two statutory licenses in the Copyright Act that enable a digital audio service to transmit performances of copyrighted sound recordings: section 112 and section 114. 17 U.S.C. 112 & 114. Congress initially established these licenses in the Digital Performance Right in Sound Recordings Act of 1995, Pub. L. No. 104-39, for subscription digital audio services then in existence, and later amended sections 112 and 114 in the Digital Millennium Copyright Act of 1998, Pub. L. No. 105-304, to include other types of digital audio services. It is the former category of services (hereinafter referred to as "preexisting subscription services") to which this final rule applies.

On June 24, 1998, the Copyright Office published interim regulations establishing the requirements by which copyright owners receive reasonable notice of the use of their works from preexisting subscription services, and how reports of use shall be kept and made available to copyright owners. Originally codified at §§ 201.35 through 201.37 of title 37 of the Code of Federal Regulations, these regulations have recently been moved to part 270 of the CFR, but have remained unchanged. On March 18, 2003, the preexisting subscription services—Music Choice, DMX Music Inc., and Muzak LLC—and representative organizations of copyright owners of sound recordings—SoundExchange, Inc., the American Federation of Television and Radio Artists, and the American Federation of Musicians—filed a petition with the Copyright Office seeking to amend the regulations regarding reports of use (formerly § 201.36, now § 270.2) for preexisting subscription services. At that time, the Office was conducting a rulemaking proceeding to establish notice and recordkeeping requirements for digital audio services other than preexisting subscription services and declined to include the petition in that proceeding. See 69 FR 11515, 11517 n.9 (March 11, 2004). Instead, the Office determined to address the petition "in a separate **Federal Register** document." *Id.* A Notice of Proposed Rulemaking ("NPRM") was published on March 15, 2005. 70 FR 12631 (March 15, 2005).