

Revision to Airworthiness Limitations

(g) Within 12 months after the effective date of this AD, revise the Airworthiness Limitations section of the Instructions for Continued Airworthiness by inserting a copy of Dornier Temporary Revision ALD-080, dated October 15, 2003, into the Dornier 328 Airworthiness Limitations Document. Thereafter, except as provided in paragraph (h) of this AD, no alternative inspection intervals may be approved for this fuel tank system.

Alternative Methods of Compliance (AMOCs)

(h) The Manager, International Branch, ANM-116, Transport Airplane Directorate,

FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

Related Information

(i) German airworthiness directive D-2005-001, dated January 26, 2005, also addresses the subject of this AD.

Material Incorporated by Reference

(j) You must use the service information specified in Table 2 of this AD to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approves the incorporation by reference of these documents in accordance with 5 U.S.C.

552(a) and 1 CFR part 51. To get copies of the service information, contact AvCraft Aerospace GmbH, P.O. Box 1103, D-82230 Wessling, Germany. To view the AD docket, go to the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW, room PL-401, Nassif Building, Washington, DC. To review copies of the service information, go to the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

TABLE 2.—MATERIAL INCORPORATED BY REFERENCE

Service information	Date
AvCraft Service Bulletin SB-328-00-445, including Price Information Sheet	August 23, 2004.
Dornier Temporary Revision ALD-080	October 15, 2003.

Issued in Renton, Washington, on June 15, 2005.

Kevin Mullin,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 05-12304 Filed 6-23-05; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002-NM-332-AD; Amendment 39-14158; AD 2005-13-21]

RIN 2120-AA64

Airworthiness Directives; Cessna Model 650 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to all Cessna Model 650 airplanes, that requires inspecting to determine the part number of the actuator control unit (ACU) and replacing the ACU with a new, improved ACU if necessary. This AD also requires revising the Limitations section of the airplane flight manual. The actions specified by this AD are intended to prevent uncommanded movement of the horizontal stabilizer, which could result in reduced controllability of the airplane. This action is intended to address the identified unsafe condition.

DATES: Effective July 29, 2005.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of July 29, 2005.

ADDRESSES: The service information referenced in this AD may be obtained from Cessna Aircraft Co., P.O. Box 7706, Wichita, Kansas 67277. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas.

FOR FURTHER INFORMATION CONTACT: Robert P. Busto, Aerospace Engineer, Systems and Propulsion Branch, ACE-116W, FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas 67209; telephone (316) 946-4157; fax (316) 946-4107.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to all Cessna Model 650 airplanes was published as a supplemental notice of proposed rulemaking (NPRM) in the **Federal Register** on April 22, 2005 (70 FR 20844). That action proposed to require inspecting to determine the part number of the actuator control unit (ACU) and replacing the ACU with a new, improved ACU if necessary. That action also proposed to require revising the Limitations section of the airplane flight manual.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. We did not receive any comments on the proposed AD.

Conclusion

After careful review of the available data, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

Cost Impact

There are approximately 357 airplanes of the affected design in the worldwide fleet. The FAA estimates that 285 airplanes of U.S. registry will be affected by this AD.

We estimate that it will take approximately 2 work hours per airplane to replace the ACU, and that the average labor rate is \$65 per work hour. Required parts will cost approximately \$3,000 per airplane, if the ACU is exchanged. Based on these figures, the cost impact of the AD on U.S. operators is estimated to be \$892,050, or \$3,130 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by

other administrative actions. The manufacturer may cover the cost of replacement parts associated with this proposed AD, subject to warranty conditions. As a result, the costs attributable to the proposed AD may be less than stated above.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the National Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not

have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. Section 39.13 is amended by adding the following new airworthiness directive:

2005-13-21 Cessna Aircraft Company:

Amendment 39-14158. Docket 2002-NM-332-AD.

Applicability: All Model 650 airplanes, certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To prevent uncommanded movement of the horizontal stabilizer, which could result in reduced controllability of the airplane, accomplish the following:

Inspection and Replacement if Necessary

(a) Within 12 months after the effective date of this AD, inspect to determine the part number (P/N) of the actuator control unit (ACU), in accordance with the Accomplishment Instructions of Cessna Service Bulletin SB 650-27-53, dated March 11, 2004. If an ACU having P/N 9914197-7 is installed on the airplane, then no further action is required by this paragraph. If an ACU having P/N 9914197-3 or P/N 9914197-4 is installed on the airplane, replace the existing ACU with a new, improved ACU having P/N 9914197-7, in accordance with the service bulletin. Although the service bulletin specifies to submit certain information to the manufacturer, this AD does not include that requirement.

Airplane Flight Manual (AFM) Revision

(b) Within 1 month after the effective date of this AD or concurrently with the replacement required by paragraph (a) of this AD, whichever is first: Revise the Limitations and Normal Procedures sections of the AFM by inserting into the AFM a copy of all the applicable Cessna temporary revisions (TRs) listed in Table 1 of this AD.

Note 1: When a statement identical to that in the applicable TR(s) listed in Table 1 of this AD has been included in the general revisions of the AFM, the general revisions may be inserted into the AFM, and the copy of the applicable TR may be removed from the AFM.

TABLE 1.—AFM REVISION

Applicable model 650 airplanes	Cessna TR(s)
Citation III, S/Ns 0001 through 0199 inclusive, and 0203 through 0206 inclusive; equipped with Honeywell SPZ-8000 integrated avionics system.	65C3FM TC-R02-01, dated May 12, 2004; and 65C3FM TC-R02-06, dated August 11, 2004.
Citation III, S/Ns 0001 through 0199 inclusive, and 0203 through 0206 inclusive; not equipped with Honeywell SPZ-8000 integrated avionics system.	65C3FM TC-R02-01, dated May 12, 2004; and 65C3FM TC-R02-07, dated August 11, 2004.
Citation VI, S/Ns 0200 through 0202 inclusive, and 0207 and subsequent	65C6FM TC-R04-01, dated May 12, 2004; and 65C6FM TC-R04-06, dated August 11, 2004.
Citation VII, S/Ns 7001 and subsequent	65C7FM TC-R10-01, dated May 12, 2004.
Citation VII, S/Ns 7001 and subsequent, equipped with Honeywell SPZ-8000 integrated avionics system.	65C7FM TC-R10-07, dated August 11, 2004.

Parts Installation

(c) As of the effective date of this AD, no person may install an ACU having P/N 9914197-3 or -4, on any airplane.

Alternative Methods of Compliance

(d) In accordance with 14 CFR 39.19, the Manager, Wichita Aircraft Certification

Office, FAA, is authorized to approve alternative methods of compliance for this AD.

Incorporation by Reference

(e) Unless otherwise specified in this AD, the actions must be done in accordance with the service information listed in Table 2 of this AD. This incorporation by reference was

approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. To get copies of this service information, contact Cessna Aircraft Co., P.O. Box 7706, Wichita, Kansas 67277. To inspect copies of this service information, go to the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or to the FAA, Wichita Aircraft

Certification Office, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas; or to the National Archives and

Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741-6030,

or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

TABLE 2.—MATERIAL INCORPORATED BY REFERENCE

Cessna Service Information	Date
Service Bulletin SB 650-27-53	March 11, 2004.
Temporary Revision 65C3FM TC-R02-01	May 12, 2004.
Temporary Revision 65C3FM TC-R02-06	August 11, 2004.
Temporary Revision 65C3FM TC-R02-07	August 11, 2004.
Temporary Revision 65C6FM TC-R04-01	May 12, 2004.
Temporary Revision 65C6FM TC-R04-06	August 11, 2004.
Temporary Revision 65C7FM TC-R10-01	May 12, 2004.
Temporary Revision 65C7FM TC-R10-07	August 11, 2004.

Effective Date

(f) This amendment becomes effective on July 29, 2005.

Issued in Renton, Washington, on June 14, 2005.

Kevin M. Mullin,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 05-12306 Filed 6-23-05; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2004-18784; Directorate Identifier 2004-NM-59-AD; Amendment 39-14157; AD 2005-13-20]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 747-400, -400D, -400F; 767-200, -300, -300F; and 777-200 and -300 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Boeing Model 747-400, -400D, -400F; 767-200, -300, -300F; and 777-200 and -300 series airplanes. This AD requires installing a jumper wire between the wiring of the fire extinguisher switch and the fuel shutoff switch for each engine, and other specified actions. This AD is prompted by a certain combination of conditions, which could cause the fuel spar shutoff valves to remain partially open. We are issuing this AD to prevent a latent open circuit that could leave the fuel spar shutoff valve in a partially open position when the engine fire switch is activated, which could result in fuel from the engine feeding an uncontrolled fire in the engine or the strut.

DATES: This AD becomes effective July 29, 2005.

The incorporation by reference of certain publications listed in the AD is approved by the Director of the Federal Register as of July 29, 2005.

ADDRESSES: For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

Docket: The AD docket contains the proposed AD, comments, and any final disposition. You can examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the U.S. Department of Transportation, 400 Seventh Street SW., room PL-401, Washington, DC. This docket number is FAA-2004-18784; the directorate identifier for this docket is 2004-NM-59-AD.

FOR FURTHER INFORMATION CONTACT: Sulmo Mariano, Aerospace Engineer, Propulsion Branch, ANM-140S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 917-6501; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION: The FAA proposed to amend 14 CFR part 39 with an AD for certain Boeing Model 747-400, -400D, -400F; 767-200, -300, -300F; and 777-200 and -300 series airplanes. That action, published in the **Federal Register** on August 6, 2004 (69 FR 47802), proposed to require installing a jumper wire between the wiring of the fire extinguisher switch and the fuel shutoff switch for each engine, and other specified actions.

Comments

We provided the public the opportunity to participate in the development of this AD. We have

considered the comments that have been submitted on the proposed AD.

Supportive Comment

One commenter states that they have accomplished the necessary airplane modifications on all affected Model 777-200 series airplanes in their fleet. In addition, the commenter states that no additional work is necessary to comply with Boeing Service Bulletin 777-28-0025, Revision 1, dated March 17, 2005. The commenter did not state any finding of service problems or errors in either the service bulletins or the AD, nor has the commenter suggested any change to the AD. We infer that the commenter has no objections to the AD.

Request to Revise Service Bulletin References

One commenter requests that we coordinate the release of this AD with the pending revisions to Boeing Special Attention Service Bulletins 747-28-2238, dated October 18, 2001; and 777-28-0025, dated January 10, 2002. The commenter states that several information notices describe changes to the work instructions that will be incorporated into pending service bulletin revisions. If this AD is released calling for the un-revised service bulletins, each airline would need to request an alternative method of compliance (AMOC) to allow the incorporation of the revised work instructions. We infer that the commenter wants the AD to reference the revised service bulletins.

We agree with the commenter's request to reference the revised service bulletins. We have reviewed Boeing Service Bulletins 747-28-2238, Revision 1; and 777-28-0025, Revision 1; both dated March 17, 2005. The revisions incorporate the changes described in the information notices. Paragraph (f) of this AD has been revised to refer to Revision 1 of Boeing Service Bulletins 747-28-2238 and 777-28-0025. Paragraph (g) of the