

Applicability

(c) This AD applies to Fokker Model F27 Mark 200, 400, 500, and 600 airplanes, certificated in any category; serial numbers 10505 through 10591 inclusive; not equipped with inboard wing fuel tanks.

Unsafe Condition

(d) This AD was prompted by investigation of a recent accident, which found that the rotary knobs controlling the fuel tank isolating valves had been in the shut position. We are issuing this AD to ensure that the rotary knobs are not inadvertently moved to the shut position, which could result in fuel starvation to both engines and consequent inability to maintain controlled flight and landing.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Inspection and Corrective Action if Applicable

(f) Within 3 months after the effective date of this AD, do a general visual inspection of the rotary knobs for the fuel tank isolation valves to determine if the seal wire is installed correctly and do the corrective action(s) as applicable, in accordance with the Accomplishment Instructions of Fokker Service Bulletin F27/28-67, dated February 23, 2004. Do the applicable corrective actions before further flight.

Note 1: For the purposes of this AD, a general visual inspection is: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made from within touching distance unless otherwise specified. A mirror may be necessary to ensure visual access to all surfaces in the inspection area. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or droplight and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

Credit for Alternative Method of Compliance

(g) Actions done before the effective date of this AD in accordance with Fokker Service Bulletin F27/28-58, dated May 12, 1986, are acceptable for compliance with the requirements of paragraph (f) of this AD.

Parts Installation

(h) As of the effective date of this AD, no person may install a rotary knob having part number E16032-3, 10632-10003, or P80-004 on any airplane, unless the corrective actions specified in paragraph (f) of this AD have been accomplished.

No Reporting Requirement

(i) Although the service bulletin referenced in this AD specifies to submit certain information to the manufacturer, this AD does not include that requirement.

Alternative Methods of Compliance (AMOCs)

(j) The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

Related Information

(k) Dutch airworthiness directive 2004-037 R1, dated April 14, 2005, also addresses the subject of this AD.

Issued in Renton, Washington, on June 21, 2005.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 05-12838 Filed 6-28-05; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2005-21701; Directorate Identifier 2005-NM-086-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 747 and 767 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Boeing Model 747 and 767 airplanes. This proposed AD would require reworking the electrical bonding between the airplane structure and the pump housing of the outboard boost pumps in the main fuel tank of certain Boeing Model 747 airplanes, and between the airplane structure and the pump housing of the override/jettison pumps in the left and right wing center auxiliary fuel tanks of certain Boeing Model 767 airplanes. This proposed AD would also require related investigative actions and corrective actions if necessary. This proposed AD is prompted by the results of fuel system reviews conducted by the manufacturer. We are proposing this AD to prevent insufficient electrical bonding, which could result in a potential of ignition sources inside the fuel tanks, and which, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane.

DATES: We must receive comments on this proposed AD by August 15, 2005.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

- DOT Docket Web site: Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- Government-wide rulemaking Web site: Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- Mail: Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, room PL-401, Washington, DC 20590.

- By fax: (202) 493-2251.

- Hand Delivery: Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

You can examine the contents of this AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., room PL-401, on the plaza level of the Nassif Building, Washington, DC. This docket number is FAA-2005-21701; the directorate identifier for this docket is 2005-NM-086-AD.

FOR FURTHER INFORMATION CONTACT:

Diane Pagel, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 917-6488; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:**Comments Invited**

We invite you to submit any relevant written data, views, or arguments regarding this proposed AD. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2005-21701; Directorate Identifier 2005-NM-086-AD" in the subject line of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments submitted by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of that Web

site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You can review DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you can visit <http://dms.dot.gov>.

Examining the Docket

You can examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the DOT street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the Docket Management System (DMS) receives them.

Discussion

The FAA has examined the underlying safety issues involved in recent fuel tank explosions on several large transport airplanes, including the adequacy of existing regulations, the service history of airplanes subject to those regulations, and existing maintenance practices for fuel tank systems. As a result of those findings, we issued a regulation titled "Transport Airplane Fuel Tank System Design Review, Flammability Reduction and Maintenance and Inspection Requirements" (67 FR 23086, May 7, 2001). In addition to new airworthiness standards for transport airplanes and new maintenance requirements, this rule included Special Federal Aviation Regulation No. 88 ("SFAR 88," Amendment 21-78, and subsequent Amendments 21-82 and 21-83).

Among other actions, SFAR 88 requires certain type design (*i.e.*, type certificate (TC) and supplemental type certificate (STC)) holders to substantiate that their fuel tank systems can prevent ignition sources in the fuel tanks. This requirement applies to type design holders for large turbine-powered transport airplanes and for subsequent modifications to those airplanes. It requires them to perform design reviews and to develop design changes and maintenance procedures if their designs do not meet the new fuel tank safety standards. As explained in the preamble to the rule, we intended to adopt airworthiness directives to mandate any changes found necessary to address

unsafe conditions identified as a result of these reviews.

In evaluating these design reviews, we have established four criteria intended to define the unsafe conditions associated with fuel tank systems that require corrective actions. The percentage of operating time during which fuel tanks are exposed to flammable conditions is one of these criteria. The other three criteria address the failure types under evaluation: Single failures, single failures in combination with another latent condition(s), and in-service failure experience. For all four criteria, the evaluations included consideration of previous actions taken that may mitigate the need for further action.

We have received a report indicating that the outboard boost pumps in the main fuel tank of certain Boeing Model 747 airplanes, and the override/jettison pumps in the left and right wing center auxiliary fuel tanks of certain Boeing Model 767 airplanes, have insufficient electrical bonding between the pump housing and the airplane structure. This condition, if not corrected, could result in an ignition source inside the fuel tanks, which, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane.

Relevant Service Information

We have reviewed Boeing Special Attention Service Bulletin 747-28-2259, dated November 4, 2004 (for Boeing Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series airplanes). This service bulletin describes procedures for reworking the electrical bonding between the airplane structure and the pump housing of the outboard boost pumps in the main fuel tank, and related investigative and corrective actions. The rework consists of replacing the four mounting fasteners on each of the pump housings with rivets, stenciling each new rivet with the statement: "CAUTION—BONDING RIVET," and, when the related investigative actions are completed, sealing the new rivets as specified in the airplane maintenance manual. The related investigative actions are measuring the electrical resistance of the new rivets, and doing an open-hole high-frequency eddy current (HFEC) inspection for cracks, corrosion, and damage. If the resistance is greater than the maximum allowable resistance specified in the service bulletin, the procedures include reworking the bonding as necessary according to the

standard wiring practices manual, until the resistance is within allowable limits.

We have also reviewed Boeing Special Attention Service Bulletin 767-57-0092, dated November 4, 2004 (for Boeing Model 767-200, -300, and -300F series airplanes); and Boeing Special Attention Service Bulletin 767-57-0093, dated November 4, 2004 (for Boeing Model 767-400ER series airplanes). These service bulletins describe procedures for reworking the electrical bonding between the airplane structure and the pump housing of the override/jettison pumps in the left and right wing center auxiliary fuel tanks, and related investigative actions and corrective actions. The rework consists of cleaning the wing rib/ground bracket bonding surface, installing new fasteners for the ground brackets of the fuel override/jettison pump, using new bonding processes during the installation, and sealing the ground brackets. The related investigative actions are measuring the electrical resistance at specified points in the rework process. If the electrical resistance is greater than the maximum allowable resistance specified in the service bulletin, the corrective action specified in the procedures includes repeating the applicable corrective actions and the applicable related investigative actions until the resistance is within allowable limits.

Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition.

FAA's Determination and Requirements of the Proposed AD

We have evaluated all pertinent information and identified an unsafe condition that is likely to exist or develop on other airplanes of this same type design. Therefore, we are proposing this AD, which would require accomplishing the actions specified in the service information described previously, except as discussed under "Difference Between the Proposed AD and Special Attention Service Bulletin 747-28-2259."

Difference Between the Proposed AD and Special Attention Service Bulletin 747-28-2259

Although Boeing Special Attention Service Bulletin 747-28-2259 does not specify an action to take if any crack, corrosion, or damage is found during the open-hole HFEC inspection, this proposed AD would require operators to repair those conditions in one of the following ways:

- Using a method that we approve; or

• Using data that meet the certification basis of the airplane, and that have been approved by an Authorized Representative for the Boeing Delegation Option Authorization

Organization whom we have authorized to make those findings.

Costs of Compliance

There are about 3,401 airplanes of the affected design in the worldwide fleet.

The following table provides the estimated costs for U.S. operators to comply with this proposed AD.

ESTIMATED COSTS

Action	Work hour	Average labor rate per hour	Cost per airplane	Number of U.S.-registered airplanes	Fleet cost
Rework electrical bonding for Boeing Model 747 airplanes	10	\$65	\$650	1,115	\$724,750
Rework electrical bonding for Boeing Model 767 airplanes	9	65	585	921	538,785

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not

have a substantial direct effect on the States, on the relationship between the National Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation: 1. Is not a “significant regulatory action” under Executive Order 12866; 2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and 3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD. See the ADDRESSES section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator,

the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Boeing: Docket No. FAA–2005–21701; Directorate Identifier 2005–NM–086–AD.

Comments Due Date

(a) The Federal Aviation Administration (FAA) must receive comments on this AD action by August 15, 2005.

Affected ADs

(b) None.

Applicability

(c) This AD applies to the Boeing airplane models identified in Table 1 of this AD, certificated in any category.

TABLE 1.—AIRPLANES AFFECTED BY THIS AD

Model—	As identified in Boeing special attention service bulletin—
747–100, 747–100B, 747–100B SUD, 747–200B, 747–200C, 747–200F, 747–300, 747–400, 747–400D, 747–400F, 747SR, and 747SP series airplanes.	747–28–2259, dated November 4, 2004.
767–200, –300, and –300F series airplanes	767–57–0092, dated November 4, 2004.
767–400ER series airplanes	767–57–0093, dated November 4, 2004.

Unsafe Condition

(d) This AD was prompted by the results of fuel system reviews conducted by the manufacturer. We are issuing this AD to prevent insufficient electrical bonding, which could result in a potential of ignition sources inside the fuel tanks, and which, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Rework Electrical Bonding

(f) Within 60 months after the effective date of this AD: Do the actions specified in paragraph (f)(1) or (f)(2) of this AD, as applicable, by accomplishing all the actions specified in the Accomplishment

Instructions of the applicable service bulletin in Table 1 of this AD. Do any related investigative and corrective actions before further flight.

(1) For Boeing Model 747–100, 747–100B, 747–100B SUD, 747–200B, 747–200C, 747–200F, 747–300, 747–400, 747–400D, 747–400F, 747SR, and 747SP series airplanes: Rework the electrical bonding between the airplane structure and the pump housing of the outboard boost pumps in the main fuel tank, and do related investigative and

applicable corrective actions. If any crack, corrosion, or damage is found during the open-hole high-frequency eddy current inspection specified in Boeing Special Attention Service Bulletin 747-28-2259, dated November 4, 2004: Before further flight, repair in accordance with a method approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA; or in accordance with data meeting the certification basis of the airplane approved by an Authorized Representative for the Boeing Delegation Option Authorization Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the approval must specifically reference this AD.

(2) For Boeing Model 767-200, -300, -300F, and -400ER series airplanes: Rework the electrical bonding between the airplane structure and the pump housing of the override/jettison pumps in the left and right wing center auxiliary fuel tanks, and do the related investigative and applicable corrective actions.

Alternative Methods of Compliance (AMOCs)

(g) The Manager, Seattle ACO, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

Issued in Renton, Washington, on June 21, 2005.

Ali Bahrami,

Manager, Transport Airplane Directorate,
Aircraft Certification Service.

[FR Doc. 05-12840 Filed 6-28-05; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2005-21702; Directorate Identifier 2005-NM-024-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A330 and A340 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Airbus Model A330 and A340 series airplanes. This proposed AD would require repetitive borescope inspections of the left and right fuel tanks of the trimmable horizontal stabilizers (trim tanks) for detached or damaged float valves; related investigative/corrective actions if necessary; and the eventual replacement of all float valves in the left and right

trim tanks with new, improved float valves, which terminates the need for the repetitive inspections. This proposed AD would also require repetitive replacement of certain new, improved float valves. This proposed AD is prompted by reports of detached and damaged float valves in the trim tanks. We are proposing this AD to prevent, in the event of a lightning strike to the horizontal stabilizer, sparking of metal parts and debris from detached and damaged float valves, or a buildup of static electricity, which could result in ignition of fuel vapors and consequent fire or explosion.

DATES: We must receive comments on this proposed AD by July 29, 2005.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

- DOT Docket Web site: Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- Government-wide rulemaking Web site: Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- Mail: Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, room PL-401, Washington, DC 20590.

- By fax: (202) 493-2251.

- Hand Delivery: Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France.

You can examine the contents of this AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., room PL-401, on the plaza level of the Nassif Building, Washington, DC. This docket number is FAA-2005-21702; the directorate identifier for this docket is 2005-NM-024-AD.

FOR FURTHER INFORMATION CONTACT: Tim Backman, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2797; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to submit any relevant written data, views, or arguments regarding this proposed AD. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-

2005-21702; Directorate Identifier 2005-NM-024-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments submitted by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of our docket Web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You can review the DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you can visit <http://dms.dot.gov>.

Examining the Docket

You can examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the DOT street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the DMS receives them.

Discussion

We have examined the underlying safety issues involved in recent fuel tank explosions on several large transport airplanes, including the adequacy of existing regulations, the service history of airplanes subject to those regulations, and existing maintenance practices for fuel tank systems. As a result of those findings, we issued a regulation titled "Transport Airplane Fuel Tank System Design Review, Flammability Reduction and Maintenance and Inspection Requirements" (67 FR 23086, May 7, 2001). In addition to new airworthiness standards for transport airplanes and new maintenance requirements, this rule included Special Federal Aviation Regulation No. 88 ("SFAR 88," Amendment 21-78, and subsequent Amendments 21-82 and 21-83).

Among other actions, SFAR 88 requires certain type design approval