

referred to in paragraph I hereof, as augmented by the provisions specified in paragraph II hereof, shall be and are the provisions of this marketing agreement as if set out in full herein.

I. The findings and determinations, order relative to handling, and the provisions of §§ 1033.1 to 1033.86 all inclusive, of the order regulating the handling of milk in the Mideast marketing area (7 CFR part 1033) which is annexed hereto; and

II. The following provisions: Record of milk handled and authorization to correct typographical errors.

(a) Record of milk handled. The undersigned certifies that he/she handled during the month of __, 2005, __ hundredweight of milk covered by this marketing agreement.

(b) Authorization to correct typographical errors. The undersigned hereby authorizes the Deputy Administrator, or Acting Deputy Administrator, Dairy Programs, Agricultural Marketing Service, to correct any typographical errors which may have been made in this marketing agreement.

Effective date. This marketing agreement shall become effective upon the execution of a counterpart hereof by the Department in accordance with Section 900.14(a) of the aforesaid rules of practice and procedure.

In Witness Whereof, The contracting handlers, acting under the provisions of the Act, for the purposes and subject to the limitations herein contained and not otherwise, have hereunto set their respective hands and seals.

Signature

By (Name) _____

(Title) _____

(Address) _____

(Seal)

Attest

[FR Doc. 05-14769 Filed 7-26-05; 8:45 am]

BILLING CODE 3410-02-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2005-21968; Directorate Identifier 2005-NM-077-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 757-200, -200CB, and -300 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Boeing Model 757-200, -200CB, and -300 series airplanes. This proposed AD would require repetitive detailed inspections for proper functioning of the girt bar leaf springs for the escape slides at passenger doors 1, 2, and 4, and corrective actions if necessary. This proposed AD is prompted by a report that the escape slides failed to deploy correctly during an operator's tests of the escape slides. We are proposing this AD to prevent escape slides from disengaging from the airplane during deployment or in use, which could result in injuries to passengers or flightcrew.

DATES: We must receive comments on this proposed AD by September 12, 2005.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

- DOT Docket Web site: Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- Government-wide rulemaking Web site: Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- Mail: Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., Nassif Building, Room PL-401, Washington, DC 20590.

- By fax: (202) 493-2251.
- Hand Delivery: Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing Commercial Airplanes, PO Box 3707, Seattle, Washington 98124-2207.

You can examine the contents of this AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., Room PL-401, on the plaza level of the Nassif Building, Washington, DC. This docket number is FAA-2005-21968; the directorate identifier for this docket is 2005-NM-077-AD.

FOR FURTHER INFORMATION CONTACT:

David Crotty, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM-150S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 917-6422; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to submit any relevant written data, views, or arguments regarding this proposed AD. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2005-21968; Directorate Identifier 2005-NM-077-AD" in the subject line of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments submitted by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of that Web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You can review DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you can visit <http://dms.dot.gov>.

Examining the Docket

You can examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the DOT street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the Docket Management System (DMS) receives them.

Discussion

We have received a report indicating that the escape slides failed to deploy correctly during an operator's tests on Boeing Model 757-200, -200CB, and -300 series airplanes. Further examination showed that the girt bar, which attaches the deployed escape slide to the airplane floor, did not stay attached to the floor fitting. When an escape slide is being deployed, sliders on the forward and aft ends of the girt bar engage with the floor fittings and are held in place by leaf springs. The airplane manufacturer and operators have found that it is possible for the leaf

springs to be deformed and damaged in service, and that deformed or damaged leaf springs may not keep the girt bar sliders engaged with the floor fittings. This condition, if not corrected, could cause escape slides to disengage from the airplane during deployment or in use, which could result in injuries to passengers or flightcrew.

Relevant Service Information

We have reviewed Boeing Special Attention Service Bulletin 757-52-0085, dated March 24, 2005 (for Boeing Model 757-200 and -200CB series airplanes); and Boeing Special Attention Service Bulletin 757-52-0086, dated March 24, 2005 (for Boeing Model 757-300 series airplanes). The service bulletins describe procedures for doing repetitive detailed inspections for discrepancies of the leaf springs. Discrepancies include inadequate spring retention force and inadequate girt bar slider engagement dimensions. For airplanes on which an inspection shows an engagement dimension of less than 0.37 inch, the service bulletins describe procedures for corrective action. The corrective action is replacing the leaf spring or the girt bar assembly with new parts, and doing girt bar assembly adjustments and testing. Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition.

FAA's Determination and Requirements of the Proposed AD

We have evaluated all pertinent information and identified an unsafe condition that is likely to exist or develop on other airplanes of this same type design. Therefore, we are proposing this AD, which would require accomplishing the actions specified in the service information described previously, except as discussed under "Difference Between the Proposed AD and the Service Bulletins."

Difference Between the Proposed AD and the Service Bulletins

The service bulletins specify that operators may accomplish certain actions in accordance with the Boeing 757 Airplane Maintenance Manual (AMM), the Boeing 757 Component Maintenance Manual (CMM), or an "approved equivalent procedure." However, for actions in Part 1—"Inspection" of the Accomplishment Instructions of the applicable service bulletin, this proposed AD would require operators to accomplish the actions in accordance with the applicable chapter of the AMM or CMM specified in the applicable service bulletin. An "approved equivalent

procedure" may be used only if it is approved as an alternative method of compliance in accordance with paragraph (h) of this proposed AD.

Costs of Compliance

There are about 944 airplanes of the affected design in the worldwide fleet. This proposed AD would affect about 632 airplanes of U.S. registry. The proposed inspection would take about 2 work hours per airplane, at an average labor rate of \$65 per work hour. Based on these figures, the estimated cost of the proposed AD for U.S. operators is \$82,160, or \$130 per airplane, per inspection cycle.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the National Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD. See the **ADDRESSES**

section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Boeing: Docket No. FAA-2005-21968; Directorate Identifier 2005-NM-077-AD.

Comments Due Date

(a) The Federal Aviation Administration (FAA) must receive comments on this AD action by September 12, 2005.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Boeing Model 757-200 and -200CB series airplanes, certificated in any category; as identified in Boeing Special Attention Service Bulletin 757-52-0085, dated March 24, 2005; and Boeing Model 757-300 series airplanes, certificated in any category; as identified in Boeing Special Attention Service Bulletin 757-52-0086, dated March 24, 2005.

Unsafe Condition

(d) This AD was prompted by a report that the escape slides failed to deploy correctly during an operator's tests of the escape slides. We are issuing this AD to prevent escape slides from disengaging from the airplane during deployment or in use, which could result in injuries to passengers or flightcrew.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Detailed Inspection and Corrective Actions

(f) Within 24 months after the effective date of this AD: Do a detailed inspection for inadequate spring retention force and inadequate girt bar slider dimensions of the girt bar leaf springs for the escape slides at passenger doors 1, 2, and 4; and do any applicable corrective actions before further flight. Do all the actions in accordance with the Accomplishment Instructions of the applicable service bulletin in paragraph (f)(1) or (f)(2) of this AD, except as provided by paragraph (g) of this AD. Repeat the

inspection thereafter at intervals not to exceed 24 months, or after each maintenance task where removal of and installation of the girt bar is necessary, whichever occurs earlier.

(1) For Boeing Model 757-200 and -200CB series airplanes: Boeing Special Attention Service Bulletin 757-52-0085, dated March 24, 2005.

(2) For Boeing Model 757-300 series airplanes: Boeing Special Attention Service Bulletin 757-52-0086, dated March 24, 2005.

Equivalent Procedures

(g) Where Part 1—"Inspection" of the applicable service bulletin in paragraph (f)(1) or (f)(2) of this AD specifies that actions may be accomplished in accordance with an "approved equivalent procedure": The corrective actions must be accomplished in accordance with the chapter of the Boeing 757 Airplane Maintenance Manual (AMM) or Boeing 757 Component Maintenance Manual (CMM) specified in the applicable service bulletin.

Alternative Methods of Compliance (AMOCs)

(h) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

Issued in Renton, Washington, on July 13, 2005.

Ali Bahrami,

*Manager, Transport Airplane Directorate,
Aircraft Certification Service.*

[FR Doc. 05-14790 Filed 7-26-05; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF HOMELAND SECURITY

Coast Guard

33 CFR Part 100

[CGD05-05-076]

RIN 1625-AA08

Special Local Regulations for Marine Events; Sunset Lake, Wildwood Crest, NJ

AGENCY: Coast Guard, DHS.

ACTION: Notice of proposed rulemaking.

SUMMARY: The Coast Guard proposes to establish special local regulations during the "Sunset Lake Hydrofest", a marine event to be held September 24 and 25, 2005, on the waters of Sunset Lake, Wildwood Crest, New Jersey. These special local regulations are necessary to provide for the safety of life on navigable waters during the event. This action is intended to restrict vessel traffic in portions of Sunset Lake during the event.

DATES: Comments and related material must reach the Coast Guard on or before August 26, 2005.

ADDRESSES: You may mail comments and related material to Commander (oax), Fifth Coast Guard District, 431 Crawford Street, Portsmouth, Virginia 23704-5004, hand-deliver them to Room 119 at the same address between 9 a.m. and 2 p.m., Monday through Friday, except Federal holidays, or fax them to (757) 398-6203. The Auxiliary and Recreational Boating Safety Branch, Fifth Coast Guard District, maintains the public docket for this rulemaking. Comments and material received from the public, as well as documents indicated in this preamble as being available in the docket, will become part of this docket and will be available for inspection or copying at the above address between 9 a.m. and 2 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: Dennis Sens, Project Manager, Auxiliary and Recreational Boating Safety Branch, at (757) 398-6204.

SUPPLEMENTARY INFORMATION:

Request for Comments

We encourage you to participate in this rulemaking by submitting comments and related material. If you do so, please include your name and address, identify the docket number for this rulemaking (CGD05-05-076), indicate the specific section of this document to which each comment applies, and give the reason for each comment. Please submit all comments and related material in an unbound format, no larger than 8½ by 11 inches, suitable for copying. If you would like to know they reached us, please enclose a stamped, self-addressed postcard or envelope. We will consider all comments and material received during the comment period. We may change this proposed rule in view of them.

In order to provide notice and an opportunity to comment before issuing an effective rule, we are providing a shorter than normal comment period. A 30-day comment period is sufficient to allow those who might be affected by this rulemaking to submit their comments because the regulations have a narrow, local application, and there will be local notifications in addition to the **Federal Register** publication such as press releases, marine information broadcasts, and the Local Notice to Mariners.

Public Meeting

We do not now plan to hold a public meeting. But you may submit a request

for a meeting by writing to the address listed under **ADDRESSES** explaining why one would be beneficial. If we determine that one would aid this rulemaking, we will hold one at a time and place announced by a later notice in the **Federal Register**.

Background and Purpose

On September 24 and 25, 2005, the Sunset Lake Hydrofest Association will sponsor the "Sunset Lake Hydrofest", on the waters of Sunset Lake near Wildwood Crest, New Jersey. The event will consist of approximately 100 inboard hydroplanes, Jersey Speed Skiffs and flat-bottom ski boats racing in heats counter-clockwise around an oval racecourse. A fleet of approximately 100 spectator vessels is expected to gather nearby to view the competition. Due to the need for vessel control during the event, vessel traffic will be temporarily restricted to provide for the safety of participants, spectators and transiting vessels.

Discussion of Proposed Rule

The Coast Guard proposes to establish temporary special local regulations on specified waters of Sunset Lake. The temporary special local regulations would be enforced from 8:30 a.m. to 5:30 p.m. on September 24 and 25, 2005, and will restrict general navigation in the regulated area during the event. Except for participants and vessels authorized by the Coast Guard Patrol Commander, no person or vessel will be allowed to enter or remain in the regulated area. These regulations are needed to control vessel traffic during the event to enhance the safety of participants, spectators and transiting vessels.

Regulatory Evaluation

This proposed rule is not a "significant regulatory action" under section 3(f) of Executive Order 12866, Regulatory Planning and Review, and does not require an assessment of potential costs and benefits under section 6(a)(3) of that Order. The Office of Management and Budget has not reviewed it under that Order. It is not "significant" under the regulatory policies and procedures of the Department of Homeland Security (DHS).

We expect the economic impact of this proposed rule to be so minimal that a full Regulatory Evaluation under the regulatory policies and procedures of DHS is unnecessary.

Although this proposed regulation will prevent traffic from transiting a portion of Sunset Lake during the event, the effect of this regulation would not be