

(2) If no crack is found in any door assembly integral frame, do the following:

(i) Visually inspect the weather seal set in each door assembly to determine if it is airworthy and installed properly. If it is not airworthy, before further flight, replace it with either the weather seal set, P/N 74418X14L and P/N 74814X12BL, supplied by Tech-Tool Plastics, Inc., in accordance with the "Door Weather Seal Installation" section of the SB, or replace it with any other airworthy door weather seal set in accordance with the applicable FAA-approved installation instructions. If an airworthy weather seal set, P/N 74418X14L and P/N 74814X12BL, is not installed properly, before further flight, reinstall it in accordance with the "Door Weather Seal Installation" section of the SB. If the improperly installed weather seal set is not the weather seal set supplied by Tech-Tool Plastics, Inc., before further flight, reinstall it in accordance with the applicable FAA-approved installation instructions.

(ii) Visually inspect each door hinge on each door assembly to determine if the cotter pins, P/N MS24665-136, are installed in accordance with the "Cotter Pin Installation" section of the SB. If a cotter pin is not installed in accordance with the "Cotter Pin Installation" section of the SB, before further flight, install the cotter pins in accordance with the "Cotter Pin Installation" section of the SB.

Note: The installation of nylon adjustment screws and the trimming of door assembly edges are important maintenance actions that may reduce the strength of a door assembly if not done properly.

(b) After accomplishing the inspections in paragraphs (a) through (a)(2)(ii) of this AD, at intervals not to exceed 100 hours time-in-service, visually inspect each pilot and copilot door assembly integral frame for a crack in the locations depicted in Figure 1 of this AD.

(c) If a crack is found, before further flight, replace the cracked door assembly, P/N R-22-101-51 or P/N R-22-101-53 (left-hand door assembly), or P/N R-22-101-52 or P/N R-22-101-54 (right-hand door assembly), with an airworthy door assembly. If the replacement door assembly is P/N R-22-101-51 or P/N R-22-101-53 (left-hand door assembly), or P/N R-22-101-52 or P/N R-22-101-54 (right-hand door assembly), then install it in accordance with Tech-Tool Plastics, Inc. Installation Instructions TTP-1R, Revision A, dated November 21, 1997, and "Door Weather Seal Installation" and "Cotter Pin Installation" sections of the SB.

(d) If any of the inspections required by this AD reveal a crack in any door assembly frame, report the following information to the FAA within 30 days after discovering the crack: a description of the crack and the specific helicopter model involved. You may submit your report via mail, Fax, or telephone to the FAA, ATTN: ASW-170 (Marc Belhumeur), 2601 Meacham Blvd., Fort Worth, Texas 76137, telephone (817) 222-5177, fax (817) 222-5783. Information collection requirements contained in this AD have been approved by the Office of Management and Budget (OMB) under the provisions of the Paperwork Reduction Act of

1980 (44 U.S.C. 3501 *et seq.*) and have been assigned OMB Control Number 2120-0056.

(e) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Contact the Rotorcraft Certification Office, Rotorcraft Directorate, FAA, for information about previously approved alternative methods of compliance.

(f) The inspections, repairs and replacements, if necessary, shall be done in accordance with the specified portions of Tech-Tool Plastics, Inc. Installation Instructions TTP-1R, Revision A, dated November 21, 1997, which provides door assembly installation instructions, and the specified portions of Tech-Tool Plastics, Inc. Service Bulletin No. TTP2005-01, Revision A, dated February 1, 2005, which describes door weather seal and cotter pin installation procedures and door assembly inspection procedures. The Director of the Federal Register approved this incorporation by reference in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Tech-Tool Plastics, Inc., 7800 Skyline Park Drive, Fort Worth, Texas, 76108; telephone: (817) 246-4694; fax: (817) 246-7402; E-mail: info@tech-tool.com.

(g) This amendment becomes effective on August 26, 2005.

Issued in Fort Worth, Texas, on July 29, 2005.

S. Frances Cox,

*Acting Manager, Rotorcraft Directorate,
Aircraft Certification Service.*

[FR Doc. 05-15580 Filed 8-10-05; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2005-22054; Directorate Identifier 2005-NM-137-AD; Amendment 39-14216; AD 2005-04-14 R1]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 757-200, 757-200CB, and 757-200PF Series Airplanes Equipped With Rolls Royce Model RB211 Engines

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule; request for comments.

SUMMARY: The FAA is revising an existing airworthiness directive (AD), which applies to certain Boeing Model 757-200, 757-200CB, and 757-200PF series airplanes. That AD currently requires repetitive inspections to detect horizontal or vertical movement of the shims at the joint of the mid-bulkhead and the upper link fittings; repetitive inspections for cracking of the mid-

bulkhead; and corrective action if necessary. That AD also provides optional terminating action for the repetitive inspections. This AD continues to require the existing requirements and optional actions and clarifies certain terminating actions. This AD results from comments received in response to an existing AD, requesting clarification. We are issuing this AD to detect and correct migration of shims at the joint of the mid-bulkhead and the upper link fittings and cracking of the mid-bulkhead, which could result in cracking of the strut and consequent loss of the strut and engine.

DATES: Effective March 15, 2005.

On March 15, 2005 (70 FR 9511, February 28, 2005), the Director of the Federal Register approved the incorporation by reference of Boeing Service Bulletin 757-54A0039, Revision 2, dated December 2, 2004; and Boeing Service Bulletin 757-54A0039, Revision 3, dated January 13, 2005.

On April 18, 2003 (68 FR 16200, April 3, 2003), the Director of the Federal Register approved the incorporation by reference of Boeing Alert Service Bulletin 757-54A0039, Revision 1, dated June 20, 2002.

We must receive any comments on this AD by October 11, 2005.

ADDRESSES: Use one of the following addresses to submit comments on this AD:

- DOT Docket Web site: Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- Government-wide rulemaking Web site: Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- Mail: Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590.

- Fax: (202) 493-2251.

- Hand Delivery: Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207, for service information identified in this AD.

FOR FURTHER INFORMATION CONTACT: Dennis Stremick, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 917-6450; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:

Discussion

On February 14, 2005, we issued AD 2005-04-14, amendment 39-13986 (70 FR 9511, February 28, 2005). That AD applies to certain Boeing Model 757-200, 757-200CB, and 757-200PF series airplanes. That AD requires repetitive detailed inspections to detect horizontal or vertical movement of the shims at the joint of the mid-bulkhead and the upper link fittings; repetitive detailed inspections for cracking of the mid-bulkhead; and corrective action if necessary. That AD also provides optional terminating action for the repetitive inspections. That AD resulted from reports of cracks in the mid-bulkhead lower vertical flange common to the lower chord and stiffener and reports of cracking at other locations on the mid-bulkhead. The actions specified in that AD are intended to detect and correct migration of shims at the joint of the mid-bulkhead and the upper link fittings and cracking of the mid-bulkhead, which could result in cracking of the strut and consequent loss of the strut and engine.

Comments

We provided the public the opportunity to submit any relevant written data, views, or arguments about AD 2005-04-14. We have considered the comments received. We have revised AD 2005-04-14 based on the following comments:

Requests To Clarify Terminating Actions

One commenter, the airplane manufacturer, requests that paragraph (k) of AD 2005-04-14 be revised to clarify that accomplishing the optional one-time high frequency eddy current (HFEC) inspection specified only in paragraph (m) ends the repetitive inspections required by paragraph (j)(1). The commenter notes that those repetitive inspections are only applicable to airplanes on which the actions specified in Boeing Alert Service Bulletin (ASB) 757-54A0039, dated November 2, 2000, have been accomplished prior to April 18, 2003. The commenter states that operators of those airplanes have already done the shim replacement specified in paragraph (l), making that action redundant.

We agree and have revised paragraph (k) of AD 2005-04-14 in this AD accordingly.

The same commenter also requests that paragraphs (k) and (s) of AD 2005-04-14 be revised to clarify that accomplishing the optional one-time HFEC inspection specified in

paragraphs (m) and (u), as applicable, ends the repetitive detailed inspections required by paragraph (r)(1). The commenter notes that, in paragraph (k), similar repetitive detailed inspections required by paragraph (j)(1) are terminated by accomplishing the optional actions specified in paragraphs (l) and (m). The commenter also states that the optional one-time HFEC inspection in paragraph (m) is equivalent to that in paragraph (u).

We partially agree. We agree with the commenter that paragraphs (k) and (s) need to be revised. However, we do not agree with the commenter that accomplishing the actions specified only in paragraphs (m) and (u), as applicable, ends the repetitive inspection in paragraph (r)(1). We have determined that accomplishing the optional terminating actions specified in both paragraphs (l) and (m) and both paragraphs (t) and (u), as applicable, are necessary to end the repetitive detailed inspections in paragraph (r)(1). We have revised paragraphs (k) and (s) of AD 2005-04-14 in this AD accordingly.

Another commenter requests that AD 2005-04-14 be revised to clarify that accomplishing the initial detailed inspection required by paragraph (r) ends the repetitive detailed inspections required by paragraph (j)(1). The commenter believes that the detailed inspections in paragraph (r) are redundant to those in paragraph (j). The commenter states that the detailed inspections required by paragraph (r) seem inconsistent with the explanation in "Differences Between the AD and the Service Information" section of AD 2005-04-14. That section states, "[The FAA has] determined that, for airplanes on which the actions specified in Parts I and II of the Accomplishment Instructions of Boeing Alert SB 757-54A0039, dated November 2, 2000, have been accomplished previously, a detailed inspection for cracking, and repair if necessary, within 90 days of the effective date of this AD, and repetitive detailed inspections, are adequate to continue to provide an acceptable level of safety for this interim action." The commenter further states that paragraph (r) requires a detailed inspection of all airplanes, including those on which the optional one-time HFEC inspection specified in paragraph (m) or (u) has been previously done.

We agree with the commenter that clarification is necessary. The detailed inspections required by paragraphs (j) and (r) of AD 2005-04-14 are identical. The affected airplanes of those two paragraphs are different; however, there is some overlap in the affected airplanes. Paragraph (r), which is

applicable to "Groups 1, 2, and 3 airplanes, identified in Boeing Service Bulletin 757-54A0039, Revision 3, dated January 13, 2005," includes all airplanes specified in paragraph (j) (*i.e.*, airplanes on which the actions specified in Boeing ASB 757-54A0039, dated November 2, 2000, have been accomplished prior to April 18, 2003). It was our intent that, after accomplishing the initial detailed inspection required by paragraph (r) at the new compliance time, the repetitive detailed inspections required by paragraph (j)(1) end for affected airplanes. Therefore, we have revised paragraph (r) of this AD to clarify this point.

In addition, our intent in the "Difference Between the AD and the Service Information" section of AD 2005-04-14 was to point out that referenced Boeing ASB 757-54A0039 recommended a one-time non-destructive test and/or HFEC inspection whereas the AD required repetitive detailed inspections. As discussed in that AD, we determined that the repetitive detailed inspections were adequate to continue to provide an acceptable level of safety for the interim. That section does not reappear in this AD. Therefore, no change to this AD is necessary in this regard.

Request To Refer to Additional Figure

One commenter requests that the last sentence in paragraph (r) be revised to "* * * perform a detailed inspection for cracking around the four Lower Mid-Spar Bolts as shown in Figure 9 or Figure 17 of SB 757-54A0039, Revision 3, dated January 13, 2005." The commenter believes that, like Figure 9, Figure 17 "Mid-Bulkhead Inspection" in Revision 3 of Boeing Service Bulletin 757-54A0039 also addresses the areas around the four lower mid-spar bolts. The commenter states that Figure 17 provides pictorial views of the subject two front and two rear lower mid-bulkhead bolts whereas Figure 9 shows a sectional view of the area only.

We partially agree. We agree with the commenter to revise paragraph (r) to refer to Figure 17 as an alternative figure for accomplishing the required detailed inspection, but do not agree with the commenter's revised description of the area. We find that "around the four bolt heads, nuts, washer, and radius fillers" is more descriptive of the required inspection area. Therefore, we have revised paragraph (r) to state, "* * * perform a detailed inspection * * * specified in Figure 9 or 17 of the Accomplishment Instructions of Boeing SB 757-54A0039, Revision 3, dated January 13, 2005."

FAA's Determination and Requirements of This AD

The unsafe condition described previously is likely to exist or develop on other airplanes of the same type design. For this reason, we are issuing this AD to revise AD 2005-04-14. This new AD continues to require repetitive detailed inspections to detect horizontal or vertical movement of the shims at the joint of the mid-bulkhead and the upper link fittings; repetitive detailed inspections for cracking of the mid-bulkhead; and corrective action if necessary. This new AD also continues to provide optional terminating actions for certain repetitive inspections. This new AD also clarifies certain terminating actions.

Interim Action

This is considered to be interim action. We are currently considering requiring HFEC inspections for cracking in and around the bolt holes of the left and right side of the mid-bulkhead strut, and repair if necessary. However, the planned compliance time for the HFEC inspections in this AD "is sufficiently long so that notice and opportunity for prior public comment will be practicable."

FAA's Determination of the Effective Date

An unsafe condition exists that requires the immediate adoption of this AD; therefore, providing notice and opportunity for public comment before the AD is issued is impracticable, and good cause exists to make this AD effective in less than 30 days.

Comments Invited

This AD is a final rule that involves requirements that affect flight safety and was not preceded by notice and an opportunity for public comment; however, we invite you to submit any relevant written data, views, or arguments regarding this AD. Send your comments to the address listed under the **ADDRESSES** section. Include "Docket No. FAA-2005-22054; Directorate Identifier 2005-NM-137-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the AD that might suggest a need to modify it.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this AD. Using the search function of that Web site, anyone

can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You may review the DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you may visit <http://dms.dot.gov>.

Examining the Dockets

You may examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the DOT street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the Docket Management System receives them.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the National Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and

3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The Federal Aviation Administration (FAA) amends § 39.13 by removing amendment 39-13986 (70 FR 9511, February 28, 2005) and adding the following new airworthiness directive (AD):

2005-04-14 R1 Boeing: Amendment 39-14216. Docket No. FAA-2005-22054; Directorate Identifier 2005-NM-137-AD.

Effective Date

(a) The effective date of this AD is March 15, 2005.

Affected ADs

(b) This AD revises AD 2005-04-14, amendment 39-13986.

Applicability

(c) This AD applies to Boeing Model 757-200, 757-200CB, and 757-200PF series airplanes; certificated in any category; equipped with Rolls Royce Model RB211 engines; as identified in Boeing Service Bulletin 757-54A0039, Revision 3, dated January 13, 2005.

Unsafe Condition

(d) This AD was prompted by reports of cracks in the mid-bulkhead lower vertical flange common to the lower chord and stiffener and reports of cracking at other locations on the mid-bulkhead. We are issuing this AD to detect and correct migration of shims at the joint of the mid-bulkhead and the upper link fittings and cracking on the mid-bulkhead, which could result in cracking of the strut and consequent loss of the strut and engine.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Requirements of 2005-04-14

Inspection for Movement of Shims and Corrective Actions

(f) For Groups 1 and 2 airplanes, as identified in Boeing Alert Service Bulletin (ASB) 757-54A0039, Revision 1, dated June 20, 2002; Boeing Service Bulletin (SB) 757-54A0039, Revision 2, dated December 2, 2004; and Boeing SB 757-54A0039, Revision 3, dated January 13, 2005; with the exception of the airplanes specified in paragraph (j) of this AD: Within 90 days after April 18, 2003 (the effective date of AD 2003-07-08, amendment 39-13104), perform a detailed inspection to detect horizontal or vertical movement of the shims at the joint of the mid-bulkhead and the upper link fittings, per Boeing ASB 757-54A0039, Revision 1, dated June 20, 2002; or Boeing SB 757-54A0039, Revision 2, dated December 2, 2004, or Revision 3, dated January 13, 2005.

Note 1: For the purposes of this AD, a detailed inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

(g) If all laminated shims have not moved, or if all laminated shims have moved less than 0.25 inch: Before further flight, perform the actions specified in either paragraph (g)(1) or (g)(2) of this AD, per Boeing ASB 757-54A0039, Revision 1, dated June 20, 2002; or Boeing SB 757-54A0039, Revision 2, dated December 2, 2004, or Revision 3, dated January 13, 2005.

(1) Perform the actions specified in paragraph 3.B.6 of the Accomplishment Instructions of the ASB (e.g., measure and record movement of the shim, cut the exposed plies, and seal adjacent surfaces and edges), and repeat the detailed inspections at intervals not to exceed 12,000 flight cycles or 72 months, whichever occurs first. At each inspection interval, the previously recorded measurement must be added to the current measurement so that the cumulative total movement of the shim is recorded. If the cumulative total movement exceeds 0.25 inch but is less than 0.90 inch, before further flight, perform the actions specified in paragraph (h) of this AD. If the cumulative total movement measures 0.90 inch or more: Before further flight, perform the actions specified in paragraph (i) of this AD. Or

(2) Perform the actions specified in paragraphs (l) and (m) of this AD.

(h) If any laminated shim has moved 0.25 inch or more but less than 0.90 inch: Before further flight, perform the actions specified in paragraph (h)(1) or (h)(2) of this AD, per Boeing ASB 757-54A0039, Revision 1, dated June 20, 2002; or Boeing SB 757-54A0039,

Revision 2, dated December 2, 2004, or Revision 3, dated January 13, 2005.

(1) Before further flight, perform the actions specified in paragraph 3.B.6 of the Accomplishment Instructions of the ASB (e.g., measure and record movement of the shim, cut the exposed plies and seal adjacent surfaces and edges), and repeat the detailed inspections at intervals not to exceed 3,000 flight cycles or 18 months, whichever occurs first. At each inspection interval, the previously recorded measurement must be added to the current measurement so that the cumulative total movement of the shim is recorded. If the cumulative total movement measures 0.90 inch or more, before further flight, perform the actions specified in paragraph (i) of this AD. Or,

(2) Perform the actions specified in paragraphs (l) and (m) of this AD.

(i) If any laminated shim has moved 0.90 inch or more: Before further flight, perform the actions specified in paragraphs (l) and (m) of this AD.

Inspection of Lower Mid-Spar Bolts

(j) For airplanes on which the actions specified in Boeing ASB 757-54A0039, dated November 2, 2000, have been accomplished prior to April 18, 2003: Within 90 days after April 18, 2003, perform a detailed inspection for cracking around the four bolt heads, nuts, washers, and radius fillers specified in Figure 9 of Boeing ASB 757-54A0039, Revision 1, dated June 20, 2002; or Boeing SB 757-54A0039, Revision 2, dated December 2, 2004, or Revision 3, dated January 13, 2005.

(1) If no cracking is found, repeat the detailed inspection at intervals not to exceed 3,000 flight cycles.

(2) If any cracking is found, before further flight, repair per a method approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA; or per data meeting the type certification basis of the airplane approved by a Boeing Company Designated Engineering Representative (DER) who has been authorized by the Manager, Seattle ACO, to make such findings; or by an Authorized Representative (AR) for the Boeing Delegation Option Authorization (DOA) Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the approval must specifically reference this AD.

Terminating Action for Certain Requirements of This AD

(k) For Groups 1, 2, and 3, as identified in Boeing SB 757-54A0039, Revision 2, dated December 2, 2004; or Revision 3, dated January 13, 2005: Accomplishment of the actions specified in paragraphs (l) and (m) of this AD constitutes terminating action for the repetitive inspection requirements of paragraphs (g)(1), (h)(1), and (r)(1) of this AD. Accomplishment of paragraphs (l) and (m) of this AD also constitutes terminating action for paragraphs (o), (p), and (q), if accomplished prior to March 15, 2005 (the effective date of AD 2005-04-14). For airplanes specified in paragraph (j) of this AD, accomplishment of paragraph (m) of this AD constitutes terminating action for paragraph (j) of this AD.

(l) Replace any laminated shim with a solid shim; replace existing sleevebolts with new, oversized sleevebolts; and perform a general visual and high-frequency eddy current (HFEC) inspection to detect cracking and deformation in the sleevebolt holes and in the fittings, as shown in Part II, Figure 3, of Boeing ASB 757-54A0039, Revision 1, dated June 20, 2002; or Boeing SB 757-54A0039, Revision 2, dated December 2, 2004, or Revision 3, dated January 13, 2005. If any shim cannot be removed, or if any cracking or deformation is found: Before further flight, repair per a method approved by the Manager, Seattle ACO, FAA; or per data meeting the type certification basis of the airplane approved by a Boeing DER who has been authorized by the Manager, Seattle ACO, to make such findings; or by an AR for the Boeing DOA Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair to be approved, the approval must specifically reference this AD. No further action is required by this paragraph.

(m) Perform a one-time HFEC inspection for cracking in and around the bolt holes of the left and right side of the mid-bulkhead strut as shown in Part III, Figure 9, of Boeing ASB 757-54A0039, Revision 1, dated June 20, 2002; or Boeing SB 757-54A0039, Revision 2, dated December 2, 2004, or Revision 3, dated January 13, 2005.

(1) If no cracking is found during any inspection specified in paragraph (m) of this AD, before further flight, install oversized bolts per Figure 10 of the ASB. No further action is required by this paragraph.

(2) If any cracking is found during any inspection specified in paragraph (m) of this AD that is within the limits specified in the ASB: Before further flight, repair per the ASB.

(3) If any cracking is found during any inspection specified in paragraph (m) of this AD that is outside the limits specified by the ASB and the ASB specifies to contact Boeing for appropriate action: Before further flight, repair per a method approved by the Manager, Seattle ACO, FAA; or per data meeting the type certification basis of the airplane approved by a Boeing DER who has been authorized by the Manager, Seattle ACO, to make such findings; or by an AR for the Boeing DOA Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the approval must specifically reference this AD.

Detailed Inspections of the Mid-Bulkhead

(n) For all airplanes: Prior to the accumulation of 8,000 total flight cycles, or within 90 days after March 15, 2005, whichever occurs later, perform a detailed inspection for cracking of the entire mid-bulkhead, in accordance with the Accomplishment Instructions of Boeing SB 757-54A0039, Revision 3, dated January 13, 2005.

(1) If no cracking is detected, repeat the inspection thereafter at intervals not to exceed 3,000 flight cycles.

(2) If any cracking is detected, before further flight, repair in accordance with a method approved by the Manager, Seattle

ACO, FAA; or according to data meeting the certification basis of the airplane approved by an AR for the Boeing DOA Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the approval must specifically reference this AD.

Thereafter, repeat the inspection at intervals not to exceed 3,000 flight cycles.

Inspections for Migration of Shims for Certain Airplanes

(o) For Group 3 airplanes, as identified in Boeing SB 757-54A0039, Revision 3, dated January 13, 2005: Within 90 days after March 15, 2005, perform a detailed inspection to detect horizontal or vertical movement of the shims at the joint of the mid-bulkhead and the upper link fittings; in accordance with the Accomplishment Instructions of the SB. If the total shim migration is 0.3 inch or less, repeat the inspection thereafter at intervals not to exceed 3,000 flight cycles.

Accomplishment of paragraphs (l) and (m) of this AD constitute terminating action for the requirements of this paragraph, if accomplished prior to March 15, 2005.

Inspections for Migration of Shims for Certain Other Airplanes

(p) For Groups 1 and 2 airplanes, as identified in Boeing SB 757-54A0039, Revision 3, dated January 13, 2005: If the total shim migration was 0.3 inch or less at the last inspection performed in accordance with paragraph (g)(1) of this AD, within 3,000 flight cycles after the last inspection performed, or within 90 days after March 15, 2005, whichever occurs later, perform the next shim migration inspection in accordance with the Accomplishment Instructions of Revision 3 of the SB. Thereafter, repeat the inspection at intervals not to exceed 3,000 flight cycles. Accomplishment of the initial inspection in accordance with Revision 3 terminates the requirements of paragraphs (g) and (h) of this AD. Accomplishment of paragraphs (l) and (m) of this AD constitute terminating action for the requirements of this paragraph, if accomplished prior to March 15, 2005.

For Shim Migration That Is More Than 0.3 Inch

(q) For Groups 1, 2, and 3 airplanes, as identified in Boeing SB 757-54A0039, Revision 3, dated January 13, 2005: If any total shim migration is more than 0.30 inch, prior to further flight or within 90 days after March 15, 2005, whichever occurs later, perform the actions specified in paragraphs (t) and (u) of this AD. Accomplishment of paragraphs (l) and (m) of this AD constitute terminating action for the requirements of this paragraph, if accomplished prior to March 15, 2005.

Note 2: For the purposes of this AD, a general visual inspection is: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made from within touching distance unless otherwise specified. A mirror may be necessary to ensure visual access to all surfaces in the inspection area. This level of inspection is made under normally

available lighting conditions such as daylight, hangar lighting, flashlight, or droplight and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

Inspection of Lower Mid-Spar Bolts

(r) For Groups 1, 2, and 3 airplanes, identified in Boeing SB 757-54A0039, Revision 3, dated January 13, 2005: Within 90 days after March 15, 2005, or within 3,000 flight cycles after the last inspection of the lower mid-spar bolts required by paragraph (j) of this AD, whichever occurs later, perform a detailed inspection for cracking around the four bolt heads, nuts, washers, and radius fillers specified in Figure 9 or 17 of the Accomplishment Instructions of Boeing SB 757-54A0039, Revision 3, dated January 13, 2005. Accomplishing the initial detailed inspection ends the repetitive detailed inspection requirements of paragraph (j)(1) this AD.

(1) If no cracking is found, repeat the detailed inspection at intervals not to exceed 3,000 flight cycles.

(2) If any cracking is found, before further flight, repair per a method approved by the Manager, Seattle ACO, FAA; or per data meeting the type certification basis of the airplane approved by an AR for the Boeing DOA Organization who has been authorized by the Manager, Seattle ACO, to make such findings. For a repair method to be approved, the approval must specifically reference this AD. Thereafter, repeat the inspection at intervals not to exceed 3,000 flight cycles.

Terminating Action for Certain Requirements

(s) For Groups 1, 2, and 3 airplanes, identified in Boeing SB 757-54A0039, Revision 3, dated January 13, 2005: Accomplishment of paragraphs (t) and (u) of this AD constitutes terminating action for the repetitive inspections of paragraphs (g)(1), (h)(1), (o), (p), and (r)(1) of this AD.

Replacement of Shims and Sleevebolts

(t) For Groups 1, 2, and 3 airplanes, identified in Boeing SB 757-54A0039, Revision 3, dated January 13, 2005: Replace all laminated shims with solid shims; replace existing sleevebolts with new, oversized sleevebolts; and perform a general visual and HFEC inspection to detect cracking and deformation in the sleevebolt holes and in the fittings; as specified in Part II of the Accomplishment Instructions of Boeing SB 757-54A0039, Revision 3, dated January 13, 2005. If any shim cannot be removed, or if any cracking or deformation is found: Before further flight, repair in accordance with a method approved by the Manager, Seattle ACO, FAA; or according to data meeting the certification basis of the airplane approved by an AR for the Boeing DOA Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the approval must specifically reference this AD.

One-Time HFEC Inspection

(u) For Groups 1, 2, and 3, as identified in Boeing SB 757-54A0039, Revision 3, dated January 13, 2005: Perform a one-time HFEC

inspection for cracking in and around the bolt holes of the right and left side of the mid-bulkhead lower flanges, in accordance with Part III of the Accomplishment Instructions of Boeing SB 757-54A0039, Revision 3, dated January 13, 2005.

(1) If no cracking is found: Before further flight, install oversized bolts per Figure 10 of the SB.

(2) If any cracking is found that is within the limits of the SB: Before further flight, repair per the SB.

(3) If any cracking is found that is outside the limits of the SB and the SB specifies to contact Boeing for appropriate action: Before further flight, repair in accordance with a method approved by the Manager, Seattle ACO, FAA; or according to data meeting the certification basis of the airplane approved by an AR for the Boeing DOA Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the approval must specifically reference this AD.

Alternative Methods of Compliance (AMOCs)

(v)(1) The Manager, Seattle ACO, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by an AR for the Boeing DOA Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the approval must specifically reference this AD.

Material Incorporated by Reference

(w) You must use Boeing Alert Service Bulletin 757-54A0039, Revision 1, dated June 20, 2002; Boeing Service Bulletin 757-54A0039, Revision 2, dated December 2, 2004; or Boeing Service Bulletin 757-54A0039, Revision 3, dated January 13, 2005; to perform the actions that are required by this AD, unless the AD specifies otherwise.

(1) On March 15, 2005 (70 FR 9511, February 28, 2005), the Director of the Federal Register approved the incorporation by reference of Boeing Service Bulletin 757-54A0039, Revision 2, dated December 2, 2004; and Boeing Service Bulletin 757-54A0039, Revision 3, dated January 13, 2005.

(2) On April 18, 2003 (68 FR 16200, April 3, 2003), the Director of the Federal Register approved the incorporation by reference of Boeing Alert Service Bulletin 757-54A0039, Revision 1, dated June 20, 2002.

(3) Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207, for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Room PL-401, Nassif Building, Washington, DC; on the Internet at <http://dms.dot.gov>; or at the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on August 1, 2005.

Ali Bahrami,

Manager, Transport Airplane Directorate,
Aircraft Certification Service.

[FR Doc. 05-15801 Filed 8-10-05; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2005-22070; Directorate Identifier 2005-NE-23-AD; Amendment 39-14218; AD 2005-16-12]

RIN 2120-AA64

Airworthiness Directives; Rolls-Royce Deutschland Ltd & Co KG (formerly Rolls-Royce Deutschland GmbH, formerly BMW Rolls-Royce GmbH) Model BR700-715A1-30, BR700-715B1-30, and BR700-715C1-30 Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for Rolls-Royce Deutschland Ltd & Co KG (RRD) (formerly Rolls-Royce Deutschland GmbH, formerly BMW Rolls-Royce GmbH) model BR700-715A1-30, BR700-715B1-30, and BR700-715C1-30 turbofan engines. This AD requires a onetime inspection of the Independent Overspeed Protection (IOP) unit, part number (P/N) 112E9321G2, for 19 specific serial numbers (SNs), and removal from service of those units. This AD results from a report that incorrect capacitors were installed in 19 IOP units. The incorrect capacitor in the IOP unit can lead to an inadvertent IOP command resulting in an in-flight engine shutdown. We are issuing this AD to prevent inadvertent dual-engine in-flight shutdown.

DATES: Effective August 26, 2005.

We must receive any comments on this AD by October 11, 2005.

ADDRESSES: Use one of the following addresses to comment on this AD:

- DOT Docket Web site: Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- Government-wide rulemaking Web site: Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- Mail: Docket Management Facility; U.S. Department of Transportation, 400

Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-0001.

- Fax: (202) 493-2251.

- Hand Delivery: Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Contact Rolls-Royce Deutschland Ltd & Co KG, Eschenweg 11, 15827 Blankenfelde-Mahlow, Germany, telephone: 011 49 (0) 33-7086-1768, fax: 011 49 (0) 33-7086-3356 for the service information identified in this AD.

FOR FURTHER INFORMATION CONTACT:

Jason Yang, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-5299; telephone: (781) 238-7747, fax: (781) 238-7199.

SUPPLEMENTARY INFORMATION: The Luftfahrt-Bundesamt (LBA), which is the airworthiness authority for Germany, recently notified us that an unsafe condition may exist on RRD model BR700-715A1-30, BR700-715B1-30, and BR700-715C1-30 turbofan engines. The LBA advises that the supplier of the IOP unit informed RRD that incorrect capacitors were installed in 19 IOP units, P/N 112E9321G2. The incorrect capacitor in the IOP unit can lead to an inadvertent IOP command and an in-flight engine shutdown. If both engines of an airplane have an affected IOP unit, inadvertent dual-engine in-flight shutdown could occur. The LBA issued airworthiness directive D-2005-221, dated June 17, 2005, in order to ensure the airworthiness of these engines in Germany.

Bilateral Airworthiness Agreement

These model BR700-715A1-30, BR700-715B1-30, and BR700-715C1-30 turbofan engines are manufactured in Germany and are type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Under this bilateral airworthiness agreement, the LBA kept the FAA informed of the situation described above. We have examined the findings of the LBA, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

FAA's Determination and Requirements of This AD

The unsafe condition described previously is likely to exist or develop on other model BR700-715A1-30, BR700-715B1-30, and BR700-715C1-30 turbofan engines of the same type design. We are issuing this AD to prevent inadvertent dual-engine in-flight shutdown. This AD requires:

- Within 10 flight cycles after the effective date of the AD, inspection of each engine's IOP unit, part number 112E9321G2, for the affected serial numbers; and
- If neither engine has an IOP unit listed in Table 1 of this AD, no further action is required; and
- If both engines have IOP units listed in Table 1 of this AD installed, remove at least one of the IOP units from service before further flight.
- If one engine has an IOP unit listed in Table 1 of this AD, remove the listed IOP from service no later than August 31, 2005.

FAA's Determination of the Effective Date

Since an unsafe condition exists that requires the immediate adoption of this AD, we have found that notice and opportunity for public comment before issuing this AD are impracticable, and that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety and was not preceded by notice and an opportunity for public comment; however, we invite you to send us any written relevant data, views, or arguments regarding this AD. Send your comments to an address listed under **ADDRESSES**. Include "AD Docket No. FAA-2005-22070; Directorate Identifier 2005-NE-23-AD" in the subject line of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify it.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this AD. Using the search function of the Docket Management System (DMS) Web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on