

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2005-17-02 Boeing: Amendment 39-14223. Docket No. FAA-2005-20350; Directorate Identifier 2004-NM-202-AD.

Effective Date

(a) This AD becomes effective September 26, 2005.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Boeing Model 777-200 and -300 series airplanes, certificated in any category; as identified in Boeing Special Attention Service Bulletin 777-28-0033, dated August 14, 2003.

Unsafe Condition

(d) This AD was prompted by reports of six incidents of the valve control and indication

wire bundles of the fuel system chafing against the rear spar stiffeners outside the fuel tank. We are issuing this AD to prevent this chafing, which could result in wire damage leading to a short circuit, subsequent ignition of flammable vapors, and possible uncontrollable fire during fueling or flight.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Detailed Inspection/Corrective Action

(f) Within 18 months after the effective date of this AD: Do a detailed inspection of the valve control and indication wire bundles of the fuel system of the wing rear spar for discrepancies (including any applicable corrective action), by doing all the actions specified in the Accomplishment Instructions of Boeing Special Attention Service Bulletin 777-28-0033, dated August 14, 2003. Any applicable corrective action must be done before further flight. Part number (P/N) BACC10GU105P, shown in the part list table of Kit 005W3225 and in the step tables in Figures 3 and 4 of the Accomplishment Instructions of the service bulletin, is not a valid P/N; the correct P/N that must be used is P/N BACC10JU105P.

Note 1: For the purposes of this AD, a detailed inspection is: "An intensive examination of a specific item, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at an intensity deemed appropriate. Inspection aids such as mirror, magnifying lenses, etc., may be necessary. Surface cleaning and elaborate procedures may be required."

Alternative Methods of Compliance (AMOCs)

(g) The Manager, Seattle Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

Material Incorporated by Reference

(h) You must use Boeing Special Attention Service Bulletin 777-28-0033, dated August 14, 2003, to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approves the incorporation by reference of this document in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. To get copies of the service information, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207. To view the AD docket, go to the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., room PL-401, Nassif Building, Washington, DC. To review copies of the service information, go to the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on August 10, 2005.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 05-16265 Filed 8-19-05; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2005-20353; Directorate Identifier 2004-NM-255-AD; Amendment 39-14224; AD 2005-17-03]

RIN 2120-AA64

Airworthiness Directives; Bombardier Model CL-600-2B19 (Regional Jet Series 100 & 440) Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Bombardier Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes. This AD requires installing additional shielding of the hydraulic lines in the wing box area. This AD results from the determination that the additional hydraulic line shields will protect the lines from possible impact by tire debris if the tire tread fails. We are issuing this AD to prevent damage to the hydraulic lines and subsequent leakage from the two hydraulic systems, which could result in loss of braking capability on the affected side of the airplane, asymmetrical braking, and reduced directional control—particularly during a rejected takeoff.

DATES: Effective September 26, 2005.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of September 26, 2005.

ADDRESSES: You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC.

For the service information identified in this AD, contact Bombardier, Inc., Canadair, Aerospace Group, P.O. Box 6087, Station Centre-ville, Montreal, Quebec H3C 3G9, Canada.

FOR FURTHER INFORMATION CONTACT: Daniel Parillo, Aerospace Engineer, Systems and Flight Test Branch, ANE-172, FAA, New York Aircraft

Certification Office, 1600 Stewart Avenue, suite 410, Westbury, New York 11590; telephone (516) 228-7305; fax (516) 794-5531.

SUPPLEMENTARY INFORMATION:

Examining the Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the street address stated in the **ADDRESSES** section.

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to certain Bombardier Model CL-

600-2B19 (Regional Jet Series 100 & 440) airplanes. That NPRM was published in the **Federal Register** on February 15, 2005 (70 FR 7674). That NPRM proposed to require installing additional shielding of the hydraulic lines in the wing box area.

Comments

We provided the public the opportunity to participate in the development of this AD. We received no comments on the NPRM or on the determination of the cost to the public.

Change to the NPRM

Since the NPRM was issued, Bombardier has revised Service Bulletin 601R-57-021. Revision 'D,' dated July 11, 2005, adds a procedure to cut the shield, changes the illustration, and incorporates minor editorial changes. The technical content remains otherwise unchanged from that in

Revision 'C.' We have revised paragraphs (f) and (g) in this final rule to indicate that accomplishment of the actions specified in revision 'B,' 'C,' or 'D' of the service bulletin is acceptable for compliance with the requirements of this AD.

Conclusion

We have carefully reviewed the available data and determined that air safety and the public interest require adopting the AD, with the change described previously. We have determined that this change will neither increase the economic burden on any operator nor increase the scope of the AD.

Costs of Compliance

The following table provides the estimated costs for U.S. operators to comply with this AD.

ESTIMATED COSTS

Action	Work hours	Average labor rate per hour	Parts	Cost per airplane	Number of U.S.-registered airplanes	Fleet cost
Shield installation	16	\$65	\$0	\$1,040	91	\$94,640

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and

responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

2005-17-03 Bombardier, Inc. (Formerly Canadair): Amendment 39-14224. Docket No. FAA-2005-20353; Directorate Identifier 2004-NM-255-AD.

Effective Date

(a) This AD becomes effective September 26, 2005.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Bombardier Model CL-600-2B19 (Regional Jet series 100 & 440) airplanes, certificated in any category, serial numbers 7003 through 7067 inclusive, 7069 through 7165 inclusive, 7167 through 7169 inclusive, and 7171 through 7188 inclusive.

Unsafe Condition

(d) This AD was prompted by the determination that additional shielding of the hydraulic lines in the wing box area will protect the lines from possible impact by tire debris if the tire tread fails. We are issuing this AD to prevent damage to the hydraulic lines and subsequent leakage from the two hydraulic systems, which could result in loss of braking capability on the affected side of the airplane, asymmetrical braking, and

reduced directional control—particularly during a rejected takeoff.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Installation of Hydraulic Line Shields

(f) Within 24 months after the effective date of this AD, install additional shielding of the hydraulic lines in the wing box area, by doing all the actions specified in the Accomplishment Instructions of Bombardier Service Bulletin 601R-57-021, Revision D, dated July 11, 2005.

(g) Installations accomplished before the effective date of this AD according to Bombardier Service Bulletin 601R-57-021, Revision "B," dated July 18, 2001; or Revision "C," dated February 23, 2004; are considered acceptable for compliance with the corresponding action specified in this AD.

Alternative Methods of Compliance (AMOCs)

(h) The Manager, New York Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

Related Information

(i) Canadian airworthiness directive CF-2004-20, dated October 5, 2004, also addresses the subject of this AD.

Material Incorporated by Reference

(j) You must use Bombardier Service Bulletin 601R-57-021, Revision D, dated July 11, 2005, to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of this document in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Bombardier, Inc., Canadair, Aerospace Group, P.O. Box 6087, Station Centreville, Montreal, Quebec H3C 3G9, Canada, for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., Room PL-401, Nassif Building, Washington, DC; on the internet at <http://dms.dot.gov>; or at the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on August 10, 2005.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 05-16264 Filed 8-19-05; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2005-20730; Directorate Identifier 2004-NM-68-AD; Amendment 39-14172; AD 2005-13-35]

RIN 2120-AA64

Airworthiness Directives; Bombardier Model DHC-8-100, DHC-8-200, and DHC-8-300 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is superseding an existing airworthiness directive (AD), which applies to all Bombardier Model DHC-8-100, DHC-8-200, and DHC-8-300 series airplanes. That AD currently requires installation of a placard on the instrument panel of the cockpit to advise the flightcrew that positioning of the power levers below the flight idle stop during flight is prohibited. Additionally, the existing AD requires eventual installation of an FAA-approved system that would prevent such positioning of the power levers during flight. Installation of that system terminates the requirement for installation of a placard. This new AD requires operators who have incorporated a certain Bombardier service bulletin to perform repetitive operational checks of the beta lockout system and to revise the Airworthiness Limitations document. This AD is prompted by in-service issues reported by operators who incorporated Bombardier Service Bulletin 8-76-24 as an alternative method of compliance to the existing AD. We are issuing this AD to prevent the inadvertent activation of ground beta mode during flight, which could lead to engine overspeed, engine damage or failure, and consequent reduced controllability of the airplane.

DATES: This AD becomes effective September 26, 2005.

The incorporation by reference of certain publications listed in the AD is approved by the Director of the Federal Register as of September 26, 2005.

ADDRESSES: For service information identified in this AD, contact Bombardier, Inc., Bombardier Regional Aircraft Division, 123 Garratt Boulevard, Downsview, Ontario M3K 1Y5, Canada.

Docket: The AD docket contains the proposed AD, comments, and any final disposition. You can examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket

Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the U.S. Department of Transportation, 400 Seventh Street SW., room PL-401, Washington, DC. This docket number is FAA-2005-20730; the directorate identifier for this docket is 2004-NM-68-AD.

FOR FURTHER INFORMATION CONTACT: Richard Fiesel, Aerospace Engineer, Airframe and Propulsion Branch, ANE-171, Federal Aviation Administration, New York Aircraft Certification Office, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone (516) 228-7304; fax (516) 794-5531.

SUPPLEMENTARY INFORMATION: The FAA proposed to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) with an AD to supersede AD 2000-02-13, amendment 39-11531 (65 FR 4095, January 26, 2000). The existing AD applies to all Bombardier Model DHC-8-101, -102, -103, -106, -201, -202, -301, -311, and -315 airplanes. The proposed AD was published in the **Federal Register** on March 30, 2005 (70 FR 16164), to continue to require installation of a placard on the instrument panel of the cockpit and eventual installation of an FAA-approved system to prevent positioning of the power levers below the flight idle stop. The proposed AD would also require operators who have incorporated a certain Bombardier service bulletin to perform repetitive operational checks of the beta lockout system and to revise the Airworthiness Limitations document.

Comments

We provided the public the opportunity to participate in the development of this AD. We have considered the comment that has been submitted on the proposed AD. The commenter supports the proposed AD.

Explanation of Change to Applicability

We have revised the applicability of the proposed AD to identify model designations as published in the most recent type certificate data sheet for the affected models.

Conclusion

We have carefully reviewed the available data, including the comment that has been submitted, and determined that air safety and the public interest require adopting the AD with the change described previously. We have determined that this change will neither increase the economic