

determine if the serial number (S/N) of the elevator is listed in Airbus All Operators Telex (AOT) A300–600–55A6032, dated June 23, 2004 (for Model A300 B4–601, B4–603, B4–620, B4–622, B4–605R, B4–622R, C4–605R Variant F, F4–605R, and F4–622R airplanes); or in Airbus AOT A310–55A2033, dated June 23, 2004 (for Model A310–203,

–204, –221, –222, –304, –322, –324, and –325 airplanes).

(1) If the S/N does not match any S/N on either AOT S/N list, no further action is required by this paragraph.

(2) If the S/N matches a S/N listed in an AOT, before further flight, do the actions listed in Table 1 of this AD, and any

corrective action as applicable, in accordance with Airbus AOT A300–600–55A6032, dated June 23, 2004; or Airbus AOT A310–55A2033, dated June 23, 2004; as applicable. Repeat the inspections at intervals not to exceed 600 flight hours. Do applicable corrective actions before further flight.

TABLE 1.—REPETITIVE INSPECTIONS

Do a—	Of the—	For any—
Detailed inspection	Elevator upper and lower external skin surfaces	Damage (i.e., breaks in the graphite fiber reinforced plastic (GFRP)/Tedar film protection, debonded GFRP/Tedar film protection, bulges, torn-out plies).
Visual inspection with a low-angle light.	Elevator upper and lower external skin surfaces	Differences in the surface reflection.
Tap-test inspection	Upper and lower external skin surfaces of the honeycomb core panels in the elevator.	Honeycomb core that has debonded from the carbon fiber reinforced plastic (CFRP).

Note 1: For the purposes of this AD, a detailed inspection is “an intensive examination of a specific item, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at an intensity deemed appropriate. Inspection aids such as mirrors magnifying lenses, etc. may be necessary. Surface cleaning and elaborate procedures may be required.”

Repair Approval

(g) Where the AOT says to contact the manufacturer for repair instructions, or an alternative inspection method: Before further flight, repair or do the alternative inspection method according to a method approved by either the Manager, International Branch, ANM–116, FAA, Transport Airplane Directorate; or the Direction Générale de l'Aviation Civile (DGAC) (or its delegated agent).

Parts Installation

(h) As of the effective date of this AD, no carbon fiber elevator having part number (P/N) A55276055000 (left-hand side) or P/N A55276056000 (right-hand side) may be installed on any airplane unless it is inspected according to paragraph (f) of this AD.

No Reporting Required

(i) Although the AOTs referenced in this AD specify to submit inspection reports to the manufacturer, this AD does not include that requirement.

Alternative Methods of Compliance (AMOCs)

(j)(1) The Manager, International Branch, ANM–116, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with 14 CFR 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

Related Information

(k) French airworthiness directive F–2004–131, dated August 4, 2004, also addresses the subject of this AD.

Material Incorporated by Reference

(l) You must use Airbus All Operators Telex A300–600–55A6032, dated June 23, 2004; or Airbus All Operators Telex A310–55A2033, dated June 23, 2004; as applicable; to perform the actions that are required by this AD, unless the AD specifies otherwise. (The document number and date are only included on the first page of these documents.) The Director of the Federal Register approved the incorporation by reference of these documents in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France, for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., Room PL–401, Nassif Building, Washington, DC; on the Internet at <http://dms.dot.gov>; or at the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741–6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on December 15, 2005.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 05–24531 Filed 12–29–05; 8:45 am]

BILLING CODE 4910–13–U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002–NM–89–AD; Amendment 39–14436; AD 2005–26–15]

RIN 2120–AA64

Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model EMB–135 Airplanes; and Model EMB–145, –145ER, –145MR, –145LR, –145XR, –145MP, and –145EP Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain EMBRAER Model EMB–135 airplanes; and Model EMB–145, –145ER, –145MR, –145LR, –145XR, –145MP, and –145EP airplanes, that requires performing repetitive inspections for cracks, ruptures, or bends in certain components of the elevator control system; replacing discrepant components; and, for certain airplanes, installing a new spring cartridge and implementing new logic for the electromechanical gust lock system. The AD also requires eventual modification of the elevator gust lock system to replace the mechanical system with an electromechanical system, which will terminate the repetitive inspections. The actions specified by this AD are intended to prevent discrepancies in the elevator control system, which could result in reduced control of the elevator and consequent reduced controllability of the airplane. This action is intended to address the identified unsafe condition.

DATES: Effective February 3, 2006.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of February 3, 2006.

ADDRESSES: The service information referenced in this AD may be obtained from Empresa Brasileira de Aeronautica S.A. (EMBRAER), P.O. Box 343—CEP 12.225, Sao Jose dos Campos—SP, Brazil. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Todd Thompson, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-1175; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain EMBRAER Model EMB-135 and -145 series airplanes was published as a supplemental notice of proposed rulemaking (NPRM) in the **Federal Register** on September 21, 2005 (70 FR 55310). That action proposed to require performing repetitive inspections for cracks, ruptures, or bends in certain components of the elevator control system; replacing discrepant components; and, for certain airplanes, installing a new spring cartridge and implementing new logic for the electromechanical gust lock system. The proposed AD also would have required eventual modification of the elevator gust lock system to replace the mechanical system with an electromechanical system, which would terminate the repetitive inspections.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments to the proposed AD were received.

Correction to Final Rule

In paragraph (c)(2) of the supplemental NPRM we inadvertently used an incorrect date for EMBRAER Service Bulletin 145-27-0086, Change 04, dated March 21, 2005, and have corrected the date accordingly in the final rule.

Clarification of Appropriate Service Information

We have revised paragraphs (c)(1)(i) and (c)(1)(ii) of this AD to clarify that the actions required by those paragraphs must be done in accordance with EMBRAER Service Bulletin 145-27-0075, Revision 08, dated March 3, 2005.

Clarification of Alternative Method of Compliance (AMOC) Paragraph

We have revised this action to clarify the appropriate procedure for notifying the principal inspector before using any approved AMOC on any airplane to which the AMOC applies.

Explanation of Change to Applicability

We specify model designations in the applicability of this proposed AD as those designations are published in the most recent type certificate data sheet for the affected models. These model designations differ in the referenced service bulletin(s).

Conclusion

We have carefully reviewed the available data and determined that air safety and the public interest require adopting the AD with the changes described previously. We have determined that these changes will neither increase the economic burden on any operator nor increase the scope of the AD.

Cost Impact

We estimate that 300 airplanes of U.S. registry will be affected by this AD.

It will take approximately 1 work hour per airplane, per inspection cycle, to accomplish the inspection, at an average labor rate of \$65 per work hour. Based on these figures, the cost impact of this action on U.S. operators is estimated to be \$19,500, or \$65 per airplane, per inspection cycle.

We estimate that 108 airplanes of U.S. registry will be subject to EMBRAER Service Bulletin 145-27-0075, Revision 08, dated March 3, 2005. For these airplanes, it will take up to 65 work hours to accomplish the modification in that service bulletin, at an average labor rate of \$65 per work hour. Required parts will cost up to \$14,000 per airplane. Based on these figures, the cost impact of this action on U.S. operators is estimated to be up to \$1,968,300, or \$18,225 per airplane.

We estimate that 192 airplanes of U.S. registry will be subject to EMBRAER Service Bulletin 145-27-0086, Change 04, dated March 21, 2005. For these airplanes, it will take approximately 133 work hours to accomplish the modification in that service bulletin, at an average labor rate of \$65 per work

hour. Required parts will cost up to \$23,164 per airplane. Based on these figures, the cost impact of this action on U.S. operators is estimated to be up to \$6,107,328, or \$31,809 per airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the National Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory

Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. Section 39.13 is amended by adding the following new airworthiness directive:

2005–26–15 Empresa Brasileira de Aeronautica S.A. (EMBRAER):

Amendment 39–14436. Docket 2002–NM–89–AD.

Applicability: Model EMB–135BJ, –135ER, –135KE, –135KL, and –135LR airplanes; and Model EMB–145, –145ER, –145MR, –145LR, –145XR, –145MP, and –145EP airplanes, certificated in any category; serial numbers 145001 through 145189 inclusive, 145191 through 145362 inclusive, 145364 through 145373 inclusive, 145375, 145377 through 145411 inclusive, 145413 through 145424 inclusive, 145426 through 145430 inclusive, 145434 through 145436 inclusive, 145440 through 145445 inclusive, 145448, 145450, and 145801; equipped with a mechanical gust lock system, certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To prevent discrepancies in the elevator control system, which could result in reduced control of the elevator and consequent reduced controllability of the airplane, accomplish the following:

Repetitive Inspections

(a) Within 800 flight hours after the effective date of this AD, do a detailed inspection of the elevator control system for any crack, rupture, or bend in any component, in accordance with the Accomplishment Instructions of EMBRAER Service Bulletin 145–27–0087, Change 03, dated September 27, 2002. Where this service bulletin specifies to return discrepant parts and report inspection results to the manufacturer, this AD does not require these actions. Repeat the inspection thereafter at intervals not to exceed 2,500 flight hours or 15 months, whichever is first.

Note 1: For the purposes of this AD, a detailed inspection is defined as: “An

intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required.”

Replacement of Discrepant Parts

(b) If any discrepant part is found during any inspection required by paragraph (a) of this AD, before further flight, replace the discrepant part with a new part, in accordance with the Accomplishment Instructions of EMBRAER Service Bulletin 145–27–0087, Change 03, dated September 27, 2002.

Modification

(c) Within 10,000 flight hours or 60 months after the effective date of this AD, whichever is first, modify the elevator gust lock by accomplishing paragraph (c)(1) or (c)(2) of this AD, as applicable. This modification terminates the repetitive inspections required by paragraph (a) of this AD.

(1) For airplanes listed in EMBRAER Service Bulletin 145–27–0075, Revision 08, dated March 3, 2005: Do paragraph (c)(1)(i) or (c)(1)(ii) of this AD, as applicable, and install a new spring cartridge and implement new logic for the electromechanical gust lock system by doing all actions in section 3.D. (Part IV) of the Accomplishment Instructions of the service bulletin. After accomplishing the actions in EMBRAER Service Bulletin 145–27–0101; as specified in the Accomplishment Instructions of EMBRAER Service Bulletin 145–27–0075, Revision 08; the airplane flight manual (AFM) revision required by AD 2002–26–51, amendment 39–13008, may be removed from the Limitations section of the EMBRAER EMB–145 AFM. Accomplishing the actions specified in the Accomplishment Instructions of EMBRAER Service Bulletin 145–27–0102; as specified by EMBRAER Service Bulletin 145–27–0075, Revision 08; terminates the repetitive inspections required by AD 2005–24–11, amendment 39–14391.

(i) Replace the mechanical gust lock system with an electromechanical gust lock system, and replace the control stand with a reworked control stand, by doing all the actions (including a detailed inspection to ensure that certain parts have been removed previously per EMBRAER Service Bulletin 145–27–0076) in and per section 3.A. (Part I) or 3.B. (Part II) of the Accomplishment Instructions of EMBRAER Service Bulletin 145–27–0075, Revision 08, as applicable. If the inspection reveals that certain subject parts have not been removed previously, before further flight, remove the subject parts in accordance with EMBRAER Service Bulletin 145–27–0075, Revision 08. Where Parts I and II of the Accomplishment Instructions of EMBRAER Service Bulletin 145–27–0075, Revision 08, specify to remove and “send the control stand to be reworked in a workshop,” replace the control stand with a control stand reworked as specified in EMBRAER Service Bulletin 145–27–0075, Revision 08.

(ii) Replace the return spring and spring terminal of the gust lock control lever with improved parts by doing all the actions in and per section 3.C. (Part III) of the Accomplishment Instructions of EMBRAER Service Bulletin 145–27–0075, Revision 08.

Note 2: Part IV of the Accomplishment Instructions of EMBRAER Service Bulletin 145–27–0075, Revision 08, refers to EMBRAER Service Bulletin 145–27–0101, currently at Revision 02, dated December 27, 2004; and EMBRAER Service Bulletin 145–27–0102, currently at Revision 02, dated January 20, 2005; as additional sources of instructions for accomplishing the installation of a new spring cartridge and implementation of the new logic for the electromechanical gust lock system.

(2) For airplanes listed in EMBRAER Service Bulletin 145–27–0086, Change 04, dated March 21, 2005: Do paragraphs (c)(2)(i), (c)(2)(ii), (c)(2)(iii), and (c)(2)(iv) of this AD, as applicable.

(i) Rework the tail carbon box and the horizontal stabilizer by doing all the actions (including the inspection for delamination) in and per section 3.A. (Part I) of the Accomplishment Instructions of the service bulletin. If any delamination is found that is outside the limits specified in the service bulletin, before further flight, repair per a method approved by either the Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, or the Departamento de Aviação Civil (or its delegated agent).

(ii) Install wiring and electrical components by doing all the actions in and per section 3.B. (Part II) of the Accomplishment Instructions of the service bulletin.

(iii) Install and activate the electromechanical gust lock system by doing all actions in section 3.D. (Part IV) of the Accomplishment Instructions of the service bulletin. Where Part IV of the Accomplishment Instructions of the service bulletin specifies to remove and “send the control stand to be reworked in a workshop,” replace the control stand with a control stand reworked as specified in Part III of the service bulletin.

(iv) Install a new spring cartridge and implement new logic for the electromechanical gust lock system by doing all actions in section 3.E. (Part V) of the Accomplishment Instructions of the service bulletin, as applicable. After accomplishing the actions in EMBRAER Service Bulletin 145–27–0101; as specified in the Accomplishment Instructions of EMBRAER Service Bulletin 145–27–0086, Change 04; the AFM revision required by AD 2002–26–51, amendment 39–13008, may be removed from the Limitations section of the EMBRAER EMB–145 AFM. Accomplishing the actions in EMBRAER Service Bulletin 145–27–0102; as specified in the Accomplishment Instructions of EMBRAER Service Bulletin 145–27–0086, Change 04; terminates the repetitive inspections required by AD 2005–24–11, amendment 39–14391.

Note 3: Part V of the Accomplishment Instructions of EMBRAER Service Bulletin 145–27–0086, Change 04, refers to EMBRAER Service Bulletin 145–27–0101, currently at

Revision 02, dated December 27, 2004; and EMBRAER Service Bulletin 145-27-0102, currently at Revision 02, dated January 20, 2005; as additional sources of instructions for accomplishing the installation of a new spring cartridge and implementation of the new logic for the electromechanical gust lock system.

Actions Accomplished Previously

(d) Actions accomplished before the effective date of this AD are acceptable for compliance with corresponding requirements of this AD as specified in paragraphs (d)(1), (d)(2), and (d)(3) of this AD.

(1) Modification of the elevator gust lock system before the effective date of this AD in accordance with EMBRAER Service Bulletin 145-27-0075, Change 06, dated July 16, 2002, is acceptable for compliance with paragraph (c)(1) of this AD, provided that, within the compliance time specified in paragraph (c) of this AD, a new spring

cartridge is installed and new logic for the electromechanical gust lock system is implemented in accordance with Part IV of EMBRAER Service Bulletin 145-27-0075, Revision 07, dated March 2, 2004, or Revision 08, dated March 3, 2005.

(2) Modification of the elevator gust lock system before the effective date of this AD in accordance with EMBRAER Service Bulletin 145-27-0075, Revision 07, dated March 2, 2004, is acceptable for compliance with paragraph (c)(1) of this AD.

(3) Modification of the elevator gust lock system before the effective date of this AD in accordance with EMBRAER Service Bulletin 145-27-0086, Change 02, dated December 23, 2003; or EMBRAER Service Bulletin 145-27-0086, Change 03, dated April 14, 2004; is acceptable for compliance with paragraph (c)(2) of this AD.

Alternative Methods of Compliance

(e)(1) In accordance with 14 CFR 39.19, the Manager, International Branch, ANM-116, is

authorized to approve alternative methods of compliance for this AD.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

Note 4: The subject of this AD is addressed in Brazilian airworthiness directive 2002-01-01R3, dated November 8, 2002.

Material Incorporated by Reference

(f) Unless otherwise specified in this AD, the actions must be done in accordance with the EMBRAER service information listed in Table 1 of this AD. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. EMBRAER Service Bulletin 145-27-0075, Revision 08, dated March 3, 2005, contains the following effective pages:

Page Nos.	Revision level shown on page	Date shown on page
1-6, 8, 30-34, 39, 41, 51, 58, 62, 68, 110	08	March 3, 2005.
7, 9-29, 35-38, 40, 42-50, 52-57, 59-61, 63-67, 69-109, 111-117	07	March 2, 2004.

EMBRAER Service Bulletin 145-27-0086, Change 04, dated March 21, 2005, contains the following effective pages:

Page Nos.	Change level shown on page	Date shown on page
1-2, 5, 11-12, 23, 31, 32, 40, 62, 95	04	March 21, 2005.
3-4, 6-10, 13-22, 24-30, 33-39, 41-61, 63-94, 96-137	03	April 14, 2004.

To get copies of this service information, contact Empresa Brasileira de Aeronautica S.A. (EMBRAER), P.O. Box 343—CEP 12.225, Sao Jose dos Campos—SP, Brazil. To inspect copies of this service information, go to the

FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or to the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA,

call (202) 741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

TABLE 1.—MATERIAL INCORPORATED BY REFERENCE

EMBAER service bulletin	Revision/change level	Date
145-27-0075	Revision 08	March 3, 2005.
145-27-0086	Change 04	March 21, 2005.
145-27-0087	Change 03	September 27, 2002.

Effective Date

(g) This amendment becomes effective on February 3, 2006.

Issued in Renton, Washington, on December 13, 2005.

Ali Bahrami,

*Manager, Transport Airplane Directorate,
Aircraft Certification Service.*

[FR Doc. 05-24530 Filed 12-29-05; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2005-22148; Directorate Identifier 2005-NM-033-AD; Amendment 39-14437; AD 2005-26-16]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A300 B2 and A300 B4 Series Airplanes; A300 B4-600, B4-600R, and F4-600R Series Airplanes, and C4-605R Variant F Airplanes (Collectively Called A300-600 Series Airplanes); and Airbus Model A310-200 and A310-300 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is superseding an existing airworthiness directive (AD) that applies to certain Airbus Model A300-600 and A310 series airplanes. That AD currently requires repetitive visual inspections to detect corrosion on the lower rim area of the fuselage rear pressure bulkhead; and follow-on actions, if necessary. This new AD requires new repetitive inspections for corrosion on the rear pressure bulkhead between stringer (STGR) 27 (right hand) and STGR27 (left hand), and related investigative and corrective actions if necessary. This AD also requires sending a report of certain information to the manufacturer. The AD also adds airplanes to the applicability of the existing AD. This AD results from findings of severe corrosion on airplanes previously inspected in accordance with the existing AD. We are issuing this AD to detect and correct corrosion at the lower rim area of the fuselage rear pressure bulkhead, which could result in reduced structural integrity of the bulkhead, and consequent decompression of the cabin.

DATES: This AD becomes effective February 3, 2006.

The Director of the Federal Register approved the incorporation by reference

of certain publications listed in the AD as of February 3, 2006.

ADDRESSES: You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., Nassif Building, room PL-401, Washington, DC.

Contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France, for service information related to Airbus Model A310 series airplanes identified in this AD. Contact Jacques Leborgne, Airbus Customer Service Directorate, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; fax (+33) 5 61 93 36 14, for service information related to Airbus Model A300 identified in this AD.

FOR FURTHER INFORMATION CONTACT: Tim Backman, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2797; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:**Examining the Docket**

You may examine the airworthiness directive (AD) docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the street address stated in the **ADDRESSES** section.

ADDRESSES**Discussion**

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that supersedes AD 98-19-22, amendment 39-10763 (63 FR 49656, September 17, 1998). The existing AD applies to certain Airbus Model A300-600 and A310 series airplanes. That NPRM was published in the **Federal Register** on August 22, 2005 (70 FR 48911). That NPRM proposed to require repetitive inspections for corrosion on the rear pressure bulkhead between stringer (STGR) 27 (right hand) and STGR27 (left hand), and related investigative/corrective actions if necessary; and sending a report of certain information to the manufacturer.

Comments

We provided the public the opportunity to participate in the development of this AD. We have considered the comments that have been received on the NPRM.

Request To Reference Latest Issue of Service Bulletin

The commenter states that Airbus has revised Service Bulletin A300-53-6136, dated October 27, 2004, which was referenced as the appropriate source of service information for accomplishing the proposed actions for certain Airbus airplanes. The commenter points out that this service bulletin is now at Revision 01, dated July 18, 2005. The commenter states that Revision 01 of Service Bulletin A300-53-6136 corrects the flow chart in Figure 1 of the service bulletin by changing the sequence of certain inspections, removes information in a flag note, and removes the replacement of titanium fasteners in certain circumstances. The commenter recommends that we reference Airbus Service Bulletin A300-53-6136, Revision 01, and that we also give credit for actions done before the effective date of this AD in accordance with the original issue of this service bulletin.

We agree with the commenter. We have revised Table 1 of the AD to refer to Airbus Service Bulletin A300-53-6136, Revision 01, dated July 18, 2005. In addition, the other service bulletins referenced in the NPRM have also been revised. (Airbus Service Bulletins A300-53-0363 and A310-53-2114, both dated October 27, 2004, were referenced as the appropriate source of service information for accomplishing the proposed actions for certain other Airbus airplanes.) The additional new revisions are Airbus Service Bulletin A300-53-0363, Revision 01, dated June 10, 2005; and Airbus Service Bulletin A310-53-2114, Revision 01, dated September 1, 2005. The revised service bulletins change the compliance of the service bulletin from "recommended" to "mandatory," and amend the effectivity. None of the revisions increase the economic burden on any operator or increase the scope of the AD. We have also added a new paragraph (j) to the AD to give credit to operators that have accomplished the actions in accordance with the original issue of the service bulletins.

Request To Give Credit for Actions Accomplished Previously

The commenter requests that we ensure that operators of airplanes on which the proposed inspections were done before the effective date of the AD be given credit for inspections accomplished before that date. The commenter states that, as defined in paragraph (g) of the NPRM, operators that had previously accomplished the inspections would be forced to re-accomplish the inspections within 18