

or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at an intensity deemed appropriate. Inspection aids such as mirror, magnifying lenses, etc., may be necessary. Surface cleaning and elaborate procedures may be required.”

#### Reporting

(g) Before further flight, submit a report of the findings (both positive and negative) of the inspection required by paragraph (f) of this AD to Robert A. Romero, Aerospace Engineer, ACO, ASW-150, Rotorcraft Directorate, FAA, 2601 Meacham Boulevard, Fort Worth, Texas 76137-4298; fax (817) 222-5960. The report must include the inspection results, a description of any discrepancies found, the airplane serial number, and the number of total flight cycles and flight hours on the airplane. Under the provisions of the Paperwork Reduction Act of 1980 (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements contained in this AD and has assigned OMB Control Number 2120-0056.

#### Repair

(h) If any cracking or corrosion is found during the inspection required by paragraph (f) of this AD, repair before further flight, in accordance with a method approved by the Manager, ACO, ASW-150, Rotorcraft Directorate, FAA.

#### Special Flight Permit

(i) Special flight permits, as described in Section 21.197 (“Special flight permits”) and Section 21.199 (“Issue of special flight permits”) of the Federal Aviation Regulations (14 CFR 21.197 and 21.199), may be issued to operate the airplane to a location where the requirements of this AD can be accomplished but concurrence by the Manager, ACO, ASW-150, Rotorcraft Directorate, FAA, is required prior to issuance of the special flight permit.

#### Alternative Methods of Compliance (AMOCs)

(j)(1) The Manager, ACO, ASW-150, Rotorcraft Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

#### Material Incorporated by Reference

(k) None.

Issued in Renton, Washington, on January 5, 2006.

**Ali Bahrami,**

Manager, Transport Airplane Directorate,  
Aircraft Certification Service.

[FR Doc. 06-259 Filed 1-11-06; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2005-22791; Directorate Identifier 2005-NM-083-AD; Amendment 39-14448; AD 2006-01-09]

RIN 2120-AA64

#### Airworthiness Directives; BAE Systems (Operations) Limited Model BAe 146-100A and -200A Series Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for all BAE Systems (Operations) Limited Model BAe 146-100A and -200A series airplanes. This AD requires inspecting the nose landing gear (NLG) assembly to determine the part number of the NLG main fitting subassembly. For subject NLG main fitting subassemblies, this AD also requires determining the total number of accumulated landings on a subject NLG main fitting subassembly, and eventually replacing the NLG assembly. This AD results from a report indicating that the airplane maintenance manual contains incorrect safe-life limit information for certain NLG assemblies. We are issuing this AD to ensure that affected NLG fitting subassemblies are removed from service before they reach their approved safe-life limit. Operating with an NLG fitting subassembly that is beyond its approved safe-life limit could result in failure of the NLG and consequent loss of directional control on the ground and major structural damage to the airplane.

**DATES:** This AD becomes effective February 16, 2006.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of February 16, 2006.

**ADDRESSES:** You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC.

Contact British Aerospace Regional Aircraft American Support, 13850 Mclearen Road, Herndon, Virginia 20171, for service information identified in this AD.

**FOR FURTHER INFORMATION CONTACT:** Todd Thompson, Aerospace Engineer, International Branch, ANM-116,

Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-1175; fax (425) 227-1149.

#### SUPPLEMENTARY INFORMATION:

##### Examining the Docket

You may examine the airworthiness directive (AD) docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the street address stated in the **ADDRESSES** section.

##### Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to all BAE Systems (Operations) Limited Model BAe 146-100A and -200A series airplanes. That NPRM was published in the **Federal Register** on October 27, 2005 (70 FR 61916). That NPRM proposed to require inspecting the nose landing gear (NLG) assembly to determine the part number of the NLG main fitting subassembly. For subject NLG main fitting subassemblies, that NPRM also proposed to require determining the total number of accumulated landings on a subject NLG main fitting subassembly, and eventually replacing the NLG assembly.

##### Comments

We provided the public the opportunity to participate in the development of this AD. We received no comments on the NPRM or on the determination of the cost to the public.

##### Conclusion

We have carefully reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

##### Costs of Compliance

This AD will affect about 18 airplanes of U.S. registry. The required inspection will take about 1 work hour per airplane, at an average labor rate of \$65 per work hour. Based on these figures, the estimated cost of the AD for U.S. operators is \$1,170, or \$65 per airplane.

##### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more

detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

■ 2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

**2006-01-09 BAE Systems (Operations) Limited (Formerly British Aerospace Regional Aircraft):** Amendment 39-14448. Docket No. FAA-2005-22791; Directorate Identifier 2005-NM-083-AD.

#### Effective Date

(a) This AD becomes effective February 16, 2006.

#### Affected ADs

(b) None.

#### Applicability

(c) This AD applies to all BAE Systems (Operations) Limited Model BAe 146-100A and -200A series airplanes, certificated in any category.

#### Unsafe Condition

(d) This AD results from a report indicating that the airplane maintenance manual contains incorrect safe-life limit information for certain nose landing gear (NLG) assemblies. We are issuing this AD to ensure that affected NLG fitting subassemblies are removed from service before they reach their approved safe-life limit. Operating with an NLG fitting subassembly that is beyond its approved safe-life limit could result in failure of the NLG and consequent loss of directional control on the ground and major structural damage to the airplane.

#### Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

#### Service Bulletin Reference

(f) The term "service bulletin," as used in this AD, means the Accomplishment Instructions of BAE Systems (Operations) Limited Model BAe 146 Modification Service Bulletin ISB.32-169, dated October 4, 2004.

(1) The service bulletin refers to Messier-Dowty Service Bulletin 146-32-155, dated July 16, 2004, as an additional source of service information for inspecting to determine the part number of the NLG main fitting subassembly, determining the number of accumulated landings on the NLG main fitting subassembly, and replacing the NLG assembly.

(2) Although the service bulletin specifies to submit certain information to the manufacturer and to return replaced NLG assemblies to the manufacturer or other overhaul facility, this AD does not require those actions.

#### Inspection To Determine Part Number

(g) Within 30 days after the effective date of this AD: Inspect the NLG assembly to determine the part number of the NLG main fitting subassembly, in accordance with the service bulletin. If the part number of the NLG main fitting subassembly is not listed in paragraph 1.A.(2) of the service bulletin, then this paragraph requires no further action. A review of airplane maintenance records is acceptable in lieu of this inspection if the part number of the NLG main fitting subassembly can be conclusively determined from that review.

### Replacement of NLG

(h) If the part number of the NLG main fitting subassembly is listed in paragraph 1.A.(2) of the service bulletin: Determine the total accumulated landings on the subassembly (since the subassembly was new or overhauled), and replace the NLG with a new, serviceable, or overhauled subassembly, in accordance with the service bulletin. (For the purposes of this AD, a serviceable NLG is one on which the NLG main fitting subassembly has been identified, the number of landings has been determined, and the number of landings does not exceed the limits specified in paragraphs (h), (h)(1) or (h)(2) of this AD, as applicable.) Do the actions specified in this paragraph at the applicable time specified in paragraph (h)(1) or (h)(2) of this AD, or within 500 landings after the effective date of this AD, whichever is later. A review of airplane maintenance records is acceptable in lieu of this inspection if the total accumulated landings on the subassembly (since the subassembly was new or overhauled) can be conclusively determined from that review.

(1) If the NLG has not been overhauled previously: Prior to the accumulation of 35,000 total landings on the NLG.

(2) If the NLG has been overhauled previously: Within 8,000 landings since the most recent overhaul.

### Parts Installation

(i) After the effective date of this AD, no person may install an NLG that is equipped with a main fitting subassembly having a part number identified in paragraph 1.A.(2) of the service bulletin, unless all of the applicable actions in paragraphs (g) and (h) of this AD have been done.

### Alternative Methods of Compliance (AMOCs)

(j)(1) The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with 14 CFR 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

### Related Information

(k) British airworthiness directive G-2005-0001, dated January 12, 2005, also addresses the subject of this AD.

### Material Incorporated by Reference

(l) You must use BAE Systems (Operations) Limited Model BAe 146 Modification Service Bulletin ISB.32-169, dated October 4, 2004, to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of this document in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact British Aerospace Regional Aircraft American Support, 13850 Mclearen Road, Herndon, Virginia 20171, for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation,

400 Seventh Street, SW., Room PL-401, Nassif Building, Washington, DC; on the Internet at <http://dms.dot.gov>; or at the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

Issued in Renton, Washington, on December 30, 2005.

**Linda Navarro,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 06-184 Filed 1-11-06; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2005-21275; Directorate Identifier 2005-CE-28-AD; Amendment 39-14450; AD 2006-01-11]

RIN 2120-AA64

#### **Airworthiness Directives; The Cessna Aircraft Company Models 208 and 208B Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** The FAA adopts a new airworthiness directive (AD) for all The Cessna Aircraft Company (Cessna) Models 208 and 208B airplanes. This AD requires you to install the pilot assist handle (part number (P/N) SK208-146-2) (or FAA-approved equivalent part number) and deicing boots on the cargo pod and landing gear fairings (part number (P/N) AK208-6C) (or FAA-approved equivalent part number); and make changes to the Pilot's Operating Handbook (POH) and FAA-approved Airplane Flight Manual (AFM). This AD results from reports of several accidents involving the affected airplanes during operations in flight and in ground icing conditions. We are issuing this AD to provide a safe method to detect ice, snow, frost, or slush adhering to the upper wing (a critical surface) prior to takeoff; and to reduce drag in-flight by shedding ice on the cargo pod and landing gear fairings. Ice adhering to the upper wing surface, cargo pod, or landing gear fairings could result in a reduction in airplane performance with the consequences that the airplane cannot perform a safe takeoff or climb.

**DATES:** This AD becomes effective on February 22, 2006.

As of February 22, 2006, the Director of the Federal Register approved the incorporation by reference of certain publications listed in the regulation.

**ADDRESSES:** To get the service information identified in this AD, contact The Cessna Aircraft Company, Product Support, P.O. Box 7706, Wichita, Kansas 67277-7706; telephone: (316) 517-5800; facsimile: (316) 942-9006.

To view the AD docket, go to the Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-001 or on the Internet at <http://dms.dot.gov>. The docket number is FAA-2005-21275; Directorate Identifier 2005-CE-28-AD.

**FOR FURTHER INFORMATION CONTACT:** Paul Pellicano, Aerospace Engineer (Icing), FAA, Small Airplane Directorate, c/o Atlanta Aircraft Certification Office (ACO), One Crown Center, 1985 Phoenix Boulevard, Suite 450, Atlanta, GA 30349; telephone: (770) 703-6064; facsimile: (770) 703-6097; or Robert P. Busto, Aerospace Engineer, Wichita ACO, FAA, 1801 Airport Road, Wichita, Kansas 67209; telephone: (316) 946-4157; facsimile: (316) 946-4107.

#### **SUPPLEMENTARY INFORMATION:**

##### **Discussion**

*What events have caused this AD?* The FAA has received several reports of accidents and incidents concerning problems with Cessna Models 208 and 208B airplanes during operations in icing conditions. This includes a total of six accidents in the previous two icing seasons and nine other incidents. One-third of the Model 208 icing-related accidents occurred as a result of loss of control after takeoff in ground icing conditions. One-third is suspected to have occurred in supercooled large droplets, icing conditions outside the 14 CFR part 25 Appendix C certification envelope. The Cessna Models 208 and 208B are certificated to 14 CFR part 23, but 14 CFR part 23 references 14 CFR part 25 Appendix C for icing certification.

Findings from the accidents conclude that there was a reduction in airplane performance due to drag from airframe ice accretion. The airplanes could not perform a safe takeoff, climb, or maintain altitude.

*What is the potential impact if FAA took no action?* Ice adhering to critical surfaces could result in a reduction in airplane performance with the consequence that the airplane cannot climb or maintain altitude.

*Has FAA taken any action to this point?* We issued a proposal to amend part 39 of the Federal Aviation Regulations (FAR) (14 CFR part 39) to include an AD that would apply to all The Cessna Aircraft Company (Cessna) Models 208 and 208B airplanes. This proposal was published in the **Federal Register** as a notice of proposed rulemaking (NPRM) on June 21, 2005 (70 FR 35565). The NPRM proposed to require you to install a pilot assist handle, Cessna part number SK208-146-2, for all affected airplanes, install deicing boots on landing gear struts and cargo pod, Cessna part number AK208-6C, for all affected airplanes, and make changes to the Pilot's Operating Handbook (POH) and FAA-approved Airplane Flight Manual (AFM), and to the POH and AFM Supplement S1 for all affected airplanes.

#### **Comments**

*Was the public invited to comment?* We provided the public the opportunity to participate in developing this AD. The following presents the comments received on the proposal and FAA's response to each comment:

#### **Comment Issue No. 1: Allow Installation of Replacements Parts Approved Under 14 CFR 21.303**

*What is the commenter's concern?* The commenter, the Modification and Replacement Parts Association (MARPA), states that the Parts Manufacturer Approval (PMA), 14 CFR 21.303, provides an alternative mechanism for the design, production, sale, and installation of aeronautical items other than those specified by the original equipment manufacturer (OEM). While no alternative PMA parts are currently known to exist, alternative PMA parts may be created in the future and the AD action should take into account that possibility.

The MARPA requests that the AD language state that installation of replacements parts approved under 14 CFR 21.303 is permitted.

*What is FAA's response to the concern?* We agree with the MARPA. The FAA will add the phrase "or FAA-approved equivalent part number", and add language to cover the PMA replacement parts.

#### **Comment Issue No. 2: Withdraw the Requirement for the Pilot Assist Handle**

*What is the commenter's concern?* Three commenters, two owners/operators and the Regional Air Cargo Carriers Association (RACCA), request the withdrawal of the requirement for the pilot assist handle.