

TABLE 2.—MATERIAL INCORPORATED BY REFERENCE—Continued

Service bulletin	Revision level	Date
McDonnell Douglas DC-9 Alert Service Bulletin A27-307	1	May 16, 1989.
McDonnell Douglas DC-9 Alert Service Bulletin A27-307	4	June 3, 1991.
McDonnell Douglas DC-9 Alert Service Bulletin A27-307	5	February 14, 1992.
McDonnell Douglas DC-9 Alert Service Bulletin A27-307	6	December 19, 1994.

McDonnell Douglas Alert Service Bulletin A27-307, Revision 6, dated December 19, 1994, contains the following effective pages:

Page Number	Revision level shown on page	Date shown on page
1-24	6	December 19, 1994.
25-36	5	February 14, 1992.

The Director of the Federal Register approved the incorporation by reference of these documents in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Boeing Commercial Airplanes, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024), for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., room PL-401, Nassif Building, Washington, DC; on the Internet at <http://dms.dot.gov>; or at the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on March 31, 2006.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 06-3380 Filed 4-10-06; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2006-23816; Directorate Identifier 2005-NM-247-AD; Amendment 39-14553; AD 2006-07-26]

RIN 2120-AA64

Airworthiness Directives; Aerospatiale Model ATR42 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all

Aerospatiale Model ATR42 airplanes. This AD requires one-time inspections to detect discrepancies (e.g., cracking, loose/sheared fasteners, distortion) of the upper skin and rib feet of the outer wing boxes, and repair if necessary.

This AD results from a report of cracking on the upper skin and ribs of the outer wing box on an in-service airplane. We are issuing this AD to detect and correct these discrepancies, which could result in reduced structural integrity of the airplane.

DATES: This AD becomes effective May 16, 2006.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of May 16, 2006.

ADDRESSES: You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., Nassif Building, Room PL-401, Washington, DC.

Contact Aerospatiale, 316 Route de Bayonne, 31060 Toulouse, Cedex 03, France, for service information identified in this AD.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-1137; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Examining the Docket

You may examine the airworthiness directive (AD) docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the street address stated in the **ADDRESSES** section.

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to all Aerospatiale Model ATR42 airplanes. That NPRM was published in the **Federal Register** on February 8, 2006 (71 FR 6413). That NPRM proposed to require one-time inspections to detect discrepancies (e.g., cracking, loose/sheared fasteners, distortion) of the upper skin and rib feet of the outer wing boxes, and repair if necessary.

Comments

We provided the public the opportunity to participate in the development of this AD. We received no comments on the NPRM or on the determination of the cost to the public.

Clarification of Reporting

In the preamble of the NPRM we stated that although “the French airworthiness directive and the service bulletin specify to submit certain information to the manufacturer, this proposed AD does not include that requirement.” However, we did not include this exception in the body of the NPRM. We have added paragraph (h) to clarify that reporting is not required.

Conclusion

We have carefully reviewed the available data and determined that air safety and the public interest require adopting the AD with the change described previously. We have determined that this change will neither

increase the economic burden on any operator nor increase the scope of the AD.

Costs of Compliance

This AD will affect about 14 airplanes of U.S. registry. The actions will take about 6 work hours per airplane if the internal borescopic inspection method is chosen, and about 44 work hours per airplane if the internal detailed inspection method (with the leading edge removed) is chosen. Both estimates include the time necessary for the external detailed inspection. The average labor rate is \$65 per work hour. Based on these figures, the estimated cost of the AD for U.S. operators is between \$5,460 and \$40,040, or either \$390 or \$2,860 per airplane.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

2006-17-26 Aerospace: Amendment 39-14553. Docket No. FAA-2006-23816; Directorate Identifier 2005-NM-247-AD.

Effective Date

(a) This AD becomes effective May 16, 2006.

Affected ADs

(b) None.

Applicability

(c) This AD applies to all *Aerospatiale* Model ATR42-200, -300, -320, and -500 airplanes, certificated in any category.

Unsafe Condition

(d) This AD results from a report of cracking on the upper skin and ribs of the outer wing box on an in-service airplane. We are issuing this AD to detect and correct discrepancies (e.g., cracking, loose/sheared fasteners, distortion) of the upper skin and rib feet of the outer wing boxes, which could result in reduced structural integrity of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

External Inspection and Repair

(f) Before the accumulation of 4,000 total flight cycles, or within 3 months after the effective date of this AD, whichever is later: Do an external detailed inspection for discrepancies of the upper skin panels of the outer wing box on the left and right wing, from rib 24 to rib 29. Do the inspection in accordance with Part A of the Accomplishment Instructions of Avions de Transport Regional Service Bulletin ATR42-57-0064, dated December 16, 2004.

(1) If any discrepancy is found: Before further flight, do the actions in paragraphs (f)(1)(i) and (f)(1)(ii) of this AD.

(i) Repair using a method approved by either the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the Direction Générale de l'Aviation Civile (DGAC) (or its delegated agent).

(ii) Do the internal inspection in accordance with paragraph (g) of this AD.

(2) If no discrepancy is found: Within 4 months after doing the external detailed inspection, do the internal inspection in accordance with paragraph (g) of this AD.

Note 1: For the purposes of this AD, a detailed inspection is: "An intensive examination of a specific item, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at an intensity deemed appropriate. Inspection aids such as mirror, magnifying lenses, etc., may be necessary. Surface cleaning and elaborate procedures may be required."

Internal Inspection and Repair

(g) At the applicable time specified in paragraph (f)(1)(ii) or (f)(2) of this AD: Inspect for discrepancies of the rib feet from rib 24 to rib 29 using one of the inspection methods specified in paragraph (g)(1) or (g)(2) of this AD. Do the inspection in accordance with Part B of the Accomplishment Instructions of Avions de Transport Regional Service Bulletin ATR42-57-0064, dated December 16, 2004. If any discrepancy is found during any inspection required by this paragraph: Before further flight, repair using a method approved by either the Manager, International Branch, ANM-116, FAA, or the DGAC (or its delegated agent).

(1) A borescopic inspection through access doors.

(2) A detailed inspection after removing the leading edge of the wing.

No Reporting

(h) Although Avions de Transport Regional Service Bulletin ATR42-57-0064, dated December 16, 2004, specifies to submit certain information to the manufacturer, this AD does not include that requirement.

Alternative Methods of Compliance (AMOCs)

(i)(1) The Manager, International Branch, ANM-116, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

Related Information

(j) French airworthiness directive F-2004-191, dated December 22, 2004, also addresses the subject of this AD.

Material Incorporated by Reference

(k) You must use Avions de Transport Regional Service Bulletin ATR42-57-0064,

dated December 16, 2004, to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of this document in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Aerospatiale, 316 Route de Bayonne, 31060 Toulouse, Cedex 03, France, for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., Room PL-401, Nassif Building, Washington, DC; on the Internet at <http://dms.dot.gov>; or at the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on March 31, 2006.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 06-3382 Filed 4-10-06; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2004-19140; Directorate Identifier 2004-NM-84-AD; Amendment 39-14548; AD 2006-07-21]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 757 Airplanes Powered by Pratt & Whitney Engines

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Boeing Model 757 airplanes. This AD requires repetitive inspections for corrosion and cracking of the midspar fittings in the nacelle struts, and corrective actions if necessary. This AD also provides an optional terminating action for the repetitive inspections. This AD results from reports of corrosion and cracking on midspar fittings on the nacelle struts of several Boeing Model 757 airplanes. We are issuing this AD to detect and correct cracking in the midspar fittings of the nacelle struts, consequent reduced structural integrity of the struts, and possible separation of an engine and strut from the airplane.

DATES: This AD becomes effective May 16, 2006.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of May 16, 2006.

ADDRESSES: You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., Nassif Building, room PL-401, Washington, DC.

Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207, for service information identified in this AD.

FOR FURTHER INFORMATION CONTACT: Dennis Stremick, Aerospace Engineer, Airframe Branch, ANM-120S, Seattle Aircraft Certification Office, FAA, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 917-6450; fax (425) 914-6590.

SUPPLEMENTARY INFORMATION:

Examining the Docket

You may examine the airworthiness directive (AD) docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the street address stated in the **ADDRESSES** section.

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to certain Boeing Model 757 series airplanes. That NPRM was published in the **Federal Register** on September 21, 2004 (69 FR 56375). That NPRM proposed to require repetitive inspections for corrosion and cracking of the midspar fittings in the nacelle struts, and corrective actions if necessary. That NPRM also proposed to provide an optional terminating action for the repetitive inspections.

Explanation of Revised Service Information

Since we issued the NPRM, Boeing revised Special Attention Service Bulletin 757-54-0042, dated May 13, 1999, which was specified in the NPRM as the appropriate source of service information for accomplishing the proposed requirements of this AD. We have reviewed Boeing Service Bulletin 757-54-0042, Revision 1, dated July 7, 2005, which, among other changes, incorporates the information specified in Boeing Information Notices 757-54-0042 IN 01, dated July 22, 1999; 757-

54-0042 IN 02, dated January 6, 2000; and 757-54-0042 IN 03, dated November 21, 2000; revises incorrect part number references; and contains a revised Figure 6.

Figure 6 of Service Bulletin 757-54-0042, Revision 1, specifies an optional action to replacing any cracked or corroded midspar fitting. That option involves one-time high-frequency eddy current (HFEC) and borescope inspections to detect corrosion or cracking within the fitting bolt holes. Revision 1 also describes the related repair of any cracked or corroded bolt hole; and repetitive detailed inspections and general visual inspections for recurrent corrosion or cracking of the repaired fitting until the fitting is replaced. We have determined that these new inspections and corrective actions are adequate to maintain airplane operational safety, and we have revised the AD to refer to Service Bulletin 757-54-0042, Revision 1, as the appropriate source of service information for accomplishing the requirements of the AD, except as discussed under "Difference Between Service Information and This AD."

Difference Between Service Information and This AD

Service Bulletin 757-54-0042, Revision 1, specifies to contact the manufacturer for instructions on how to repair certain conditions, but this AD requires repairing those conditions in one of the following ways:

- Using a method that we approve; or
- Using data that meet the certification basis of the airplane, and that have been approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization whom we have authorized to make those findings.

Comments

We provided the public the opportunity to participate in the development of this AD. We have considered the comments received.

AD Not Applicable

One commenter, American Airlines, states that none of its airplanes are affected by this AD.

Request To Correct Errors in Service Information

Two commenters, ATA and UPS, request that we revise the service information. The commenters state that Boeing has released 3 INs that correct errors in the service bulletins, but that the INs are not FAA-approved. Therefore, the commenters assert that