

(2) Repeat the inspection required by paragraph (f) of this AD thereafter at intervals not to exceed 3,000 flight cycles.

Optional Terminating Inspection

(i) Accomplishment of the initial detailed inspection of the Section 46 lower lobe frames required by paragraph (f)(2) or (i)(2) of AD 2005-20-30 constitutes terminating action for the requirements of this AD only for airplanes identified in Boeing Alert Service Bulletin 747-53A2408, Revision 1, dated April 4, 2002, as Group 1 airplanes. Accomplishment of the initial detailed inspection of the Section 46 lower lobe frames required by paragraph (f) of AD 2006-05-02 constitutes terminating action for the requirements of this AD only for airplanes identified in Boeing Alert Service Bulletin 747-53A2408, Revision 1, dated April 4, 2002, as Group 2 airplanes.

Alternative Methods of Compliance (AMOCs)

(j)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane.

(4) AMOCs approved previously in accordance with AD 99-07-12, are approved as AMOCs for the corresponding provisions of this AD.

Material Incorporated by Reference

(k) You must use Boeing Alert Service Bulletin 747-53A2408, dated April 25, 1996; or Boeing Alert Service Bulletin 747-53A2408, Revision 1, dated April 4, 2002; as applicable; to perform the actions that are required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of Boeing Alert Service Bulletin 747-53A2408, Revision 1, dated April 4, 2002, in accordance with 5 U.S.C. 552(a) and 1 CFR part 51.

(2) On May 5, 1999 (64 FR 15298, March 31, 1999), the Director of the Federal Register approved the incorporation by reference of Boeing Alert Service Bulletin 747-53A2408, dated April 25, 1996.

(3) Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207, for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., room PL-401, Nassif Building, Washington, DC; on the Internet at <http://dms.dot.gov>; or

at the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on April 20, 2006.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 06-4054 Filed 5-2-06; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2006-23762; Directorate Identifier 2005-NM-226-AD; Amendment 39-14580; AD 2006-09-09]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 767 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Boeing Model 767 airplanes. This AD requires repetitive inspections for cracking in the skin, the bulkhead outer chord, and the strap of the bulkhead outer chord at station (STA) 1725.5; and repair if necessary. This AD also provides for repairs, which are optional for airplanes on which no cracking is found, that terminate certain inspections. This AD results from reports of cracking in the skin panel common to stringer 7R and aft of the STA 1725.5 butt splice, and in the strap of the bulkhead outer chord at STA 1725.5. We are issuing this AD to detect and correct cracking in the skin, the bulkhead outer chord, or the strap of the bulkhead outer chord in this area, which could progress into surrounding areas and result in reduced structural integrity of the support structure for the vertical or horizontal stabilizer and subsequent loss of control of the airplane.

DATES: This AD becomes effective June 7, 2006.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of June 7, 2006.

ADDRESSES: You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket

Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC.

Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207, for service information identified in this AD.

FOR FURTHER INFORMATION CONTACT: Candice Gerretsen, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 917-6428; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:

Examining the Docket

You may examine the airworthiness directive (AD) docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the street address stated in the **ADDRESSES** section.

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to all Boeing Model 767 airplanes. That NPRM was published in the **Federal Register** on February 2, 2006 (71 FR 5623). That NPRM proposed to require repetitive inspections for cracking in the skin, the bulkhead outer chord, and the strap of the bulkhead outer chord at station (STA) 1725.5; and repair if necessary. That NPRM also proposed to provide for repairs, which are optional for airplanes on which no cracking is found, that terminate certain inspections.

Comments

We provided the public the opportunity to participate in the development of this AD. We have considered the comment received. The commenter, Boeing, supports the NPRM.

Conclusion

We have carefully reviewed the available data, including the comment received, and determined that air safety and the public interest require adopting the AD as proposed.

Costs of Compliance

There are about 905 airplanes of the affected design in the worldwide fleet. The following table provides the estimated costs for U.S. operators to comply with this AD.

ESTIMATED COSTS

| Action | Work hours | Average labor rate per hour | Cost per airplane | Number of U.S.-registered airplanes | Fleet cost |
|---|------------|-----------------------------|-----------------------------------|-------------------------------------|---------------------------------|
| Part 1 Inspection, per inspection cycle. | 5 | \$65 | \$325, per inspection cycle | 387 | \$125,775 per inspection cycle. |
| Part 2 Inspections, per inspection cycle. | 9 | 65 | \$585, per inspection cycle | 387 | \$226,395 per inspection cycle. |

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

2006-09-09 Boeing: Amendment 39-14580.
Docket No. FAA-2006-23762;
Directorate Identifier 2005-NM-226-AD.

Effective Date

(a) This AD becomes effective June 7, 2006.

Affected ADs

(b) None.

Applicability

(c) This AD applies to all Boeing Model 767-200, -300, -300F, and -400ER series airplanes, certificated in any category.

Unsafe Condition

(d) This AD results from reports of cracking in the skin panel common to stringer 7R and aft of the station (STA) 1725.5 butt splice, and in the strap of the bulkhead outer chord at STA 1725.5. We are issuing this AD to detect and correct cracking in the skin, the bulkhead outer chord, or the strap of the bulkhead outer chord in this area, which could progress into surrounding areas and result in reduced structural integrity of the support structure for the vertical or horizontal stabilizer and subsequent loss of control of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Repetitive Inspections

(f) Perform repetitive detailed and high frequency eddy current inspections for cracking in the skin, the bulkhead outer chord, and the strap of the bulkhead outer chord at STA 1725.5, in accordance with the Accomplishment Instructions of Boeing

Special Attention Service Bulletin 767-53-0118, dated September 8, 2005. Do the initial and repetitive Part 1 and Part 2 inspections at the times specified in paragraph 1.E., Compliance, of the service bulletin; except, where the service bulletin specifies a compliance time after the issuance of the service bulletin, this AD requires compliance within the specified compliance time after the effective date of this AD.

Repair

(g) If any cracking is found during any inspection required by paragraph (f) of this AD: Before further flight, perform applicable repairs in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 767-53-0118, dated September 8, 2005; except, where the service bulletin specifies to contact Boeing for repair instructions, before further flight, repair the cracking using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

Optional Terminating Action

(h) Completing repairs specified in the Accomplishment Instructions of Boeing Special Attention Service Bulletin 767-53-0118, dated September 8, 2005, terminates the repetitive inspections required by paragraph (f) of this AD, as specified in paragraphs (h)(1) and (h)(2) of this AD.

(1) Completing repairs specified in paragraph 3.B.3.a. of the service bulletin terminates both the Part 1 and Part 2 inspections required by paragraph (f) of this AD.

(2) Completing repairs specified in paragraph 3.B.4.a. of the service bulletin terminates the Part 1 inspections required by paragraph (f) of this AD. Part 2 inspections must continue as required by paragraph (f) of this AD until the repairs specified in paragraph 3.B.3.a. of the service bulletin are completed.

Alternative Methods of Compliance (AMOCs)

(i)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by an

Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

Material Incorporated by Reference

(j) You must use Boeing Special Attention Service Bulletin 767-53-0118, dated September 8, 2005, to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of this document in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207, for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Room PL-401, Nassif Building, Washington, DC; on the Internet at <http://dms.dot.gov>; or at the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on April 21, 2006.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 06-4055 Filed 5-2-06; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2006-24588; Directorate Identifier 2006-SW-07-AD; Amendment 39-14581; AD 2006-09-10]

RIN 2120-AA64

Airworthiness Directives; Eurocopter France Model SA-365 N1, AS-365 N2, N3, SA 366 G1, and EC-155B and B1 Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) for the specified Eurocopter France (Eurocopter) Model SA-365 N1, AS-365 N2, N3, SA 366 G1, and EC-155B and B1 helicopters. This action requires a one-time inspection for end play in the pitch control rod assembly double bearing (bearing) using the tail rotor (T/R) hub control plate, and before further flight, replacing the bearing if end play

is present. This amendment is prompted by one incident in which a pilot lost T/R pitch control of a helicopter while landing. The actions specified in this AD are intended to detect damage to the bearing, resulting in end play and prevent loss of T/R pitch control and subsequent loss of control of the helicopter.

DATES: Effective May 18, 2006.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of May 18, 2006.

Comments for inclusion in the Rules Docket must be received on or before July 3, 2006.

ADDRESSES: Use one of the following addresses to submit comments on this AD:

- DOT Docket Web site: Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically;
- Government-wide rulemaking Web site: Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically;
- Mail: Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590;
- Fax: (202) 493-2251; or
- Hand Delivery: Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

You may get the service information identified in this AD from American Eurocopter Corporation, 2701 Forum Drive, Grand Prairie, Texas 75053-4005, telephone (972) 641-3460, fax (972) 641-3527.

Examining the Docket

You may examine the docket that contains the AD, any comments, and other information on the Internet at <http://dms.dot.gov>, or in person at the Docket Management System (DMS) Docket Offices between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone (800) 647-5227) is located on the plaza level of the Department of Transportation Nassif Building at the street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the DMS receives them.

FOR FURTHER INFORMATION CONTACT: Uday Garadi, Aviation Safety Engineer, FAA, Rotorcraft Directorate, Regulations and Guidance Group, Fort Worth, Texas 76193-0110, telephone (817) 222-5123, fax (817) 222-5961.

SUPPLEMENTARY INFORMATION: This amendment adopts a new AD for Eurocopter Model SA-365 N1, AS-365 N2, N3, SA 366 G1, and EC-155B and B1 helicopters. This action requires, within 50 hours time-in-service (TIS), a one-time inspection of the T/R hub control plate for end play in the bearing, and if end play is present, replacing the bearing before further flight. This amendment is prompted by one incident in which a pilot lost T/R pitch control of a helicopter while landing. The loss of the T/R pitch control was due to significant damage to the bearing of the control rod in the tail gearbox. This condition, if not detected, could result in loss of T/R pitch control and subsequent loss of control of the helicopter.

The European Aviation Safety Agency (EASA) notified us that an unsafe condition may exist on Eurocopter France Model AS 365 N, SA 366, and EC 155 helicopters. EASA advises that the loss of pitch control is due to significant damage to the bearing of the control rod in the tail gearbox.

Eurocopter has issued Alert Service Bulletin (ASB) No. 05.00.52, applicable to the Model 365 N1, N2, and N3 helicopters; ASB No. 05.36, applicable to Model 366 G1 helicopters; and ASB No. 05A013, applicable to Model EC-155B and B1 helicopters, all dated February 15, 2006, and all of which specify a check at regular intervals to ensure there is no end play in the bearing of the T/R pitch control rod. EASA classified this ASB as mandatory and issued AD No. 2006-0051-E, dated February 20, 2006, to ensure the continued airworthiness of these helicopters in France. This AD does not require repetitive inspections because helicopters in this fleet do not normally accrue enough flight hours in a short period of time to justify issuing an immediately adopted final rule requiring repetitive inspections without allowing the public time to first comment on such a proposal. We may issue further AD action at a later date to propose repetitive 110-hours TIS inspections.

This helicopter model is manufactured in France and is type certificated for operation in the United States under the provisions of Sec. 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral agreement. Under this agreement, EASA has kept the FAA informed of the situation described above. We have examined EASA's findings, evaluated all pertinent information, and determined that AD action is necessary for products of this type design that are