

Netherlands, Portugal, Republic of Ireland, Spain, Sweden, and the United Kingdom (England, Scotland, Wales, the Isle of Man, and Northern Ireland).

* * * * *

Restricted zone for classical swine fever. An area, delineated by the relevant competent veterinary authorities of the region in which the area is located, that surrounds and includes the location of an outbreak of classical swine fever in domestic swine or detection of the disease in wild boar, and from which the movement of domestic swine is prohibited.

* * * * *

■ 11. Section 98.38 is revised to read as follows:

§ 98.38 Restrictions on the importation of swine semen from the EU-15.

In addition to meeting all other applicable provisions of this part, swine semen imported from the EU-15 must meet the following conditions, except as noted in paragraph (h) of this section with regard to swine semen imported from Denmark, Finland, the Republic of Ireland, Sweden, or the United Kingdom:

(a) The semen must come from a semen collection center approved for export by the competent veterinary authority of the EU-15 Member State.

(b) The semen must not have been collected from a donor boar that was in any of the following regions or zones, unless the semen was collected after the periods described:

(1) Any region when the region was classified in §§ 94.9(a) and 94.10(a) of this chapter as one in which classical swine fever is known to exist, except for the EU-15;

(2) A restricted zone in the EU-15 established because of the detection of classical swine fever in domestic swine, from the time of detection until the designation of the zone as a restricted zone is removed by the competent veterinary authority of an EU-15 Member State or until 6 months following depopulation of the swine on affected premises in the restricted zone and the cleaning and disinfection of the last affected premises in the zone, whichever is later; or

(3) A restricted zone in the EU-15 established because of the detection of classical swine fever in wild boar, from the time of detection until the designation of the zone as a restricted zone is removed by the competent veterinary authority of the EU-15 Member State.

(c) The semen must not have been collected from a donor boar that was commingled with swine that at any time

were in any of the regions or zones described in paragraphs (b)(1) through (b)(3) of this section, unless the semen was collected after the periods described.

(d) The semen must not have been collected from a donor boar that transited any region or zone described in paragraphs (b)(1) through (b)(3) of this section during the periods described, unless the donor boar was moved directly through the region or zone in a sealed means of conveyance with the seal determined to be intact upon arrival at the point of destination, or unless the semen was collected after the periods described;

(e) The donor boar must be held in isolation for at least 30 days prior to entering the semen collection center.

(f) No more than 30 days prior to being held in isolation as required by paragraph (e) of this section, the donor boar must be tested with negative results with a classical swine fever test approved by the Office International des Epizooties (World Organization for Animal Health).

(g) No equipment or materials used in transporting the donor boar from the farm of origin to the semen collection center may have been used previously for transporting swine that do not meet the requirements of this section, unless such equipment or materials have first been cleaned and disinfected.

(h) Except for semen collected from swine in Denmark, Finland, the Republic of Ireland, Sweden, or the United Kingdom, before the semen is exported to the United States, the donor boar must be held at the semen collection center and observed by the center veterinarian for at least 40 days following collection of the semen, and, along with all other swine at the semen collection center, exhibit no clinical signs of classical swine fever.

(i) The semen must be accompanied by a certificate issued by a salaried veterinary officer of the competent veterinary authority of the EU-15 Member State, stating that the provisions of paragraphs (a) through (h) of this section have been met.³

(Approved by the Office of Management and Budget under control numbers 0579-0218 and 0579-0265).

Done in Washington, DC, this 16th day of May 2006.

Jeremy Stump,

Acting Under Secretary for Marketing and Regulatory Programs.

[FR Doc. 06-4681 Filed 5-18-06; 8:45 am]

BILLING CODE 3410-34-P

³ The certification required may be placed on the certificate required under § 98.35(c) or may be contained in a separate document.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2006-24517; Directorate Identifier 2006-NE-18-AD; Amendment 39-14591; AD 2006-10-07]

RIN 2120-AA64

Airworthiness Directives; Hamilton Sundstrand Model 14RF-9 Propellers; Correction

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; correction.

SUMMARY: This document makes a correction to Airworthiness Directive (AD) 2006-10-07. That AD applies to Hamilton Sundstrand Model 14RF-9 propellers. We published AD 2006-10-07 in the *Federal Register* on May 12, 2006 (71 FR 27600). An incorrect phrase was used in the compliance section, which impacts the intent of the compliance. This document corrects that phrase. In all other respects, the original document remains the same.

DATES: *Effective Date:* Effective May 19, 2006.

FOR FURTHER INFORMATION CONTACT: Frank Walsh, Aerospace Engineer, Boston Aircraft Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; telephone (781) 238-7158; fax (781) 238-7170.

SUPPLEMENTARY INFORMATION: A final rule AD, FR Doc. 06-4390, that applies to Hamilton Sundstrand Model 14RF-9 propellers was published in the *Federal Register* on May 12, 2006 (71 FR 27600). The following correction is needed:

§ 39.13 [Corrected]

■ On page 27601, in the third column, in compliance paragraph (i)(1), in the second line, “after accumulating an additional 500 flight cycles” is corrected to read “within an additional 500 flight cycles”.

Issued in Burlington, MA, on May 15, 2006.

Robert J. Ganley,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 06-4679 Filed 5-18-06; 8:45 am]

BILLING CODE 4910-13-P