

Information and Regulatory Affairs of OMB.

List of Subjects in 10 CFR Part 73

Criminal penalties, Export, Hazardous materials transportation, Import, Nuclear materials, Nuclear power plants and reactors, Reporting and recordkeeping requirements, Security measures.

■ For the reasons set out in the preamble, and under the authority of the Atomic Energy Act of 1954, as amended; the Energy Reorganization Act of 1974, as amended; the Energy Policy Act of 2005, and 5 U.S.C. 552 and 553; the NRC is adopting the following amendments to 10 CFR part 73.

PART 73—PHYSICAL PROTECTION OF PLANTS AND MATERIALS

■ 1. The authority citation for part 73 is revised to read as follows:

Authority: Secs. 53, 161, 149, 68 Stat. 930, 948, as amended, sec. 147, 94 Stat. 780 (42 U.S.C. 2073, 2167, 2169, 2201); sec. 201, as amended, 204, 88 Stat. 1242, as amended, 1245, sec. 1701, 106 Stat. 2951, 2952, 2953 (42 U.S.C. 5841, 5844, 2297f); sec. 1704, 112 Stat. 2750 (44 U.S.C. 3504 note); Energy Policy Act of 2005, Public Law No. 109–58, 119 Stat. 594 (2005).

Section 73.1 also issued under secs. 135, 141, Public Law 97–425, 96 Stat. 2232, 2241 (42 U.S.C. 10155, 10161). Section 73.37(f) also issued under sec. 301, Public Law 96–295, 94 Stat. 789 (42 U.S.C. 5841 note). Section 73.57 is issued under sec. 606, Public Law 99–399, 100 Stat. 876 (42 U.S.C. 2169).

■ 2. A new § 73.59 is added to read as follows:

§ 73.59 Relief from fingerprinting and criminal history records check for designated categories of individuals.

(a) For purposes of this section, the phrase “Safeguards Information” means information not otherwise classified as National Security Information or Restricted Data, which specifically identifies a licensee’s or applicant’s detailed—

(1) Control and accounting procedures or security measures (including security plans, procedures, and equipment) for the physical protection of special nuclear material, by whomever possessed, whether in transit or at fixed sites, in quantities determined by the Commission to be significant to the public health and safety or the common defense and security;

(2) Security measures (including security plans, procedures, and equipment) for the physical protection of source material or byproduct material, by whomever possessed, whether in transit or at fixed sites, in quantities determined by the

Commission to be significant to the public health and safety or the common defense and security;

(3) Security measures (including security plans, procedures, and equipment) for the physical protection of and the location of certain plant equipment vital to the safety of production or utilization facilities involving nuclear materials covered by paragraphs (a)(1) and (a)(2) of this section; or

(4) Any other information within the scope of Section 147 of the Atomic Energy Act of 1954, as amended, the unauthorized disclosure of which, as determined by the Commission through order or regulation, could reasonably be expected to have a significant adverse effect on the health and safety of the public or the common defense and security by significantly increasing the likelihood of radiological sabotage or theft or diversion of source, byproduct, or special nuclear material.

(b) Notwithstanding any other provision of the Commission’s regulations, fingerprinting and the identification and criminal history records checks required by section 149 of the Atomic Energy Act of 1954, as amended, are not required for the following individuals prior to granting access to Safeguards Information:

(1) An employee of the Commission or of the Executive Branch of the United States government who has undergone fingerprinting for a prior U.S. government criminal history check;

(2) A member of Congress;

(3) An employee of a member of Congress or Congressional committee who has undergone fingerprinting for a prior U.S. government criminal history check;

(4) The Governor of a State or his or her designated State employee representative;

(5) A representative of a foreign government organization that is involved in planning for, or responding to, nuclear or radiological emergencies or security incidents who the Commission approves for access to Safeguards Information;

(6) Federal, State, or local law enforcement personnel;

(7) State Radiation Control Program Directors and State Homeland Security Advisors or their designated State employee representatives;

(8) Agreement State employees conducting security inspections on behalf of the NRC pursuant to an agreement executed under section 274.i of the Atomic Energy Act;

(9) Representatives of the International Atomic Energy Agency (IAEA) engaged in activities associated

with the U.S./IAEA Safeguards Agreement who have been certified by the NRC.

Dated at Rockville, Maryland, this 7th day of June, 2006.

For the Nuclear Regulatory Commission.

Annette L. Vietti-Cook,
Secretary of the Commission.

[FR Doc. E6–9178 Filed 6–12–06; 8:45 am]

BILLING CODE 7590–01–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2006–24245; Directorate Identifier 2005–NM–166–AD; Amendment 39–14643; AD 2006–12–17]

RIN 2120–AA64

Airworthiness Directives; Boeing Model 737–200C Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is superseding an existing airworthiness directive (AD) which applies to all Boeing Model 737–200C series airplanes. That AD currently requires a one-time external detailed inspection for cracking of the fuselage skin in the lower lobe cargo compartment; repetitive internal detailed inspections for cracking of the frames in the lower lobe cargo compartment; repair of cracked parts; and terminating action for the repetitive internal detailed inspections. This new AD restates the requirements of the existing AD and adds a requirement to perform repetitive detailed inspections of the body station (BS) 360 and BS 500 fuselage frames, after accomplishing the terminating action, and repair if necessary. This AD results from multiple reports that the existing AD is not fully effective in preventing cracks in the BS 360 and BS 500 fuselage frames. We are issuing this AD to detect and correct cracking of the fuselage frames from BS 360 to BS 500B, which could lead to loss of the cargo door during flight and consequent rapid decompression of the airplane.

DATES: This AD becomes effective July 18, 2006.

On August 9, 1993 (58 FR 36863, July 9, 1993), the Director of the Federal Register approved the incorporation by reference of certain publications listed in the AD.

ADDRESSES: You may examine the AD docket on the Internet at <http://>

dms.dot.gov or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC.

Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207, for service information identified in this AD.

FOR FURTHER INFORMATION CONTACT: Howard Hall, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 917-6430; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:

Examining the Docket

You may examine the airworthiness directive (AD) docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the street address stated in the **ADDRESSES** section.

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that supersedes AD 99-12-08, amendment 39-11192 (64 FR 31488, June 11, 1999). The existing AD applies to all Boeing Model 737-200C series airplanes. That NPRM was published in the **Federal Register** on March 30, 2006 (71 FR 16063). That NPRM proposed to require a one-time external detailed inspection for cracking of the fuselage skin in the lower lobe cargo compartment; repetitive internal detailed inspections for cracking of the frames in the lower lobe cargo compartment; repair of cracked parts; and terminating action for the repetitive internal detailed inspections. That NPRM also proposed to add a requirement to perform repetitive detailed inspections of the body station (BS) 360 and BS 500 fuselage frames, after accomplishing the terminating action, and repair if necessary.

Comments

We provided the public the opportunity to participate in the development of this AD. We have considered the one comment received. The commenter, Boeing, supports the NPRM.

Conclusion

We have carefully reviewed the available data, including the comment

received, and determined that air safety and the public interest require adopting the AD as proposed.

Costs of Compliance

There are about 90 airplanes of the affected design in the worldwide fleet. This AD will affect about 18 airplanes of U.S. registry.

The modification required by AD 99-12-08, and retained in this AD, takes approximately 160 work hours per airplane to accomplish, at an average labor rate of \$80 per work hour. Required parts cost about \$5,500 per airplane. Based on these figures, the estimated cost of the currently required modification for U.S. operators is \$329,400, or \$18,300 per airplane.

The new inspections will take about 3 work hours per airplane, at an average labor rate of \$80 per work hour. Based on these figures, the estimated cost of the new inspections specified in this AD for U.S. operators is \$4,320, or \$240 per airplane, per inspection cycle.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and

(3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The Federal Aviation Administration (FAA) amends § 39.13 by removing amendment 39-11192 (64 FR 31488, June 11, 1999) and by adding the following new airworthiness directive (AD):

2006-12-17 Boeing: Amendment 39-14643. Docket No. FAA-2006-24245; Directorate Identifier 2005-NM-166-AD.

Effective Date

- (a) This AD becomes effective July 18, 2006.

Affected ADs

- (b) This AD supersedes AD 99-12-08.

Applicability

- (c) This AD applies to all Boeing Model 737-200C series airplanes, certificated in any category.

Unsafe Condition

(d) This AD results from multiple reports that the modification required by AD 99-12-08 is not fully effective in preventing cracks in the body station (BS) 360 and BS 500 fuselage frames. We are issuing this AD to detect and correct cracking of the fuselage frames from BS 360 to BS 500B, which could lead to loss of the cargo door during flight and consequent rapid decompression of the airplane.

Compliance

- (e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Restatement of Requirements of AD 99-12-08

One-Time External Detailed Inspection

(f) Prior to the accumulation of 29,000 total flight cycles or within 250 flight cycles after August 9, 1993 (the effective date AD 93-13-02, amendment 39-8615, which was superseded by AD 99-12-08), whichever occurs later, accomplish an external detailed inspection to detect cracks of the fuselage skin between stringers 19 left and 25 left and at BS 360 to BS 540, in accordance with Boeing Alert Service Bulletin 737-53A1160, dated October 24, 1991; or Boeing Service Bulletin 737-53A1160, Revision 1, dated April 29, 1993. If any crack is found, prior to further flight, accomplish the requirements of paragraphs (f)(1) and (f)(2) of this AD.

(1) Perform an internal detailed inspection to detect cracks of the frames between stringers 19 left and 25 left and at BS 360 to BS 500B, in accordance with either service bulletin.

(2) Repair all cracks in accordance with a method approved by the Manager, Seattle Aircraft Certification Office (ACO), Transport Airplane Directorate, FAA.

Internal Detailed Inspections

(g) Within 3,000 flight cycles after completing the requirements of paragraph (f) of this AD, unless accomplished within the last 6,000 flight cycles prior to August 9, 1993, perform an internal detailed inspection to detect cracks of the frames between stringers 19 left and 25 left and at body stations 360 to 500B, in accordance with Boeing Alert Service Bulletin 737-53A1160, dated October 24, 1991; or Boeing Service Bulletin 737-53A1160, Revision 1, dated April 29, 1993. Thereafter, repeat the internal detailed inspection at intervals not to exceed 9,000 flight cycles. If any crack is found during any inspection required by this paragraph, before further flight, repair as specified in paragraph (g)(1) or (g)(2) of this AD, as applicable.

(1) If any crack is found that does not exceed the limits specified in the Boeing 737 Structural Repair Manual (SRM), repair the crack in accordance with a method approved by the Manager, Seattle ACO; or in accordance with the procedures specified in paragraph (k)(4) of this AD. The SRM is one approved source of information for accomplishing the requirements of this paragraph. Repeat the internal detailed inspection thereafter at intervals not to exceed 9,000 flight cycles.

(2) If any crack is found that exceeds the limits specified in the SRM, repair the crack in accordance with a method approved by the Manager, Seattle ACO; or in accordance with the procedures specified in paragraph (k)(4) of this AD. Repeat the internal detailed visual inspection thereafter at intervals not to exceed 9,000 flight cycles.

Install Doublers

(h) Prior to the accumulation of 75,000 total flight cycles, or within 3,000 flight cycles after July 16, 1999 (the effective date of AD 99-12-08), whichever occurs later, install doublers on the specified frames located between stringers 19 left and 25 left from BS 360 to BS 500B, in accordance with

Boeing Service Bulletin 737-53A1160, Revision 1, dated April 29, 1993. Installing these doublers on the specified fuselage frames ends the repetitive inspections required by paragraphs (f) and (g) of this AD.

New Requirements of This AD

Repetitive Inspection of Certain Frames

(i) Within 9,000 flight cycles after accomplishing the modification required by paragraph (h) of this AD, or within 4,500 flight cycles after the effective date of this AD, whichever occurs later, perform an internal detailed inspection to detect cracking in the fuselage frame at BS 360 and the fuselage frame at BS 500, between stringers 19 left and 25 left, in accordance with Boeing Alert Service Bulletin 737-53A1160, dated October 24, 1991; or Boeing Service Bulletin 737-53A1160, Revision 1, dated April 29, 1993. Thereafter, repeat the internal detailed inspection of the BS 360 and BS 500 frames at intervals not to exceed 9,000 flight cycles.

(j) If any crack is found during any inspection required by paragraph (i) of this AD, before further flight, repair the crack using a method approved in accordance with the procedures specified in paragraph (k) of this AD.

Note 1: For the purposes of this AD, a detailed inspection is: "An intensive examination of a specific item, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at an intensity deemed appropriate. Inspection aids such as mirror, magnifying lenses, etc., may be necessary. Surface cleaning and elaborate procedures may be required."

Alternative Methods of Compliance (AMOCs)

(k)(1) The Manager, Seattle ACO, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with 14 CFR 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

(3) AMOCs approved previously in accordance with AD 99-12-08, including AMOCs approved previously in accordance with AD 93-13-02, are approved as AMOCs for the corresponding provisions specified in paragraphs (f), (g), and (h) of this AD.

(4) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

Material Incorporated by Reference

(l) You must use Boeing Alert Service Bulletin 737-53A1160, dated October 24, 1991; or Boeing Service Bulletin 737-

53A1160, Revision 1, dated April 29, 1993, as applicable, to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of these documents on August 9, 1993 (58 FR 36863, July 9, 1993). Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207, for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., Room PL-401, Nassif Building, Washington, DC; on the Internet at <http://dms.dot.gov>; or at the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on June 5, 2006.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 06-5287 Filed 6-12-06; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2004-19002; Directorate Identifier 2003-NM-27-AD; Amendment 39-14639; AD 2006-12-13]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A300 B2 and A300 B4 Series Airplanes; A300 B4-600, B4-600R, and F4-600R Series Airplanes; and Model C4-605R Variant F Airplanes (Collectively Called A300-600 Series Airplanes)

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is superseding an existing airworthiness directive (AD), which applies to certain Airbus Model A300 and A300-600 series airplanes. That AD currently requires repetitive inspections to detect cracks in Gear Rib 5 of the main landing gear (MLG) attachment fittings at the lower flange, and repair, if necessary. That AD also requires modification of Gear Rib 5 of the MLG attachment fittings, which constitutes terminating action for the repetitive inspections. This new AD requires new repetitive inspections at reduced compliance times. This new AD also requires new repetitive inspections of certain areas of the