

Compliance

(e) To address this problem, you must do the following:

Actions	Compliance	Procedures
(1) Inspect, visually and using fluorescent dye penetrant, the support structures for the in-board and center aileron hinge fittings on both wings for cracks.	Within the next 150 hours time-in-service or 12 months after August 21, 2006 (the effective date of this AD), whichever occurs first.	Follow Twin Commander Aircraft LLC Alert Service Bulletin 236A and Alert Service Bulletin 238, both dated December 21, 2004, as applicable.
(2) If you do not find cracks during the inspection required in paragraph (e)(1) of this AD, reinforce the support structures for the in-board and center aileron hinge fittings on both wings that are crack free.	Before further flight after the inspection required in paragraph (e)(1) of this AD. After doing the reinforcement, no further action is required.	Follow Twin Commander Aircraft LLC Alert Service Bulletin 236A and Alert Service Bulletin 238, both dated December 21, 2004, as applicable.
(3) If you find cracks during the inspection required in paragraph (e)(1) of this AD, replace and reinforce the cracked support structure.	Before further flight after the inspection required in paragraph (e)(1) of this AD. After doing the replacement and reinforcement, no further action is required.	Follow Twin Commander Aircraft LLC Alert Service Bulletin 236A and Alert Service Bulletin 238, both dated December 21, 2004, as applicable.

Alternative Methods of Compliance (AMOCs)

(f) The Manager, Seattle Aircraft Certification Office (ACO), FAA, ATTN: Vince Massey, Aerospace Engineer, Seattle, ACO, 1601 Lind Avenue SW., Renton, WA 98057; telephone: (425) 917-6475; facsimile: (425) 917-6590, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

Material Incorporated by Reference

(g) You must do the actions required by this AD following Twin Commander Aircraft LLC Alert Service Bulletin 236A and Twin Commander Aircraft LLC Alert Service Bulletin 238, both dated December 21, 2004. The Director of the Federal Register approved the incorporation by reference of these service bulletins in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. To get a copy of this service information, contact Twin Commander Aircraft LLC, 19010 59th Drive NE., Arlington, WA 98223, telephone: (360) 435-9797; facsimile: (360) 435-1112. To review copies of this service information, go to the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html or call (202) 741-6030. To view the AD docket, go to the Docket Management Facility; US Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-001 or on the Internet at <http://dms.dot.gov>. The docket number is FAA-2006-23785; Directorate Identifier 2006-CE-10-AD.

Issued in Kansas City, Missouri, on July 7, 2006.

Kim Smith,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 06-6225 Filed 7-14-06; 8:45 am]

BILLING CODE 4910-13-M

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2006-24522; Directorate Identifier 2006-NM-002-AD; Amendment 39-14680; AD 2006-14-09]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A330-200 and -300, and A340-200 and -300 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Airbus Model A330-200 and -300, and A340-200 and -300 series airplanes. This AD requires modifying certain rotary actuator assemblies for the leading edge slat. This AD results from a leak found at the seal of the torque limiter output shaft of the Type A rotary actuator of leading edge slat No. 1. We are issuing this AD to prevent a decrease in the torque limiter function, which could result in degradation and damage to the attachment bolts of the leading edge slat, loss of the slat, and consequent reduced control of the airplane.

DATES: This AD becomes effective August 21, 2006.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the AD as of August 21, 2006.

ADDRESSES: You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street,

SW., Nassif Building, Room PL-401, Washington, DC.

Contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France, for the service information identified in this AD.

FOR FURTHER INFORMATION CONTACT: Tim Backman, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2797; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:**Examining the Docket**

You may examine the airworthiness directive (AD) docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the street address stated in the **ADDRESSES** section.

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to certain Airbus Model A330-200 and -300, and A340-200 and -300 series airplanes. That NPRM was published in the **Federal Register** on April 21, 2006 (71 FR 20599). That NPRM proposed to require modifying certain rotary actuator assemblies for the leading edge slat.

Comments

We provided the public the opportunity to participate in the development of this AD. We have considered the single comment received.

Request To Revise the Applicability

Airbus requests that Model A330–302 and –303 airplanes be included in the applicability of paragraph (c) of the NPRM. Airbus states that those airplanes are in the process of being type certificated in the U.S.

We agree. We have determined that Model A330–302 and –303 airplanes are subject to the identified unsafe condition of this AD. Therefore, we have revised the applicability of paragraph (c) of this AD to include those airplanes to ensure that the identified unsafe condition is addressed if any of those affected airplanes are imported and placed on the U.S. Register in the future.

Conclusion

We have carefully reviewed the available data, including the comment received, and determined that air safety and the public interest require adopting the AD with the change described previously. This change will neither increase the economic burden on any operator nor increase the scope of the AD.

Costs of Compliance

This AD affects about 9 airplanes of U.S. registry. The modification (including operational test) takes about 4 work hours per airplane, at an average labor rate of \$80 per work hour. Required parts are free of charge. Based on these figures, the estimated cost of the AD for U.S. operators is \$2,880, or \$320 per airplane.

Currently, there are no affected Model A330–302 and –303 airplanes on the U.S. Register. However, if an affected airplane is imported and placed on the U.S. Register in the future, it would be subject to the same per-airplane cost specified above.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition

that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

2006–14–09 Airbus: Amendment 39–14680. Docket No. FAA–2006–24522; Directorate Identifier 2006–NM–002–AD.

Effective Date

(a) This AD becomes effective August 21, 2006.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Airbus Model A330–201, 202, –203, –223, and –243; A330–301, –302, –303, –321, –322, –323, –341, –342,

and –343; A340–211, –212, and –213; and A340–311, –312, and –313 airplanes, certificated in any category; except airplanes on which Airbus Modification 50138 was done during production.

Unsafe Condition

(d) This AD results from a leak found at the seal of the torque limiter output shaft of the Type A rotary actuator of leading edge slat No. 1. We are issuing this AD to prevent a decrease in the torque limiter function, which could result in degradation and damage to the attachment bolts of the leading edge slat, loss of the slat, and consequent reduced control of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Modification

(f) Within 38 months after the effective date of this AD: Modify any Type A rotary actuator assembly for the leading edge slat having part number (P/N) 954A0000–01 or 954A0000–02, or P/N 954B0000–01, as applicable, by doing all the applicable actions in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330–27–3100, Revision 01, dated May 23, 2005; or A340–27–4106, Revision 01, dated May 23, 2005; as applicable.

(g) Modification of any Type A rotary actuator assembly for the leading edge slat having P/N 954B0000–01, in accordance with Airbus Service Bulletin A330–27–3105 or A340–27–4110, both Revision 02, both dated October 10, 2005; as applicable; is acceptable for compliance with the corresponding modification specified in paragraph (f) of this AD.

Note 1: Airbus Service Bulletins A330–27–3100 and A340–27–4106 refer to Goodrich Actuation Systems Service Bulletin 954–27–M954–07, Revision 2, dated August 9, 2004; and Airbus Service Bulletins A330–27–3105 and A340–27–4110 refer to Goodrich Actuation Systems Service Bulletin 954–27–M954–06, Revision 2, dated May 20, 2004; as additional sources of service information for modifying the rotary actuator assembly for the leading edge slat.

Parts Installation

(h) As of the effective date of this AD, no Type A rotary actuator assembly for the leading edge slat having P/N 954A0000–01, –02, or 954B0000–01 may be installed unless the part has been modified in accordance with the actions required by paragraph (f) or (g) of this AD, as applicable.

Actions Accomplished Previously

(i) Modifications done before the effective date of this AD in accordance with Airbus Service Bulletins A330–27–3100, dated October 30, 2002; A330–27–3105, dated October 30, 2002, or Revision 01, dated March 27, 2003; A340–27–4106, dated October 30, 2002; or A340–27–4110, dated October 30, 2002, or Revision 01, dated March 27, 2003; as applicable; are acceptable

for compliance with the corresponding requirements of paragraphs (f) and (g) of this AD, as applicable.

Alternative Methods of Compliance (AMOCs)

(j)(1) The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

Related Information

(k) French airworthiness directives F-2005-067 and F-2005-068, both dated April 27, 2005, also address the subject of this AD.

Material Incorporated by Reference

(l) You must use the applicable Airbus service bulletin identified in Table 1 of this AD to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of these documents in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France, for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., Room PL-401, Nassif Building, Washington, DC; on the Internet at <http://dms.dot.gov>; or at the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

TABLE 1.—MATERIAL INCORPORATED BY REFERENCE

Airbus Service Bulletin	Revision level	Date
A330-27-3100 ..	01	May 23, 2005.
A330-27-3105 ..	02	Oct. 10, 2005.
A340-27-4106 ..	01	May 23, 2005.
A340-27-4110 ..	02	Oct. 10, 2005.

Issued in Renton, Washington, on July 6, 2006.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 06-6180 Filed 7-14-06; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2006-23644; Directorate Identifier 2006-CE-03-AD; Amendment 39-14679; AD 2006-14-08]

RIN 2120-AA64

Airworthiness Directives; Mitsubishi Heavy Industries MU-2B Series Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA adopts a new airworthiness directive (AD) for some Mitsubishi Heavy Industries (MHI) MU-2B series airplanes. This AD requires you to verify that the current flight idle blade angles are set at 12 degrees. If not already set at that angle, set the flight idle blade angles to 12 degrees. This AD results from a recent safety evaluation that used a data-driven approach to analyze the design, operation, and maintenance of the MU-2B series airplanes in order to determine their safety and define what steps, if any, are necessary for their safe operation. Part of that evaluation was the identification of unsafe conditions that exist or could develop on the affected type design airplanes. We are issuing this AD to prevent incorrect flight idle blade angle settings. This unsafe condition, if not corrected, could lead to an asymmetric thrust situation in certain flight conditions, which could result in airplane controllability problems.

DATES: This AD becomes effective on August 21, 2006.

As of August 21, 2006, the Director of the Federal Register approved the incorporation by reference of certain publications listed in the regulation.

ADDRESSES: To get the service information identified in this AD, contact Mitsubishi Heavy Industries America, Inc., 4951 Airport Parkway, Suite 800, Addison, Texas 75001; telephone: 972-934-5480; facsimile: 972-934-5488.

To view the AD docket, go to the Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-001 or on the Internet at <http://dms.dot.gov>. The docket number is FAA-2006-23644; Directorate Identifier 2006-CE-03-AD.

FOR FURTHER INFORMATION CONTACT: Rao Edupuganti, Aerospace Engineer, Fort Worth ACO, ASW-150, Rotorcraft

Directorate, FAA, 2601 Meacham Boulevard, Fort Worth, Texas 76137-4298; telephone: 817-222-5284; facsimile: 817-222-5960.

SUPPLEMENTARY INFORMATION:

Discussion

On February 3, 2006, we issued a proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to some MHI MU-2B series airplanes. This proposal was published in the **Federal Register** as a notice of proposed rulemaking (NPRM) on February 9, 2006 (71 FR 6685). The NPRM proposed to require you to check the flight idle blade angle setting and set to 12 degrees if not already.

Comments

We provided the public the opportunity to participate in developing this AD. The following presents the comment received on the proposal and FAA's response to the comment:

Comment Issue: Need for Issuance of This AD After 25 Years Since the Issuance of the Service Bulletin

Mitsubishi Heavy Industries America, Inc. questions the need for an AD 25 years after the service bulletin has been issued. In 1980, MHI (Mitsubishi Aircraft International, Inc. at the time of issuance) issued Service Bulletin No. SB016/61-001, dated March 18, 1980, to change the flight blade angles from 16 degrees to 12 degrees. The type certificate data sheet for the affected airplanes was also revised to incorporate this change, which included Note 3 to indicate a small group of airplanes that may not have incorporated Service Bulletin No. SB016/61-001. No Japanese AD was issued because no airplanes on the Japanese type certificate were affected by this change. The Japanese airplanes had already incorporated the intent of the service bulletin.

At the time the service bulletin was issued, the FAA evaluated the available information and found that there were no reports of problems or incidents of flight idle blade angle settings with airplanes of U.S. registry. Therefore, we did not issue an airworthiness directive at that time.

Based on information received from the safety evaluation done in 2005 for the MU-2B series airplanes, we identified flight idle blade angles set at 16 degrees instead of 12 degrees as a potential problem.

After analyzing this issue using our risk-based methodology and the information received from the safety evaluation, we identified that an unsafe