

(i) Perform an initial torque check within 250 CIS after the effective date of this AD, or before the next engine removal for any cause, whichever occurs sooner.

(ii) Thereafter, perform torque checks at intervals of no fewer than 750 or no more than 1,250 CIS since last torque check.

(4) Remove from service front pylon mount bolts P/N 54T670, at or before reaching the life limit of 11,000 CSN.

(5) Before further flight, replace all four bolts using Part (A), Paragraph 1(D) of the Accomplishment Instructions of the ASB, if any of the bolts are loose or broken.

MP159 Material Bolts Inspections

(g) Perform initial and repetitive torque checks of front pylon mount bolts, P/N 51U615, using the Accomplishment Instructions of PW ASB PW4G-100-A71-32, dated April 15, 2005, as follows:

(1) For front pylon mount bolts with fewer than 2,200 CSN on the effective date of this AD, perform the initial torque inspection before accumulating 2,700 CSN, or at the next engine removal for any cause, whichever occurs sooner.

(2) For front pylon mount bolts with 2,200 CSN or more on the effective date of this AD, perform the initial torque check within the next 500 CIS, or at the next engine removal for any cause, whichever occurs sooner.

(3) Thereafter, perform torque inspections at intervals not to exceed 2,700 CIS since last torque inspection.

(4) Before further flight, replace all four bolts using Paragraph 1.E. of the Accomplishment Instructions of the ASB, if any are loose or broken.

Primary Mount Thrust Load Path Inspections

(h) Perform initial and repetitive visual inspections of the primary mount thrust load path using the Accomplishment Instructions of PW ASB PW4G-100-A71-18, Revision 2, dated January 15, 2002, as follows:

(1) For forward engine mount assemblies with fewer than 1,000 CSN on the effective date of this AD, perform the initial visual inspection at the earlier of the following:

- (i) Before accumulating 1,250 CSN; or
- (ii) The next engine removal for any cause.

(2) For forward engine mount assemblies with 1,000 CSN or more on the effective date of this AD, perform the initial visual inspection within 250 CIS after the effective date of this AD, or the next engine removal for any cause, whichever occurs sooner.

(3) Thereafter, perform visual inspections at intervals of no fewer than 750 or no more than 1,250 CIS since-last-visual-inspection.

(4) Before further flight, replace all cracked parts with serviceable parts and inspect the primary thrust load path components using Paragraph 4 of the Accomplishment Instructions of the ASB.

Terminating Action

(i) Replacement of the forward engine mount bearing housing, P/N 59T794 or P/N 54T659 with P/N 52U420, using SB PW4G-100-71-22, dated January 15, 2002, constitutes terminating action to the inspection requirements of paragraph (h) of this AD.

Alternative Methods of Compliance

(j) The Manager, Engine Certification Office, has the authority to approve

alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

Related Information

(k) None.

Material Incorporated by Reference

(l) You must use the Pratt & Whitney service information specified in Table 1 of this AD to perform the actions required by this AD. The Director of the Federal Register approved the incorporation by reference of Pratt & Whitney Alert Service Bulletin (ASB) PW4G-100-A71-32, dated April 15, 2005, in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. The Director of the Federal Register previously approved the incorporation by reference of Pratt & Whitney ASB PW4G-100-A71-9, Revision 1, dated November 24, 1997, as of October 16, 2000, and, ASB PW4G-100-A71-18, Revision 2, dated January 15, 2002, and ASB PW4G-100-71-22, dated January 15, 2002, as of February 6, 2003. Contact Pratt & Whitney, 400 Main St., East Hartford, CT 06108; telephone (860) 565-7700, fax (860) 565-1605 for the service information identified in this AD. You may review copies at the Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-0001, on the Internet at <http://dms.dot.gov>, or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

TABLE 1.—INCORPORATION BY REFERENCE

Alert Service Bulletin (ASB) or Service Bulletin (SB) No.	Page	Revision	Date
ASB PW4G-100-A71-9	1	1	November 24, 1997.
	2	Original	July 31, 1997.
	3	1	November 24, 1997.
	4-7	Original	July 31, 1997.
	8-9	1	November 24, 1997.
	10-11	Original	July 31, 1997.
	Total Pages: 11		
ASB PW4G-100-A71-18	1-2	2	January 15, 2002.
	3	1	December 9, 1999.
	4	2	January 15, 2002.
	5-6	Original	September 15, 1999.
	7	2	January 15, 2002.
	8-12	Original	September 15, 1999.
	ALL	Original	January 15, 2002.
	Total Pages: 12		
SB PW4G-100-71-22	ALL	Original	January 15, 2002.
Total Pages: 8			
ASB PW4G-100-A71-32	ALL	Original	April 15, 2005.
Total Pages: 9			

Issued in Burlington, Massachusetts, on July 27, 2006.

Francis A. Favara,

Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. E6-12564 Filed 8-3-06; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 43

Removal of References to Part 123 From 14 CFR Part 43

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; technical amendment.

SUMMARY: In the final rule, Certification and Operation Rules for Certain Large Airplanes, which the FAA published in the **Federal Register** on October 9, 1980, the FAA revoked part 123, effective January 1, 1983. However, references to part 123 remain in part 43. The purpose of this action is to remove those

references. In addition, we are taking this opportunity to make some minor editorial corrections to part 43.

DATES: Effective Dates: Effective on August 4, 2006.

FOR FURTHER INFORMATION CONTACT: Kim Barnette, Aircraft Maintenance Division, Flight Standards Service, Federal Aviation Administration, 800 Independence Avenue, SW., Washington, DC 20591. Telephone: (202-493-4922); facsimile: (202-267-5115); e-mail: *kim.a.barnette@faa.gov*.

SUPPLEMENTARY INFORMATION: In a 1980 final rule,¹ the FAA revoked part 123, effective January 1, 1983, because of the diminishing number of operators under that part. As an alternative, we allowed those operators to seek certification either under part 121 or part 125. Since the effective date of the revocation was January 1, 1983, we should have removed all references to part 123 from part 43 as of that date. However, we recently learned that part 123 references remain in § 43.11(a), § 43.11(a)(7), § 43.15(a), § 43.15(a)(2), and § 43.16. This action removes those references. In addition, it corrects some editorial inconsistencies. For example, we lowercased the word "Part" in several of the previously referenced sections to make it consistent with other sections.

Technical Amendment

The technical amendment will remove references to part 123 from part 43 and will make minor editorial corrections to part 43.

List of Subjects in 14 CFR Part 43

Aircraft, Aviation safety, Reporting and recordkeeping requirements.

■ Accordingly, Title 14 of the Code of Federal Regulations (CFR) part 43 is amended as follows:

PART 43—MAINTENANCE, PREVENTIVE MAINTENANCE, REBUILDING, AND ALTERATION

■ 1. The authority citation for part 43 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701, 44703, 44705, 44707, 44711, 44713, 44717, 44725.

■ 2. Amend § 43.11 by revising paragraphs (a) introductory text and (a)(7) to read as follows:

§ 43.11 Content, form, and disposition of records for inspections conducted under parts 91 and 125 and §§ 135.411(a)(1) and 135.419 of this chapter.

(a) *Maintenance record entries.* The person approving or disapproving for

return to service an aircraft, airframe, aircraft engine, propeller, appliance, or component part after any inspection performed in accordance with part 91, 125, § 135.411(a)(1), or § 135.419 shall make an entry in the maintenance record of that equipment containing the following information:

* * * * *

(7) If an inspection is conducted under an inspection program provided for in part 91, 125, or § 135.411(a)(1), the entry must identify the inspection program, that part of the inspection program accomplished, and contain a statement that the inspection was performed in accordance with the inspections and procedures for that particular program.

* * * * *

■ 3. Amend § 43.15 by revising paragraphs (a) introductory text and (a)(2) to read as follows:

§ 43.15 Additional performance rules for inspections.

(a) *General.* Each person performing an inspection required by part 91, 125, or 135 of this chapter, shall—

* * * * *

(2) If the inspection is one provided for in part 125, 135, or § 91.409(e) of this chapter, perform the inspection in accordance with the instructions and procedures set forth in the inspection program for the aircraft being inspected.

* * * * *

■ 4. Amend § 43.16 by revising it to read as follows:

§ 43.16 Airworthiness limitations.

Each person performing an inspection or other maintenance specified in an Airworthiness Limitations section of a manufacturer's maintenance manual or Instructions for Continued Airworthiness shall perform the inspection or other maintenance in accordance with that section, or in accordance with operations specifications approved by the Administrator under part 121 or 135, or an inspection program approved under § 91.409(e).

Issued in Washington, DC, on July 27, 2006.

Tony F. Fazio,

Director, Office of Rulemaking, Aviation Safety.

[FR Doc. E6-12655 Filed 8-3-06; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2006-24869; Airspace Docket No. 06-ACE-4]

Modification of Class E Airspace; Wellington, KS

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Direct final rule; confirmation of effective date.

SUMMARY: This document confirms the effective date of the direct final rule which revises Class E airspace at Wellington, KS.

DATES: Effective Date: 0901 UTC, September 28, 2006.

FOR FURTHER INFORMATION CONTACT: Brenda Mumper, Air Traffic Division, Airspace Branch, ACE-520A, DOT Regional Headquarters Building, Federal Aviation Administration, 901 Locust, Kansas City, MO 64106; telephone: (816) 329-2524.

SUPPLEMENTARY INFORMATION: The FAA published this direct final rule with a request for comments in the **Federal Register** on June 5, 2006 (71 FR 32271). The FAA uses the direct final rulemaking procedure for a non-controversial rule where the FAA believes that there will be no adverse public comment. This direct final rule advised the public that no adverse comments were anticipated, and that unless a written adverse comment, or a written notice of intent to submit such an adverse comment, were received within the comment period, the regulation would become effective on September 28, 2006. No adverse comments were received, and thus this notice confirms that this direct final rule will become effective on that date.

Issued in Kansas City, MO, on July 26, 2006.

Donna R. McCord,

Acting Area Director, Western Flight Services Operations.

[FR Doc. 06-6699 Filed 8-3-06; 8:45 am]

BILLING CODE 4910-13-M

¹ Certification and Operation Rules for Certain Large Airplanes (45 FR 67214; October 9, 1980).