

(1) For Model EMB-135ER, -135KE, -135KL, -135LR, -145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP airplanes: EMBRAER Service Bulletin 145-28-0023, Revision 05, dated May 15, 2006.

(2) For Model EMB-135BJ airplanes: EMBRAER Service Bulletin 145LEG-28-0018, Revision 01, dated April 20, 2005.

Credit for Actions Accomplished Using Prior Revisions of Service Information

(g) Actions accomplished before the effective date of this AD in accordance with

the service information specified in Table 1 of this AD are considered acceptable for compliance with the corresponding actions specified in this AD.

TABLE 1.—EMBRAER SERVICE INFORMATION

Service Bulletin	Revision level	Dated
145-28-0023	04	November 7, 2005.
145-28-0023	03	April 27, 2005.
145-28-0023	02	November 8, 2004.
145-28-0023	01	June 9, 2004.
145-28-0023	Original	April 19, 2004.
145LEG-28-0018	Original	April 23, 2004.

Alternative Methods of Compliance (AMOCs)

(h)(1) The Manager, ANM-116, International Branch, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

Related Information

(i) Brazilian airworthiness directive 2006-06-02, dated June 28, 2006, also addresses the subject of this AD.

Issued in Renton, Washington, on November 8, 2006.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E6-19540 Filed 11-17-06; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2006-26191; Directorate Identifier 2006-CE-60-AD]

RIN 2120-AA64

Airworthiness Directives; EADS SOCATA Model TBM 700 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI)

issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as an excessive lateral play caused by a nonconforming washer might lead to the deterioration of the elevator trim tab bearing fatigue resistance. The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by December 20, 2006.

ADDRESSES: You may send comments by any of the following methods:

- *DOT Docket Web Site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.
- *Fax:* (202) 493-2251.
- *Mail:* Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-0001.
- *Hand Delivery:* Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.
- *Federal eRulemaking Portal:* <http://www.regulations.gov>. Follow the instructions for submitting comments.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5227) is in the **ADDRESSES** section.

Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Albert J. Mercado, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri, 64106; *telephone:* (816) 329-4119; *fax:* (816) 329-4090.

SUPPLEMENTARY INFORMATION:

Streamlined Issuance of AD

The FAA is implementing a new process for streamlining the issuance of ADs related to MCAI. The streamlined process will allow us to adopt MCAI safety requirements in a more efficient manner and will reduce safety risks to the public. This process continues to follow all FAA AD issuance processes to meet legal, economic, Administrative Procedure Act, and **Federal Register** requirements. We also continue to meet our technical decision-making responsibilities to identify and correct unsafe conditions on U.S.-certificated products.

This proposed AD references the MCAI and related service information that we considered in forming the engineering basis to correct the unsafe condition. The proposed AD contains text copied from the MCAI and for this reason might not follow our plain language principles.

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2006-26191; Directorate Identifier 2006-CE-60-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this

proposed AD because of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The Direction générale de l'aviation civile (DGAC), which is the aviation authority for France, has issued French AD No F-2006-028, dated February 1, 2006 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states an excessive lateral play caused by a nonconforming washer might lead to the deterioration of the elevator trim tab bearing fatigue resistance. If not corrected, lateral play could generate deterioration of bearing fatigue life. The MCAI requires a check for absence of play and installation, if necessary, of a setting washer. You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

EADS SOCATA has issued TBM Aircraft Mandatory Service Bulletin SB 70-135, ATA No. 55, dated December 2005. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Differences Between This Proposed AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are described in a separate paragraph of the proposed AD. These requirements, if ultimately adopted, will take precedence over the actions copied from the MCAI.

Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 52 products of U.S. registry. We also estimate that it would take about 2 work-hours per product to comply with the proposed AD. The average labor rate is \$80 per work-hour. Required parts would cost about \$500 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these costs. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$34,320, or \$660 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

EADS SOCATA: Docket No. FAA-2006-26191; Directorate Identifier 2006-CE-60-AD.

Comments Due Date

- (a) We must receive comments by December 20, 2006.

Affected ADs

- (b) None.

Applicability

- (c) This AD applies to EADS SOCATA TBM 700 airplanes, serial numbers 271 through 328, certificated in any category.

Reason

- (d) The mandatory continuing airworthiness information (MCAI) states an excessive lateral play caused by a nonconforming washer might lead to the deterioration of the elevator trim tab bearing fatigue resistance.

Actions and Compliance

- (e) Unless already done, within the next 100 hours time-in-service (TIS) or 12 months, whichever occurs first, after the effective date of this AD, verify there is no lateral play for both elevator trim tabs and correct, as necessary, by installing a setting washer as instructed in the EADS SOCATA TBM Aircraft Mandatory Service Bulletin SB 70-135, ATA No. 55, dated December 2005.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows:

Compliance time is defined as within 100 hours TIS or 12 months whichever occurs first.

Other FAA AD Provisions

(f) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, Standards Staff, FAA, ATTN: Albert J. Mercado, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri, 64106; telephone: (816) 329-4119; fax: (816) 329-4090, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements*: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 et seq.), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(g) Refer to MCAI Direction générale de l'aviation civile Airworthiness Directive No. F-2006-028, dated February 01, 2006; and EADS SOCATA TBM Aircraft Mandatory Service Bulletin SB 70-135, ATA No. 55, dated December 2005, for related information.

Issued in Kansas City, Missouri, on November 9, 2006.

David R. Showers,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E6-19545 Filed 11-17-06; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF COMMERCE

Bureau of Economic Analysis

15 CFR Part 801

[Docket No. 061005856-6256-01]

RIN 0691-AA61

International Services Surveys: BE-125, Quarterly Survey of Transactions in Selected Services and Intangible Assets With Foreign Persons

AGENCY: Bureau of Economic Analysis, Commerce.

ACTION: Notice of proposed rulemaking.

SUMMARY: This proposed rule amends regulations of the Bureau of Economic Analysis, Department of Commerce (BEA) to set forth the reporting

requirements for the BE-125, Quarterly Survey of Transactions in Selected Services and Intangible Assets with Foreign Persons. This rule would replace the rule for a similar but more limited survey, the BE-25, Quarterly Survey of Transactions with Unaffiliated Foreign Persons in Selected Services and in Intangible Assets. A new agency form number and survey title are being introduced because the survey program is being reconfigured to begin collection of data on transactions with affiliated foreigners using the same survey instruments as are used to collect information on transactions with unaffiliated foreigners and because services once collected on an annual basis would now be collected quarterly. This change will allow respondents to report transactions in services and intangible assets with foreign persons on one quarterly survey, rather than on as many as three different quarterly surveys and one annual survey. If adopted the BE-125 survey would be conducted quarterly beginning with the first quarter of 2007.

The proposed BE-125 survey data are used to update universe estimates from similar data reported on the BE-120, Benchmark Survey of Transactions in Selected Services and Intangible Assets with Foreign Persons and on the benchmark and quarterly direct investment surveys that were administered to collect data on transactions with affiliated foreign persons.

DATES: Comments on this proposed rule will receive consideration if submitted in writing on or before 5 p.m. January 19, 2007.

ADDRESSES: You may submit comments, identified by RIN 0691-AA61, and referencing the agency name (Bureau of Economic Analysis), by any of the following methods:

- *Federal eRulemaking Portal:* <http://www.regulations.gov>. Follow the instructions for submitting comments. For agency, select "Commerce Department—all."

- *E-mail:* Obie.Whichard@bea.gov.
- *Fax:* Office of the Chief, International Investment Division, (202) 606-5318.

- *Mail:* Office of the Chief, International Investment Division, U.S. Department of Commerce, Bureau of Economic Analysis, BE-50, Washington, DC 20230.

- *Hand Delivery/Courier:* Office of the Chief, International Investment Division, U.S. Department of Commerce, Bureau of Economic Analysis, BE-50, Shipping and Receiving, Section M100,

1441 L Street, NW., Washington, DC 20005.

- *Public Inspection:* Comments may be inspected at BEA's offices, 1441 L Street, NW., Room 7006, between 8:30 a.m. and 5 p.m., Eastern Time Monday through Friday.

FOR FURTHER INFORMATION CONTACT: Obie G. Whichard, Chief, International Investment Division (BE-50), Bureau of Economic Analysis, U.S. Department of Commerce, Washington, DC 20230; e-mail Obie.Whichard@bea.gov; or phone (202) 606-9890.

SUPPLEMENTARY INFORMATION: This proposed rule would amend 15 CFR part 801.9 to replace the reporting requirements for the BE-25, Quarterly Survey of Transactions with Unaffiliated Foreign Persons in Selected Services and in Intangible Assets, with requirements for the BE-125, Quarterly Survey of Transactions in Selected Services and Intangible Assets with Foreign Persons. The Department of Commerce, as part of its continuing effort to reduce paperwork and respondent burden, invites the general public and other Federal agencies to comment on proposed and/or continuing information collections, as required by the Paperwork Reduction Act of 1995.

Description of Changes

The proposed BE-125 survey would be a mandatory survey and would be conducted, beginning with transactions for the first quarter of 2007, by BEA under the International Investment and Trade in Services Survey Act (22 U.S.C. 3101-3108), hereinafter, "the Act." For the initial quarter of coverage, BEA would send the survey to potential respondents in March of 2007; responses would be due by May 15, 2007.

BEA maintains a continuing dialogue with respondents and with data users, including its own internal users, to ensure that, as far as possible, the required data serve their intended purposes and are available from existing records, that instructions are clear, and that unreasonable burdens are not imposed. In reaching decisions on what questions to include in the survey, BEA considered the Government's need for the data, the burden imposed on respondents, the quality of the likely responses (for example, whether the data are available on respondents' books), and BEA's experience in previous related annual and quarterly surveys.

If implemented, the BE-125 would collect all the same information as the BE-25, Quarterly Survey of