

§ 7.30 Custody and use of books, records, and documents.

(a) All books, records, and documents of or used by the county committee in the administration of programs assigned to it, or in the conduct of elections, shall be the property of the Commodity Credit Corporation or the United States Department of Agriculture, as applicable, and shall be maintained in good order in the county office.

(b) For polling and mail-type elections, voted ballots shall be placed into and remain in sealed containers, such containers not being opened until the prescribed date and time for counting. Following the counting of ballots in all types of elections, the ballots shall be placed in sealed containers and retained for 1 year unless otherwise determined by the Deputy Administrator.

(c) The books, records, and documents referred to in paragraph (a) of this section shall be available for use and examination:

(1) At all times by authorized representatives of the Secretary; the Administrator, or a designee of the Administrator.

(2) By state and county committee members, and authorized employees of the State and county office in the performance of duties assigned to them under this part, subject to instructions issued by the Deputy Administrator;

(3) At any reasonable time to any program participant insofar as such person's interests under the programs administered by the county committee may be affected, subject to instructions issued by the Deputy Administrator; and

(4) To any other person only in accordance with instructions issued by the Deputy Administrator.

§ 7.31 Administrative operations.

The administrative operations of county committees including but not limited to the following, shall be conducted, except as otherwise provided in these regulations, in accordance with official instructions issued: annual, sick, and other types of employee leave; the calling, and conduct of elections; and the maintenance of records of county committee meetings.

§ 7.32 Implementation.

Unless specifically provided in this part, the Deputy Administrator, Field Operations, FSA, is authorized to issue the instructions and procedures referred to herein which implement the provisions of this part.

§ 7.33 Applicability.

This part shall apply to the United States, its territories, and Puerto Rico.

§ 7.34 Retention of authority.

Nothing in this part shall preclude the Secretary, the Administrator, or the Deputy Administrator from administering any or all programs, or exercising other functions delegated to the county committee, State committee, or any employee of such committees. In exercising this authority, the Secretary, the Administrator, or the Deputy Administrator may designate for such period of time as deemed necessary a person or persons of their choice to be in charge with full authority to carry on the programs or other functions without regard to the normal duties of such committees or employees.

Signed at Washington, DC November 17, 2006.

Chuck Connor,

Acting Secretary of Agriculture.

[FR Doc. E6-20052 Filed 11-27-06; 8:45 am]

BILLING CODE 3410-05-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2006-26232; Directorate Identifier 2006-CE-62-AD]

RIN 2120-AA64

Airworthiness Directives; EADS SOCATA Model TBM 700 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as a report of a master cylinder yoke failure. The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by December 28, 2006.

ADDRESSES: You may send comments by any of the following methods:

- *DOT Docket Web Site:* Go to <http://dms.dot.gov> and follow the

instructions for sending your comments electronically.

- *Fax:* (202) 493-2251.
- *Mail:* Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-0001.

- *Hand Delivery:* Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

- *Federal eRulemaking Portal:* <http://www.regulations.gov>. Follow the instructions for submitting comments.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5227) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; fax: (816) 329-4090.

SUPPLEMENTARY INFORMATION:**Streamlined Issuance of AD**

The FAA is implementing a new process for streamlining the issuance of ADs related to MCAI. The streamlined process will allow us to adopt MCAI safety requirements in a more efficient manner and will reduce safety risks to the public. This process continues to follow all FAA AD issuance processes to meet legal, economic, Administrative Procedure Act, and **Federal Register** requirements. We also continue to meet our technical decision-making responsibilities to identify and correct unsafe conditions on U.S.-certificated products.

This proposed AD references the MCAI and related service information that we considered in forming the engineering basis to correct the unsafe condition. The proposed AD contains text copied from the MCAI and for this reason might not follow our plain language principles.

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the

ADDRESSES section. Include “Docket No. FAA–2006–26232; Directorate Identifier 2006–CE–62–AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the European Community, has issued AD No.: 2006–0189, dated July 4, 2006 (referred to after this as “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states there was a report of a master cylinder yoke failure. The AD requirements are to detect defective yokes on aircraft and replace them. The aim of this AD is to ensure that normal braking is available at any time to prevent possible runway excursions in the event of failure of the master cylinder yoke. You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

EADS SOCATA has issued TBM Aircraft Mandatory Service Bulletin SB 70–136, ATA No. 32, dated December 2005. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA’s Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Differences Between This Proposed AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in

general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are described in a separate paragraph of the proposed AD. These requirements, if ultimately adopted, will take precedence over the actions copied from the MCAI.

Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 270 products of U.S. registry. We also estimate that it would take about 1.5 work-hours per product to comply with the proposed AD. The average labor rate is \$80 per work-hour. Required parts would cost about \$600 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these costs. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$194,400, or \$720 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This

proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

EADS SOCATA: Docket No. FAA–2006–26232; Directorate Identifier 2006–CE–62–AD

Comments Due Date

- (a) We must receive comments by December 28, 2006.

Affected ADs

- (b) None.

Applicability

- (c) This AD applies to SOCATA Model TBM 700 airplanes, all serial numbers, certificated in any category.

Reason

- (d) The mandatory continuing airworthiness information (MCAI) states there was a report of a master cylinder yoke failure. The AD requirements are to detect defective yokes on aircraft and replace them. The aim of this AD is to ensure that normal braking is available at any time to prevent possible runway excursions in the event of failure of the master cylinder yoke.

Actions and Compliance

(e) Unless already done, do the following actions.

(1) For the serial numbers indicated below, within the next 100 hours time-in-service or 12 months after the effective date of this AD, whichever occurs first, do the following actions, unless already done:

(i) For airplane serial numbers 269 and 339 and up, check the aircraft records to determine whether cylinder yoke part number ZOO.N7134732200 or the yokes in master cylinder assembly part number ZOO.N6068757280 (left hand side) and ZOO.N6068757281 (right hand side) have been replaced. This check can be done by an owner/operator holding at least a private pilot certificate as authorized by section 43.7 of the Federal Aviation Regulations (14 CFR 43.7).

(A) If you can positively identify that master cylinder yoke part number ZOO.N7134732200 or the yokes in master cylinder assembly part number ZOO.N6068757280 (left hand side) and ZOO.N6068757281 (right hand side) have been replaced, then you must comply with paragraph (e)(1)(ii) of this AD.

(B) If you can positively identify that master cylinder yoke part number ZOO.N7134732200 or the yokes in master cylinder assembly part number ZOO.N6068757280 (left hand side) and ZOO.N6068757281 (right hand side) have not been replaced, then make an entry in the aircraft records showing compliance with this AD per section 43.9 of the Federal Aviation Regulations (14 CFR 43.9).

(ii) For all airplane serial numbers, unless the action is shown not to apply per paragraph (e)(1)(i)(B) of this AD, inspect for misalignment of the master cylinder yokes from their threaded pins, as instructed in the EADS SOCATA TBM Aircraft Mandatory Service Bulletin SB 70-136, ATA No. 32, dated December 2005, accomplishment instructions paragraph.

(A) If a yoke is found satisfactory, proceed to its re-installation on aircraft.

(B) If a yoke is found defective, prior to further flight, discard the yoke and install a new part number T700A324004810000 (or FAA-approved equivalent part number) yoke in accordance with EADS SOCATA TBM Aircraft Mandatory Service Bulletin SB 70-136, ATA No. 32, dated December 2005.

(2) For all airplane serial numbers, as of the effective date of this AD, do not install part number ZOO.N7134732200 yokes or yokes in master cylinder assembly part number ZOO.N6068757280 (left hand side) and ZOO.N6068757281 (right hand side), unless EADS SOCATA TBM Aircraft Mandatory Service Bulletin SB 70-136, ATA No. 32, dated December 2005, is complied with.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows:

(1) It does not allow interim use of yokes found defective during inspection. FAA policy is to replace defective parts on critical systems.

(2) It applies to all serial numbers. This will assure that, if any of the airplanes had the affected part number yokes installed after

delivery of the airplane, the unsafe condition is still addressed. It also will assure that any of the affected part number yokes are inspected per the AD and service bulletin before future installation of these parts.

Other FAA AD Provisions

(f) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Staff, FAA, ATTN: Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; fax: (816) 329-4090, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(g) Refer to European Aviation Safety Agency (EASA) AD No.: 2006-0189, dated July 4, 2006; and EADS SOCATA TBM Aircraft Mandatory Service Bulletin SB 70-136, ATA No. 32, dated December 2005, for related information.

Issued in Kansas City, Missouri, on November 20, 2006.

David R. Showers,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E6-20122 Filed 11-27-06; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2006-26180; Directorate Identifier 2006-CE-59-AD]

RIN 2120-AA64

Airworthiness Directives; EADS SOCATA Model TBM 700 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the

products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as the discovery of propeller control cables with a defective crimping. Two cable ends were found uncrimped at the factory after an engine run-up test, and one cable end was also found uncrimped on the first 100 hour aircraft maintenance check. The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by December 28, 2006.

ADDRESSES: You may send comments by any of the following methods:

- **DOT Docket Web Site:** Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- **Fax:** (202) 493-2251.

- **Mail:** Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-0001.

- **Hand Delivery:** Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

- **Federal eRulemaking Portal:** <http://www.regulations.gov>. Follow the instructions for submitting comments.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5227) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Albert J. Mercado, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone (816) 329-4119; fax: (816) 329-4090.

SUPPLEMENTARY INFORMATION:

Streamlined Issuance of AD

The FAA is implementing a new process for streamlining the issuance of ADs related to MCAI. The streamlined process will allow us to adopt MCAI