## **Related Information**

(g) Refer to MCAI European Aviation Safety Agency (EASA) AD No. 2006–0085, dated April 12, 2006, and EADS SOCATA TBM Aircraft Mandatory Service Bulletin SB 70–130, ATA No. 32, dated January 2006, for related information.

Issued in Kansas City, Missouri, on December 15, 2006.

## Kim Smith,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E6–21929 Filed 12–21–06; 8:45 am] BILLING CODE 4910–13–P

## **DEPARTMENT OF TRANSPORTATION**

## **Federal Aviation Administration**

#### 14 CFR Part 39

[Docket No. FAA-2006-26401; Directorate Identifier 2006-CE-72-AD]

#### RIN 2120-AA64

Airworthiness Directives; B–N Group Ltd. BN–2, BN–2A, BN–2B, BN–2T, and BN–2T–4R Series (All Individual Models Included in Type Certificate Data Sheet (TCDS) A17EU, Revision 16, Dated December 9, 2002), and BN– 2A–MkIII Trislander Series (All Individual Models Included in Type Certificate Data Sheet (TCDS) A29EU, Revision 4, Dated December 9, 2002) Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT). **ACTION:** Notice of proposed rulemaking

(NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as: "incidences have been reported to Britten-Norman Aircraft Ltd where cracks have been found in the inner shell of the pitot/static pressure heads. This could result in incorrect readings on the pressure instrumentation, e.g. altimeters, vertical speed indicators (rate-of-climb) and airspeed indicators." The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

**DATES:** We must receive comments on this proposed AD by January 22, 2007.

**ADDRESSES:** You may send comments by any of the following methods:

• DOT Docket Web Site: Go to http:// dms.dot.gov and follow the instructions for sending your comments electronically.

• Fax: (202) 493-2251.

• *Mail:* Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL–401, Washington, DC 20590– 0001.

• *Hand Delivery:* Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

• Federal eRulemaking Portal: http:// www.regulations.gov. Follow the instructions for submitting comments.

#### **Examining the AD Docket**

You may examine the AD docket on the Internet at *http://dms.dot.gov;* or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647– 5227) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Taylor B. Martin, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329– 4138; facsimile: (816) 329–4090. SUPPLEMENTARY INFORMATION:

## Streamlined Issuance of AD

The FAA is implementing a new process for streamlining the issuance of ADs related to MCAI. The streamlined process will allow us to adopt MCAI safety requirements in a more efficient manner and will reduce safety risks to the public. This process continues to follow all FAA AD issuance processes to meet legal, economic, Administrative Procedure Act, and **Federal Register** requirements. We also continue to meet our technical decision-making responsibilities to identify and correct unsafe conditions on U.S.-certificated products.

This proposed AD references the MCAI and related service information that we considered in forming the engineering basis to correct the unsafe condition. The proposed AD contains text copied from the MCAI and for this reason might not follow our plain language principles.

#### **Comments Invited**

We invite you to send any written relevant data, views, or arguments about

this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA–2006–26401; Directorate Identifier 2006–CE–72–AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to *http:// dms.dot.gov*, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

## Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA AD No. 2006-0143, Effective Date: May 30, 2006, referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states: "incidences have been reported to Britten-Norman Aircraft Ltd. where cracks have been found in the inner shell of the pitot/static pressure heads. This could result in incorrect readings on the pressure instrumentation, e.g. altimeters, vertical speed indicators (rate-of-climb) and airspeed indicators. This condition has been determined to be potentially hazardous." The MCAI requires an inspection procedure and a leak test procedure to detect cracks, and a check of the drain traps for moisture.

## **Relevant Service Information**

B–N Group LTD has issued Service Bulletin SB 310 effective date March 1, 2006. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

# FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

## Differences Between This Proposed AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are described in a separate paragraph of the proposed AD. These requirements, if ultimately adopted, will take precedence over the actions copied from the MCAI.

## **Costs of Compliance**

Based on the service information, we estimate that this proposed AD would affect about 135 products of U.S. registry. We also estimate that it would take about 2 work-hours per product to comply with the proposed AD. The average labor rate is \$80 per work-hour. Required parts would cost about \$10,000 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these costs. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$1,371,600, or \$10,160 per product.

## Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

## **Regulatory Findings**

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;

2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and

3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

## List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

## **The Proposed Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

B-N Group Ltd: Docket No. FAA-2006– 26401; Directorate Identifier 2006–CE– 72–AD.

#### **Comments Due Date**

(a) We must receive comments by January 22, 2007.

## Affected ADs

(b) None.

## Applicability

(c) This AD applies to B–N Group Ltd BN– 2, BN–2A, BN–2B, BN–2T, and BN–2T–4R Series (all individual models included in Type Certificate Data Sheet (TCDS) A17EU, Revision 16, dated December 9, 2002), and BN–2A–Mklll Trislander Series (all individual models included in TCDS A29EU, Revision 4, dated December 9, 2002) airplanes, certificated in any category.

#### Reason

(d) The mandatory continuing airworthiness information (MCAI) states: "incidences have been reported to Britten-Norman Aircraft Ltd. where cracks have been found in the inner shell of the pitot/static pressure heads. If not corrected this could result in incorrect readings on the pressure instrumentation, e.g. altimeters, vertical speed indicators (rate-of-climb) and airspeed indicators."

## **Actions and Compliance**

(e) Unless already done, do the following actions in accordance with B–N Group Service Bulletin 310, Issue 2, dated March 1, 2006:

(1) Within the next 60 days after the effective date of this AD, perform the inspection procedure and the leak test procedure as detailed in Section 6 Action, of B–N Service Bulletin 310 Issue 2. Repeat this inspection procedure and leak test procedures at intervals not to exceed 500 hours.

(2) In addition within 500 hours after the initial inspection, perform an initial inspection of the drain traps for moisture. Repeat this inspection at intervals not exceeding 500 hours.

(3) Prior to further flight, correct, modify, or replace as specified in the service information.

## **FAA AD Differences**

**Note:** This AD differs from the MCAI and/ or service information as follows: No differences.

## **Other FAA AD Provisions**

(f) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Standards Staff, FAA, ATTN: Taylor B. Martin, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri, 64106; telephone: (816) 329–4138; facsimile: (816) 329–4090, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAAapproved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120–0056.

## **Related Information**

(g) Refer to MCAI European Aviation Safety Agency (EASA), AD No.: 2006–0143, dated May 30, 2006, and Britten-Norman Service Bulletin SB 310, dated March 1, 2006, for related information. Issued in Kansas City, Missouri, on December 15, 2006.

## Kim Smith,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E6–21924 Filed 12–21–06; 8:45 am] BILLING CODE 4910–13–P

## DEPARTMENT OF TRANSPORTATION

## Federal Aviation Administration

## 14 CFR Part 71

[Docket No. FAA-2006-25944; Airspace Docket No. 06-ACE-14]

## Proposed Establishment of Class E5 Airspace; Potosi, MO

**AGENCY:** Federal Aviation Administration (FAA), DOT. **ACTION:** Notice of proposed rulemaking.

**SUMMARY:** This notice proposes to amend Part 71 of the Federal Aviation Regulations (14 CFR Part 71) by establishing a Class E airspace area extending upward from 700 feet above the surface at Potosi, Washington County Airport, MO.

**DATES:** Comments for inclusion in the Rules Docket must be received on or before January 15, 2007

ADDRESSES: Send comments on this proposal to the Docket Management System, U.S. Department of Transportation, Room Plaza 401, 400 Seventh Street, SW., Washington, DC 20590-0001. You must identify the docket number FAA-2006-25944/ Airspace Docket No. 06–ACE–14, at the beginning of your comments. You may also submit comments on the Internet at http://dms.dot.gov. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone 1-800-647-5527) is on the plaza level of the Department of Transportation NASSIF Building at the above address.

FOR FURTHER INFORMATION CONTACT: Grant Nichols, System Support, DOT Regional Headquarters Building, Federal Aviation Administration, 901 Locust Kansas City, MO 64106; telephone: (816) 329–2522.

## SUPPLEMENTARY INFORMATION:

## **Comments Invited**

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis

supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. Communications should identify both docket numbers and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. FAA-2006-25944/Airspace Docket No. 06–ACE–14." The postcard will be date/time stamped and returned to the commenter.

## Availability of NPRM's

An electronic copy of this document may be downloaded through the Internet at *http://dms.dot.gov*. Recently published rulemaking documents can also be accessed through the FAA's web page at *http://www.faa.gov* or the Superintendent of Document's web page at *http://www.access.gpo.gov/nara*.

Additionally, any person may obtain a copy of this notice by submitting a request to the Federal Aviation Administration (FAA), Office of Air Traffic Airspace Management, ATA-400, 800 Independence Avenue, SW., Washington, DC 20591, or by calling (202) 267-8783. Communications must identify both docket numbers for this notice. Persons interested in being placed on a mailing list for future NPRM's should contact the FAA's Office of Rulemaking (202) 267-9677, to request a copy of Advisory Circular No. 11–2A, Notice of Proposed Rulemaking Distribution System, which describes the application procedure.

## The Proposal

This notice proposes to amend Part 71 of the Federal Aviation Regulations (14 CFR Part 71) by establishing a Class E airspace area extending upward from 700 feet above the surface at Potosi, Washington County Airport, MO. The establishment of Area Navigation (RNAV) Global Positioning System (GPS) Instrument Approach Procedures (IAP) to runways 2 and 20 have made this action necessary. The intended effect of this proposal is to provide adequate controlled airspace for Instrument Flight Rules operations at Potosi, Washington County Airport, MO. The area would be depicted on appropriate aeronautical charts.

Class E airspace areas extending upward from 700 feet or more above the surface of the earth are published in Paragraph 6005 of FAA Order 7400.9P, dated September 1, 2006, and effective September 16, 2006, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designations listed in this document would be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore, (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

This proposed rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of the airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This proposed regulation is within the scope of that authority since it would contain aircraft executing instrument approach procedures to Potosi, Washington County Airport, MO.

## List of Subjects in 14 CFR Part 71

Airspace Incorporation by reference, Navigation (Air).

#### **The Proposed Admendment**

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

## PART 71—DESIGNATION OF CLASS A, CLASS B, CLASS C, CLASS D, AND CLASS E AIRSPACE AREAS; AIRWAYS; ROUTES; AND REPORTING POINTS

1. The authority citation for part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

## §71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation