

New Requirements of This AD*Modification or Replacement, as Applicable*

(f) Within 48 months after the effective date of this AD: Modify the decompression panels on the smoke barrier or replace the smoke barrier with an improved smoke barrier, by accomplishing all of the actions specified in Work Package 1 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-25A3353, dated December 9, 2004, as applicable.

Repetitive Inspection

(g) Within 20 months or 6,000 flight hours after accomplishing the actions in paragraph (f) of this AD, whichever occurs first: Do a general visual inspection of the decompression (vent) panels on the smoke barrier for any changes from their installed condition, and do all corrective actions before further flight after the inspection, by accomplishing all of the actions specified in Work Package 2 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-25A3353, dated December 9, 2004, as applicable. Repeat the inspection thereafter at intervals not to exceed 20 months or 6,000 flight hours, whichever occurs first.

Note 1: For the purposes of this AD, a general visual inspection is: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made from within touching distance unless otherwise specified. A mirror may be necessary to ensure visual access to all surfaces in the inspection area. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or droplight and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

Alternative Methods of Compliance (AMOCs)

(h)(1) The Manager, Seattle Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

Material Incorporated by Reference

(i) You must use Boeing Alert Service Bulletin 747-25A3353, dated December 9, 2004, to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of this document in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207, for a copy of this service information. You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration

(NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on February 6, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-2511 Filed 2-15-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2006-26049; Directorate Identifier 2006-NM-177-AD; Amendment 39-14949; AD 2007-04-17]

RIN 2120-AA64

Airworthiness Directives; McDonnell Douglas Model DC-10-10, DC-10-10F, DC-10-15, DC-10-30, and DC-10-30F (KC-10A and KDC-10) Airplanes; Model DC-10-40 and DC-10-40F Airplanes Equipped With Pratt & Whitney JT9-20 or JT9-20J Engines; and Model MD-10-10F and MD-10-30F Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for the McDonnell Douglas airplanes previously described. This AD requires replacing the control modules of the fire detection systems of the propulsion engines with new, improved control modules. This AD results from a report of broken or severed wiring between engine fire detectors and the fire detection system control module, which caused the fire detection system to become non-functional without flightcrew awareness. We are issuing this AD to prevent unannounced fire in a propulsion engine, which could cause injury to flightcrew and passengers or loss of the airplane.

DATES: This AD becomes effective March 23, 2007.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of March 23, 2007.

ADDRESSES: You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC.

Contact Meggitt Safety Systems, 1915 Voyager Avenue, Simi Valley, California 93063, for service information identified in this AD.

FOR FURTHER INFORMATION CONTACT:

Samuel Lee, Aerospace Engineer, Propulsion Branch, ANM-140L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5262; fax (562) 627-5210.

SUPPLEMENTARY INFORMATION:**Examining the Docket**

You may examine the airworthiness directive (AD) docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the street address stated in the **ADDRESSES** section.

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to all McDonnell Douglas Model DC-10-10, DC-10-10F, DC-10-15, DC-10-30, and DC-10-30F (KC-10A and KDC-10) airplanes; Model DC-10-40 and DC-10-40F airplanes equipped with Pratt & Whitney JT9-20 or JT9-20J engines; and all Model MD-10-10F and MD-10-30F airplanes. That NPRM was published in the **Federal Register** on October 13, 2006 (71 FR 60448). That NPRM proposed to require replacing the control modules of the fire detection systems of the propulsion engines with new, improved control modules.

Comments

We provided the public the opportunity to participate in the development of this AD. We have considered the comments received.

Support for the NPRM

FedEx concurs with the NPRM as written and states its intent to also modify the fire detection systems of the auxiliary power units of subject FedEx airplanes, as described in the service information mandated by the AD.

Request To Clarify Service Information Requirement

Hawaiian Airlines requests that we revise the NPRM to clarify what service information is acceptable for compliance with the AD. The commenter asserts that the NPRM states that the use of Meggitt Safety Systems Service Bulletin 26-34, Revision 2,

dated August 15, 2006, is acceptable for compliance. However, the commenter states that, according to Revision 1 and Revision 2 of the service bulletin, no further work is required. Therefore, the commenter inquires whether compliance with the original issue or Revision 1 of the service information will be acceptable.

We partially agree. Although we can find no statement in Service Bulletin 26–34, Revision 1, dated July 17, 2006 (which is the original issue); or Revision 2; that no further work is required, we have confirmed that Revision 1 and Revision 2 are technically identical and differ only in issues of format and style. Therefore, we have added new paragraph (g) to the AD to specify that actions accomplished before the effective date of the AD in accordance with Revision 1 of Service Bulletin 26–34 are acceptable for compliance with the requirements of the AD. We have re-identified subsequent paragraphs of the AD accordingly.

Request To Include Statement of Intent To Incorporate by Reference

The Modification and Replacement Parts Association (MARPA) requests that, during the NPRM stage of AD rulemaking, the FAA state its intent to incorporate by reference (IBR) any relevant service information. MARPA states that without such a statement in the NPRM, it is unclear whether the relevant service information will be incorporated by reference in the final rule.

We do not concur with the commenter's request. When we reference certain service information in a proposed AD, the public can assume we intend to IBR that service information, as required by the Office of the Federal Register. No change to the AD is necessary in regard to the commenter's request.

Request To Post IBR Documents on the Docket Management System (DMS)

MARPA asserts that IBR documents should be made available to the public by publication in the DMS, keyed to the action that incorporates them. MARPA therefore requests that such documents be published in the DMS prior to release of the final rule.

We do not agree with this request. We are currently in the process of reviewing issues surrounding the posting of service bulletins on the DMS as part of an AD docket. Once we have thoroughly examined all aspects of this issue and have made a final determination, we will consider whether our current practice needs to be revised. No change to the AD is necessary in this regard.

Conclusion

We have carefully reviewed the available data, including the comments received, and determined that air safety and the public interest require adopting the AD with the changes described previously. We have determined that these changes will neither increase the economic burden on any operator nor increase the scope of the AD.

Costs of Compliance

There are about 305 airplanes of the affected design in the worldwide fleet. This AD affects about 233 airplanes of U.S. registry. The required actions take about 6 work hours per airplane, at an average labor rate of \$80 per work hour. Required parts cost about \$9,900 per airplane. Based on these figures, the estimated cost of the AD for U.S. operators is \$2,418,540, or \$10,380 per airplane.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities

under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

2007–04–17 McDonnell Douglas:

Amendment 39–14949. Docket No. FAA–2006–26049; Directorate Identifier 2006–NM–177–AD.

Effective Date

(a) This AD becomes effective March 23, 2007.

Affected ADs

(b) None.

Applicability

(c) This AD applies to McDonnell Douglas airplanes, certificated in any category; as specified in paragraphs (c)(1), (c)(2), and (c)(3) of this AD.

(1) All Model DC–10–10, DC–10–10F, DC–10–15, DC–10–30, and DC–10–30F (KC–10A and KDC–10) airplanes;

(2) Model DC–10–40 and DC–10–40F airplanes equipped with Pratt & Whitney JT9–20 or JT9–20J engines; and

(3) All Model MD–10–10F and MD–10–30F airplanes.

Unsafe Condition

(d) This AD results from a report of broken or severed wiring between engine fire detectors and the fire detection system control module, which caused the fire detection system to become non-functional without flightcrew awareness. We are issuing this AD to prevent unannounced fire in a propulsion engine, which could cause injury to flightcrew and passengers or loss of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Control Module Replacement

(f) Within 60 months after the effective date of this AD, replace the control modules of the fire detection systems of the propulsion engines with new, improved control modules, in accordance with paragraph 2., "Main Engine Control Module Replacement Instructions," of Meggitt Safety Systems Service Bulletin 26-34, Revision 2, dated August 15, 2006.

Credit for Previous Revisions of Service Bulletins

(g) Actions done before the effective date of this AD in accordance with Meggitt Safety Systems Service Bulletin 26-34, Revision 1, dated July 17, 2006, are acceptable for compliance with the corresponding actions required by paragraph (f) of this AD.

Alternative Methods of Compliance (AMOCs)

(h)(1) The Manager, Los Angeles Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

Material Incorporated by Reference

(i) You must use Meggitt Safety Systems Service Bulletin 26-34, Revision 2, dated August 15, 2006, to perform the actions that are required by this AD, unless the AD specifies otherwise. Meggitt Safety Systems Service Bulletin 26-34, Revision 2, dated August 15, 2006, contains the following effective pages:

Page number	Revision level shown on page	Date shown on page
1-26	2	August 15, 2006.
27-61	1	July 17, 2006.

The Director of the Federal Register approved the incorporation by reference of this document in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Meggitt Safety Systems, 1915 Voyager Avenue, Simi Valley, California 93063, for a copy of this service information. You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on February 8, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate,
Aircraft Certification Service.

[FR Doc. E7-2639 Filed 2-15-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2006-25563; Directorate Identifier 2006-NM-083-AD; Amendment 39-14950; AD 2007-04-18]

RIN 2120-AA64

Airworthiness Directives; Learjet Model 23, 24, 24A, 24B, 24B-A, 24C, 24D, 24D-A, 24E, 24F, 24F-A, 25, 25A, 25B, 25C, 25D, 25F, 28, 29, 31, 31A, 35, 35A (C-21A), 36, 36A, 55, 55B, and 55C Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Learjet Model 23, 24, 24A, 24B, 24B-A, 24C, 24D, 24D-A, 24E, 24F, 24F-A, 25, 25A, 25B, 25C, 25D, 25F, 28, 29, 31, 31A, 35, 35A (C-21A), 36, 36A, 55, 55B, and 55C airplanes. This AD requires modifying the left- and right-hand standby fuel pump switches. This AD also requires revising the Emergency and Abnormal Procedures sections of the airplane flight manual to advise the flightcrew of the proper procedures to follow in the event of failure of the standby fuel pump to shut off. This AD results from a report of inadvertent operation of a standby fuel pump due to an electrical system malfunction. We are issuing this AD to prevent this inadvertent operation, which could result in inadvertent fuel transfer by the left or right wing fuel system and subsequent over-limit fuel imbalance between the left and right wing fuel loads. This imbalance could affect lateral control of the airplane which could result in reduced controllability.

DATES: This AD becomes effective March 23, 2007.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the AD as of March 23, 2007.

ADDRESSES: You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC.

Contact Learjet, Inc., One Learjet Way, Wichita, Kansas 67209-2942, for service information identified in this AD.

FOR FURTHER INFORMATION CONTACT: James Galstad, Aerospace Engineer, Mechanical Systems and Propulsion

Branch, ACE-116W, FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas 67209; telephone (316) 946-4135; fax (316) 946-4107.

SUPPLEMENTARY INFORMATION:

Examining the Docket

You may examine the airworthiness directive (AD) docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the street address stated in the **ADDRESSES** section.

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to certain Learjet Model 23, 24, 24A, 24B, 24B-A, 24C, 24D, 24D-A, 24E, 24F, 24F-A, 25, 25A, 25B, 25C, 25D, 25F, 28, 29, 31, 31A, 35, 35A (C-21A), 36, 36A, 55, 55B, and 55C airplanes. That NPRM was published in the **Federal Register** on August 16, 2006 (71 FR 47154). That NPRM proposed to require modifying the left- and right-hand standby fuel pump switches. That NPRM also proposed to require revising the Emergency and Abnormal Procedures sections of the airplane flight manual (AFM) to advise the flightcrew of the proper procedures to follow in the event of failure of the standby fuel pump to shut off.

Comments

We provided the public the opportunity to participate in the development of this AD. We have considered the comments received.

Requests To Withdraw the NPRM

One private citizen states that the flight department he works for operates three Learjet Model 35A airplanes and a Learjet Model 31 airplane. He adds that the airplanes have never had an inadvertent operation of the fuel pumps resulting in an over-limit fuel imbalance. He also notes that the fuel crossflow valve must be open in order to transfer fuel; this requires two switches to be selected—the standby fuel pump and the crossflow valve. He states that even if a standby fuel pump is inadvertently activated, no fuel will be transferred unless the crossflow valve is also open. He concludes that there is already enough protection in the system to avoid an over-limit fuel imbalance.