

less, as of the effective date of this AD: Perform the inspections before the accumulation of 5,600 total flight hours or 2,400 total landings after the effective date of this AD, or within 6 months after the effective date of this AD, whichever occurs latest.

(ii) For airplanes having accumulated more than 5,600 flight hours but less than or equal to 8,000 flight hours, or more than 2,400 landings but less than or equal to 3,600 landings, as of the effective date of this AD: Perform the inspections before the accumulation of 200 flight hours or 100 landings after the effective date of this AD, whichever occurs first.

(iii) For airplanes having accumulated more than 8,000 flight hours or more than 3,600 landings as of the effective date of this AD: Perform the inspections within 14 days after the effective date of this AD.

(2) For airplanes other than those identified in paragraph (f)(1) of this AD: Perform the NDIs at the applicable time specified in paragraph (f)(2)(i), (f)(2)(ii), or (f)(2)(iii) of this AD. Do the inspections as defined in EADS-CASA All Operator Letter 212-018, Revision 1, dated December 1, 2006.

(i) For airplanes having accumulated 10,000 flight hours or less, and 10,000 landings or less as of the effective date of this AD: Perform the inspections before the accumulation of 10,000 total flight hours or 10,000 total landings after the effective date of this AD, or within 6 months after the effective date of this AD, whichever occurs latest.

(ii) For airplanes having accumulated more than 10,000 flight hours but less than or equal to 15,000 flight hours, or more than 10,000 landings but less than or equal to 15,000 landings, as of the effective date of this AD: Perform the inspections before the accumulation of 200 flight hours or 100 landings after the effective date of this AD, whichever occurs first.

(iii) For airplanes having accumulated more than 15,000 flight hours or more than 15,000 landings as of the effective date of this AD: Perform the inspections within 14 days after the effective date of this AD.

(3) No further flight is allowed if any cracks are detected when performing the actions specified in paragraphs (f)(1) and (f)(2) of this AD. Before further flight, repair any cracking found during any inspection required by this AD using a method approved by either the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA) (or its delegated agent). Within 30 days after cracks are detected, or within 30 days after the effective date of this AD, whichever occurs later, send a detailed report of the findings (both positive and negative) of the inspections required by paragraph (f) of this AD to EADS-CASA for evaluation at the following address: EADS-CASA, Military Transport Aircraft Division, Integrated Customer Services, Technical Services, Avenida de Aragon 404, 28022-Madrid, Spain; telephone 34-91-624-6306; fax 34-91-585-5505. E-mail: MTA, [TechnicalService@casa.eads.net](mailto:TechnicalService@casa.eads.net). In any case, a confirmation of the accomplishment of this

inspection is required to be sent to EADS-CASA.

#### FAA AD Differences

**Note:** This AD differs from the MCAI and/or service information as follows:

(1) **Compliance Time:** For certain airplanes, the compliance time required by the MCAI or service information for performing the non-destructive inspections is before further flight; however, to avoid inadvertently grounding airplanes, this AD requires performing those inspections within 14 days after the effective date of this AD.

(2) **Repair:** Although the MCAI or service information does not include a repair procedure for cracking, this AD requires the repair of any cracking per the FAA, EASA, or its delegated agent.

#### Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) **Alternative Methods of Compliance (AMOCs):** The Manager, International Branch, ANM-116, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Shahram Daneshmandi, Aerospace Engineer; 1601 Lind Avenue, SW., Renton, WA 98057-3356; telephone (425) 227-1112; fax (425) 227-1149. Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office. Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

(2) **Airworthy Product:** For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) **Reporting Requirements:** For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

#### Related Information

(h) Refer to MCAI EASA Emergency Airworthiness Directive 2006-0365-E, dated December 4, 2006; and EADS-CASA All Operator Letter 212-018, Revision 1, dated December 1, 2006, for related information.

#### Material Incorporated by Reference

(i) You must use EADS-CASA All Operator Letter 212-018, Revision 1, dated December 1, 2006, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Construcciones Aeronauticas, S.A., Getafe, Madrid, Spain.

(3) You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on February 16, 2007.

**Ali Bahrami,**

*Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. E7-3164 Filed 2-26-07; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2006-26496 Directorate Identifier 2006-CE-81-AD; Amendment 39-14958; AD 2007-04-25]

RIN 2120-AA64

#### Airworthiness Directives; Alpha Aviation Design Limited R2160 Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as a deficiency in compliance with 14 CFR 23.967(d). There have been instances indicating that production aircraft may not have a metal barrier between the cabin and the fuel tank bay. Lack of a barrier could allow flammable fuel vapors to enter the cabin. We are issuing this AD to require actions to correct the unsafe condition on these products.

**DATES:** This AD becomes effective April 3, 2007.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of April 3, 2007.

**ADDRESSES:** You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility, U.S. Department

of Transportation, 400 Seventh Street SW., Nassif Building, Room PL-401, Washington, DC.

**FOR FURTHER INFORMATION CONTACT:** Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4146; fax: (816) 329-4090.

#### SUPPLEMENTARY INFORMATION:

##### Streamlined Issuance of AD

The FAA is implementing a new process for streamlining the issuance of ADs related to MCAI. The streamlined process will allow us to adopt MCAI safety requirements in a more efficient manner and will reduce safety risks to the public. This process continues to follow all FAA AD issuance processes to meet legal, economic, Administrative Procedure Act, and **Federal Register** requirements. We also continue to meet our technical decision-making responsibilities to identify and correct unsafe conditions on U.S.-certificated products.

This AD references the MCAI and related service information that we considered in forming the engineering basis to correct the unsafe condition. The AD contains text copied from the MCAI and for this reason might not follow our plain language principles.

##### Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on January 5, 2007 (72 FR 481). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states that there have been instances indicating that production aircraft may not have a metal barrier between the cabin and the fuel tank bay. Lack of a barrier could allow flammable fuel vapors to enter the cabin. The MCAI requires that you, to ensure that the aircraft is in compliance with 14 CFR 23.967(d), inspect the aircraft to determine if a metal barrier is installed behind the seats and, if not installed, to manufacture and install a barrier.

##### Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

##### Conclusion

We reviewed the available data and determined that air safety and the

public interest require adopting the AD as proposed.

##### Differences Between this AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have required different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are described in a separate paragraph of the AD, and take precedence over the actions copied from the MCAI.

##### Costs of Compliance

We estimate that this AD will affect 10 products of U.S. registry. We also estimate that it will take about 3 work-hours per product to comply with this AD. The average labor rate is \$80 per work-hour. Required parts will cost about \$300 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these parts. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here. Based on these figures, we estimate the cost of this AD to the U.S. operators to be \$5,400 or \$540 per product.

##### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

##### Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD Docket.

##### Examining the AD Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5227) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

##### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

##### Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

##### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

##### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

**2007-04-25 Alpha Aviation Design Limited:** Amendment 39-14958; Docket No. FAA-2006-26496; Directorate Identifier 2006-CE-81-AD.

##### Effective Date

(a) This airworthiness directive (AD) becomes effective April 3, 2007.

**Affected ADs**

(b) None.

**Applicability**

(c) This AD applies to Model R2160 airplanes, serial numbers 001 through 378, certificated in any category.

**Reason**

(d) The mandatory continuing airworthiness information (MCAI) states that there have been instances indicating that production aircraft may not have a metal barrier between the cabin and the fuel tank bay. Lack of a barrier could allow flammable fuel vapors to enter the cabin. The MCAI requires that, to ensure that the aircraft is in compliance with 14 CFR 23.967(d), inspect the aircraft to determine if a metal barrier is installed behind the seats and, if not installed, to manufacture and install a barrier.

**Actions and Compliance**

(e) Unless already done, do the following actions within the next 100 hours time-in-service or within 6 months after April 3, 2007 (the effective date of this AD), whichever occurs first.

(1) Inspect the aircraft to determine if a metal barrier is installed behind the seats per Alpha Aviation Service Bulletin AA-SB-28-001, dated July 10, 2006.

(2) If a metal barrier is installed per Alpha Aviation Service Bulletin AA-SB-28-001, dated July 10, 2006, and (e)(1) of this AD, then no further action is required.

(3) If a metal barrier is not installed, manufacture and install a barrier per Alpha Aviation Service Bulletin AA-SB-28-001, dated July 10, 2006, and Alpha Aviation Drawing No. 60-53-119 (page 3 of 3 of the Service Bulletin).

**FAA AD Differences**

**Note:** This AD differs from the MCAI and/or service information as follows: No differences.

**Other FAA AD Provisions**

(f) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Staff, FAA, ATTN: Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4146; fax: (816) 329-4090, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection

requirements and has assigned OMB Control Number 2120-0056.

**Related Information**

(g) Refer to MCAI Civil Aviation Authority of New Zealand AD DCA/R2000/38, dated June 29, 2006, for related information.

**Material Incorporated by Reference**

(h) You must use Alpha Aviation Service Bulletin AA-SB-28-001, dated July 10, 2006, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Alpha Aviation Ltd, Ingram Road, Hamilton Airport RD 2, Hamilton 2021, New Zealand; telephone: 011 64 7 843 7070; fax: 011 64 7 843 8040; Internet: <http://www.alphaaviation.co.nz>.

(3) You may review copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on February 15, 2007.

**David R. Showers,**

*Acting Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. E7-3163 Filed 2-26-07; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

**[Docket No. FAA-2006-25391; Directorate Identifier 2006-NM-097-AD; Amendment 39-14956; AD 2007-04-23]**

**RIN 2120-AA64**

**Airworthiness Directives; Fokker Model F.28 Mark 0070 and 0100 Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** The FAA is superseding an existing airworthiness directive (AD), which applies to certain Fokker Model F.28 Mark 0070 and 0100 airplanes. That AD currently requires a one-time inspection of the sliding members in the main landing gear (MLG) for cracking and replacement of the sliding members with serviceable parts if necessary. This new AD adds repetitive magnetic particle inspections of the sliding members of the MLG for cracking and

corrective actions as necessary. This AD results from inspection findings that have shown repetitive inspections are needed to establish fleet safety. We are issuing this AD to detect and correct fatigue cracking of the sliding member, which could result in possible separation of the MLG from the airplane and consequent reduced controllability of the airplane upon landing and possible injury to passengers.

**DATES:** This AD becomes effective April 3, 2007.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the AD as of April 3, 2007.

On May 19, 2004 (69 FR 19759, April 14, 2004), the Director of the Federal Register approved the incorporation by reference of Fokker Service Bulletin SBF100-32-133, dated April 1, 2002.

**ADDRESSES:** You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., Nassif Building, Room PL-401, Washington, DC.

Contact Fokker Services B.V., Technical Services Dept., P.O. Box 231, 2150 AE Nieuw-Vennep, the Netherlands, for service information identified in this AD.

**FOR FURTHER INFORMATION CONTACT:** Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149.

**SUPPLEMENTARY INFORMATION:****Examining the Docket**

You may examine the airworthiness directive (AD) docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the street address stated in the **ADDRESSES** section.

**Discussion**

The FAA issued a supplemental notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that supersedes AD 2004-08-01, amendment 39-13570 (69 FR 19759, April 14, 2004). The existing AD applies to certain Fokker Model F.28 Mark 0070 and 0100 airplanes. That supplemental NPRM was published in the **Federal Register** on December 28, 2006 (71 FR 78107). That supplemental NPRM