

frame cracking, which, if not corrected, could lead to a severed frame that, combined with cracking of the skin lap splice above stringer 10, could result in rapid decompression of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Service Bulletin Reference

(f) The term "service bulletin," as used in this AD, means Boeing Special Attention Service Bulletin 737-25-1544, dated October 4, 2006.

Inspections

(g) Before the accumulation of 36,000 total flight cycles, or within 72 months after the effective date of this AD, whichever occurs later: Do a general visual inspection to determine if the support bracket of any A/C outlet extrusion between body station (BS) 360 and BS 907 has a two-rivet attachment fitting, then do the actions described by paragraph (g)(1) and (g)(2) of this AD; in accordance with part 2 of the accomplishment instructions of the service bulletin.

(1) For any subject support bracket not attached with a two-rivet attachment fitting, no further action is required by paragraph (g) of this AD.

(2) For any subject support bracket having a two-rivet attachment fitting, do medium- and high-frequency eddy current inspections for cracking of the frame around the attachment holes of the support bracket. If any cracking is discovered, before further flight, repair the cracking in accordance with part 3 of the accomplishment instructions of the service bulletin.

Modification

(h) Before the accumulation of 36,000 total flight cycles, or within 72 months after the effective date of this AD, whichever occurs later, replace the support fittings of all A/C outlet extrusions between BS 360 and BS 907 with new, improved support fittings, in accordance with part 4 of the accomplishment instructions of the service bulletin.

Alternative Methods of Compliance (AMOCs)

(i)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option

Authorization Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

Issued in Renton, Washington, on May 15, 2007.

Ali Bahrami,

*Manager, Transport Airplane Directorate,
Aircraft Certification Service.*

[FR Doc. E7-10137 Filed 5-24-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-28281; Directorate Identifier 2006-NM-238-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 767 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all Boeing Model 767 airplanes. This proposed AD would require repetitive replacement of the internal electrical feed-through connectors of the main fuel tank boost pumps. This proposed AD results from a report of cracking in the epoxy potting compound on the internal feed-through connector of the fuel boost pump in the area of the soldered wire connector lugs. We are proposing this AD to prevent a hazardous electrical path from the dry side to the wet side of the fuel boost pump through a cracked feed-through connector, which could create an ignition source on the wet side of the fuel boost pump and lead to subsequent explosion of the fuel tank.

DATES: We must receive comments on this proposed AD by July 9, 2007.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

- *DOT Docket Web site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- *Government-wide rulemaking Web site:* Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- *Mail:* Docket Management Facility, U.S. Department of Transportation, 400

Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590.

- *Fax:* (202) 493-2251.

- *Hand Delivery:* Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207, for the service information identified in this proposed AD.

FOR FURTHER INFORMATION CONTACT: Judy Coyle, Aerospace Engineer, Propulsion Branch, ANM-140S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6497; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to submit any relevant written data, views, or arguments regarding this proposed AD. Send your comments to an address listed in the **ADDRESSES** section. Include the docket number "FAA-2007-28281; Directorate Identifier 2006-NM-238-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of that web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You may review DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you may visit <http://dms.dot.gov>.

Examining the Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the DOT

street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the Docket Management System receives them.

Discussion

We have received a report that, after close examination of the internal electrical circuit of the fuel boost pump, supplier tests revealed cracking in the epoxy potting compound on the feed-through connector in the area of the soldered wire connector lugs of several pumps. This condition, if not corrected, could allow a hazardous electrical path from the dry side to the wet side of the fuel boost pump through a cracked feed-through connector, which could create an ignition source on the wet side of the fuel boost pump and lead to subsequent explosion of the fuel tank.

Relevant Service Information

We have reviewed Boeing Alert Service Bulletins 767-28A0095 (for Model 767-200, -300, and -300F airplanes) and 767-28A0096 (for Model 767-400ER airplanes), both dated September 15, 2005, which describe procedures for repetitively replacing the internal electrical feed-through connectors of the main fuel tank boost pumps with new feed-through connectors. This may be accomplished by replacing the fuel boost pump with a new fuel boost pump or with a modified and re-identified fuel boost pump having a new feed-through connector installed.

The alert service bulletins refer to Hamilton Sundstrand Alert Service Bulletin 5006003-28-A4, dated May 9, 2005, as an additional source of service information for replacing the feed-through connector of the fuel boost pump.

FAA's Determination and Requirements of the Proposed AD

We have evaluated all pertinent information and identified an unsafe condition that is likely to exist or develop on other airplanes of this same type design. For this reason, we are proposing this AD, which would require accomplishing the actions specified in the Boeing service information described previously.

Interim Action

We consider this proposed AD interim action. The manufacturer is currently developing a modification that will address the unsafe condition identified in this AD. Once this modification is developed, approved, and available, we may consider additional rulemaking.

Costs of Compliance

There are about 941 airplanes of the affected design in the worldwide fleet. This proposed AD would affect about 414 airplanes of U.S. registry, at an average labor rate of \$80 per work hour.

The proposed fuel boost pump replacement would take about 3 work hours per boost pump (4 boost pumps per airplane) or up to 12 work hours per airplane, per replacement cycle. The parts cost for replacement fuel boost pumps would be offset by returning the existing fuel boost pumps to the manufacturer for rework. Based on these figures, the estimated cost of the proposed AD for U.S. operators to replace the fuel boost pumps is up to \$397,440, or up to \$960 per airplane, per replacement cycle.

If done, the proposed feed-through connector replacement would take about 3 work hours per connector (4 connectors per airplane) or up to 12 work hours per airplane, per replacement cycle. Required parts would cost \$691 per connector (up to \$2,764 per airplane). Based on these figures, the estimated cost of the proposed AD for U.S. operators to replace the feed-through connectors is up to \$1,541,736, or up to \$3,724 per airplane, per replacement cycle.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and

responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

Boeing: FAA-2007-28281; Directorate Identifier 2006-NM-238-AD.

Comments Due Date

- (a) The FAA must receive comments on this AD action by July 9, 2007.

Affected ADs

- (b) None.

Applicability

- (c) This AD applies to all Boeing Model 767-200, -300, -300F, and -400ER series airplanes, certificated in any category.

Unsafe Condition

- (d) This AD results from a report of cracking in the epoxy potting compound on the internal feed-through connector of the fuel boost pump in the area of the soldered wire connector lugs. We are issuing this AD to prevent a hazardous electrical path from the dry side to the wet side of the fuel boost pump through a cracked feed-through connector, which could create an ignition source on the wet side of the fuel boost pump and lead to subsequent explosion of the fuel tank.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Compliance Times

(f) At the later of the times specified in paragraphs (f)(1) and (f)(2) of this AD, do the actions specified in paragraph (g) of this AD, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 767-28A0095 or 767-28A0096; both dated September 15, 2005; as applicable.

(1) Within 96 months since the date of issuance of the original standard airworthiness certificate or the date of issuance of the original export certificate of airworthiness, or before the accumulation of 40,000 total flight hours, whichever comes first.

(2) Within 24 months after the effective date of this AD.

Replacement of Fuel Boost Pump Feed-Through Connector

(g) At the compliance time specified in paragraph (f) of this AD: Replace the feed-through connector of each fuel boost pump as described in paragraph (g)(1) or (g)(2) of this AD. Repeat this replacement thereafter at intervals not to exceed 40,000 flight hours or 96 months, whichever comes first.

(1) Replace the fuel boost pump with a new fuel boost pump.

(2) Replace the fuel boost pump with a modified and re-identified fuel boost pump having a new feed-through connector installed.

Note 1: Boeing Alert Service Bulletins 767-28A0095 and 767-28A0096 refer to Hamilton Sundstrand Alert Service Bulletin 5006003-28-A4, dated May 9, 2005, as a source of service information for replacing the feed-through connector and re-identifying the fuel boost pump.

Parts Installation

(h) As of the effective date of this AD, no person may install a fuel boost pump on any airplane, unless that pump meets the requirements of paragraph (g) of this AD.

Alternative Methods of Compliance (AMOCs)

(i)(1) The Manager, Seattle Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

Issued in Renton, Washington, on May 17, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate,
Aircraft Certification Service.

[FR Doc. E7-10105 Filed 5-24-07; 8:45 am]

BILLING CODE 4910-13-P

POSTAL REGULATORY COMMISSION

[Docket No. RM2007-1; Order No. 15]

39 CFR Part 3001

Administrative Practice and Procedure, Postal Service

AGENCY: Postal Regulatory Commission.

ACTION: Advance notice of proposed rulemaking.

SUMMARY: The Commission has received general comments on the development of regulations implementing new statutory provisions pertaining to market dominant and competitive postal products. It now seeks more specific comments on the same topic. The Commission anticipates using these comments as guidance for drafting proposed regulations.

DATES: Initial comments due June 18, 2007; reply comments due July 3, 2007.

ADDRESSES: Submit comments electronically via the Commission's Filing Online system at <http://www.prc.gov>.

FOR FURTHER INFORMATION CONTACT:

Stephen L. Sharfman, General Counsel,
202-789-6820 and
stephen.sharfman@prc.gov.

SUPPLEMENTARY INFORMATION:

Regulatory History

72 FR 5230 (February 5, 2007).

I. Introduction

Thirty sets of initial comments were filed in response to Order No. 2, which afforded interested persons an opportunity to comment on how the Commission can best fulfill its responsibilities under the Postal Accountability and Enhancement Act (PAEA), Public Law 109-435, 120 Stat. 3198 (December 20, 2006), regarding establishing rate regulation for market dominant products and competitive products.¹ Twenty-one sets of reply comments were also filed. The Commission appreciates those thoughtful and comprehensive comments and has found them very useful. For the most part, the comments are general in nature, taking a more global view of the type of regulations to be implemented, *e.g.*, endorsing a light-handed approach, or advocating that competitive products make the maximum possible contribution to institutional costs,² rather than

¹ PRC Order No. 2, Advance Notice of Proposed Rulemaking on Regulations Establishing a System of Ratemaking, Docket No. RM2007-1, January 30, 2007.

² *See, e.g.*, Initial Comments of the United States Postal Service, April 6, 2007, at 4-5; Comments of

suggesting specific proposals to implement the PAEA.³

In considering the regulations to be issued pursuant to sections 3622 and 3633 of the Postal Reorganization Act, as amended by the PAEA, the Commission concludes that the record would be enhanced by affording interested persons an opportunity to comment more specifically on potential ways to implement the statutory language prior to issuing proposed regulations. Therefore, the Commission is issuing this second advance notice of proposed rulemaking inviting interested persons to comment on specific issues central to implementing the necessary regulations. Interested persons are invited to comment on all (or any) of the following issues. Parties are encouraged to explain the basis for their position. The explanation need not be lengthy but should include whatever support the commenter believes to be relevant. Furthermore, although section III, below, addresses competitive products, persons primarily interested in market dominant products may wish to comment on common issues, *e.g.*, section III, item 9, concerning the term "product." Comments are due June 18, 2007. Reply comments are due July 3, 2007.

Following this round of comments, the Commission intends to issue a formal notice of proposed rulemaking setting forth specific rules applicable to rate changes for market dominant and competitive products. Interested persons will have an opportunity to comment on those proposed rules. It is the Commission's current expectation that the final rules on these topics will be issued before the end of October, 2007.

II. Regulations Concerning Market Dominant Products

1. In Appendix C of its reply comments, the Postal Service provides a series of examples to illustrate its proposal for calculations that would

Alliance of Nonprofit Mailers, National Association of Presort Mailers and National Postal Policy Council on Advance Notice of Proposed Rulemaking, April 6, 2007, at 4; Initial Comments of Time Warner Inc. in Response to Commission Order No. 2, April 6, 2007, at 9; Comments of United Parcel Service in Response to Advance Notice of Proposed Rulemaking on Regulations Establishing a System of Ratemaking, April 6, 2007, at 5.

³ Some commenters did suggest that provisions of the PAEA be defined in certain ways. *See, e.g.*, Reply Comments of the United States Postal Service, May 7, 2007, at 3-10, and Appendix C; Initial Comments of Pitney Bowes Inc. in Response to Advance Notice of Proposed Rulemaking on Regulations Establishing a System of Ratemaking, April 6, 2007, at 3-4, 17-20, 35-36; and Comments of the Parcel Shippers Association, April 6, 2007, at 24-26.