

the service information described previously.

Costs of Compliance

There are about 757 airplanes of the affected design in the worldwide fleet. This proposed AD would affect about 575 airplanes of U.S. registry. The proposed actions would take about 10 work hours per airplane, at an average labor rate of \$80 per work hour. Required parts would cost about \$400 per airplane. Based on these figures, the estimated cost of the proposed AD for U.S. operators is \$690,000, or \$1,200 per airplane.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket. See the **ADDRESSES** section

for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

Raytheon Aircraft Company (Formerly Beech); Docket No. FAA-2007-28308; Directorate Identifier 2007-NM-016-AD.

Comments Due Date

(a) The FAA must receive comments on this AD action by July 13, 2007.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Raytheon (Beech) Model 400, 400A, and 400T series airplanes, certificated in any category; as identified in Raytheon Service Bulletin SB 54-3788, dated December, 2006.

Unsafe Condition

(d) This AD results from several reports of loose attachment fasteners found on the engine cowling panels, and subsequently the panels either peeling back or separating from the airplane during flight. We are issuing this AD to prevent failure of the attachment fasteners on the engine cowling panels, which could result in separation of a panel from the airplane, and consequent damage to airplane structure. These conditions could adversely affect continued safe flight and landing of the airplane, or cause injury to people or damage to property on the ground.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Modification

(f) Within 200 flight hours after the effective date of this AD: Modify the attachment fasteners on the engine cowling panels by doing all the actions in accordance with the Accomplishment Instructions of Raytheon Service Bulletin SB 54-3788, dated December, 2006.

Alternative Methods of Compliance (AMOCs)

(g)(1) The Manager, Wichita Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Issued in Renton, Washington, on May 22, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-10216 Filed 5-25-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-28301; Directorate Identifier 2007-NM-061-AD]

RIN 2120-AA64

Airworthiness Directives; McDonnell Douglas Model MD-11, MD-11F, DC-10-10, DC-10-10F, DC-10-15, DC-10-30 and DC-10-30F (KC-10A and KDC-10), DC-10-40, DC-10-40F, MD-10-10F, and MD-10-30F Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all McDonnell Douglas Model MD-11 and MD-11F airplanes and certain Model DC-10-10, DC-10-10F, DC-10-15, DC-10-30 and DC-10-30F (KC-10A and KDC-10), DC-10-40, DC-10-40F, MD-10-10F, and MD-10-30F airplanes. This proposed AD would require rerouting system 3 hydraulic piping, installing new pipe assemblies and unions, and installing redesigned support brackets for the system 3 hydraulic piping. This proposed AD results from a report of damage to the hydraulic system that occurred when pieces of a ruptured tire from the left main landing gear penetrated the wing trailing edge access panel during takeoff. We are proposing this AD to prevent damage to the system 3 hydraulic piping, which could result in loss of the hydraulic system.

DATES: We must receive comments on this proposed AD by July 13, 2007.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

- *DOT Docket Web site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- *Government-wide rulemaking Web site:* Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- *Mail:* Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590.

- *Fax:* (202) 493-2251.

- *Hand Delivery:* Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Contact Boeing Commercial Airplanes, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, CA 90846, *Attention:* Data and Service Management, Dept. C1-L5A (D800-0024), for the service information identified in this proposed AD.

FOR FURTHER INFORMATION CONTACT: Ken Sujishi, Aerospace Engineer, Cabin Safety/Mechanical and Environmental Systems Branch, ANM-150L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; telephone (562) 627-5353; fax (562) 627-5210.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to submit any relevant written data, views, or arguments regarding this proposed AD. Send your comments to an address listed in the **ADDRESSES** section. Include the docket number "FAA-2007-28301; Directorate Identifier 2007-NM-061-AD" at the beginning of your comments. We specifically invite comments on the

overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of that Web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You may review DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you may visit <http://dms.dot.gov>.

Examining the Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the DOT street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the Docket Management System receives them.

Discussion

We have received a report of damage to the hydraulic system that occurred when pieces of a ruptured tire from the left main landing gear (MLG) penetrated the wing trailing edge access panel during takeoff. During the incident, hydraulic piping routed in the wing trailing edge was damaged, which

resulted in the loss of two of the three hydraulic systems. Boeing's analysis of the hydraulic piping for systems 1, 2, and 3, in the area above the left and right wing MLG tires, revealed the need to enhance the protection of the system 3 hydraulic pipes. Rerouting and installing thicker-walled system 3 hydraulic piping in the wing trailing edge areas will enhance the protection of the hydraulic pipes in the event of an MLG tireburst. If not corrected, damage to the system 3 hydraulic piping could result in possible loss of the hydraulic system.

Relevant Service Information

We have reviewed Boeing Alert Service Bulletin DC10-29A147, dated February 9, 2007; and Boeing Alert Service Bulletin MD11-29A068, Revision 1, dated February 9, 2007. The service bulletins describe procedures for rerouting system 3 hydraulic piping, installing new pipe assemblies and unions, and installing redesigned support brackets for the system 3 hydraulic piping. Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition.

FAA's Determination and Requirements of the Proposed AD

We have evaluated all pertinent information and identified an unsafe condition that is likely to exist or develop on other airplanes of this same type design. For this reason, we are proposing this AD, which would require accomplishing the actions specified in the service information described previously.

Costs of Compliance

There are about 430 airplanes of the affected design in the worldwide fleet. The following table provides the estimated costs for U.S. operators to comply with this proposed AD.

ESTIMATED COSTS

Work hours	Average labor rate per hour	Parts	Cost per airplane	Number of U.S.-registered airplanes	Fleet cost
60	\$80	\$14,020 to \$14,620	\$18,820 to \$19,420	260	\$4,893,200 to \$5,049,200.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII,

Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that

section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority

because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

McDonnell Douglas: Docket No. FAA-2007-28301; Directorate Identifier 2007-NM-061-AD.

Comments Due Date

- (a) The FAA must receive comments on this AD action by July 13, 2007.

Affected ADs

- (b) None.

Applicability

(c) This AD applies to the following McDonnell Douglas airplanes, certificated in any category:

- (1) All Model MD-11 and MD-11F airplanes.
- (2) DC-10-10, DC-10-10F, DC-10-15, DC-10-30 and DC-10-30F (KC-10A and KDC-10), DC-10-40, DC-10-40F, MD-10-10F, and MD-10-30F airplanes; as identified in Boeing Alert Service Bulletin DC10-29A147, dated February 9, 2007.

Unsafe Condition

(d) This AD results from a report of damage to the hydraulic system that occurred when pieces of a ruptured tire from the left main landing gear penetrated the wing trailing edge access panel during takeoff. We are issuing this AD to prevent damage to the system 3 hydraulic piping, which could result in loss of the hydraulic system.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Modification

(f) Within 24 months after the effective date of this AD, reroute system hydraulic piping, install new pipe assemblies and unions, and install redesigned support brackets for system 3 hydraulic piping. Do these actions in accordance with the Accomplishment Instructions of McDonnell Douglas Service Bulletin MD11-29A068, Revision 1, dated February 9, 2007 (for Model MD-11 and MD-11F airplanes), or McDonnell Douglas Service Bulletin DC10-29A147, dated February 9, 2007 (for Model DC-10-10, DC-10-10F, DC-10-15, DC-10-30 and DC-10-30F (KC-10A and KDC-10), DC-10-40, DC-10-40F, MD-10-10F, and MD-10-30F airplanes).

(g) Accomplishment before the effective date of this AD of the modification required by paragraph (f) of this AD in accordance with McDonnell Douglas Alert Service Bulletin MD11-29A068, dated January 23, 2007, is acceptable for compliance with the requirements of paragraph (f) of this AD.

Alternative Methods of Compliance (AMOCs)

(h)(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Issued in Renton, Washington, on May 21, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-10215 Filed 5-25-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-28300; Directorate Identifier 2006-NM-292-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A300 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

The Chromic Acid Anodising (CAA) Lead Fleet Program was established in 1989 to observe corrosion/debonding behaviour of CAA-treated panels. CAA lead fleet includes the inspection of lap joints, circumferential joints, stringers and doublers on selected aircraft.

The findings in combination with analytical corrosion investigations have been analysed by the TC (type certificate) holder and an appropriate inspection program for debonding has been developed.

This airworthiness directive requires inspection of the concerned areas to detect any corrosion and/or debonding which could affect the structural integrity. * * *

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by June 28, 2007.

ADDRESSES: You may send comments by any of the following methods:

- *DOT Docket Web Site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- *Fax:* (202) 493-2251.

- *Mail:* Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-0001.