

# Proposed Rules

Federal Register

Vol. 72, No. 116

Monday, June 18, 2007

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2007-28374; Directorate Identifier 2007-NM-067-AD]

RIN 2120-AA64

#### Airworthiness Directives; Airbus Model A300-600R Series Airplanes; and Model A310-300 Series Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

While they were gaining access to the THS (trimmable horizontal stabilizer) fuel tank for maintenance check, several operators have found one or several of the 8 THS hoist point fitting bases cracked or broken-off. The breakage resulted in metallic debris being released within the Trim Tank. The origin of the damage is most probably due to interference with the THS hoisting lugs that are stowed in the hoist point fittings in the reverse position, being screwed too deep inside the THS hoist fittings. Damaged hoist point fittings could cause the release of metallic debris within the THS fuel system.

\* \* \* Compliance with the requirements of this AD will also eliminate potential contributing factor[s] to ignition risks.

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

**DATES:** We must receive comments on this proposed AD by July 18, 2007.

**ADDRESSES:** You may send comments by any of the following methods:

- *DOT Docket Web Site:* Go to <http://dms.dot.gov> and follow the

instructions for sending your comments electronically.

- *Fax:* (202) 493-2251.
- *Mail:* Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-0001.
- *Hand Delivery:* Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.
- *Federal eRulemaking Portal:* <http://www.regulations.gov>. Follow the instructions for submitting comments.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5227) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Tom Stafford, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1622; fax (425) 227-1149.

#### SUPPLEMENTARY INFORMATION:

##### Streamlined Issuance of AD

The FAA is implementing a new process for streamlining the issuance of ADs related to MCAI. This streamlined process will allow us to adopt MCAI safety requirements in a more efficient manner and will reduce safety risks to the public. This process continues to follow all FAA AD issuance processes to meet legal, economic, Administrative Procedure Act, and **Federal Register** requirements. We also continue to meet our technical decision-making responsibilities to identify and correct unsafe conditions on U.S.-certificated products.

This proposed AD references the MCAI and related service information that we considered in forming the engineering basis to correct the unsafe condition. The proposed AD contains text copied from the MCAI and for this

reason might not follow our plain language principles.

#### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2007-28374; Directorate Identifier 2007-NM-067-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

#### Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Airworthiness Directive 2007-0024, dated January 25, 2007 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

While they were gaining access to the THS (trimmable horizontal stabilizer) fuel tank for maintenance check, several operators have found one or several of the 8 THS hoist point fitting bases cracked or broken-off. The breakage resulted in metallic debris being released within the Trim Tank. The origin of the damage is most probably due to interference with the THS hoisting lugs that are stowed in the hoist point fittings in the reverse position, being screwed too deep inside the THS hoist fittings. Damaged hoist point fittings could cause the release of metallic debris within the THS fuel system.

This Airworthiness Directive (AD) requires the repair of any damaged THS hoist point fittings to prevent any risk of further hoist point fittings damage as well as any fuel leak. Compliance with the requirements of this AD will also eliminate potential contributing factor[s] to ignition risks.

The MCAI requires an inspection of the internal base of the THS hoist point fittings for signs of score, cracks, perforation or other damage; and an inspection of the hoist point fittings base inside the fuel tank for structural damage, as applicable, and applicable

corrective actions (repair damaged fittings and install new plastic plugs). Corrective actions must be done before return to revenue service. You may obtain further information by examining the MCAI in the AD docket.

#### Relevant Service Information

Airbus has issued Service Bulletins A300–55–6041, and A310–55–2042, both dated September 13, 2006. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

#### FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

#### Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a NOTE within the proposed AD.

#### Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 137 products of U.S. registry. We also estimate that it would take about 10 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$80 per work-hour. Required parts would cost about \$332 per product. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$155,084, or \$1,132 per product.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

#### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

**Airbus:** Docket No. FAA–2007–28374; Directorate Identifier 2007–NM–067–AD.

#### Comments Due Date

- (a) We must receive comments by July 18, 2007.

#### Affected ADs

- (b) None.

#### Applicability

(c) This AD applies to Airbus Model A310–300 and A300–600R series airplanes; certificated in any category; all serial numbers fitted with a THS (trimmable horizontal stabilizer) containing fuel on which, during production Airbus Modifications 04801 and 04802 have been embodied, and Airbus Modification 06549 has not been embodied; except aircraft on which Airbus Modification 13191 has been embodied in production, or Airbus Service Bulletin A310–55–2042 or A300–55–6041 has been incorporated in service.

#### Subject

- (d) Stabilizers.

#### Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

While they were gaining access to the THS (trimmable horizontal stabilizer) fuel tank for maintenance check, several operators have found one or several of the 8 THS hoist point fitting bases cracked or broken-off. The breakage resulted in metallic debris being released within the Trim Tank. The origin of the damage is most probably due to interference with the THS hoisting lugs that are stowed in the hoist point fittings in the reverse position being screwed too deep inside the THS hoist fittings. Damaged hoist point fittings could cause the release of metallic debris within the THS fuel system.

This Airworthiness Directive (AD) requires the repair of any damaged THS hoist point fittings to prevent any risk of further hoist point fittings damage as well as any fuel leak. Compliance with the requirements of this AD will also eliminate potential contributing factor[s] to ignition risks.

The MCAI requires an inspection of the internal base of the THS hoist point fittings for signs of score, cracks, perforation or other damage; and an inspection of the hoist point fittings base inside the fuel tank for structural damage, as applicable, and applicable corrective actions (repair damaged fittings and install new plastic plugs). Corrective actions must be done before return to revenue service.

#### Actions and Compliance

(f) Unless already done, within 60 months after the effective date of this AD, do the actions specified in paragraphs (f)(1) through (f)(6) of this AD in accordance with the instructions given in Airbus Service Bulletin A300–55–6041 or A310–55–2042, both dated September 13, 2006, as applicable.

- (1) Remove the 8 THS metallic hoisting lugs.

(2) Do a detailed visual inspection of the internal base of the 8 THS hoist point fittings in order to detect visible signs of score, cracks, perforation or other damage.

(3) In case of no finding, install the new plastic plugs.

(4) In case of any finding, entry into the fuel trim tank is required to do a detailed visual inspection for structural damage of the hoist point fittings base inside the fuel tank.

(5) If structural damage is not confirmed, blend-out/protect the scoring area of the fitting internal base and install the new plastic plugs.

(6) If structural damage is confirmed, repair the damaged fittings and install the new plastic plugs.

#### FAA AD Differences

**Note:** This AD differs from the MCAI and/or service information as follows: No differences.

#### Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM-116, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Tom Stafford, Aerospace Engineer, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1622; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

#### Related Information

(h) Refer to MCAI European Aviation Safety Agency Airworthiness Directive 2007-0024, dated January 25, 2007; and Airbus Service Bulletins A300-55-6041 and A310-55-2042, both dated September 13, 2006; for related information.

Issued in Renton, Washington, on June 8, 2007.

**Stephen P. Boyd,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. E7-11677 Filed 6-15-07; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2006-24270; Directorate Identifier 2005-NM-200-AD]

RIN 2120-AA64

#### Airworthiness Directives; Boeing Model 777 Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Supplemental notice of proposed rulemaking (NPRM); reopening of comment period.

**SUMMARY:** The FAA is revising an earlier proposed airworthiness directive (AD) for all Boeing Model 777-200, -300, and -300ER series airplanes. The original NPRM would have required, for the drive mechanism of the horizontal stabilizer, repetitive detailed inspections for discrepancies; repetitive lubrication of the ballnut and ballscrew; repetitive measurements of the freeplay between the ballnut and the ballscrew; and corrective action if necessary. The original NPRM resulted from a report of extensive corrosion of a ballscrew in the drive mechanism of the horizontal stabilizer on a Boeing Model 757 airplane, which is similar in design to the ballscrew on Model 777 airplanes. This action revises the original NPRM by adding airplanes to the applicability. We are proposing this supplemental NPRM to prevent an undetected failure of the primary load path for the ballscrew in the horizontal stabilizer and subsequent wear and failure of the secondary load path, which could lead to loss of control of the horizontal stabilizer and consequent loss of control of the airplane.

**DATES:** We must receive comments on this supplemental NPRM by July 13, 2007.

**ADDRESSES:** Use one of the following addresses to submit comments on this supplemental NPRM.

- *DOT Docket Web site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- *Government-wide rulemaking Web site:* Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- *Mail:* Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590.

- *Fax:* (202) 493-2251.

- *Hand Delivery:* Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207, for the service information identified in this proposed AD.

#### FOR FURTHER INFORMATION CONTACT:

Kelly McGuckin, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6490; fax (425) 917-6590.

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

We invite you to submit any relevant written data, views, or arguments regarding this supplemental NPRM. Send your comments to an address listed in the **ADDRESSES** section. Include the docket number "FAA-2006-24270; Directorate Identifier 2005-NM-200-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this supplemental NPRM. We will consider all comments received by the closing date and may amend this supplemental NPRM in light of those comments.

We will post all comments submitted, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this supplemental NPRM. Using the search function of that Web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You may review the DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you may visit <http://dms.dot.gov>.

##### Examining the Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level in the Nassif Building at the DOT street address stated in **ADDRESSES**. Comments will be available in the AD docket shortly after the Docket Management System receives them.