

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2007-27787; Directorate Identifier 2007-CE-032-AD]

RIN 2120-AA64

Airworthiness Directives; DG Flugzeugbau GmbH Model DG-1000T Gliders**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).**ACTION:** Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

The digital engine indicating system (DEI-NT) and associated control unit must get their latest software update. It has been found out in operation, that some combinations of system states while pressing switches can cause electrical damages to the system. A new software update is mandated to correct this deficiency and to incorporate additional safety functions to the system.

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by July 30, 2007.

ADDRESSES: You may send comments by any of the following methods:

- *DOT Docket Web Site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- *Fax:* (202) 493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>; or in

person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5227) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Greg Davison, Glider Program Manager, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4130; fax: (816) 329-4090.

SUPPLEMENTARY INFORMATION:**Streamlined Issuance of AD**

The FAA is implementing a new process for streamlining the issuance of ADs related to MCAI. This streamlined process will allow us to adopt MCAI safety requirements in a more efficient manner and will reduce safety risks to the public. This process continues to follow all FAA AD issuance processes to meet legal, economic, Administrative Procedure Act, and Federal Register requirements. We also continue to meet our technical decision-making responsibilities to identify and correct unsafe conditions on U.S.-certificated products.

This proposed AD references the MCAI and related service information that we considered in forming the engineering basis to correct the unsafe condition. The proposed AD contains text copied from the MCAI and for this reason might not follow our plain language principles.

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the

ADDRESSES section. Include "Docket No. FAA-2007-27787; Directorate Identifier 2007-CE-032-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA AD No. 2007-0040, dated February 23, 2007 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

The digital engine indicating system (DEI-NT) and associated control unit must get their latest software update. It has been found out in operation, that some combinations of system states while pressing switches can cause electrical damages to the system. A new software update is mandated to correct this deficiency and to incorporate additional safety functions to the system.

As a result, the Flight and Maintenance Manuals need to be revised, specifically regarding the stall warning.

You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

DG Flugzeugbau GmbH has issued Technical Note No. 1000/09, EASA approved December 12, 2006. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Differences Between This Proposed AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are

highlighted in a NOTE within the proposed AD.

Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 1 product of U.S. registry. We also estimate that it would take about 1 work-hour per product to comply with the basic requirements of this proposed AD. The average labor rate is \$80 per work-hour.

Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$80, or \$80 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

DG Flugzeugbau GmbH: Docket No. FAA–2007–27787; Directorate Identifier 2007–CE–032–AD.

Comments Due Date

(a) We must receive comments by July 30, 2007.

Affected ADs

(b) None.

Applicability

(c) This AD applies to DG–1000T gliders, all serial numbers, certificated in any category.

Subject

(d) Air Transport Association of America (ATA) Code 77: Engine Indicating.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

The digital engine indicating system (DEI-NT) and associated control unit must get their latest software update. It has been found out in operation, that some combinations of system states while pressing switches can cause electrical damages to the system. A new software update is mandated to correct this deficiency and to incorporate additional safety functions to the system.

As a result, the Flight and Maintenance Manuals need to be revised, specifically regarding the stall warning.

Actions and Compliance

(f) Within the next 60 days after the effective day of this AD, unless already done, do the following actions:

(1) Replace the Digital Indicating System (DEI-NT) unit with an updated unit that incorporates software version V1.5, and replace the control unit with an updated unit that incorporates software version V1.9 following DG-Flugzeugbau GmbH Technical Note No. 1000/09, EASA approved December 12, 2006.

(2) Insert the new Flight Manual pages 0.1, 0.5, 7.14, and 7.15 and the new Maintenance Manual pages 0.1, 0.3, 0.6, 0.10, 1.22, and 1.23, issued October 2006 marked with TN1000/09, and add Diagram 15a into your maintenance program (maintenance manual)

following DG-Flugzeugbau GmbH Technical Note No. 1000/09, EASA approved December 12, 2006.

(3) Prior to further flight after the action required by paragraph (f)(1) of this AD, do not install a DEI-NT or control unit in any DG–1000T airplane, unless it incorporates the software versions required in this AD.

Note 1: The referenced DG-Flugzeugbau GmbH Technical Note No. 1000/09, EASA approved December 12, 2006, also includes instructions for replacement of the fuel cock, which is not required by this AD.

Note 2: As specified in the flight manual, the glider can only be operated in the non-powered configuration without the DEI-NT installed. Engine operation is not possible.

FAA AD Differences

Note 3: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Standards Staff, FAA, ATTN: Greg Davison, Glider Program Manager, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329–4130; fax: (816) 329–4090, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120–0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency (EASA) AD No. 2007–0040, dated February 23, 2007; and DG-Flugzeugbau GmbH Technical Note No. 1000/09, EASA approved December 12, 2006, for related information.

Issued in Kansas City, Missouri, on June 21, 2007.

David R. Showers,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7–12508 Filed 6–27–07; 8:45 am]

BILLING CODE 4910–13–P