

approved AMOC on any airplane to which the AMOC applies.

### Conclusion

We have carefully reviewed the available data, including the comment received, and determined that air safety and the public interest require adopting the AD with the changes described previously. We have determined that these changes will neither increase the economic burden on any operator nor increase the scope of the AD.

### Costs of Compliance

There are about 5 airplanes of the affected design in the worldwide fleet. This AD affects about 5 airplanes of U.S. registry. The required actions take about 2 work hours per airplane, at an average labor rate of \$80 per work hour. The cost of required parts is negligible. Based on these figures, the estimated cost of the AD for U.S. operators is \$800, or \$160 per airplane.

### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and

(3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

**2007-13-10 McDonnell Douglas:** Amendment 39-15114. Docket No. FAA-2007-27302; Directorate Identifier 2006-NM-273-AD.

#### Effective Date

(a) This AD becomes effective August 3, 2007.

#### Affected ADs

(b) None.

#### Applicability

(c) This AD applies to McDonnell Douglas Model DC-10-30 and DC-10-30F airplanes, certificated in any category; as identified McDonnell Douglas DC-10 Service Bulletin 24-128, dated January 19, 1984.

#### Unsafe Condition

(d) This AD results from fuel system reviews conducted by the manufacturer. We are issuing this AD to prevent the potential of ignition sources inside fuel tanks, which, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane.

#### Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

#### Modification

(f) Within 60 months after the effective date of this AD, install Teflon sleeving around the fuel pump wire harness inside the conduit in the aft supplemental fuel tank, in

accordance with the Accomplishment Instructions of McDonnell Douglas DC-10 Service Bulletin 24-128, dated January 19, 1984.

### Alternative Methods of Compliance (AMOCs)

(g)(1) The Manager, Los Angeles Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

### Material Incorporated by Reference

(h) You must use McDonnell Douglas DC-10 Service Bulletin 24-128, dated January 19, 1984, to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of this document in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Boeing Commercial Airplanes, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024), for a copy of this service information. You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on June 13, 2007.

**Ali Bahrami,**

*Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. E7-11932 Filed 6-28-07; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2007-27723 Directorate Identifier 2007-CE-029-AD; Amendment 39-15116; AD 2007-13-12]

RIN 2120-AA64

### Airworthiness Directives; PIAGGIO AERO INDUSTRIES S.p.A. Model P-180 Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

EASA EAD 2006-0072-E was issued on 31st March 2006 following a further failure of the forward support of the Main Wing Outboard Flap (MWOFF), caused by corrosion. This condition, if not corrected, may cause surface twisting during deployment at landing. The analysis of that event highlighted the need for the reduction of the previous inspection interval which was mandated by ENAC through AD 2004-523, approved by EASA with reference 2004-12521.

We are issuing this AD to require actions to correct the unsafe condition on these products.

**DATES:** This AD becomes effective August 3, 2007.

On August 3, 2007, the Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD.

**ADDRESSES:** You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the U.S. Department of Transportation, Docket Operations, M-30 West Building Ground Floor, Room W12-140, New Jersey Avenue, SE., Washington, DC.

**FOR FURTHER INFORMATION CONTACT:** Sarjapur Nagarajan, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4145; fax: (816) 329-4090.

**SUPPLEMENTARY INFORMATION:**

**Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on April 24, 2007 (72 FR 20298). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states that:

EASA EAD 2006-0072-E was issued on 31st March 2006 following a further failure of the forward support of the Main Wing Outboard Flap (MWOFF), caused by corrosion. This condition, if not corrected, may cause surface twisting during deployment at landing. The analysis of that event highlighted the need for the reduction of the previous inspection interval which was mandated by ENAC through AD 2004-523, approved by EASA with reference 2004-12521.

Now the TC holder has developed a new type of forward support for the Main Wing

Outboard Flap with characteristics that improve the resistance to corrosion. When the new support is installed, the repetitive Eddy current inspection that was introduced by EASA EAD 2006-0072-E is no longer required.

**Comments**

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

**Conclusion**

We reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

**Differences Between This AD and the MCAI or Service Information**

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have required different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a **Note** within the AD.

**Costs of Compliance**

We estimate that this AD will affect 7 products of U.S. registry. We also estimate that it will take about 16 work-hours per product to comply with basic requirements of this AD. The average labor rate is \$80 per work-hour.

Based on these figures, we estimate the cost of this AD to the U.S. operators to be \$8,960 or \$1,280 per product.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority

because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD Docket.

**Examining the AD Docket**

You may examine the AD docket on the Internet at <http://dms.dot.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**Adoption of the Amendment**

- Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

- 2. The FAA amends § 39.13 by adding the following new AD:

**2007-13-12 Piaggio Aero Industries S.p.A.:**  
Amendment 39-15116; Docket No.

FAA-2007-27723; Directorate Identifier 2007-CE-029-AD.

#### Effective Date

(a) This airworthiness directive (AD) becomes effective August 3, 2007.

#### Affected ADs

(b) None.

#### Applicability

(c) This AD applies to Model P-180 airplanes, serial numbers 1002, 1004 through 1107, 1109, and 1110, certificated in any category.

#### Subject

(d) Air Transport Association of America (ATA) Code 57: Wings.

#### Reason

(e) The mandatory continuing airworthiness information (MCAI) states: EASA EAD 2006-0072-E was issued on 31st March 2006 following a further failure of the forward support of the Main Wing Outboard Flap (MWOFF), caused by corrosion. This condition, if not corrected, may cause surface twisting during deployment at landing. The analysis of that event highlighted the need for the reduction of the previous inspection interval which was mandated by ENAC through AD 2004-523, approved by EASA with reference 2004-12521.

Now the TC holder has developed a new type of forward support for the Main Wing Outboard Flap with characteristics that improve the resistance to corrosion. When the new support is installed, the repetitive Eddy current inspection that was introduced by EASA EAD 2006-0072-E is no longer required.

#### Actions and Compliance

(f) Unless already done, do the following actions:

(1) Within the next 200 hours time-in-service (TIS) after August 3, 2007 (the effective date of this AD) or within 60 days after August 3, 2007 (the effective date of this AD), whichever occurs first, replace the outboard flap track forward bushing and the outboard flap track forward support. Do the replacements using the Accomplishment Instructions detailed in Part A of Piaggio Aero Industries S.p.A. Mandatory Service Bulletin (SB) No. 80-0210, Rev 4, dated July 19, 2006.

(2) At intervals not to exceed 1,500 hours TIS after doing the replacements required in paragraph (f)(1) of this AD, visually inspect the outboard flap track forward support for traces of any kind of corrosion and/or protective coat/finishing wear damage. Do the inspections using the Accomplishment Instructions detailed in Part B of Piaggio Aero Industries S.p.A. Mandatory SB No. 80-0210, Rev 4, dated July 19, 2006.

(3) Before further flight after each inspection required in paragraph (f)(2) of this AD in which any kind of corrosion or wear damage is found, contact the manufacturer for a repair scheme and incorporate the repair.

#### FAA AD Differences

**Note:** This AD differs from the MCAI and/or service information as follows: No differences.

#### Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Staff, FAA, Small Airplane Directorate, ATTN: Sarjapur Nagarajan, Aerospace Engineer, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4145; fax: (816) 329-4090, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

#### Related Information

(h) Refer to MCAI European Aviation Safety Agency (EASA) AD No. 2006-0305, dated October 9, 2006; and Piaggio Aero Industries S.p.A. Mandatory Service Bulletin No. 80-0210, Rev 4, dated July 19, 2006, for related information.

#### Material Incorporated by Reference

(i) You must use Piaggio Aero Industries S.p.A. Mandatory Service Bulletin No. 80-0210, Rev 4, dated July 19, 2006, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact PIAGGIO AERO INDUSTRIES S.p.A. Via Cibrario 4, 16154 Genoa, Italy; telephone: +39 010 6481 856; facsimile: +39 010 6481 374.

(3) You may review copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on June 15, 2007.

**Kim Smith,**

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-12008 Filed 6-28-07; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2007-27508; Directorate Identifier 2006-NM-252-AD; Amendment 39-15117; AD 2007-13-13]

RIN 2120-AA64

#### Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (EMBRAER) ERJ 170 Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) issued by an airworthiness authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as an obstruction at the cargo compartment fire extinguisher system drier metering unit (DMU) inlet, affecting the system effectiveness and, consequently, making the fire extinguishing capability at those compartments inadequate should a fire erupt. We are issuing this AD to require actions to correct the unsafe condition on these products.

**DATES:** This AD becomes effective August 3, 2007.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of August 3, 2007.

**ADDRESSES:** You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC.

**FOR FURTHER INFORMATION CONTACT:** Todd Thompson, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1175; fax (425) 227-1149.