

APPENDIX 1.—IMPLEMENTING FUEL TANK SYSTEM AIRWORTHINESS LIMITATIONS ON MODEL 747-400, -400D, AND -400F SERIES AIRPLANES—Continued

AWL No.	ALI/CDCCL	ATA section or CMM document	Task title	Task No.
28-AWL-20	CDCCL	AMM 28-22-07/401	CMCS Message MAIN TK 3 FWD OVERRIDE/JETTISON PUMP SYSTEM FAIL—Fault Isolation. Front Spar Bulkhead Fitting—Installation.	28-31 Task 831. 28-22-07-400-805-001. 28-22-07-400-806-002. 28-22-07-400-807-003. 28-22-07-400-808-004.
28-AWL-21	ALI	AMM 28-22-00/501. AMM 28-17-00/501.		
28-AWL-22	CDCCL	AMM 28-22-03/401	Main Tank Boost Pump Motor/Impeller Unit Installation.	28-22-03-404-019-001. 28-22-03-404-026-002.
28-AWL-23	CDCCL	AMM 28-41-24/401.		
47-AWL-01	CDCCL	AMM 47-21-06/401	Flame Arrestor Installation	47-21-06-400-801.
47-AWL-02	CDCCL			
47-AWL-03	ALI	AMM 47-00-01/501	Functional Test of the Nitrogen Generation System.	47-00-01-720-801.
47-AWL-04	ALI	AMM 47-43-02/501	Thermal Switch Functional Test. Thermal Switch Operational Test.	47-43-02-700-801. 47-43-02-700-802.
47-AWL-05	ALI	AMM 47.		
47-AWL-06	ALI	AMM 47.		

Issued in Renton, Washington, on June 22, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate,
Aircraft Certification Service.

[FR Doc. E7-12816 Filed 7-2-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-28388; Directorate Identifier 2006-NM-163-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 767-200, -300, -300F, and -400ER Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Boeing Model 767-200, -300, -300F, and -400ER series airplanes. This proposed AD would require revising the FAA-approved maintenance program to incorporate new airworthiness limitations (AWLs) for fuel tank systems to satisfy Special

Federal Aviation Regulation No. 88 requirements. This proposed AD would also require the initial inspection of certain repetitive AWL inspections to phase in those inspections, and repair if necessary. This proposed AD results from a design review of the fuel tank systems. We are proposing this AD to prevent the potential for ignition sources inside fuel tanks caused by latent failures, alterations, repairs, or maintenance actions, which, in combination with flammable fuel vapors, could result in a fuel tank explosion and consequent loss of the airplane.

DATES: We must receive comments on this proposed AD by August 17, 2007.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

- *DOT Docket Web site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- *Government-wide rulemaking Web site:* Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Fax:* (202) 493-2251.

- *Hand Delivery:* Room W12-140 on the ground floor of the West Building,

1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207, for the service information identified in this proposed AD.

FOR FURTHER INFORMATION CONTACT: Kathrine Rask, Aerospace Engineer, Propulsion Branch, ANM-140S, FAA, Seattle Aircraft Certification Office, 1601 Lind Ave SW., Renton, Washington 98057-3356; telephone (425) 917-6505; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to submit any relevant written data, views, or arguments regarding this proposed AD. Send your comments to an address listed in the **ADDRESSES** section. Include the docket number "FAA-2007-28388; Directorate Identifier 2006-NM-163-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal

information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of that Web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You may review DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you may visit <http://dms.dot.gov>.

Examining the Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Operations office (telephone (800) 647-5527) is located on the ground floor of the West Building at the DOT street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the Docket Management System receives them.

Discussion

The FAA has examined the underlying safety issues involved in fuel tank explosions on several large transport airplanes, including the adequacy of existing regulations, the service history of airplanes subject to those regulations, and existing maintenance practices for fuel tank systems. As a result of those findings, we issued a regulation titled "Transport Airplane Fuel Tank System Design Review, Flammability Reduction and Maintenance and Inspection Requirements" (67 FR 23086, May 7, 2001). In addition to new airworthiness standards for transport airplanes and new maintenance requirements, this rule included Special Federal Aviation Regulation No. 88 ("SFAR 88," Amendment 21-78, and subsequent Amendments 21-82 and 21-83).

Among other actions, SFAR 88 requires certain type design (i.e., type certificate (TC) and supplemental type certificate (STC)) holders to substantiate that their fuel tank systems can prevent ignition sources in the fuel tanks. This requirement applies to type design holders for large turbine-powered transport airplanes and for subsequent modifications to those airplanes. It requires them to perform design reviews and to develop design changes and maintenance procedures if their designs do not meet the new fuel tank safety standards. As explained in the preamble

to the rule, we intended to adopt airworthiness directives to mandate any changes found necessary to address unsafe conditions identified as a result of these reviews.

In evaluating these design reviews, we have established four criteria intended to define the unsafe conditions associated with fuel tank systems that require corrective action. The percentage of operating time during which fuel tanks are exposed to flammable conditions is one of these criteria. The other three criteria address the failure types under evaluation: Single failures, single failures in combination with another latent condition(s), and in-service failure experience. For all four criteria, the evaluations included consideration of previous actions taken that may mitigate the need for further action.

We have determined that the actions identified in this proposed AD are necessary to reduce the potential of ignition sources inside fuel tanks, which, in combination with flammable fuel vapors, could result in a fuel tank explosion and consequent loss of the airplane.

Relevant Service Information

We have reviewed Subsection D, "AIRWORTHINESS LIMITATIONS—SYSTEMS," of Boeing 767 Maintenance Planning Data (MPD) Document, D622T001-9, Section 9, Revision March 2006 (hereafter referred to as "Revision March 2006 of the MPD"). Subsection D of Revision March 2006 of the MPD describes new airworthiness limitations (AWLs) for fuel tank systems. The new AWLs include:

- AWL inspections, which are periodic inspections of certain features for latent failures that could contribute to an ignition source; and
- Critical design configuration control limitations (CDCCLs), which are limitation requirements to preserve a critical ignition source prevention feature of the fuel tank system design that is necessary to prevent the occurrence of an unsafe condition. The purpose of a CDCCL is to provide instruction to retain the critical ignition source prevention feature during configuration change that may be caused by alterations, repairs, or maintenance actions. A CDCCL is not a periodic inspection.

Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition.

FAA's Determination and Requirements of the Proposed AD

We have evaluated all pertinent information and identified an unsafe condition that is likely to exist or develop on other airplanes of this same type design. For this reason, we are proposing this AD, which would require revising the FAA-approved maintenance program to incorporate the information in Subsection D of Revision March 2006 of the MPD. This proposed AD would also require the initial inspection of certain repetitive AWL inspections to phase in those inspections, and repair if necessary.

Explanation of Compliance Time

In most ADs, we adopt a compliance time allowing a specified amount of time after the AD's effective date. In this case, however, the FAA has already issued regulations that require operators to revise their maintenance/inspection programs to address fuel tank safety issues. The compliance date for these regulations is December 16, 2008. To provide for efficient and coordinated implementation of these regulations and this proposed AD, we are using this same compliance date in this proposed AD, instead of the 18-month compliance time recommended by Boeing.

Rework Required When Implementing AWLs Into an Existing Fleet

The maintenance program revision for the fuel tank systems specified in paragraph (g) of this proposed AD, which involves incorporating the information specified in Revision March 2006 of the MPD, would affect how operators maintain their airplanes. After doing that maintenance program revision, operators would need to do any maintenance on the fuel tank system as specified in the CDCCLs. Maintenance done before the maintenance program revision specified in paragraph (g) would not need to be redone in order to comply with paragraph (g). For example, the AWL that requires fuel pumps to be repaired and overhauled per an FAA-approved component maintenance manual (CMM) applies to fuel pumps repaired after the maintenance programs are revised; spare or on-wing fuel pumps do not need to be reworked. For AWLs that require repetitive inspections, the initial inspection interval (threshold) starts from the date the maintenance program revision specified in paragraph (g) is done, except as provided by paragraph (h) of this proposed AD. This proposed AD would require only the maintenance program revision specified in paragraph (g), and initial inspections specified in

paragraph (h). No other fleet-wide inspections need to be done.

Changes to Fuel Tank System AWLs

Paragraph (g) of this proposed AD would require revising the FAA-approved maintenance program by incorporating certain information specified in Revision March 2006 of the MPD. Paragraph (g) allows accomplishing the maintenance program revision in accordance with later revisions of the MPD as an acceptable method of compliance if they are approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA. Paragraph (h) allows accomplishing the initial inspections and repair in accordance with later revisions of the MPD as an acceptable method of compliance if they are approved by the Manager, Seattle ACO. In addition, Subsection D of Revision March 2006 of the MPD specifies that any deviations from the published AWL instructions, including AWL intervals, in that MPD must be approved by the Manager, Seattle ACO. Therefore, after the maintenance program revision, any further revision to an AWL or AWL interval should be done as an AWL change, not as an alternative method of compliance (AMOC). For U.S.-registered airplanes, operators must make requests through an appropriate FAA Principal Maintenance Inspector (PMI) or Principal Avionics Inspector (PAI) for approval by the Manager, Seattle ACO. A non-U.S. operator should coordinate changes with its governing regulatory agency.

Exceptional Short-Term Extensions

Subsection D of Revision March 2006 of the MPD has provisions for an exceptional short-term extension of 30 days. An exceptional short-term extension is an increase in an AWL interval that may be needed to cover an uncontrollable or unexpected situation. For U.S.-registered airplanes, the FAA PMI or PAI must concur with any exceptional short-term extension before it is used, unless the operator has identified another appropriate procedure with the local regulatory

authority. The FAA PMI or PAI may grant the exceptional short-term extensions described in Subsection D without consultation with the Manager, Seattle ACO. A non-U.S. operator should coordinate changes with its governing regulatory agency. As explained in Revision March 2006 of the MPD, exceptional short-term extensions must not be used for fleet AWL extensions. An exceptional short-term extension should not be confused with an operator's short-term escalation authorization approved in accordance with the Operations Specifications or the operator's reliability program.

Ensuring Compliance With Fuel Tank System AWLs

Boeing has revised applicable maintenance manuals and task cards to address AWLs and to include notes about CDCCLs. Operators that do not use Boeing's revision service should revise their maintenance manuals and task cards to highlight actions tied to CDCCLs to ensure that maintenance personnel are complying with the CDCCLs. Appendix 1 of this proposed AD contains a list of Air Transport Association (ATA) sections for the revised maintenance manuals. Operators might wish to use the appendix as an aid to implement the AWLs.

Recording Compliance With Fuel Tank System AWLs

The applicable operating rules of the Federal Aviation Regulations (14 CFR parts 91, 121, 125, and 129) require operators to maintain records with the identification of the current inspection status of an airplane. Some of the AWLs contained in Subsection D of Revision March 2006 of the MPD are inspections for which the applicable sections of the operating rules apply. Other AWLs are CDCCLs, which are tied to conditional maintenance actions. An entry into an operator's existing maintenance record system for corrective action is sufficient for recording compliance with CDCCLs, as long as the applicable maintenance manual and task cards identify actions that are CDCCLs.

Changes to CMMs Cited in Fuel Tank System AWLs

Some of the AWLs in Subsection D of Revision March 2006 of the MPD refer to specific revision levels of the CMMs as additional sources of service information for doing the AWLs. Boeing is referring to the CMMs by revision level in the applicable AWL for certain components rather than including information directly in the MPD because of the volume of that information. As a result, the Manager, Seattle ACO, must approve the CMMs. Any later revision of those CMMs will be handled like a change to the AWL itself. Any use of parts (including the use of parts manufacturer approval (PMA) approved parts), methods, techniques, and practices not contained in the CMMs need to be approved by the Manager, Seattle ACO, or governing regulatory authority. For example, certain pump repair/overhaul manuals must be approved by the Manager, Seattle ACO.

Changes to AMMs Referenced in Fuel Tank System AWLs

In other AWLs in Subsection D of Revision March 2006 of the MPD, the AWLs contain all the necessary data. The applicable section of the maintenance manual is usually included in the AWLs. Boeing intended this information to assist operators in maintaining the maintenance manuals. A maintenance manual change to these tasks may be made without approval by the Manager, Seattle ACO, through an appropriate FAA PMI or PAI, by the governing regulatory authority, or by using the operator's standard process for revising maintenance manuals. An acceptable change would have to maintain the information specified in the AWL such as the pass/fail criteria or special test equipment.

Costs of Compliance

There are about 824 airplanes of the affected design in the worldwide fleet. The following table provides the estimated costs, at an average labor rate of \$80 per hour, for U.S. operators to comply with this proposed AD.

ESTIMATED COSTS

Action	Work hours	Parts	Cost per airplane	Number of U.S.-registered airplanes	Fleet cost
Maintenance program revision	8	None	\$640	332	\$212,480
Inspections	8	None	640	332	212,480

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator,

the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

Boeing: Docket No. FAA-2007-28388; Directorate Identifier 2006-NM-163-AD.

Comments Due Date

(a) The FAA must receive comments on this AD action by August 17, 2007.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Boeing Model 767-200, -300, -300F, and -400ER series airplanes, certificated in any category; with an original standard airworthiness certificate or original export certificate of airworthiness issued before April 22, 2006.

Note 1: Airplanes with an original standard airworthiness certificate or original export certificate of airworthiness issued on or after April 22, 2006, must already be in compliance with the airworthiness limitations specified in this AD because those limitations were applicable as part of the airworthiness certification of those airplanes.

Note 2: This AD requires revisions to certain operator maintenance documents to include new inspections and maintenance actions. Compliance with these limitations is required by 14 CFR 43.16 and 91.403(c). For airplanes that have been previously modified, altered, or repaired in the areas addressed by these limitations, the operator may not be able to accomplish the actions described in the revisions. In this situation, to comply with 14 CFR 43.16 and 91.403(c), the operator must request approval for revision to the airworthiness limitations (AWLs) in the Boeing 767 Maintenance Planning Data (MPD) Document, D622T001-9, according to paragraph (g) or (i) of this AD, as applicable.

Unsafe Condition

(d) This AD results from a design review of the fuel tank systems. We are issuing this AD to prevent the potential for ignition sources inside fuel tanks caused by latent failures, alterations, repairs, or maintenance actions, which, in combination with

flammable fuel vapors, could result in a fuel tank explosion and consequent loss of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Service Information Reference

(f) The term "Revision March 2006 of the MPD" as used in this AD, means Boeing 767 Maintenance Planning Data (MPD) Document, D622T001-9, Section 9, Revision March 2006.

Maintenance Program Revision

(g) Before December 16, 2008, revise the FAA-approved maintenance program by incorporating the information in Subsection D, "AIRWORTHINESS LIMITATIONS—SYSTEMS," of Revision March 2006 of the MPD; except that the initial inspections specified in Table 1 of this AD must be done at the compliance times specified in Table 1. Accomplishing the revision in accordance with a later revision of the MPD is an acceptable method of compliance if the revision is approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA.

Initial Inspections and Repair if Necessary

(h) Do the inspections specified in Table 1 of this AD and repair any discrepancy, in accordance with Subsection D, "AIRWORTHINESS LIMITATIONS—SYSTEMS," of Revision March 2006 of the MPD. The repair must be done before further flight. Accomplishing the actions required by this paragraph in accordance with a later revision of the MPD is an acceptable method of compliance if the revision is approved by the Manager, Seattle ACO.

Note 3: For the purposes of this AD, a detailed inspection is: "An intensive examination of a specific item, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at an intensity deemed appropriate. Inspection aids such as mirror, magnifying lenses, etc., may be necessary. Surface cleaning and elaborate procedures may be required."

Note 4: For the purposes of this AD, a special detailed inspection is: "An intensive examination of a specific item, installation, or assembly to detect damage, failure, or irregularity. The examination is likely to make extensive use of specialized inspection techniques and/or equipment. Intricate cleaning and substantial access or disassembly procedure may be required."

TABLE 1.—INITIAL INSPECTIONS

AWL No.	Description	Compliance time (whichever occurs later)	
		Threshold	Grace period
28-AWL-01	A detailed inspection of external wires over the center fuel tank for damaged clamps, wire chafing, and wire bundles in contact with the surface of the center fuel tank.	Before the accumulation of 36,000 total flight cycles, or within 144 months since the date of issuance of the original standard airworthiness certificate or the date of issuance of the original export certificate of airworthiness, whichever occurs first.	Within 72 months after the effective date of this AD.
8-AWL-05	A special detailed inspection of the bulkhead fitting bond for the hydraulic line tank penetration.	Before the accumulation of 25,000 total flight cycles, or within 72 months since the date of issuance of the original standard airworthiness certificate or the date of issuance of the original export certificate of airworthiness, whichever occurs first.	Within 60 months after the effective date of this AD.
8-AWL-18	A special detailed inspection of the lightning shield to ground termination on the out-of-tank fuel quantity indicating system to verify functional integrity.	Before the accumulation of 36,000 total flight cycles, or within 144 months since the date of issuance of the original standard airworthiness certificate or the date of issuance of the original export certificate of airworthiness, whichever occurs first.	Within 24 months after the effective date of this AD.
8-AWL-26	A special detailed inspection of the lightning shield to ground termination on the out-of-tank surge tank fuel level sensor to verify functional integrity.	Before the accumulation of 36,000 total flight cycles, or within 144 months since the date of issuance of the original standard airworthiness certificate or the date of issuance of the original export certificate of airworthiness, whichever occurs first.	Within 24 months after the effective date of this AD.

Alternative Methods of Compliance (AMOCs)

(i)(1) The Manager, Seattle ACO, FAA, has the authority to approve AMOCs for this AD,

if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on

any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

APPENDIX 1.—IMPLEMENTING FUEL TANK SYSTEM AIRWORTHINESS LIMITATIONS ON MODEL 767-200, -300, -300F, AND -400ER SERIES AIRPLANES

AWL No.	ALI/CDCCL	ATA section or CMM document	Task title	Task No.
28-AWL-01	ALI	AMM 28-11-00/601	External Wires Over the Center Tank Inspection.	28-11-00-206-258.
28-AWL-02	CDCCL	SWPM 20-10-11	Wiring Assembly and Installation Configuration.	
28-AWL-03	CDCCL	AMM 28-22-07/401	Install the Fuel Lines and Fittings.	Varies with configuration.
28-AWL-04	CDCCL	AMM 29-11-27/401	Install the Heat Exchanger	29-11-27-424-015.
28-AWL-05	ALI	AMM 29-11-27/601	Bonding Resistance Check of the Heat Exchanger Lines.	29-11-27-026-001.
28-AWL-06	CDCCL	CMM 28-22-01, Revision 12; CMM 28-22-12, Revision 16; CMM 28-22-21, Revision 7; or subsequent revisions.		
28-AWL-07	CDCCL	AMM 28-22-03/401	Install the Housing of the Fuel Boost Pump.	28-22-03-404-027.
		AMM 28-22-05/401	Install the Housing of the Override (or Override/jettison) Pump.	Varies with configuration.
28-AWL-08	CDCCL			
28-AWL-09	CDCCL	SWPM 20-10-11	Wiring Assembly and Installation Configuration.	
28-AWL-10	CDCCL	AMM 28-21-02/401	Install the Fueling Shutoff Valve.	28-21-02-404-021.
		AMM 28-21-12/401	Install the Control Unit of the Fueling Shutoff Valve.	28-21-12-404-021.
28-AWL-11	CDCCL	CMM 28-41-68, Revision 4 or subsequent revisions.		

APPENDIX 1.—IMPLEMENTING FUEL TANK SYSTEM AIRWORTHINESS LIMITATIONS ON MODEL 767–200, –300, –300F, AND –400ER SERIES AIRPLANES—Continued

AWL No.	ALI/CDCCL	ATA section or CMM document	Task title	Task No.
28-AWL-12	CDCCL	CMM 28-40-56, Revision 4; CMM 28-40-59, Revision 4; CMM 28-40-62, Revision 3; CMM 28-41-68, Revision 4; CMM 28-41-01, Revision 5; CMM 28-41-07, Revision 4; CMM 28-41-09, Revision 6; CMM 28-41-30, Revision 1; CMM 28-41-33, Revision 2; CMM 28-41-34, Revision 1; CMM 28-41-35, Revision 1; CMM 28-41-36, Revision 7; CMM 28-41-39, Revision 7; CMM 28-41-41, Revision 5; CMM 28-41-42, Revision 0; or subsequent revisions.		
28-AWL-13	CDCCL	SWPM 20-14-12	Repair of Fuel Quantity Indicator System (FQIS) Wire Harness.	
		AMM 28-41-09/401	Install the Tank Wiring Harness.	Varies with configuration.
28-AWL-14	CDCCL	AMM 28-11-01/401	Install the Main Tank Access Door.	28-11-01-404-005.
		AMM 28-11-02/401	Install the Auxiliary Tank Access Door.	28-11-02-404-013.
		AMM 28-11-03/401	Install the Surge Tank Access Door.	28-11-03-404-011.
28-AWL-15	CDCCL	CMM 28-21-01, Revision 1 or subsequent revisions.		
28-AWL-16	CDCCL	SWPM 20-14-12	Repair of Fuel Quantity Indicator System (FQIS) Wire Harness.	
		AMM 28-21-11/401	Surge Tank Sensor Harness Installation.	28-21-11-424-032.
28-AWL-17	CDCCL	FIM 28-22-00/101.		
28-AWL-18	ALI	AMM 20-55-54/601	FQIS Wiring and Bonding Inspection/Check.	20-55-54-206-002.
28-AWL-19	CDCCL	SWPM 20-10-15	Assembly of Shield Ground Wires.	
28-AWL-20	ALI	AMM 28-22-00/501	Override Pump Auto Shutoff Functional Test.	28-22-00-725-529.
28-AWL-21				
28-AWL-22	CDCCL	AMM 28-41-24/401	Densitometer Hot Short Protector Installation.	28-41-24-404-017.
28-AWL-23	CDCCL	AMM 28-22-01/401	Install the Adapter Shaft of the Engine Fuel Shutoff Valve.	28-22-01-404-030.
		AMM 28-22-02/401	Install the Adapter Shaft of the Engine Crossfeed Valve.	28-22-02-404-023.
		AMM 28-22-11/401	Install the Actuator of the Engine Fuel Shutoff Valve.	28-22-11-404-008.
		AMM 28-22-12/401	Install the Actuator of the Engine Fuel Crossfeed Valve.	28-22-12-404-010.
		AMM 28-26-01/401	Install the Adapter Shaft of the Defueling Valve.	28-26-01-404-059.
		AMM 28-26-02/401	Install the Defueling Valve Actuator.	28-26-11-404-020.
28-AWL-24	CDCCL	CMM 28-20-21.		
28-AWL-25	CDCCL	SWPM 20-10-15	Assembly of Shield Ground Wires.	
28-AWL-26	ALI	AMM 20-55-54/601.		

Issued in Renton, Washington, on June 22, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate,
Aircraft Certification Service.

[FR Doc. E7-12817 Filed 7-2-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2007-28235; Airspace
Docket No. 07-ANM-9]

Proposed Establishment of Class E Airspace; Hulett, WY

AGENCY: Federal Aviation
Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This action proposes to establish Class E airspace at Hulett, WY. Additional controlled airspace is necessary to accommodate aircraft using a new Area Navigation (RNAV) Global Positioning System (GPS) Instrument Approach Procedure (IAP) at Hulett Municipal Airport. The FAA is proposing this action to enhance the safety and management of aircraft operations at Hulett Municipal Airport, Hulett, WY.

DATES: Comments must be received on or before August 17, 2007.

ADDRESSES: Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room @12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590. Telephone (202) 366-9826. You must identify FAA Docket No. FAA-2007-28235; Airspace Docket No. 07-ANM-9, at the beginning of your comments. You may also submit comments through the Internet at <http://dms.dot.gov>.

FOR FURTHER INFORMATION CONTACT: Ed Haeseker, Federal Aviation Administration, Western Service Area Office, System Support Group, 1601 Lind Avenue, SW., Renton, WA 98057; telephone (425) 917-6714.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments

are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers (FAA Docket No. FAA-2007-28235 and Airspace Docket No. 07-ANM-9) and be submitted in triplicate to Docket Operations (see “ADDRESSES” section for address and phone number). You may also submit comments through the Internet at <http://dms.dot.gov>.

Commenters wishing the FAA to acknowledge receipt of their comments on this action must submit with those comments a self-addressed stamped postcard on which the following statement is made: “Comments to FAA Docket No. FAA-2007-28235 and Airspace Docket No. 07-ANM-9”. The postcard will be date/time stamped and returned to the commenter.

All communications received on or before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this action may be changed in light of comments received. All comments submitted will be available for examination in the public docket both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRM's

An electronic copy of this document may be downloaded through the Internet at <http://dms.dot.gov>. Recently published rulemaking documents can also be accessed through the FAA's web page at <http://www.faa.gov> or the **Federal Register's** web page at <http://www.gpoaccess.gov/fr/index.html>.

You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office (see the “ADDRESSES” section for the address and phone number) between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. An informal docket may also be examined during normal business hours at the Northwest Mountain Regional Office of the Federal Aviation Administration, Air Traffic Organization, Western Service Area, System Support Group, 1601 Lind Avenue, SW., Renton, WA 98057.

Persons interested in being placed on a mailing list for future NPRM's should contact the FAA's Office of Rulemaking, (202) 267-9677, for a copy of Advisory Circular No. 11-2A, Notice of Proposed Rulemaking Distribution System, which describes the application procedure.

The Proposal

The FAA is proposing an amendment to Title 14 Code of Federal Regulations (14 CFR) part 71 by establishing Class E airspace at Hulett, WY. Controlled airspace is necessary to accommodate aircraft using the new RNAV (GPS) IAP at Hulett Municipal Airport. This action would enhance the safety and management of aircraft operations at Hulett Municipal Airport, Hulett, WY.

Class E airspace designations are published in paragraph 6005 of FAA Order 7400.9P, dated September 1, 2006, and effective September 15, 2006, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document will be published subsequently in this Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this proposed regulation: (1) Is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this proposed rule, when promulgated, would not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

1. The authority citation for 14 CFR part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

§ 71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of the FAA Order 7400.9P, Airspace Designations and Reporting