

A non-respect of the pilot door adjustment procedure could have damaged the stop fitting and could result in a consequent depressurization of the airplane.

This AD requires you to inspect the pilot door locking stop fittings for correct length and replace any incorrect length pilot door locking stop fittings found.

Requirements Retained From AD 2007-04-08

(f) Unless already done, inspect the pilot door locking stop-fittings for correct length within 30 days after March 23, 2007 (the effective date of AD 2007-04-08). Do the inspection following EADS SOCATA TBM Aircraft Mandatory Service Bulletin SB 70-131, dated July 2005, or EADS SOCATA TBM Aircraft Mandatory Service Bulletin SB 70-131, Amendment 1, dated June 2007.

New Requirements of This AD: Actions and Compliance

(g) Do the following actions, unless already done:

(1) Any incorrect length pilot door locking stop-fittings replaced following the inspection required in paragraph (f) of this AD in accordance with AD 2007-04-08, using the original issue of EADS SOCATA TBM Aircraft Mandatory Service Bulletin SB 70-131, dated July 2005, must be replaced again within the next 12 months after the effective date of this AD. Do the replacement using EADS SOCATA TBM Aircraft Mandatory Service Bulletin SB 70-131, Amendment 1, dated June 2007.

(2) Any incorrect length pilot door locking stop-fittings found during the inspection required in paragraph (f) of this AD and not previously replaced in accordance with AD 2007-04-08, must be replaced before further flight. Do the replacement using EADS SOCATA TBM Aircraft Mandatory Service Bulletin SB 70-131, Amendment 1, dated June 2007.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(h) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Albert Mercado, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4119; fax: (816) 329-4090. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State

of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 et seq.), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Special Flight Permit

(i) If you have ordered parts and they are not available, then you may fly unpressurized until parts become available or for a period not to exceed 90 days after the inspection required in paragraph (f) of this AD, whichever occurs first. You must also fabricate and install a placard as described below. Completing the action of paragraph (g)(2) of this AD terminates the placard requirement.

(1) Fabricate (using letters at least 1/8 inch in height) a warning placard that states "This airplane is prohibited from pressurized flight."

(2) Install the placard in full view of the pilot. The owner/operator holding at least a private pilot certificate as authorized by section 43.7 of the Federal Aviation Regulations (14 CFR 43.7) may install the placard as required in paragraph (h) of this AD.

Related Information

(j) Refer to MCAI Direction generale de l'aviation civile (DGAC) AD No. F-2007-016, October 10, 2007; and EADS SOCATA TBM Aircraft Mandatory Service Bulletin SB 70-131, Amendment 1, dated June 2007, for related information.

Issued in Kansas City, Missouri, on December 11, 2007.

John R. Colomy,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-24321 Filed 12-14-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-0338; Directorate Identifier 2007-NM-139-AD]

RIN 2120-AA64

Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model EMB-135BJ, -135ER, -135KE, -135KL, -135LR, -145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to supersede an existing airworthiness directive (AD) that applies to all EMBRAER Model EMB-135BJ, -135ER, -135KE, -135KL, -135LR, -145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP airplanes. The existing AD currently requires reviewing the airplane maintenance records for recent reports of vibration from the tail section or rudder pedals. The existing AD also currently requires repetitively inspecting the skin, attachment fittings, and control rods of rudder II to detect cracking, loose parts, wear, or damage; and related investigative/corrective actions if necessary. This proposed AD would require the existing repetitive inspection to be done with new service information. This proposed AD also would require replacing the locking tab washers on the control rods of the rudder II and installing springs on the hinge assemblies of the rudder II, which would terminate the repetitive inspection requirements. This proposed AD results from reports of rudder vibration due to wear. We are proposing this AD to prevent failure of the rudder control rods, which could result in jamming of the rudder II, and possible structural failure and reduced controllability of the airplane.

DATES: We must receive comments on this proposed AD by January 16, 2008.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE, Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact Empresa Brasileira de Aeronautica S.A. (EMBRAER), P.O. Box 343—CEP 12.225, Sao Jose dos Campos—SP, Brazil.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through

Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2125; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2007-0338; Directorate Identifier 2007-NM-139-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

On November 2, 2005, we issued AD 2005-25-04, amendment 39-14397 (70 FR 72902, December 8, 2005), for all EMBRAER Model EMB-135BJ, -135ER, -135KE, -135KL, -135LR, -145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP airplanes. That AD requires reviewing the airplane maintenance records for recent reports of vibration from the tail section or rudder pedals. That AD also requires repetitively inspecting the skin, attachment fittings, and control rods of rudder II to detect cracking, loose parts, wear, or damage; and related investigative/corrective actions if necessary. That AD resulted from

reports of rudder vibration due to wear. We issued that AD to prevent failure of multiple hinge fittings, which could result in severe vibration, and to prevent failure of the rudder control rods, which could result in jamming of the rudder II; and possible structural failure and reduced controllability of the airplane.

Actions Since Existing AD Was Issued

Since we issued AD 2005-25-04, the Agência Nacional de Aviação Civil (ANAC), which is the airworthiness authority for Brazil, issued Brazilian airworthiness directive 2005-09-02R2, effective May 10, 2007, to include updated procedures for the existing repetitive inspections and a terminating action for the repetitive inspections.

Relevant Service Information

EMBRAER has issued Alert Service Bulletin 145LEG-55-A010, Revision 02, dated May 16, 2006 (for Model EMB-135BJ airplanes); and 145-55-A036, Revision 03, dated May 16, 2006 (for Model EMB-135ER, -135KE, -135KL, -135LR, -145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP airplanes). (AD 2005-25-04 refers to EMBRAER Alert Service Bulletin 145LEG-55-A010, dated August 26, 2005; and 145-55-A036, Revision 01, dated September 5, 2005; as the appropriate sources of service information for accomplishing the required repetitive inspections). Revision 02 of EMBRAER Alert Service Bulletin 145LEG-55-A010 and Revision 03 of EMBRAER Alert Service Bulletin 145-55-A036 were issued to include more details for accomplishing the repetitive inspections.

EMBRAER also has issued Alert Service Bulletin 145LEG-55-0011, Revision 01, dated January 23, 2007 (for Model EMB-135BJ airplanes); and 145-55-0038, Revision 01, dated January 23, 2007 (for Model EMB-135ER, -135KE, -135KL, -135LR, -145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP airplanes). The service bulletins describe procedures for replacing the locking tab washers on the control rods of the rudder II with new improved ones, and installing springs on the hinge assemblies of the rudder II.

Accomplishment of these actions eliminates the need for the repetitive inspections specified in the service bulletins described previously.

Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition. The ANAC mandated the service information and issued Brazilian airworthiness directive 2005-09-02R2, effective May 10, 2007, to ensure the continued airworthiness of these airplanes in Brazil.

EMBRAER Alert Service Bulletin 145LEG-55-A010, Revision 02, dated May 16, 2006, refers to EMBRAER Service Bulletins 145LEG-55-0008, Revision 02, dated May 26, 2006; and 145LEG-55-0009, Revision 01, dated November 23, 2005; as additional sources of service information for installing washers in the rudder II hinge fittings and control rod assembly.

EMBRAER Alert Service Bulletin 145-55-A036, Revision 03, dated May 16, 2006, refers to EMBRAER Service Bulletins 145-55-0034, Revision 02, dated May 25, 2006; and 145-55-0035, Revision 02, dated March 28, 2006; as additional sources of service information for installing washers in the rudder II hinge fittings and control rod assembly.

FAA's Determination and Requirements of the Proposed AD

These airplanes are manufactured in Brazil and are type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the ANAC has kept the FAA informed of the situation described above. We have examined the ANAC's findings, evaluated all pertinent information, and determined that AD action is necessary for airplanes of this type design that are certificated for operation in the United States. This proposed AD would supersede AD 2005-25-04 and would retain the requirements of the existing AD. This proposed AD would also require accomplishing the actions specified in the service bulletins described previously.

Costs of Compliance

The following table provides the estimated costs for U.S. operators to comply with this proposed AD.

ESTIMATED COSTS

Action	Work hours	Average labor rate per hour	Parts	Cost per airplane	Number of U.S.-registered airplanes	Fleet cost
Records review (required by AD 2005-25-04)	1	\$80	None	\$80	463	\$37,040

ESTIMATED COSTS—Continued

Action	Work hours	Average labor rate per hour	Parts	Cost per airplane	Number of U.S.-registered airplanes	Fleet cost
Terminating action (new proposed action)	5	80	644	1,044	463	483,372

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13 by removing amendment 39-14397 (70 FR 72902, December 8, 2005) and adding the following new airworthiness directive (AD):

Empresa Brasileira de Aeronautica S.A. (EMBRAER): Docket No. FAA-2007-0338; Directorate Identifier 2007-NM-139-AD.

Comments Due Date

(a) The FAA must receive comments on this AD action by January 16, 2008.

Affected ADs

(b) This AD supersedes AD 2005-25-04.

Applicability

(c) This AD applies to all EMBRAER Model EMB-135BJ, -135ER, -135KE, -135KL, -135LR, -145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP airplanes; certificated in any category.

Unsafe Condition

(d) This AD results from reports of rudder vibration due to wear. We are issuing this AD to prevent failure of multiple hinge fittings, which could result in severe vibration, and to prevent failure of the rudder control rods, which could result in jamming of the rudder II; and possible structural failure and reduced controllability of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Requirements of AD 2005-25-04**Records Review**

(f) Within 5 days after December 23, 2005 (the effective date of AD 2005-25-04): Review the airplane maintenance records to determine whether any vibration from the tail section or rudder pedals was reported within 120 flight hours or 100 flight cycles before December 23, 2005.

Inspection

(g) At the applicable time specified in paragraph (g)(1) or (g)(2) of this AD: Do a detailed inspection of the skin, attachment fittings, and control rods of rudder II to detect cracks, loose parts, wear, or damage. Inspect in accordance with the Accomplishment Instructions of EMBRAER Alert Service Bulletin 145LEG-55-A010, dated August 26, 2005 (for Model EMB-135BJ airplanes); or 145-55-A036, Revision 01, dated September 5, 2005 (for all other airplanes); except as provided by paragraph (l) of this AD. Do all related investigative/corrective actions before further flight by doing all applicable actions specified in the service bulletin; except as required by paragraphs (i) and (l) of this AD. Repeat the inspection at intervals not to exceed 2,500 flight hours, except as required by paragraph (h) of this AD.

(1) If any vibration was reported during the time period specified in paragraph (f) of this AD, inspect within 2 days after the records review.

(2) If no vibration was reported during the time period specified in paragraph (f) of this AD, except as required by paragraph (h) of this AD, inspect before the later of:

- (i) 2,500 total accumulated flight hours.
- (ii) 600 flight hours or 500 flight cycles, whichever occurs first, after December 23, 2005.

Note 1: For the purposes of this AD, a detailed inspection is: "An intensive examination of a specific item, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at an intensity deemed appropriate. Inspection aids such as a mirror, magnifying lenses, etc., may be necessary. Surface cleaning and elaborate procedures may be required."

(h) If any vibration from the tail section or rudder pedals is reported after December 23, 2005, do the inspection specified in paragraph (g) of this AD before the next flight. Repeat the inspection thereafter at intervals not to exceed 2,500 flight hours.

Note 2: EMBRAER Alert Service Bulletin 145LEG-55-A010, dated August 26, 2005, and 145-55-A036, Revision 01, dated September 5, 2005; refer to EMBRAER Service Bulletins 145LEG-55-0008, Revision 01, dated January 14, 2005, 145LEG-55-0009, dated June 21, 2004, and 145-55-0034, Revision 01, dated January 14, 2005, as additional sources of service information for installing washers in the rudder II hinge fittings and control rod assembly.

Exceptions to Service Bulletin Specifications

(i) Where EMBRAER Alert Service Bulletins 145LEG-55-A010 and 145-55-

A036 specify to contact EMBRAER for repair instructions, operators must perform the repair before further flight using a method approved by either the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the Departamento de Aviação Civil (or its delegated agent).

(j) Although EMBRAER Alert Service Bulletins 145LEG-55-A010 and 145-55-A036 recommend sending a report of the inspection results to the manufacturer, this AD does not require a report.

Credit for Prior Accomplishment of Earlier Service Bulletin

(k) For Model -135ER, -135KE, -135KL, -135LR, -145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP airplanes: Accomplishment of the inspection and applicable related investigative/corrective actions before December 23, 2005, in accordance with EMBRAER Alert Service Bulletin 145-55-A036, dated August 20, 2005, is acceptable for compliance with the corresponding requirements of this AD.

New Requirements of This AD

New Revision to Service Bulletins

(l) As of the effective date of this AD, use only the Accomplishment Instructions of EMBRAER Alert Service Bulletin 145LEG-55-A010, Revision 02, dated May 16, 2006 (for Model EMB-135BJ airplanes); or 145-55-A036, Revision 03, dated May 16, 2006 (for all other airplanes); as applicable; to do the actions required by paragraphs (g) and (h) of this AD, until the actions required by paragraph (m) of this AD are done.

Note 3: EMBRAER Alert Service Bulletin 145LEG-55-A010, Revision 02, dated May 16, 2006 (for Model EMB-135BJ airplanes) refers to EMBRAER Service Bulletins 145LEG-55-0008, Revision 02, dated May 26, 2006; and 145LEG-55-0009, Revision 01, dated November 23, 2005; as additional sources of service information for installing washers in the rudder II hinge fittings and control rod assembly.

Note 4: EMBRAER Alert Service Bulletin 145-55-A036, Revision 03, dated May 16, 2006 (for EMB-135ER, -135KE, -135KL, -135LR, -145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP airplanes), refers to EMBRAER Service Bulletins 145-55-0034, Revision 02, dated May 25, 2006; and 145-55-0035, Revision 02, dated March 28, 2006; as additional sources of service information for installing washers in the rudder II hinge fittings and control rod assembly.

Terminating Action

(m) Within 5,500 flight hours or 36 months after the effective date of this AD, whichever occurs first, replace the locking tab washers on the control rods of the rudder II and install springs on the hinge assemblies of the rudder II, in accordance with the Accomplishment Instructions of EMBRAER Alert Service Bulletin 145LEG-55-0011, Revision 01, dated January 23, 2007 (for Model EMB-135BJ airplanes); or 145-55-0038, Revision 01, dated January 23, 2007 (for all other airplanes); as applicable.

Accomplishment of the replacement and installation constitutes terminating action for the requirements of this AD.

Credit for Prior Accomplishment of Earlier Service Bulletins

(n) Actions done before the effective date of this AD in accordance with the Accomplishment Instructions of EMBRAER Alert Service Bulletin 145LEG-55-0011, dated May 12, 2006 (for Model EMB-135BJ airplanes); or 145-55-0038, dated May 12, 2006 (for all other airplanes); as applicable; are acceptable for compliance with the requirements of paragraph (m) of this AD.

Alternative Methods of Compliance (AMOCs)

(o)(1) The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(3) AMOCs approved previously in accordance with AD 2005-25-04 are approved as AMOCs for the corresponding provisions of this AD.

Related Information

(p) Brazilian airworthiness directive 2005-09-02R2, effective May 10, 2007, also addresses the subject of this AD.

Issued in Renton, Washington, on December 10, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-24330 Filed 12-14-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-0337; Directorate Identifier 2007-NM-111-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A319, A320, and A321 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of

another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

During planned maintenance visit on two aircraft, corrosion was found on the upper surface of the wing lower skin panel N°1, inside the Right Hand (RH) inboard dry bay.

It was discovered that [certain] access panels * * * had been omitted from the access requirements of the associated AMM (airplane maintenance manual) task (AMM 05-25-40) until the August 2001 revision.

The result is that some * * * inspections may have not been fully accomplished due to non-removal of [certain] panels * * *.

If the area has not been inspected with the correct access, and if AIRBUS Service Bulletin (SB) A320-57-1121 has not been performed, then some aircraft could remain insufficiently inspected until the next scheduled inspection. This may result in a high risk of corrosion findings greater than level 1.

Corrosion findings greater than level 1 in the wing could result in reduced structural integrity of the airplane. The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by January 16, 2008.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-40, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Tim Dulin, Aerospace Engineer, International Branch, ANM-116, FAA,