

601R-27-150, dated July 12, 2007; except if torque test results are not satisfactory, before further flight, install a serviceable actuator in accordance with the service bulletin or, if no serviceable actuators are available, contact the Manager, New York Aircraft Certification Office, FAA, for corrective action. Do all applicable related investigative and corrective actions before further flight.

New Requirements of This AD: Actions and Compliance

(g) Unless already done, do the following actions.

(1) As of November 30, 2008, no affected airplane may be operated unless the flight crewmembers of that airplane have received simulator training on reduced or zero flap landing that is acceptable to the POI. Thereafter, this training must be done during the normal simulator training cycle, at intervals not to exceed 12 months.

(2) Within 24 months or 4,000 flight hours after the effective date of this AD, whichever occurs first: Do a pressure test of the flexible drive-shaft, and do all applicable corrective actions, by doing all the applicable actions specified in "PART B" of the Accomplishment Instructions of Bombardier Service Bulletin 601R-27-150, dated July 12, 2007. Do all applicable corrective actions before further flight.

(3) For airplanes having flap actuators, part numbers (P/Ns) 852D100-19/-21, 853D100-19/-20, and 854D100-19/-20, specified in paragraphs (g)(3)(i) and (g)(3)(ii) of this AD: Within 24 months after the effective date of this AD, do a low temperature torque test of the flap actuators, and do all applicable corrective actions, by doing all the applicable actions specified in "PART C" of the Accomplishment Instructions of Bombardier Service Bulletin 601R-27-150, dated July 12, 2007. Do all applicable corrective actions before further flight.

(i) Airplanes having actuators that have not been repaired and that have accumulated more than 2,000 flight hours since new.

(ii) Airplanes having actuators that have been repaired and that have accumulated more than 2,000 flight hours on the inboard pinion shaft seals, P/Ns 853SC177-1/-2.

FAA AD Differences

Note 2: This AD differs from the MCAI and/or service information as follows:

(1) The maintenance tasks specified in the first row of the table in "Part IV. Maintenance Actions" of the MCAI do not specify a corrective action if an actuator is not serviceable (*i.e.*, torque test results are not satisfactory). However, this AD requires contacting the FAA or installing a serviceable actuator before further flight if torque test results are not satisfactory. (Reference paragraph (f)(4) of this AD.)

(2) Although paragraph 2. of "Part III. Training" of the MCAI recommends accomplishing the initial training within 1 year, this AD requires accomplishing the training before November 30, 2008, in order to ensure that the actions are completed prior to the onset of cold weather operations.

(3) The MCAI does not specify which actuators are applicable to the actions specified in "Part C" of Bombardier Service

Bulletin 601R-27-150, dated July 12, 2007. This AD requires that "Part C" of the service bulletin only be done for the actuators specified in paragraph (g)(3) of this AD.

Other FAA AD Provisions

(h) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Dan Parrillo, Aerospace Engineer, Systems and Flight Test Branch, ANE-172, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone (516) 228-7305; fax (516) 794-5531. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO. AMOCs approved previously in accordance with AD 2007-17-07 are approved as AMOCs for the corresponding provisions of this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(i) Refer to MCAI Canadian Airworthiness Directive CF-2007-10, dated July 18, 2007; Bombardier Service Bulletin 601R-27-150, dated July 12, 2007; and Canadair Regional Jet Temporary Revision RJ/165, dated July 6, 2007, to the Canadair Regional Jet Airplane Flight Manual CSP A-012; for related information.

Material Incorporated by Reference

(j) You must use Bombardier Service Bulletin 601R-27-150, including Appendix A, dated July 12, 2007; and Canadair Regional Jet Temporary Revision RJ/165, dated July 6, 2007, to the Canadair Regional Jet Airplane Flight Manual CSP A-012; as applicable, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register previously approved the incorporation by reference of Bombardier Service Bulletin 601R-27-150, including Appendix A, dated July 12, 2007; and Canadair Regional Jet Temporary Revision RJ/165, dated July 6, 2007, to the Canadair Regional Jet Airplane Flight Manual CSP A-012 on September 5, 2007 (72 FR 46555, August 21, 2007).

(2) For service information identified in this AD, contact Bombardier, Inc., Canadair, Aerospace Group, P.O. Box 6087, Station Centre-ville, Montreal, Quebec H3C 3G9, Canada.

(3) You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on January 3, 2008.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-249 Filed 1-10-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-0374; Directorate Identifier 2007-SW-02-AD; Amendment 39-15313; AD 2007-26-11]

RIN 2120-AA64

Airworthiness Directives; Intertechnique Zodiac Aircraft Systems, Oxygen Reserve Cylinders

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule; request for comments.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain oxygen reserve cylinders. This AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country with which we have a bilateral agreement to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

This Airworthiness Directive (AD) is issued following information concerning the risk of high-pressure oxygen cylinder tearing with sudden emptying. These cylinders are used for missions at high altitudes or to ensure respiratory air for passengers feeling sick.

It has been demonstrated that the material characteristics of the Aluminum Alloy 5283 (AA5283) from which the cylinders are manufactured deteriorate in the course of time and may possibly lead these oxygen cylinders to tear and abruptly vent aboard an aircraft.

This unsafe condition requires immediate action due to the risk of oxygen cylinders exploding on board an aircraft and creating a fire hazard. This AD requires actions that are intended to address this unsafe condition.

DATES: This AD becomes effective January 28, 2008.

We must receive comments on this AD by March 11, 2008.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://regulations.gov> or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the economic evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5227) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Uday Garadi, Aviation Safety Engineer, FAA, Rotorcraft Directorate, Regulations and Guidance Group, Fort Worth, Texas 76193-0110, telephone (817) 222-5123, fax (817) 222-5961.

SUPPLEMENTARY INFORMATION:

Streamlined Issuance of AD

The FAA is implementing a new process for streamlining the issuance of ADs related to MCAI. This streamlined process will allow us to adopt MCAI safety requirements in a more efficient manner and will reduce safety risks to the public. This process continues to follow all FAA AD issuance processes to meet legal, economic, Administrative Procedure Act, and **Federal Register** requirements. We also continue to meet our technical decision-making responsibilities to identify and correct unsafe conditions on U.S.-certificated products.

This AD references the MCAI and related service information that we considered in forming the engineering basis to correct the unsafe condition. The AD contains text copied from the MCAI and for this reason might not follow our plain language principles.

Discussion

The European Aviation Safety Agency (EASA), which is the technical agent for the member states of the European community, has issued EASA AD No. 2006-0286R1, dated March 22, 2007, to correct an unsafe condition for the specified products.

The MCAI states:

This Airworthiness Directive (AD) is issued following information concerning the risk of high-pressure oxygen cylinder tearing with sudden emptying. These cylinders are used for missions at high altitudes or to ensure respiratory air for passengers feeling sick.

It has been demonstrated that the material characteristics of the Aluminum Alloy 5283 (AA5283) from which the cylinders are manufactured deteriorate in the course of time and may possibly lead these oxygen cylinders to tear and abruptly vent aboard an aircraft.

You may obtain further information by examining the MCAI and the service information in the AD docket.

Relevant Service Information

Intertechnique has issued Service Bulletin No. GLD/GLF-35-150, dated September 20, 2006 and Eurocopter has issued Alert Service Bulletin Nos. 05.00.54 for the Model AS350B3 helicopters and 05.42 for the Model SA 315B helicopters, both dated August 16, 2006. The actions described in the MCAI are intended to correct the same unsafe condition identified in the service information.

FAA's Determination and Requirements of This AD

The Model Airbus 300 series; Pilatus P-6; Dassault Aviation Mystere-Falcon 20; Falcon 50, Falcon 200, and Falcon 900 airplanes; Eurocopter AS350 and Eurocopter SA315 helicopters; and other aircraft may be equipped with these oxygen reserve cylinders, which are not approved by the Department of Transportation (DOT). Without the DOT approval, these oxygen reserve cylinders are not eligible for use in aircraft operating in the United States. Pursuant to our bilateral agreement with France, the State of Design, we have been notified of the unsafe condition described in the MCAI and service information. We are issuing this AD because we evaluated all pertinent information and determined the unsafe condition exists and is likely to exist or develop on aircraft of various type designs.

Differences Between the AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in

general, agree with their substance. However, we have made the following changes:

- The MCAI requires removal of the affected oxygen cylinders at specific time intervals; however, this AD requires removal before further flight.
- The MCAI requires certain procedures to be used for emptying the cylinders as well as certain action for cylinders held as spares.

These actions are beyond the scope of the action needed to correct this unsafe condition and are not included in this AD. These differences are highlighted in the "Differences Between the FAA AD and the MCAI" section of this AD.

FAA's Determination of the Effective Date

An unsafe condition exists that requires the immediate adoption of this AD. The FAA has found that the risk to the flying public justifies waiving notice and comment prior to adoption of this rule because of the risk of oxygen cylinders exploding on board an aircraft and creating a fire hazard. Therefore, we determined that notice and opportunity for public comment before issuing this AD are impracticable and that good cause exists for making this amendment effective in fewer than 30 days.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety, and we did not precede it by notice and opportunity for public comment. We invite you to send any written relevant data, views, or arguments about this AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2007-0374; Directorate Identifier 2007-SW-02-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this AD. We will consider all comments received by the closing date and may amend this AD because of those comments.

We will post all comments we receive, without change, to <http://regulations.gov> including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this AD.

Costs of Compliance

We estimate that this AD will affect about 468 aircraft of U.S. registry. We also estimate that it will take about 1/2 of a work-hour per aircraft to remove the cylinders. The average labor rate is \$80 per work-hour. Based on these figures, we estimate the cost of this AD on U.S.

operators to be \$4000, assuming that oxygen cylinders are installed on 100 aircraft.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared an economic evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

2007-26-11 Intertechnique Zodiac Aircraft Systems: Amendment 39-15313. Docket No. FAA-2007-0374; Directorate Identifier 2007-SW-02-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective January 28, 2008.

Other Affected ADs

(b) None.

Applicability

(c) This AD applies to Intertechnique (F5341), aluminum alloy AA5283, oxygen cylinders manufactured by Societe Metallurgique de Gerzat SAS with GLD series, GLF series, PC2300 or SFL300 part numbers, installed in any aircraft certificated in any category. These oxygen reserve cylinders are installed on but not limited to Model Airbus 300 series; Pilatus P-6; Dassault Aviation Mystere-Falcon 20, Falcon 50, Falcon 200, and Falcon 900 airplanes; and Eurocopter AS350 and Eurocopter SA315 helicopters.

Reason

(d) The mandatory continued airworthiness information (MCAI) states:

This Airworthiness Directive (AD) is issued following information concerning the risk of high-pressure oxygen cylinder tearing with sudden emptying. These cylinders are used for missions at high altitudes or to ensure respiratory air for passengers feeling sick.

It has been demonstrated that the material characteristics of the Aluminum Alloy 5283 (AA5283) from which the cylinders are manufactured deteriorate in the course of time and may possibly lead these oxygen cylinders to tear and abruptly vent aboard an aircraft.

Actions and Compliance

(e) Unless already done, remove any affected oxygen reserve cylinder before further flight.

Differences Between the FAA AD and the MCAI

(f) This AD differs from the MCAI as follows:

(1) The MCAI requires removal of the affected oxygen cylinders at specific time intervals; however, this AD requires removal before further flight.

(2) The MCAI requires certain procedures to be used for emptying the cylinders as well as certain action for cylinders held as spares. These actions are beyond the scope of the action needed to correct this unsafe condition and are not included in this AD.

Subject

(g) Air Transport Association of America (ATA) Code 3530: Portable Oxygen System.

Other Information

(h) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Safety Management Group, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to *ATTN:* Uday Garadi, Aviation Safety Engineer, Regulations and Guidance Group, Fort Worth, Texas 76193-0110, telephone (817) 222-5123, fax (817) 222-5961.

(2) *Airworthy Product:* Use only FAA-approved corrective actions. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent) if the State of Design has an appropriate bilateral agreement with the United States. You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(i) Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive No. 2006-0286R1, dated March 22, 2007; Intertechnique Service Bulletin No. GLD/GLF-35-150, dated September 20, 2006; and Eurocopter Alert Service Bulletin Nos. 05.00.54 for the Model AS350B3 and 05.42 for the Model SA315B, both dated August 16, 2006, contain related information.

Issued in Fort Worth, Texas, on December 3, 2007.

David A. Downey,

Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. E7-25391 Filed 1-10-08; 8:45 am]

BILLING CODE 4910-13-P

SOCIAL SECURITY ADMINISTRATION

20 CFR Parts 404 and 416

[Docket No. SSA-2006-0096]

RIN 0960-AG40

Methods for Conducting Personal Conferences When Waiver of Recovery of a Title II or Title XVI Overpayment Cannot Be Approved

AGENCY: Social Security Administration (SSA).

ACTION: Final rules.

SUMMARY: We are revising our title II regulations and adding title XVI regulations on personal conferences when waiver of recovery of an overpayment cannot be approved. These final rules allow for the conferences to be conducted face-to-face, by telephone, or by video teleconference in these circumstances.

DATES: These final rules are effective February 11, 2008.