

TABLE 1.—DRAWINGS INCLUDED IN FOKKER SERVICE BULLETIN SBF100–27–050—Continued

Fokker drawing	Sheet	Issue	Date
W41504	011	J	April 25, 2006.
W41504	012	L	April 25, 2006.
W41504	013	L	April 25, 2006.
W46140	27	AR	March 5, 2002.
W46140	28	AR	March 8, 2002.
W46143	02	K	February 26, 2002.
W46143	03	K	March 8, 2002.
W46144	06	R	March 4, 2002.
W46144	07	S	March 7, 2002.
W46912	01	D	March 12, 2002.
W46930	01	Original	March 14, 2002.
W46930	02	E	March 14, 2002.
W46932	01	D	March 13, 2002.
W59140	177	GC	February 8, 2006.
W59140	178	GB	February 6, 2006.
W59140	221	GB	February 6, 2006.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM–116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057–3356; telephone (425) 227–1137; fax (425) 227–1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120–0056.

Related Information

(h) Refer to MCAI Dutch Airworthiness Directive NL–2006–010, dated July 14, 2006; and Fokker Service Bulletin SBF100–22–050, dated April 25, 2006, including the drawings listed in Table 1 of this AD; for related information.

Issued in Renton, Washington, on February 25, 2008.

Ali Bahrami,

*Manager, Transport Airplane Directorate,
Aircraft Certification Service.*

[FR Doc. E8–3971 Filed 2–29–08; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2008–0247; Directorate Identifier 2008–CE–003–AD]

RIN 2120–AA64

Airworthiness Directives; Air Tractor, Inc. AT–200, AT–300, AT–400, AT–500, AT–600, AT–800 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to supersede Airworthiness Directive (AD) 2002–25–09, which applies to certain Air Tractor, Inc. (Air Tractor) AT–250, AT–300, AT–400, and AT–500 series airplanes. AD 2002–25–09 currently requires you to install an overturn skid plate in the cockpit area. Since we issued AD 2002–25–09, we received a report of the bolts attaching the forward end of the original design overturn skid plate to the airframe breaking in an overturn accident. This allowed the skid plate to rotate around the rear attach point and the forward end of the plate to enter the cockpit area. Consequently, this proposed AD would require the installation of a modified skid plate kit or modification to skid plate kits that are already installed, including those

already installed on AT–402B, AT–502B, AT–602, and AT–802A series airplanes during production. We are proposing this AD to prevent the front and rear connections of the overturn skid plate to the airplane from breaking, which could allow foreign debris to enter the cockpit during an airplane overturn. This condition, if not corrected, could lead to pilot injury.

DATES: We must receive comments on this proposed AD by May 2, 2008.

ADDRESSES: Use one of the following addresses to comment on this proposed AD:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Air Tractor Inc., P.O. Box 485, Olney, Texas 76374; telephone: (940) 564–5616; fax: (940) 564–5612.

FOR FURTHER INFORMATION CONTACT: Andy McAnaul, Aerospace Engineer, ASW–150, FAA San Antonio MIDO–43, 10100 Reunion Place, Suite 650, San Antonio, Texas 78216, phone: (210) 308–3365, fax: (210) 308–3370.

SUPPLEMENTARY INFORMATION:**Comments Invited**

We invite you to send any written relevant data, views, or arguments

regarding this proposed AD. Send your comments to an address listed under the ADDRESSES section. Include the docket number, "FAA-2008-0247; Directorate Identifier 2008-CE-003-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive concerning this proposed AD.

Discussion

Reports of foreign material entering the cabin area during an overturn skid on Air Tractor, Inc. (Air Tractor) AT-301 and AT-401 series airplanes caused us to issue AD 2002-25-09, Amendment 39-12985 (67 FR 78156, December 23, 2002). AD 2002-25-09 currently requires you to install overturn skid plate, part number (P/N) 11411-1-500 or an FAA-approved equivalent P/N. The manufacturer incorporated skid plates in some production models including Models AT-402B, AT-502B, AT-602, and AT-802A airplanes. Since we issued AD 2002-25-09, we received a report of the bolts breaking in an overturn accident where they attach the forward end of the original design overturn skid plate to the airframe. This allowed the skid plate to rotate around the rear attach point and the forward end of the plate to enter the cockpit area. We are proposing this AD to prevent the front and rear connections of the overturn skid plate to

the airplane from breaking, which could allow foreign debris to enter the cockpit during an airplane overturn. This condition, if not corrected, could lead to pilot injury.

Relevant Service Information

We have reviewed Snow Engineering Company Service Letter # 97, Revised November 7, 2007.

The service information describes procedures for:

- Modifying the overturn skid plate by enlarging the mounting holes and replacing existing clamps and hardware on airplanes with the overturn skid plate installed; and
- Installing the overturn skid plate for airplanes that do not have the overturn skid plate currently installed.

FAA's Determination and Requirements of the Proposed AD

We are proposing this AD because we evaluated all information and determined the unsafe condition described previously is likely to exist or develop on other products of the same type design. This proposed AD would supersede AD 2002-25-09 with a new AD that would require:

- *For airplanes with an installation previously accomplished per the original AD:* incorporating modification kit part-number (P/N) 11411-1-501 composed of the heavier attaching hardware; and
- *For airplanes without the overturn skid plate installed:* incorporating kit P/N 11411-1-502, which incorporates the skid plate and the heavier attaching hardware.

The airplanes below include all of the airplanes from the original AD, which did not have the factory-installed skid plate:

Models	Serial Nos.
AT-250, AT-300, AT-301, AT-302, AT-400, AT-400A, AT-401, AT-401A, AT-402, and AT-402A.	-0001 through -0829.
AT-501, AT-502, AT-502A.	-0001 through -0147.

The airplanes in the table below have been added to this proposed AD. They have a factory-installed skid plate and require installation of the overturn skid plate modification kit part number 1411-1-501:

Models	Serial Nos.
AT-250, AT-300, AT-301, AT-302, AT-400, AT-400A, AT-401, AT-401A, AT-402, AT-402A and AT-402B.	-0830 through -1196.
AT-501, AT-502, AT-502A, and AT-502B.	-0148 through -2620.
AT-602	-0337 through -1153.
AT-802A	-0003 through -0282.

Costs of Compliance

We estimate that this proposed AD would affect 2,026 airplanes in the U.S. registry.

We presume that all airplanes in the U.S. fleet have a skid plate installed (as required by AD 2002-25-09) and the only cost is to incorporate the modification kit P/N 11411-1-501 in determining the total cost on U.S. operators. We estimate the following costs to do the proposed modification of installing the overturn skid plate modification kit P/N 11411-1-501 to those planes that currently have the overturn skid plate installed:

Labor cost	Parts cost	Total cost per airplane	Total cost on U.S. operators
2 work-hours × \$80 per hour = \$160	\$42	\$202	\$409,252

The proposed AD includes a requirement for those few, if any, airplanes that have not operated past the compliance time of AD 2002-25-09.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

Examining the AD Docket

You may examine the AD docket that contains the proposed AD, the regulatory evaluation, any comments received, and other information on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone (800) 647-5527) is located at the street address stated in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by removing Airworthiness Directive (AD) 2002-25-09, Amendment 39-12985 (67 FR 78156, December 23, 2002), and adding the following new AD:

Air Tractor, Inc.: Docket No. FAA-2008-0247; Directorate Identifier 2008-CE-003-AD.

Comments Due Date

(a) We must receive comments on this airworthiness directive (AD) action by May 2, 2008.

Affected ADs

(b) This AD supersedes AD 2002-25-09, Amendment 39-12985.

Applicability

(c) This AD applies to the following airplane models and serial numbers that are certificated in any category:

Models	Serial Nos.
AT-250, AT-300, AT-301, AT-302, AT-400, AT-400A, AT-401, AT-401A, AT-402, AT-402A and AT-402B.	-0001 through -1196.
AT-501, AT-502, AT-502A, and AT-502B.	-0001 through -2620.
AT-602	-0337 through -1153.
AT-802A	-0003 through -0282.

Unsafe Condition

(d) Since we issued AD 2002-25-09, we received a report of the bolts that attach the forward end of the original design overturn skid plate to the airframe breaking in an overturn accident. This allowed the skid plate to rotate around the rear attach point, and the forward end of the plate to enter the cockpit area. We are proposing this AD to prevent the front and rear connections of the overturn skid plate to the airplane from breaking, which could allow foreign debris to enter the cockpit during an airplane overturn. This condition, if not corrected, could lead to pilot injury.

Compliance

(e) To address this problem, you must do the following, unless already done:

Actions	Compliance	Procedures
(1) If overturn skid plate kit part number (P/N) 11411-1-500 or an FAA-approved equivalent P/N is already installed, then install P/N 11411-1-501 modification kit.	Within the next 180 days after the effective date of this AD.	Follow Snow Engineering Co. Service Letter #97, revised November 7, 2007.
(2) If there is no overturn skid plate installed, then install overturn skid plate kit P/N 11411-1-502 or an FAA-approved equivalent part number.	Within the next 180 days after the effective date of this AD.	Follow Snow Engineering Co. Service Letter #97, revised November 7, 2007.

Alternative Methods of Compliance (AMOCs)

(f) The Manager, Fort Worth Airplane Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Andy McAnaul, Aerospace Engineer, ASW-150, FAA San Antonio MIDO-43, 10100 Reunion Place, Suite 650, San Antonio, Texas 78216, phone: (210) 308-3365; fax: (210) 308-3370. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Related Information

(g) To get copies of the service information referenced in this AD, contact Air Tractor Inc., P.O. Box 485, Olney, Texas 76374; telephone: (940) 564-5616; fax: (940) 564-5612. To view the AD docket, go to U.S. Department of Transportation, Docket Operations, M-30, West Building Ground

Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, or on the Internet at <http://www.regulations.gov>.

Issued in Kansas City, Missouri, on February 26, 2008.

James E. Jackson,
Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-4005 Filed 2-29-08; 8:45 am]

BILLING CODE 4910-13-P

ACTION: Announcement of public workshop; request for public comment.

SUMMARY: The Federal Trade Commission ("FTC" or "Commission") is planning to host a public workshop on April 30, 2008, to examine developments in green packaging claims and consumer perception of such claims. The workshop is a component of the Commission's regulatory review of the Guides for the Use of Environmental Marketing Claims, which was announced on November 26, 2007.

DATES: The workshop will be held on Wednesday, April 30, 2008, from 9 AM to 5 PM at the FTC's Satellite Building Conference Center, located at 601 New Jersey Avenue, N.W., Washington, D.C. Any written comments in response to this Notice must be received by May 19, 2008.

FEDERAL TRADE COMMISSION

16 CFR Part 260

Guides for the Use of Environmental Marketing Claims; The Green Guides and Packaging; Public Workshop

AGENCY: Federal Trade Commission.