

**§ 33.84. Engine Overtorque Test.**

(a) If approval of a maximum engine overtorque is sought for an engine incorporating a free power turbine, compliance with this section must be demonstrated by testing.

(1) The test may be run as part of the endurance test requirement of § 33.87. Alternatively, tests may be performed on a complete engine or equivalent testing on individual groups of components.

(2) Upon conclusion of tests conducted to show compliance with this section, each engine part or individual groups of components must meet the requirements of § 33.93(a)(1) and (a)(2).

(b) The test conditions must be as follows:

(1) A total of 15 minutes run at the maximum engine overtorque to be approved. This may be done in separate runs, each being of at least 2½ minutes duration.

(2) A power turbine rotational speed equal to the highest speed at which the maximum overtorque can occur in service. The test speed may not be more than the limit speed of take-off or OEI ratings longer than 2 minutes.

(3) For engines incorporating a reduction gearbox, a gearbox oil temperature equal to the maximum temperature when the maximum engine overtorque could occur in service; and for all other engines, an oil temperature within the normal operating range.

(4) A turbine entry gas temperature equal to the maximum steady state temperature approved for use during periods longer than 20 seconds, other than conditions associated with 30-second or 2-minute OEI ratings. The requirement to run the test at the maximum approved steady state temperature may be waived by the FAA if the applicant can demonstrate that other testing provides substantiation of the temperature effects when considered in combination with the other parameters identified in paragraphs (b)(1), (b)(2) and (b)(3) of this section.

Issued in Washington, DC, on March 20, 2008.

**John J. Hickey,**

*Director, Aircraft Certification Service.*

[FR Doc. E8-6148 Filed 3-25-08; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2008-0357; Directorate Identifier 2008-NM-005-AD]

RIN 2120-AA64

**Airworthiness Directives; Boeing Model 737-300, -400, and -500 Series Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for all Boeing Model 737-300, -400, and -500 series airplanes. This proposed AD would require repetitive inspections for discrepancies of the fuse pins of the inboard and outboard midspar fittings of the nacelle strut, and corrective actions if necessary. This proposed AD results from a report of corrosion damage of the chrome runout on the head side found on all four midspar fuse pins of the nacelle strut. Additionally, a large portion of the chrome plate was missing from the corroded area of the shank. We are proposing this AD to detect and correct discrepancies of the fuse pins of the inboard and outboard midspar fittings of the nacelle strut, which could result in reduced structural integrity of the fuse pins and consequent loss of the strut and separation of the engine from the airplane.

**DATES:** We must receive comments on this proposed AD by May 12, 2008.

**ADDRESSES:** You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

**Examining the AD Docket**

You may examine the AD docket on the Internet at: <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

*www.regulations.gov*; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:**

Allen Rauschendorfer, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6432; fax (425) 917-6590.

**SUPPLEMENTARY INFORMATION:****Comments Invited**

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2008-0357; Directorate Identifier 2008-NM-005-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to: <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

**Discussion**

We have received a report of corrosion damage of the chrome runout on the head side found on all four midspar fuse pins of the nacelle strut on a Model 737-300 airplane. Additionally, a large portion of the chrome plate was missing from the corroded area of the shank. The airplane had a total of 28,621 flight cycles. This condition, if not corrected, could result in discrepancies of the fuse pins of the inboard and outboard midspar fittings of the nacelle strut, reduced structural integrity of the fuse pins, and consequent loss of the strut and separation of the engine from the airplane.

**Relevant Service Information**

We have reviewed Boeing Special Attention Service Bulletin 737-54-1044, dated December 10, 2007. The service bulletin describes procedures for

repetitive detailed inspections for discrepancies (cracking, pitting, corrosion, or chrome plate damage) of the fuse pins of the left- and right-side inboard and outboard midspar fittings of the nacelle strut, and corrective actions if necessary. The corrective actions include blending out pitting or corrosion damage, inspecting blended areas to make sure all damage was removed, and repairing or replacing damaged fuse pins with new or serviceable fuse pins.

The compliance time specified in the service bulletin is the latest of the following: Within 180 months from the date of issuance of the original standard certificate of airworthiness or original export certificate of airworthiness, within 180 months from date of previous pin replacement, or within 24 months after the effective date of the service bulletin. The repetitive interval is not to exceed 60 months.

#### FAA's Determination and Requirements of This Proposed AD

We are proposing this AD because we evaluated all relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design. This proposed AD would require accomplishing the actions specified in the service information described previously.

#### Interim Action

We consider this proposed AD interim action. The manufacturer is currently developing a modification that will address the unsafe condition identified in this AD. Once this modification is developed, approved, and available, we might consider additional rulemaking.

#### Costs of Compliance

We estimate that this proposed AD would affect 616 airplanes of U.S. registry. We also estimate that it would take about 4 work-hours per product to comply with the inspection in this proposed AD. The average labor rate is \$80 per work-hour. Based on these figures, we estimate the cost of this proposed AD to the U.S. operators to be \$197,120, or \$320 per product.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866,
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979), and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

You can find our regulatory evaluation and the estimated costs of compliance in the AD Docket.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

#### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

##### § 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

**Boeing:** Docket No. FAA-2008-0357; Directorate Identifier 2008-NM-005-AD.

#### Comments Due Date

(a) We must receive comments by May 12, 2008.

#### Affected ADs

(b) None.

#### Applicability

(c) This AD applies to all Boeing Model 737-300, -400, and -500 series airplanes, certificated in any category.

#### Unsafe Condition

(d) This AD results from a report of corrosion damage of the chrome runout on the head side found on all four midspar fuse pins of the nacelle strut. Additionally, a large portion of the chrome plate was missing from the corroded area of the shank. We are issuing this AD to detect and correct damage of the fuse pins of the inboard and outboard midspar fittings of the nacelle strut, which could result in reduced structural integrity of the fuse pins and consequent loss of the strut and separation of the engine from the airplane.

#### Compliance

(e) Comply with this AD within the compliance times specified, unless already done.

#### Repetitive Inspections/Corrective Actions

(f) At the applicable time specified in paragraph 1.E., "Compliance" of Boeing Special Attention Service Bulletin 737-54-1044, dated December 10, 2007; except, where the service bulletin specifies a compliance time after the date on the service bulletin, this AD requires compliance within the specified compliance time after the effective date of this AD: Do a detailed inspection for discrepancies of the fuse pins of the inboard and outboard midspar fittings of the nacelle strut by doing all the actions, including all applicable corrective actions, in accordance with the Accomplishment Instructions of the service bulletin. Do all applicable corrective actions before further flight. Repeat the inspection at the time specified in paragraph 1.E. of the service bulletin.

#### Alternative Methods of Compliance (AMOCs)

(g)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, ATTN: Allen Rauschendorfer, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle ACO, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6432; fax (425) 917-6590; has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization who has been

authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane.

Issued in Renton, Washington, on March 19, 2008.

**Dionne Palermo,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. E8-6106 Filed 3-25-08; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF DEFENSE

### GENERAL SERVICES ADMINISTRATION

### NATIONAL AERONAUTICS AND SPACE ADMINISTRATION

#### 48 CFR Parts 3, 9, and 52

[FAR Case 2007-017; Docket 2008-0002; Sequence 2]

RIN: 9000-AK97

#### Federal Acquisition Regulation; FAR Case 2007-017; Service Contractor Employee Personal Conflicts of Interest

**AGENCIES:** Department of Defense (DoD), General Services Administration (GSA), and National Aeronautics and Space Administration (NASA).

**ACTION:** Advance notice of proposed rulemaking.

**SUMMARY:** The Civilian Agency Acquisition Council and the Defense Acquisition Regulations Council (the Councils) are interested in determining if, when, and how service contractor employees' personal conflicts of interest (PCI) need to be addressed and whether greater disclosure of contractor practices, specific prohibitions, or reliance on specified principles would be most effective and efficient in promoting ethical behavior.

**DATES:** *Comment Date:* Interested parties should submit written comments to the FAR Secretariat on or before May 27, 2008 to be considered in the formulation of any proposed or interim rule.

**ADDRESSES:** Submit comments identified by FAR case 2007-017, by any of the following methods:

- Regulations.gov: <http://www.regulations.gov>. Submit comments via the Federal eRulemaking portal by inputting "FAR Case 2007-017" under the heading "Comment or Submission". Select the link "Send a Comment or Submission" that corresponds with FAR Case 2007-017. Follow the instructions provided to complete the "Public

Comment and Submission Form". Please include your name, company name (if any), and "FAR Case 2007-017" on your attached document.

- Fax: 202-501-4067.
- Mail: General Services

Administration, Regulatory Secretariat (VPR), 1800 F Street, NW, Room 4035, ATTN: Diedra Wingate, Washington, DC 20405.

**Instructions:** Please submit comments only and cite FAR case 2007-017, in all correspondence related to this case. All comments received will be posted without change to <http://www.regulations.gov>. Please include your name and company name (if any) inside the document.

**FOR FURTHER INFORMATION CONTACT:** For clarification of content, contact Ms. Meredith Murphy, Procurement Analyst, at (202) 208-6925. For information pertaining to status or publication schedules, contact the FAR Secretariat, Room 4035, GS Building, Washington, DC 20405, (202) 501-4755. Please cite FAR Case 2007-017.

#### SUPPLEMENTARY INFORMATION:

##### A. Background

1. The Councils are considering the need for standard PCI clauses or a set of standard PCI clauses, if appropriate, for inclusion in solicitations and contracts as recommended by the Acquisition Advisory Panel's Final Report. The Councils are publishing a related advance notice of proposed rulemaking on the subject of Organizational Conflicts of Interest.

2. The Federal Government is increasingly turning to private contractors to perform a wide array of its work. As a result, contractor employees are increasingly working side-by-side with Federal employees, but are not subject to the same ethical safeguards that have been put in place for Federal employees to ensure the integrity of Government operations. Issues such as financial conflicts of interest, impartiality concerns, misuse of information, misuse of apparent or actual authority, and misuse of property are all areas of potential personal conflicts of interest for contractor employees that could result in harm to the public fisc and loss of public confidence in Government. For an introduction to the potential problems resulting from contractor employees' personal conflicts of interest, see the speech given by the Director of the Office of Government Ethics to the Defense Industry Initiative entitled "Who Are Government Workers and How Can Management Improve Worker Ethical Sensitivity?" at: [http://www.usoge.gov/pages/forms\\_pubs\\_otherdocs/fpo\\_files/reports\\_plans/cusick\\_speech061407.pdf](http://www.usoge.gov/pages/forms_pubs_otherdocs/fpo_files/reports_plans/cusick_speech061407.pdf).

[www.usoge.gov/pages/forms\\_pubs\\_otherdocs/fpo\\_files/reports\\_plans/cusick\\_speech061407.pdf](http://www.usoge.gov/pages/forms_pubs_otherdocs/fpo_files/reports_plans/cusick_speech061407.pdf).

3. The Government Accountability Office (GAO) released, on March 7, 2008, GAO-08-169, Defense Contracting: Additional Personal Conflict of Interest Safeguards Needed for Certain DOD Contractor Employees. GAO's reporting objectives, in part, were to assess (1) what safeguards exist to prevent personal conflicts of interest for contractor employees when performing DOD's tasks and (2) whether Government and defense contractor officials believe additional safeguards are necessary. To conduct this review, GAO reviewed conflicts-of-interest laws and policies and interviewed ethics officials and senior DoD leaders regarding applicability to DOD Federal and contractor employees. The public may wish to consider GAO's findings, conclusions, and recommendations regarding additional safeguards for personal conflicts of interest pertaining to contractor employees in providing comments in response to this Notice.

4. The Acquisition Advisory Panel (AAP) was chartered by the Congress at Section 1423 of the Services Acquisition Reform Act (SARA). Relevant portions of the final report of the AAP are located on the Web at <http://acquisition.gov/comp/aap/documents/Chapter6.pdf>. The Panel found that "(t)here is a need to assure that the increase in contractor involvement in agency activities does not undermine the integrity of the Government's decision-making processes" (AAP Final Report, Chapter 6, Finding 7, page 417). The AAP also found that "(m)ost of the statutory and regulatory provisions [addressing PCI] that apply to Federal employees do not apply to contractor employees, even where contractor employees are co-located and work side-by-side with Federal employees and are performing similar functions" (AAP Final Report, Chapter 6, Finding 7, page 418).

5. The AAP concluded that, "in view of the tremendous amount of Federal contracting for services, and particularly in the context of the multisector workforce, additional measures to protect against PCIs by contractor personnel [are] needed" (AAP Final Report, Chapter 6, Recommendation 5-2, page 423). While it concluded that it is not necessary to adopt any new Federal statutes, the AAP was concerned that certain types of contracts, primarily service contracts, might present greater problems than others, and it recommended that the FAR Council should identify those types of contracts where the potential