

remission of any civil penalty assessed under this part.

(e) *Limitation for not-for-profits.* With respect to any violation occurring under a contract entered into on or after August 8, 2005, in the case of any not-for-profit contractor, subcontractor, or supplier, the total amount of civil penalties paid under this part may not exceed the total amount of fees paid by DOE to that entity within the U.S. Government fiscal year in which the violation occurs.

(f) *Not-for-profit.* For purposes of this part, a “not-for-profit” contractor, subcontractor, or supplier is one for which no part of the net earnings of the contractor, subcontractor, or supplier inures to the benefit of any natural person or for-profit artificial person.

[FR Doc. E8-7763 Filed 4-10-08; 8:45 am]

BILLING CODE 6450-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2008-0426; Directorate Identifier 2008-CE-016-AD]

RIN 2120-AA64

Airworthiness Directives; MORAVAN a.s. Model Z-143L Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

Vortex inserts are used inside the heat exchanger of the carburettor heating system. Up to serial number (s/n) 0044 inclusive those inserts have been produced from aluminium alloy which has been found to be susceptible of cracks. As a consequence, if left uncorrected some loose parts could migrate in the induction system, reduce the air flow through the carburettor's venturi and lead to a loss of engine power.

From s/n 0045 onwards vortex inserts have been produced from stainless steel.

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by May 12, 2008.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; fax: (816) 329-4090.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2008-0426; Directorate Identifier 2008-CE-016-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent

for the Member States of the European Community, has issued EASA AD No. 2008-0038, dated February 27, 2008 (referred to after this as “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states:

Vortex inserts are used inside the heat exchanger of the carburettor heating system. Up to serial number (s/n) 0044 inclusive those inserts have been produced from aluminium alloy which has been found to be susceptible of cracks. As a consequence, if left uncorrected some loose parts could migrate in the induction system, reduce the air flow through the carburettor's venturi and lead to a loss of engine power.

From s/n 0045 onwards vortex inserts have been produced from stainless steel.

To address this unsafe condition, this Airworthiness Directive (AD) mandates initial inspections of the heat exchanger vortex inserts and replacement of the aluminium inserts by stainless steel ones if any damage is found; and recurrent inspections to be done as incorporated in the Revision of Airplane Maintenance Manual.

You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

Moravan Aviation s.r.o. has issued Mandatory Service Bulletin Z143L/31a, dated June 8, 2007, and new pages 01-35, 05-28, 75-7, 75-7A, 75-7B, and 75-8 of ZLIN Z 143 L Airplane Maintenance Manual, Revision No. 9, dated: June 8, 2007. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Differences Between This Proposed AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information

provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a NOTE within the proposed AD.

Costs of Compliance

We estimate that this proposed AD will affect 7 products of U.S. registry. We also estimate that it would take about 6 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$80 per work-hour. Required parts would cost about \$100 per product.

Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$4,060, or \$580 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative,

on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Moravan a.s.: Docket No. FAA-2008-0426; Directorate Identifier 2008-CE-016-AD.

Comments Due Date

(a) We must receive comments by May 12, 2008.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Model Z-143L airplanes, all serial numbers (SNs), certificated in any category.

Subject

(d) Air Transport Association of America (ATA) Code 75: Engine Air.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

Vortex inserts are used inside the heat exchanger of the carburettor heating system. Up to serial number (s/n) 0044 inclusive those inserts have been produced from aluminium alloy which has been found to be susceptible of cracks. As a consequence, if left uncorrected some loose parts could migrate in the induction system, reduce the air flow through the carburettor's venturi and lead to a loss of engine power.

From s/n 0045 onwards vortex inserts have been produced from stainless steel.

To address this unsafe condition, this Airworthiness Directive (AD) mandates initial inspections of the heat exchanger vortex inserts and replacement of the aluminium inserts by stainless steel ones if any damage is found; and recurrent inspections to be done as incorporated in the Revision of Airplane Maintenance Manual.

Actions and Compliance

(f) Unless already done, do the following actions:

(1) For all serial numbers (SNs) through SN 0044:

(i) Before further flight after the effective date of this AD, inspect the vortex inserts inside the carburetor heating system heat exchanger for cracks and/or loose or missing rivets following paragraph 8 of Moravan Aviation s.r.o. Mandatory Service Bulletin Z143L/31a, dated June 8, 2007.

(ii) Before further flight, if as a result of the inspection required by paragraph (f)(1)(i) of this AD, you find any cracks and/or loose or missing rivets for the vortex inserts, replace all vortex inserts with new vortex inserts made from stainless steel following paragraph 8 of Moravan Aviation s.r.o. Mandatory Service Bulletin Z143L/31a, dated June 8, 2007.

(2) For SN 0045 and greater: Within 110 hours time-in-service (TIS) after the effective date of this AD or within 60 days after the effective date of this AD, whichever occurs first, inspect the vortex inserts inside the carburetor heating system heat exchanger following new instructions introduced by new pages 05-28, 75-7, 75-7A, and 75-8 of ZLIN Z 143 L Airplane Maintenance Manual, Revision No. 9, dated: June 8, 2007.

(3) For all SNs: Within 60 days after the effective date of this AD, incorporate new pages 01-11, 01-12, 01-24, 01-35, 05-28, 75-7, 75-7A, 75-7B, and 75-8 of ZLIN Z 143 L Airplane Maintenance Manual, Revision No. 9, dated: June 8, 2007, into your maintenance program. These pages include compliance times and procedures for repetitive inspections.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: The MCAI requires compliance for the inspection of SN 0045 and greater at the next shop visit or within 110 hours TIS after the effective date of this AD. To assure the AD is clear for U.S. operators and all airplanes have the inspection done in a timely manner, this AD requires compliance for the inspection of SN 0045 and greater within 110 hours TIS after the effective date of this AD, whichever occurs first.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; fax: (816) 329-4090. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they

are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) **Reporting Requirements:** For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency (EASA) AD No. 2008-0038, dated February 27, 2008; Moravan Aviation s.r.o. Mandatory Service Bulletin Z143L/31a, dated June 8, 2007; and new pages 01-11, 01-12, 01-24, 01-35, 05-28, 75-7, 75-7A, 75-7B, and 75-8 of ZLIN Z 143 L Airplane Maintenance Manual, Revision No. 9, dated: June 8, 2007, for related information.

Issued in Kansas City, Missouri, on April 3, 2008.

David R. Showers,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-7654 Filed 4-10-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2008-0409; Directorate Identifier 2007-NM-265-AD]

RIN 2120-AA64

Airworthiness Directives; ATR Model ATR42 Airplanes and Model ATR72-101, -102, -201, -202, -211, and -212 Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

It has been found on in-service aircraft that some aileron tab bellcrank assemblies were not in accordance with the definition drawings.

The main item concerned is the retainer Part Number S2711004620000, which has been manufactured with a hole larger than it should be, or redrilled out of limits.

The function of the retainer is to maintain the spacer in position in case of rupture or

loss of the bolt which links the tab control rod to the bellcrank assembly. If the diameter of the retainer hole is out of limit, the retainer function is lost and fail-safe installation is no longer ensured. This condition, if not corrected, could lead to loss of the aileron tab bellcrank functionality, resulting in diminished control of the aircraft.

* * * * *

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by May 12, 2008.

ADDRESSES: You may send comments by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- **Fax:** (202) 493-2251.
- **Mail:** U.S. Department of

Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-40, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the

ADDRESSES section. Include "Docket No. FAA-2008-0409; Directorate Identifier 2007-NM-265-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory,

economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Airworthiness Directive 2006-0376, dated December 19, 2006 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

It has been found on in-service aircraft that some aileron tab bellcrank assemblies were not in accordance with the definition drawings.

The main item concerned is the retainer Part Number S2711004620000, which has been manufactured with a hole larger than it should be, or redrilled out of limits.

The function of the retainer is to maintain the spacer in position in case of rupture or loss of the bolt which links the tab control rod to the bellcrank assembly. If the diameter of the retainer hole is out of limit, the retainer function is lost and fail-safe installation is no longer ensured. This condition, if not corrected, could lead to loss of the aileron tab bellcrank functionality, resulting in diminished control of the aircraft.

For the reasons stated above, this Airworthiness Directive (AD) requires the inspection [for proper hole diameter] of the aileron tab bellcrank retainer and, if necessary, the restoration of a proper installation [replacing any retainer which does not meet specified limits with a new retainer].

Corrective actions also include doing a general visual inspection (GVI) for discrepancies (corrosion, deformation, scratches, or other defects) of the bolt and fasteners of the bellcrank assembly. You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

ATR has issued Avions de Transport Regional Service Bulletins ATR42-27-0098 and ATR72-27-1060, both dated December 19, 2006. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another