- 35171-22, or a SN 35239-01 through SN 37016-28, installed.
- (2) If the cylinder assemblies are not ECi, P/N AEL65102, no further action is required.
- (3) If the cylinder assemblies are ECi, P/N AEL65102, and if the serial number is not listed in this AD, no further action is required.
- (4) If the cylinder assemblies are ECi, P/N AEL65102, and if the serial number is listed in this AD, do the following:

# Group "A" Cylinder Assemblies

- (i) For Group "A" cylinder assemblies:
- (A) Perform an initial visual inspection as specified in paragraphs (h) through (j) of this AD, and an initial compression test as specified in paragraphs (k) through (o) of this AD, within the next 10 operating hours time-in-service (TIS), if the cylinder assembly has 350 or more operating hours TIS on the effective date of this AD, but fewer than 2,000 operating hours TIS.
- (B) Perform an initial visual inspection as specified in paragraphs (h) through (j) of this AD, and an initial compression test as specified in paragraphs (k) through (o) of this AD, before exceeding 350 operating hours TIS, if the cylinder assembly has fewer than 350 operating hours TIS on the effective date of this AD.
- (C) Replace cylinder assemblies installed in helicopter engines within the next 25 operating hours TIS after the effective date of this AD if the cylinder assembly has 1,500 operating hours TIS or more on the effective date of this AD.
- (D) Replace cylinder assemblies installed in airplane engines within the next 25 operating hours TIS after the effective date of this AD if the cylinder assembly has 2,000 operating hours TIS or more on the effective date of this AD.
- (E) Perform repetitive visual inspections as specified in paragraphs (h) through (j) of this AD, and repetitive compression tests as specified in paragraphs (k) through (o) of this AD, within every 50 operating hours TIS.
- (F) Replace cylinder assemblies installed in helicopter engines that pass the visual inspections and compression tests, no later than 1,500 operating hours TIS after the effective date of this AD.
- (G) Replace cylinder assemblies installed in airplane engines that pass the visual inspections and compression tests, no later than 2,000 operating hours TIS after the effective date of this AD.

# Group "B" Cylinder Assemblies

- (ii) For Group "B" cylinder assemblies:
- (A) Perform an initial visual inspection as specified in paragraphs (h) through (j) of this AD, and initial compression test as specified in paragraphs (k) through (o) of this AD, within an additional 10 operating hours TIS.
- (B) Replace the cylinder assembly within the next 25 operating hours TIS after the effective date of this AD if the cylinder assembly has 350 or more operating hours TIS on the effective date of this AD.
- (C) Replace cylinder assemblies that pass the initial visual inspections and compression tests, before exceeding 350 operating hours TIS after the effective date of this AD.

## **Visual Inspection**

- (h) Visually inspect around the exhaust valve side, for cracks or any signs of black or white residue of combustion leakage from cracks.
- (i) Replace cracked cylinder assemblies before further flight.
- (j) Information on cylinder assembly visual inspection can be found in ECi Mandatory Service Bulletin (MSB) No. 08–1, Revision 1, dated April 8, 2008.

## **Cylinder Assembly Compression Test**

- (k) Compression test the cylinder assembly. (l) Information on cylinder assembly compression testing can be found in ECi MSB No. 08–1, Revision 1, dated April 8, 2008.
- (m) During the compression test, if the cylinder pressure gauge reads below 70 pounds-per-square-inch, apply a water and soap solution to the side of the leaking cylinder, near the head-to-barrel interface.
- (n) Replace the cylinder assembly before further flight, if air leakage and bubbles are observed on the side of the cylinder assembly, near the head-to-barrel interface.
- (o) Repair or replace the engine cylinder assembly before further flight if the cause of the low gauge reading in paragraph (m) of this AD is from leaking intake or exhaust valves, or from leaking piston rings.

## Prohibition of ECi Cylinder Assemblies Affected By This AD

(p) After the effective date of this AD, do not install any ECi cylinder assembly, P/N AEL65102, with cylinder head, P/N AEL85099, and with SN 1138–02 through SN 35171–22, or SN 35239–01 through SN 37016–28, onto any engine, and do not attempt to repair or reuse these ECi cylinder assemblies.

# **Alternative Methods of Compliance**

(q) The Manager, Special Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

# Special Flight Permits

(r) Under 14 CFR 39.23, we will not approve special flight permits for this AD for engines that have failed the visual inspection or the cylinder assembly compression test required by this AD.

## **Related Information**

- (s) ECi Mandatory Service Bulletin No. 08– 1, Revision 1, dated April 8, 2008, pertains to the subject of this AD.
- (t) Contact Peter W. Hakala, Aerospace Engineer, Special Certification Office, FAA, Rotorcraft Directorate, 2601 Meacham Blvd., Fort Worth, TX 76193; e-mail: peter.w.hakala@faa.gov; telephone (817) 222–5145; fax (817) 222–5785, for more information about this AD.

Issued in Burlington, Massachusetts, on May 13, 2008.

## Peter A. White,

Assistant Manager, Engine and Propeller Directorate, Aircraft Certification Service. [FR Doc. E8–11116 Filed 5–16–08; 8:45 am]

## BILLING CODE 4910-13-P

## **DEPARTMENT OF TRANSPORTATION**

## **Federal Aviation Administration**

#### 14 CFR Part 71

[Docket No. FAA-2008-0434; Airspace Docket No. 08-ASW-6]

## Proposed Establishment of Class D Airspace; Victoria, TX

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking.

**SUMMARY:** This action proposes to establish Class D airspace at Victoria Regional Airport, Victoria, TX. The establishment of an air traffic control tower has made this action necessary for the safety of Instrument Flight Rule (IFR) operations at Victoria Regional Airport.

**DATES:** 0901 UTC July 31, 2008. Comments must be received on or before July 3, 2008.

**ADDRESSES:** Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, 1200 New Jersey Avenue, SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001. You must identify the docket number FAA-2008-0434/Airspace Docket No. 07-ASW-6, at the beginning of your comments. You may also submit comments on the Internet at http://www.regulations.gov. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone 1-800-647-5527) is on the ground floor of the building at the above address.

FOR FURTHER INFORMATION CONTACT: Gary Mallett, Central Service Center, System Support Group, Federal Aviation Administration, Southwest Region, 2601 Meacham Blvd., Fort Worth, TX 76193–0530; telephone: (817) 222–4949.

# SUPPLEMENTARY INFORMATION:

# **Comments Invited**

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. FAA–2008–0434/Airspace Docket No. 08–ASW–6." The postcard will be date/time stamped and returned to the commenter.

## Availability of NPRM's

An electronic copy of this document may be downloaded through the Internet at http://www.regulations.gov. Recently published rulemaking documents can also be accessed through the FAA's Web page at http://www.faagp or the Superintendent of Document's Web page at http://www.access.gpo.gov/nara.

Additionally, any person may obtain a copy of this notice by submitting a request to the Federal Aviation Administration (FAA), Office of Air Traffic Airspace Management, ATA-400, 800 Independence Avenue, SW., Washington, DC 20591, or by calling (202) 267-8783. Communications must identify both docket numbers for this notice. Persons interested in being placed on a mailing list for future NPRM's should contact the FAA's Office of Rulemaking (202) 267-9677, to request a copy of Advisory Circular No. 11-2A, Notice of Proposed Rulemaking Distribution System, which describes the application procedure.

#### The Proposal

This action proposes to amend Title 14, Code of Federal Regulations (14 CFR), part 71 by establishing a Class D airspace area for IFR operations at Victoria Regional Airport, Victoria, TX. The establishment of an air traffic control tower has made this action necessary. The area would be depicted on appropriate aeronautical charts.

Class D airspace areas are published in Paragraph 5000 of FAA Order 7400.9R, dated August 15, 2007, and effective September 15, 2007, which is incorporated by reference in 14 CFR 71.1. The Class D airspace designation listed in this document would be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore, (1) Is not a significant regulatory action" under Executive Order 12866; (2) is not a "significant

rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the U.S. Code. Subtitle 1, Section 106 describes the authority of the FAA Administrator Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it establishes controlled airspace at Victoria Regional Airport, Victoria, TX.

## List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (Air).

# The Proposed Amendment

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

# PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIRWAYS; ROUTES; AND REPORTING POINTS

1. The authority citation for part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

# §71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation Administration Order 7400.9R, Airspace Designations and Reporting Points, dated August 15, 2007, and effective September 15, 2007, is amended as follows:

Paragraph 5000 Class D Airspace.

## ASW TX D Victoria, TX (New)

Victoria Regional Airport, TX (Lat. 28°51′09″ N., long. 96°55′07″ W.)

That airspace extending upward from the surface to and including 2,600 feet MSL within a 4.7-mile radius of Victoria Regional

Airport. This Class D airspace area is effective during the specific dates and times established in advance by a Notice to Airmen. The effective date and time will thereafter be continuously published in the Airport/Facility Directory.

\* \* \* \* \*

Issued in Fort Worth, TX on May 5, 2008. **Donald R. Smith**,

Manager, System Support Group, ATO Central Service Center.

[FR Doc. E8–10953 Filed 5–16–08; 8:45 am] BILLING CODE 4910–13–M

#### **DEPARTMENT OF THE TREASURY**

## **Internal Revenue Service**

26 CFR Part 1

[REG-100798-06]

RIN 1545-BF28

# **Contributed Property**

**AGENCY:** Internal Revenue Service (IRS), Treasury.

**ACTION:** Notice of proposed rulemaking.

**SUMMARY:** These proposed regulations under section 704(c) of the Internal Revenue Code (Code) provide that the section 704(c) anti-abuse rule takes into account the tax liabilities of both the partners in a partnership and certain direct and indirect owners of such partners. The proposed regulations further provide that a section 704(c) allocation method cannot be used to achieve tax results inconsistent with the intent of subchapter K of the Code. The proposed regulations affect partnerships and their partners.

**DATES:** Written or electronic comments and requests for a public hearing must be received by August 18, 2008.

ADDRESSES: Send submissions to: CC:PA:LPD:PR (REG-100798-06), Room 5203, Internal Revenue Service, POB 7604, Ben Franklin Station, Washington, DC 20044. Submissions may be hand-delivered Monday through Friday between the hours of 8 a.m. and 4 p.m. to: CC:PA:LPD:PR (REG-100798-06), Courier's Desk, Internal Revenue Service, 1111 Constitution Avenue, NW., Washington, DC. Alternatively, taxpayers may submit comments electronically via the Federal eRulemaking Portal at http://www.regulations.gov (IRS REG-100798-06).

#### FOR FURTHER INFORMATION CONTACT:

Concerning the proposed regulations, Laura Fields or Steven A. Schmoll at (202) 622–3050; concerning submissions of comments, and hearing requests, e-