

elevator centering torsion springs with new elevator centering torsion springs by incorporating Modsum 4-113482, in accordance with Bombardier Service Bulletin 84-27-31, dated April 27, 2007.

#### FAA AD Differences

**Note:** This AD differs from the MCAI and/or service information as follows: No differences.

#### Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Fabio Buttitta, Aerospace Engineer, Systems and Flight Test Branch, ANE-172, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone (516) 228-7303; fax (516) 794-5531. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

#### Related Information

(h) Refer to MCAI Canadian Airworthiness Directive CF-2008-05R1, dated February 27, 2008, and Bombardier Service Bulletin 84-27-31, dated April 27, 2007, for related information.

Issued in Renton, Washington, on May 8, 2008.

**Michael J. Kaszycki,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. E8-11566 Filed 5-22-08; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2008-0585; Directorate Identifier 2008-NM-027-AD]

RIN 2120-AA64

#### Airworthiness Directives; Boeing Model 747SP Series Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for all Boeing Model 747SP series airplanes. This proposed AD would require repetitive lubrication of the rudder tab hinges and repetitive replacement of the rudder tab control rods. This proposed AD results from reports of freeplay-induced vibration of the control surfaces on Boeing Model 727, 737, 757, and 767 airplanes. We are proposing this AD to prevent damage to the control surface structure during flight, which could result in loss of control of the airplane.

**DATES:** We must receive comments on this proposed AD by July 7, 2008.

**ADDRESSES:** You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is in the

**ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

#### FOR FURTHER INFORMATION CONTACT:

Kathleen Arrigotti, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6426; fax (425) 917-6590.

#### SUPPLEMENTARY INFORMATION:

#### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2008-0585; Directorate Identifier 2008-NM-027-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

#### Discussion

We have received reports of freeplay-induced vibration of control surfaces on Boeing Model 727, 737, 757, and 767 airplanes. Excessive wear of components or interfaces allows excessive freeplay of the control surfaces and can cause unacceptable airframe vibration during flight. The potential for vibration of the control surface should be avoided because the point of transition from vibration to divergent flutter is unknown. Divergent flutter can cause damage to the control surface structure during flight. This condition, if not corrected, could result in loss of control of the airplane.

Although there have been no reports of freeplay-induced vibration of the rudder tabs for Model 747SP airplanes, the affected control surfaces on Boeing Model 727, 737, 757, and 767 airplanes and Boeing Model 747SP airplanes are similar in design. Therefore, all of these models might be subject to the identified unsafe condition.

#### Relevant Service Information

We have reviewed Boeing Special Attention Service Bulletin 747-27-2447, dated January 17, 2008. The service bulletin describes procedures for repetitive lubrication of the rudder tab

hinges, and repetitive replacement of the rudder tab control rods. For airplanes on which BMS 3-33 grease is used to lubricate the rudder tab hinges, the compliance time for the first lubrication is within 9 months after the date on the service bulletin, and the repetitive interval is not to exceed 18 months thereafter. For airplanes on which BMS 3-33 grease is not used to lubricate the rudder tab hinges, the compliance time for the first lubrication is 9 months after the date on the service bulletin, and the repetitive interval is not to exceed 9 months thereafter. The compliance time for all airplanes for the first replacement of the rudder tab control rods is within 6,000 flight hours after the date on the service bulletin, and the repetitive interval is not to exceed 8,000 flight hours thereafter.

**Other Relevant Rulemaking**

The following ADs resulted from reports of freeplay-induced vibration of control surfaces on Boeing Model 727, 737, 757, and 767 airplanes.

On March 30, 2006, we issued AD 2006-07-23 (amendment 39-14550, 71 FR 18194, April 11, 2006) for all Boeing Model 757 airplanes. That AD requires repetitive measurements of the freeplay of each of the three power control units that move the rudder; repetitive lubrication of rudder components; and corrective actions if necessary. That AD resulted from a report of freeplay-induced vibration of the rudder. That AD explained that the potential for vibration of the control surface should be avoided because the point of transition from vibration to divergent flutter is unknown. We issued that AD to prevent excessive vibration of the

airframe during flight, which could result in divergent flutter and loss of control of the airplane.

On June 15, 2006, we issued AD 2006-13-16 (amendment 39-14669, 71 FR 36481, June 27, 2006) for certain Boeing Model 727 airplanes. That AD requires repetitive measurements of the freeplay of the left and right outboard aileron balance tabs and of the upper and lower rudder tabs, and related investigative/corrective actions if necessary. That AD also requires repetitive lubrication of the hinge bearings and rod end bearings of the outboard aileron balance tabs. That AD resulted from reports of freeplay-induced vibration of the outboard aileron balance tabs and rudder tabs. We issued that AD to prevent excessive vibration of the airframe during flight, which could result in divergent flutter and loss of control of the airplane.

On September 28, 2006, we issued AD 2006-21-01 (amendment 39-14784, 71 FR 59368, October 10, 2006) for all Boeing Model 737 airplanes. That AD requires repetitive measurement of the freeplay of both aileron balance tabs; repetitive lubrication of the aileron balance tab hinge bearings and rod end bearings; and related investigative and corrective actions if necessary. That AD resulted from reports of freeplay-induced vibration of the aileron balance tab. That AD also explained that the potential for vibration of the control surface should be avoided because the point of transition from vibration to divergent flutter is unknown. We issued that AD to prevent excessive vibration of the airframe during flight, which could result in loss of control of the airplane.

On November 16, 2007, we issued AD 2007-24-08 (amendment 39-15274, 72 FR 67236, November 28, 2007), for all Boeing Model 767 airplanes. That AD requires repetitive measurements of the rudder freeplay and the elevator freeplay for each of the power control actuators that move the rudder and elevator, corrective and related investigative actions if necessary, and repetitive lubrications of the rudder and elevator components. For some airplanes, that AD also requires related concurrent actions. That AD also explained that the potential for vibration of the control surface should be avoided because the point of transition from vibration to divergent flutter is unknown. We issued that AD to prevent excessive vibration of the airframe during flight, which could result in loss of control of the airplane.

**FAA’s Determination and Requirements of This Proposed AD**

We are proposing this AD because we evaluated all relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the(se) same type design(s). This proposed AD would require accomplishing the actions specified in the service information described previously.

**Costs of Compliance**

We estimate that this proposed AD would affect 7 airplanes of U.S. registry. The following table provides the estimated costs for U.S. operators to comply with this proposed AD. The average labor rate is \$80 per work hour.

ESTIMATED COSTS

Action	Work hours	Parts	Cost per product	Fleet cost
Lubrication .....	2	None .....	\$160, per cycle .....	\$1,120, per cycle.
Replacement .....	16	\$39,511 .....	\$40,791, per cycle .....	\$285,537, per cycle.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in

air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a

substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866,
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979), and
3. Will not have a significant economic impact, positive or negative,

on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

You can find our regulatory evaluation and the estimated costs of compliance in the AD Docket.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

#### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

##### § 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

**Boeing:** Docket No. FAA-2008-0585; Directorate Identifier 2008-NM-027-AD.

#### Comments Due Date

(a) We must receive comments by July 7, 2008.

#### Affected ADs

(b) None.

#### Applicability

(c) This AD applies to all Boeing Model 747SP series airplanes.

#### Unsafe Condition

(d) This AD results from reports of freeplay-induced vibration of the control surfaces on Boeing Model 727, 737, 757, and 767 airplanes. We are issuing this AD to prevent damage to the control surface structure during flight, which could result in loss of control of the airplane.

#### Compliance

(e) Comply with this AD within the compliance times specified, unless already done.

#### Repetitive Lubrication and Replacement

(f) At the applicable compliance time listed in Paragraph 1.E., "Compliance," of Boeing Special Attention Service Bulletin 747-27-2447, dated January 17, 2008, lubricate the rudder tab hinges and replace the rudder tab control rods with new control rods. Repeat the lubrication and replacement thereafter at the applicable repeat interval listed in paragraph 1.E., "Compliance," of the service bulletin. Do all actions in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 747-27-2447, dated January 17, 2008. Where Boeing Special Attention Service Bulletin 747-27-2447, dated January 17, 2008, specifies a compliance time after the date on the service bulletin, this AD requires compliance within the specified compliance time after the effective date of this AD.

#### Alternative Methods of Compliance (AMOCs)

(g)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, ATTN: Kathleen Arrigotti, Aerospace Engineer, Airframe Branch, ANM-120S, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6426; fax (425) 917-6590; has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

Issued in Renton, Washington, on May 8, 2008.

**Michael J. Kaszycki,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. E8-11567 Filed 5-22-08; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2006-25390; Directorate Identifier 2005-NM-224-AD]

RIN 2120-AA64

#### Airworthiness Directives; Boeing Model 767 Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Supplemental notice of proposed rulemaking (NPRM); reopening of comment period.

**SUMMARY:** The FAA is revising an earlier proposed airworthiness directive (AD) for certain Boeing Model 767 airplanes. The original NPRM would have required repetitive inspections for cracking of the wing skin, and related investigative/corrective actions if necessary. The original NPRM resulted from reports of cracks found in the lower wing skin originating at the forward tension bolt holes of the aft pitch load fitting. This action revises the

original NPRM by revising certain compliance times. We are proposing this supplemental NPRM to detect and correct cracking in the lower wing skin for the forward tension bolt holes at the aft pitch load fitting, which could result in a fuel leak and reduced structural integrity of the airplane.

**DATES:** We must receive comments on this supplemental NPRM by June 17, 2008.

**ADDRESSES:** You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Tamara Anderson, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 917-6421; fax (425) 917-6590.

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

We invite you to submit any relevant written data, views, or arguments regarding this supplemental NPRM. Send your comments to an address listed in the **ADDRESSES** section. Include the docket number "Docket No. FAA-2006-25390; Directorate Identifier 2005-NM-224-AD" at the beginning of your comments. We specifically invite