

Proposed Rules

Federal Register

Vol. 73, No. 120

Friday, June 20, 2008

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2008-0644; Directorate Identifier 2007-NM-321-AD]

RIN 2120-AA64

Airworthiness Directives; BAE Systems (Operations) Limited (Jetstream) Model 4101 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to supersede an existing airworthiness directive (AD) that applies to all BAE Systems (Operations) Limited (Jetstream) Model 4101 airplanes. The existing AD currently requires repetitive tests for free movement of the capsule/bearing of the nose landing gear (NLG), and related investigative and corrective actions. This proposed AD would require a modified test for free movement of the capsule/bearing of the NLG at reduced repeat intervals, and replacement of the NLG assembly with a modified assembly. This proposed AD results from additional reports of the NLG failing to extend fully on an airplane that had been inspected in accordance with AD 2004-14-07. We are proposing this AD to prevent failure of the NLG to extend fully, which could result in reduced controllability of the airplane during landing.

DATES: We must receive comments on this proposed AD by July 21, 2008.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room

W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact British Aerospace Regional Aircraft American Support, 13850 Mclearen Road, Herndon, Virginia 20171.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Todd Thompson, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1175; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2008-0644; Directorate Identifier 2007-NM-321-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

On June 29, 2004, we issued AD 2004-14-07, amendment 39-13716 (69 FR 41413, July 9, 2004), for all BAE Systems (Operations) Limited (Jetstream) Model 4101 airplanes. That AD requires a test for free movement of the capsule/bearing of the nose landing gear (NLG), and related investigative, significant, and corrective actions. That AD resulted from incidents in which the NLG did not fully extend, necessitating an emergency landing. We issued that AD to prevent failure of the NLG to extend fully, which could result in reduced controllability of the airplane during landing.

Actions Since Existing AD Was Issued

Since we issued AD 2004-14-07, we have received additional reports of the NLG failing to extend fully on an airplane that had been inspected in accordance with AD 2004-14-07. Initial investigations suggest that high levels of friction can develop in the upper and lower sliding bearings, causing the shortening mechanism capsule of the NLG to bind, which prevents the NLG from extending fully. The high friction is caused by dirt contamination of the grease, along with wear in the composite material bearings. The manufacturer of the NLG has developed a NLG assembly that incorporates new aluminum bearings that have improved corrosion protection, and a new lubrication fitting between the bearings that allows clean grease to be applied without the need to remove the capsule exposing it to contamination.

Relevant Service Information

BAE Systems (Operations) Limited has issued Service Bulletin J41-A32-082, Revision 3, dated March 30, 2007. (We referred to Revision 1, dated February 20, 2004, of BAE Systems (Operations) Limited Alert Service Bulletin J41-A32-082 in AD 2004-14-07 as the applicable source of service information for doing the actions required in that AD.) The procedures described in this service bulletin are essentially the same as those described in Revision 1; however, Revision 3 also describes procedures for cleaning and re-lubricating the NLG shortening mechanism capsule. In addition, Revision 3 also specifies reporting any failures to the manufacturer. BAE Systems (Operations) Limited Service

Bulletin J41-A32-082, Revision 3, refers to APPH Service Bulletin AIR83586-32-22, Revision 3, dated December 2006, as an additional source of service information for doing the actions specified in BAE Systems (Operations) Limited Service Bulletin J41-A32-082.

BAE Systems (Operations) Limited has also issued Service Bulletin J41-32-084, dated November 30, 2005. The service bulletin describes procedures for installing a modified NLG assembly, which has new aluminum bearings with improved corrosion protection, and a new lubrication fitting between the bearings to allow clean grease to be applied without the need to remove the capsule. In addition, the service bulletin specifies inspecting the free movement of the NLG capsule in accordance with BAE Systems (Operations) Limited Service Bulletin J41-A32-082. BAE Systems (Operations) Limited Service Bulletin J41-32-084 refers to APPH Service Bulletin AIR83586-32-25, dated October 2005, as an additional source of service information for doing the actions specified in BAE Systems (Operations) Limited Service Bulletin J41-32-084.

Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition. The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, mandated

the service information and issued European airworthiness directive 2006-0131, dated May 18, 2006, to ensure the continued airworthiness of these airplanes in Europe.

Explanation of British Airworthiness Authority

Paragraph (a)(4) of the existing AD (paragraph (f)(4) of this NPRM) specifies making repairs using a method approved by either the FAA or the Civil Aviation Authority (CAA) (or its delegated agent). The EASA has assumed responsibility for the airplane model subject to this AD. Therefore, we have revised paragraph (f)(4) of this NPRM to specify making repairs using a method approved by the FAA, the CAA (or its delegated agent), or the EASA (or its delegated agent).

FAA's Determination and Requirements of the Proposed AD

These airplanes are manufactured in the United Kingdom and are type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, EASA has kept the FAA informed of the situation described above. We have examined EASA's findings, evaluated all pertinent information, and determined that AD

action is necessary for airplanes of this type design that are certificated for operation in the United States.

This proposed AD would supersede AD 2004-14-07 and would retain the requirements of the existing AD. This proposed AD would also require accomplishing the actions specified in the service information described previously.

Change to Existing AD

This proposed AD would retain the requirements of AD 2004-14-07. Since AD 2004-14-07 was issued, the AD format has been revised, and certain paragraphs have been rearranged. As a result, the corresponding paragraph identifiers have changed in this proposed AD, as listed in the following table:

REVISED PARAGRAPH IDENTIFIERS

Requirement in AD 2004-14-07	Corresponding requirement in this proposed AD
paragraph (a)	paragraph (f).
paragraph (b)	paragraph (g).
paragraph (c)	paragraph (h).
paragraph (d)	paragraph (l)

Costs of Compliance

The following table provides the estimated costs for U.S. operators to comply with this proposed AD.

ESTIMATED COSTS

Action	Work hours	Average labor rate per hour	Parts	Cost per airplane	Number of U.S.-registered airplanes	Fleet cost
Testing for free movement of the NLG capsule/bearing (required by AD 2004-14-07).	6	\$80	\$0	\$480, per cleaning, lubrication, and inspection cycle.	7	\$3,360, per cleaning, lubrication, and inspection cycle.
Cleaning, lubrication, and inspecting for free movement of the NLG capsule/bearing (new proposed action).	6	80	10	\$490, per cleaning, lubrication, and inspection cycle.	7	\$3,430, per cleaning, lubrication, and inspection cycle
NLG assembly replacement	6	80	3,100	\$3,580	7	\$25,060.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with

promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism

implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;

2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and

3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13 by removing amendment 39–13716 (69 FR 41413, July 9, 2004) and adding the following new airworthiness directive (AD):

BAE Systems (Operations) Limited (Formerly British Aerospace Regional Aircraft): Docket No. FAA–2008–0644; Directorate Identifier 2007–NM–321–AD.

Comments Due Date

(a) The FAA must receive comments on this AD action by July 21, 2008.

Affected ADs

(b) This AD supersedes AD 2004–14–07.

Applicability

(c) This AD applies to all BAE Systems (Operations) Limited Model Jetstream 4101 airplanes, certificated in any category.

Unsafe Condition

(d) This AD results from additional reports of the NLG failing to extend fully on an airplane that had been inspected in accordance with AD 2004–14–07. We are issuing this AD to prevent failure of the NLG to extend fully, which could result in reduced controllability of the airplane during landing.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Restatement of the Requirements of AD 2004–14–07

Service Bulletin Reference and Clarifications

(f) The term “service bulletin,” as used in this AD, means BAE Systems (Operations) Limited Alert Service Bulletin J41–A32–082, Revision 1, dated February 20, 2004; and the Accomplishment Instructions and the flow chart provided in paragraph 1.N. of BAE Systems (Operations) Limited Service Bulletin J41–A32–082, Revision 3, dated March 30, 2007. After the effective date of this AD, only Revision 3 of the service bulletin may be used.

(1) The term “flow chart,” as used in this AD, means the flow chart following paragraph 1.M. of BAE Systems (Operations) Limited Alert Service Bulletin J41–A32–082, Revision 1; or following paragraph 1.N. of BAE Systems (Operations) Limited Service Bulletin J41–A32–082, Revision 3.

(2) BAE Systems (Operations) Limited Alert Service Bulletin J41–A32–082, Revision 1, refers to APPH Service Bulletin AIR83586–32–22, Revision 1, dated February 2004, as an additional source of service information for accomplishing the actions in the BAE Systems (Operations) Limited service bulletin. BAE Systems (Operations) Limited Alert Service Bulletin J41–J32–082, Revision 3, refers to APPH Service Bulletin AIR83586–32–22, Revision 3, dated December 2006, as an additional source of service information for accomplishing the actions in the BAE Systems (Operations) Limited service bulletin.

(3) Actions accomplished before the effective date of this AD per the Accomplishment Instructions of BAE Systems (Operations) Limited Alert Service Bulletin J41–A32–082, dated February 11, 2004; Revision 1, dated February 20, 2004; or Revision 2, dated November 25, 2005; are considered acceptable for the corresponding actions required by this AD. (The original issue of BAE Systems (Operations) Limited Alert Service Bulletin J41–A32–082 refers to the original issue of APPH Service Bulletin AIR83586–32–22, dated February 2004, as an additional source of service information for accomplishing the actions in the BAE Systems (Operations) Limited service bulletin.)

(4) Where BAE Systems (Operations) Limited Alert Service Bulletin J41–A32–082, Revision 1; BAE Systems (Operations) Limited Alert Service Bulletin J41–A32–082, Revision 3; and APPH Service Bulletin AIR83586–32–22, Revision 1; specify to contact BAE Systems or APPH for repair instructions: Before further flight, repair per a method approved by the Manager, International Branch, ANM–116, FAA, Transport Airplane Directorate; the Civil Aviation Authority (CAA) (or its delegated agent); or EASA (or its delegated agent).

(5) Where the flow chart in BAE Systems (Operations) Limited Alert Service Bulletin J41–A32–082, Revision 1; or BAE Systems (Operations) Limited Alert Service Bulletin J41–A32–082, Revision 3; specifies “flying hours,” for the purposes of this AD, this means “flight hours.”

(6) Where BAE Systems (Operations) Limited Alert Service Bulletin J41–A32–082,

Revision 1; or BAE Systems (Operations) Limited Alert Service Bulletin J41–A32–082, Revision 3; specifies to complete a reporting form and return it to the manufacturer, this AD does not require that action.

(7) BAE Systems (Operations) Limited Alert Service Bulletin J41–A32–084, dated November 30, 2005, refers to APPH Service Bulletin AIR83586–32–25, dated October 2005, as an additional source of service information for accomplishing the actions in the BAE Systems (Operations) Limited service bulletin.

Initial Test

(g) Within 300 flight cycles or 30 days after August 13, 2004 (the effective date of AD 2004–14–07), whichever occurs first: Perform a test for free movement of the NLG capsule/bearing, as specified in the flow chart of the service bulletin. Do all of the actions per the Accomplishment Instructions of the service bulletin.

Note 1: As specified in the flow chart in the service bulletin, only the actions in paragraph 2.A. (Part 1) of the Accomplishment Instructions of APPH Service Bulletin AIR83586–32–22, Revision 1, dated February 2004, are required by paragraph (f) of this AD.

Related Investigative, Significant, and Corrective Actions

(h) Perform related investigative, significant, and corrective actions as specified in the flow chart of the service bulletin, at the compliance times specified in the flow chart of the service bulletin. Do all of the actions per the Accomplishment Instructions of the service bulletin, except as provided by paragraph (f)(4) of this AD. During any test, if the movement of the capsule/bearing is restricted, the applicable corrective actions must be accomplished before further flight.

Parts Installation

(i) As of August 13, 2004, no person may install a NLG on any airplane unless it has been inspected in accordance with the requirements of paragraphs (g) and (h) of this AD.

New Requirements of This AD

Repetitive Cleanings, Lubrications, and Inspections for Free Movement of the NLG Capsule

(j) Within 400 flight hours after the effective date of this AD, or within 800 flight hours after the last test done in accordance with paragraph (g) of this AD, whichever is later, but not exceeding 3,000 flight hours after the last test done in accordance with paragraph (g) of this AD; and before further flight after each scheduled or unscheduled NLG replacement: Clean, lubricate, and inspect for free movement of the NLG capsule/bearing in accordance with the service bulletin.

(1) For NLG capsules that have adequate free movement: At the applicable interval specified in paragraphs (j)(1)(i) and (j)(1)(ii) of this AD, repeat the cleaning, lubrication, and inspection for free movement of the NLG capsule/bearing in accordance with the service bulletin.

(i) For airplanes on which the modification specified in BAe Systems (Operations) Limited Service Bulletin J41–A32–084 (Modification JM41670), dated November 30, 2005, has not been accomplished, repeat the actions specified in paragraph (j)(1) of this AD at intervals not to exceed 800 flight hours after the last inspection done in accordance with paragraph (j) of this AD.

(ii) For airplanes on which the modification specified in BAe Systems (Operations) Limited Service Bulletin J41–A32–084 (Modification JM41670), dated November 30, 2005, has been accomplished, repeat the actions specified in paragraph (j)(1) of this AD at intervals not to exceed 3,000 flight hours after the last inspection done in accordance with paragraph (j) of this AD.

(2) For NLG capsules that do not have adequate free movement: Before further flight, replace the NLG assembly with a serviceable assembly in accordance with the service bulletin. Thereafter, repeat the actions specified in paragraph (j) of this AD at the applicable interval specified in paragraph (j)(1) of this AD.

Replace the NLG Assembly With a Modified NLG Assembly

(k) Within 48 months after the effective date of this AD: Replace the NLG assembly with a modified assembly, in accordance with BAe Systems (Operations) Limited Service Bulletin J41–32–084, dated November 30, 2005. Thereafter, repeat the actions specified in paragraph (j) of this AD at the applicable interval specified in paragraph (j)(1) of this AD.

Parts Installation

(l) As of the effective date of this AD, no person may install a NLG on any airplane unless it has been inspected in accordance with paragraph (j) of this AD.

Alternative Methods of Compliance (AMOCs)

(m)(1) The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Related Information

(n) European Aviation Safety Agency airworthiness directive 2006–0131, dated May 18, 2006, also addresses the subject of this AD.

Issued in Renton, Washington, on June 9, 2008.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8–13919 Filed 6–19–08; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2008–0645; Directorate Identifier 2007–NM–358–AD]

RIN 2120–AA64

Airworthiness Directives; Boeing Model 707 Airplanes and Model 720 and 720B Series Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all Boeing Model 707 airplanes and Model 720 and 720B series airplanes. This proposed AD would require performing an operational test of the engine fuel suction feed of the fuel system, and other related testing if necessary. This proposed AD results from a report of in-service occurrences of loss of fuel system suction feed capability, followed by total loss of pressure of the fuel feed system. We are proposing this AD to detect and correct failure of the engine fuel suction feed of the fuel system, which could result in multi-engine flameout, inability to restart the engines, and consequent forced landing of the airplane.

DATES: We must receive comments on this proposed AD by August 4, 2008.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124–2207.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through

Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800–647–5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Sue Lucier, Aerospace Engineer, Propulsion Branch, ANM–140S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, Washington 98057–3356; telephone (425) 917–6438; fax (425) 917–6590.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA–2008–0645; Directorate Identifier 2007–NM–358–AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We have received a report of in-service occurrences of loss of fuel system suction feed capability, followed by total loss of pressure of the fuel feed system. This report prompted us to review the service history of all Boeing airplane models, and we found instances of loose and leaking fuel line fittings. This condition, if not corrected, could result in multi-engine flameout, inability to restart the engines, and consequent forced landing of the airplane.

Explanation of Relevant Service Information

We have reviewed Boeing Alert Service Bulletin A3527, dated November 7, 2007. The service bulletin describes procedures for performing an operational test of the engine fuel suction feed of the fuel system, and other related testing if necessary. The other related testing includes doing a vacuum test on the applicable engine for leakage if an engine’s N1, N2, or fuel-