

Affected ADs

(b) None.

Applicability

(c) This AD applies to CAP 10B airplanes, all serial numbers up to and including 282, certificated in any category.

Subject

(d) Air Transport Association of America (ATA) Code 08: Leveling and Weighing.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

It has been determined that the currently used values for Arms of front and rear fuel tanks, and luggage compartment from the CAP 10B Airplane Flight Manuals (AFM), must be rectified.

If left uncorrected, these weight and balance data could lead to erroneous determination of the location of the Center of Gravity (CG) and possibly cause operation with the CG outside the approved limits which may result in control difficulty.

To prevent this condition, the present Airworthiness Directive (AD) mandates revision of the AFM which introduces the corrected values and replaces the previous loading graphs by loading tables.

Actions and Compliance

(f) Unless already done, within the next 50 hours time-in-service (TIS) after August 12, 2008 (the effective date of this AD), incorporate Apex Aircraft AVION CAP 10B Document Number 1000977 GB, Revision 8, dated February 2007 into the limitations section of the airplane flight manual as specified in APEX Aircraft Service Bulletin No. 030502, dated April 11, 2008. The owner/operator holding at least a private pilot certificate as authorized by section 43.7 of the Federal Aviation Regulations 14 CFR 43.7 may do this action. Make an entry in the aircraft records showing compliance with this portion of the AD following 14 CFR 43.9.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Sarjapur Nagarajan, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4145; fax: (816) 329-4090. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved.

Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency (EASA) AD No. 2008-0071, dated April 15, 2008; and APEX Aircraft Service Bulletin No. 030502, dated April 11, 2008, for related information.

Material Incorporated by Reference

(i) You must use APEX Aircraft Service Bulletin No. 030502, dated April 11, 2008, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Apex Aircraft, Bureau de Navigabilité, 1 route de Troyes, 21121 DAROIS, France.

(3) You may review copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on June 19, 2008.

David R. Showers,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-14484 Filed 7-7-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2008-0272; Directorate Identifier 2007-NM-275-AD; Amendment 39-15594; AD 2008-13-31]

RIN 2120-AA64

Airworthiness Directives; Dassault Model Falcon 2000 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results

from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

In service events have shown that, after implementation of Dassault Aviation SB (service bulletin) F2000-133 and F2000-166, a risk of engine cowlings separation from the airplane still exists, and may cause potential damages to the engine itself and to the horizontal stabilizer.

It is suspected that on-ground improper latching may lead to a radial deformation of engine cowlings in flight and to their eventual escape out of their locking devices. This situation may represent a hazard to the aircraft propulsive system and/or its structural integrity.

* * * * *

We are issuing this AD to require actions to correct the unsafe condition on these products.

DATES: This AD becomes effective August 12, 2008.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of August 12, 2008.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:**Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on March 13, 2008 (73 FR 13511). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

In service events have shown that, after implementation of Dassault Aviation SB (service bulletin) F2000-133 and F2000-166, a risk of engine cowlings separation from the airplane still exists, and may cause potential damages to the engine itself and to the horizontal stabilizer.

It is suspected that on-ground improper latching may lead to a radial deformation of engine cowlings in flight and to their eventual escape out of their locking devices.

This situation may represent a hazard to the aircraft propulsive system and/or its structural integrity.

The purpose of this Airworthiness Directive (AD) is to secure safe closure of engine cowlings and improve the existing locking devices.

You may obtain further information by examining the MCAI in the AD docket.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

We reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have required different actions in this AD from those in the MCAI in order to follow our FAA policies. Any such differences are highlighted in a NOTE within the AD.

Costs of Compliance

We estimate that this AD will affect about 229 products of U.S. registry. We also estimate that it will take about 90 work-hours per product to comply with the basic requirements of this AD. The average labor rate is \$80 per work-hour. Required parts will cost about \$0 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these parts. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here. Based on these figures, we estimate the cost of this AD to the U.S. operators to be \$1,648,800, or \$7,200 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more

detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General Requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

2008-13-31 Dassault Aviation:

Amendment 39-15594. Docket No. FAA-2008-0272; Directorate Identifier 2007-NM-275-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective August 12, 2008.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Dassault Model Falcon 2000 airplanes, certificated in any category, all serial numbers, except those that have incorporated Modification M2275 during production or Dassault Service Bulletin F2000-298 in service.

Subject

(d) Air Transport Association (ATA) of America Code 54: Nacelles/Pylons.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

In service events have shown that, after implementation of Dassault Aviation SB (service bulletin) F2000-133 and F2000-166, a risk of engine cowlings separation from the airplane still exists, and may cause potential damages to the engine itself and to the horizontal stabilizer.

It is suspected that on-ground improper latching may lead to a radial deformation of engine cowlings in flight and to their eventual escape out of their locking devices. This situation may represent a hazard to the aircraft propulsive system and/or its structural integrity.

The purpose of this Airworthiness Directive (AD) is to secure safe closure of engine cowlings and improve the existing locking devices.

Actions and Compliance

(f) Within 12 months after the effective date of this AD unless already done, do the following actions.

(1) Modify the existing engine cowlings locking system in accordance with the instructions contained in Dassault Service Bulletin F2000-298, Revision 3, dated September 26, 2007.

(2) Before or concurrent with the modification required by paragraph (f)(1) of this AD, modify the engine cowling attachments in accordance with the instructions contained in Dassault Service Bulletin F2000-166, Revision 1, dated October 24, 2001 (Modification M1579).

(3) Actions done before the effective date of this AD in accordance with Dassault Service Bulletins F2000-298, Revision 1,

dated October 31, 2006, or Revision 2, dated April 12, 2007; and F2000-166, dated June 27, 2001; are acceptable for compliance with the corresponding actions of this AD.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) **Alternative Methods of Compliance (AMOCs):** The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) **Airworthy Product:** For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) **Reporting Requirements:** For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency Airworthiness Directive 2007-0016, dated January 12, 2007; and Dassault Service Bulletins F2000-166, Revision 1, dated October 24, 2001; and F2000-298, Revision 3, dated September 26, 2007; for related information.

Material Incorporated by Reference

(i) You must use Dassault Service Bulletin F2000-166, Revision 1, dated October 24, 2001; and Dassault Service Bulletin F2000-298, Revision 3, dated September 26, 2007; to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Dassault Falcon Jet, P.O. Box 2000, South Hackensack, New Jersey 07606.

(3) You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call

(202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on June 8, 2008.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-14579 Filed 7-7-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2008-0673; Directorate Identifier 2008-NM-117-AD; Amendment 39-15606; AD 2008-14-11]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 777-200, -200LR, -300, and -300ER Series Airplanes Approved for Extended-Range Twin-Engine Operational Performance Standards (ETOPS)

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain Boeing Model 777-200, -200LR, -300, and -300ER series airplanes. This AD requires a one-time inspection to determine the part number of the cargo compartment fire suppression filter/regulator. This AD also requires, for certain airplanes, a revision of the "Maximum Diversion Time in Minutes" for ETOPS operation specified in the Operations Specifications. For certain airplanes, this AD also provides for optional replacement of the cargo compartment fire suppression filter/regulator, which would allow revision of the "Maximum Diversion Time in Minutes" for ETOPS operation specified in the Operations Specifications to restore the airplane's full ETOPS capability. This AD results from a report that the filter/regulator installed in the cargo fire suppression system did not meter the Halon for the certified duration during ETOPS flight tests. We are issuing this AD to prevent ETOPS operation with insufficient cargo fire suppression capability, which could result in an uncontained fire in the cargo compartment.

DATES: This AD is effective July 23, 2008.

The Director of the Federal Register approved the incorporation by reference

of certain publications listed in this AD as of July 23, 2008.

We must receive comments on this AD by September 8, 2008.

ADDRESSES: You may send comments by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** 202-493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>;

person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Robert Hettman, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM-150S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6457; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:

Discussion

This AD results from a report that the filter/regulator installed in the cargo fire suppression system did not meter the Halon for the certified duration during extended-range twin-engine operational performance standards (ETOPS) flight tests conducted by Boeing. Results of an investigation by the filter/regulator supplier, Kidde Aerospace, showed that an incorrect test adapter was used during the calibration procedure to set the filter/regulator flow rate. The incorrect test adapter affected the calibrated flow rate setting, allowing the Halon to flow too fast, resulting in less cargo fire suppression duration. It is