

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2008-0470 Directorate Identifier 2008-CE-026-AD; Amendment 39-15645; AD 2008-17-07]

RIN 2120-AA64

Airworthiness Directives; APEX Aircraft Model CAP 10 B Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

An internal review evidenced that the flight controls tie rod bolts currently installed on the airplane are not in accordance with the design data. Indeed the bolt shank length has been determined too short and the material properties of the spacers have been found inadequate according to the prescribed torque value.

Therefore, bolts' threads could be subject to excessive wear, which might induce play in flight controls and consequently, induce vibrations in the control surfaces and reduce the airplane handling.

We are issuing this AD to require actions to correct the unsafe condition on these products.

DATES: This AD becomes effective September 23, 2008.

On September 23, 2008, the Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Sarjapur Nagarajan, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; *telephone:* (816) 329-4145; *fax:* (816) 329-4090.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on June 13, 2008 (73 FR 33738). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

An internal review evidenced that the flight controls tie rod bolts currently installed on the airplane are not in accordance with the design data. Indeed the bolt shank length has been determined too short and the material properties of the spacers have been found inadequate according to the prescribed torque value.

Therefore, bolts' threads could be subject to excessive wear, which might induce play in flight controls and consequently, induce vibrations in the control surfaces and reduce the airplane handling.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

We reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have required different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a NOTE within the AD.

Costs of Compliance

Based on the service information, we estimate that this AD will affect 31 products of U.S. registry. We also estimate that it will take about 3 work-hours per product to comply with basic requirements of this AD. The average labor rate is \$80 per work-hour. Required parts will cost about \$100 per product.

Based on these figures, we estimate the cost of this AD to the U.S. operators to be \$10,540 or \$340 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD Docket.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

2008-17-07 APEX Aircraft: Amendment 39-15645; Docket No. FAA-2008-0470; Directorate Identifier 2008-CE-026-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective September 23, 2008.

Affected ADs

(b) None.

Applicability

(c) This AD applies to the following Model CAP 10 B airplanes, certificated in any category:

- (1) Serial numbers 300 through 317; and
- (2) All other serial numbers that incorporate APEX change 000302 (fibre carbon wing spars).

Subject

(d) Air Transport Association of America (ATA) Code 27: Flight Controls.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

An internal review evidenced that the flight controls tie rod bolts currently installed on the airplane are not in accordance with the design data. Indeed the bolt shank length has been determined too short and the material properties of the spacers have been found inadequate according to the prescribed torque value.

Therefore, bolts' threads could be subject to excessive wear, which might induce play in flight controls and consequently, induce vibrations in the control surfaces and reduce the airplane handling.

To prevent this condition, the present Airworthiness Directive (AD) mandates replacement of the tie rod bolts and spacers.

Actions and Compliance

(f) Unless already done, do the following actions:

- (1) Within 50 hours time-in-service after September 23, 2008 (the effective date of this AD), remove tie rod bolts part number (P/N) 95.56.11.066 and spacers P/N 11.56.27.038 and replace them with tie rod bolts P/N 95.56.11.418 and spacers P/N 11.56.27.138,

following APEX Aircraft Service Bulletin No. 040206, dated September 21, 2007.

(2) As of September 23, 2008 (the effective date of this AD), do not install any tie rod bolt P/N 95.56.11.066 or spacer P/N 11.56.27.038.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Sarjapur Nagarajan, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; *telephone:* (816) 329-4145; *fax:* (816) 329-4090. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency (EASA) AD No. 2008-0060, dated April 1, 2008; and APEX Aircraft Service Bulletin No. 040206, dated September 21, 2007, for related information.

Material Incorporated by Reference

(i) You must use APEX Aircraft Service Bulletin No. 040206, dated September 21, 2007, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Apex Aircraft, Bureau de Navigabilité, 1 route de Troyes, 21121 DAROIS, France.

(3) You may review copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on August 7, 2008.

Kim Smith,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-18807 Filed 8-18-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF JUSTICE**28 CFR Part 14****Administrative Claims Under the Federal Tort Claims Act; Delegation of Authority**

AGENCY: Department of Justice.

ACTION: Final rule.

SUMMARY: On June 17, 2003, the Assistant Attorney General in charge of the Civil Division delegated to the Secretary of Homeland Security the authority to settle administrative tort claims presented pursuant to the Federal Tort Claims Act where the amount of the settlement does not exceed \$50,000. By including this delegation of authority in the Code of Federal Regulations, the Civil Division is alerting the general public to the delegation. This rule also implements the Administrative Dispute Resolution Act.

EFFECTIVE DATE: August 19, 2008.

FOR FURTHER INFORMATION CONTACT: Phyllis J. Pyles, Director, Torts Branch, Civil Division, U.S. Department of Justice, P.O. Box 888, Washington, DC 20044, (202) 616-4400.

SUPPLEMENTARY INFORMATION: This rule is a delegation of authority from the Assistant Attorney General for the Civil Division to the Secretary of Homeland Security, a matter solely related to the division of responsibility between the Department of Justice and the Department of Homeland Security. As such, this rule is a rule of agency organization, procedure, and practice that is limited to matters of agency management and personnel. Accordingly: (1) This rule is exempt from the notice requirement of 5 U.S.C. * 553(b) and is made effective upon issuance; (2) the Department certifies under 5 U.S.C. * 605(b) that this rule will not have a significant economic impact on a substantial number of small entities and further that no Regulatory Flexibility Analysis was required to be prepared for this final rule since the Department was not required to publish a general notice of proposed rulemaking; (3) this action is not a "regulation" or "rule" as defined by Executive Order 12866, "Regulatory