

# Proposed Rules

Federal Register

Vol. 73, No. 181

Wednesday, September 17, 2008

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2008-0990; Directorate Identifier 2008-CE-060-AD]

RIN 2120-AA64

#### Airworthiness Directives; Pilatus Aircraft Ltd. Model PC-6 Series Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

This Airworthiness Directive (AD) is prompted by a potential problem with the freedom of the brake pedals of some PC-6 series aircraft.

The freedom of the brake pedals could be prevented because of an insufficient clearance between the rudder bar lugs on a few aircraft. In such conditions, it is possible that the master brake cylinder is not re-filled with the fluid from the reservoir, which can lead to a degradation of brake effectiveness. Mostly during landing, this can lead to difficulties with the directional control of the aircraft on ground and could cause a runway excursion.

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

**DATES:** We must receive comments on this proposed AD by October 17, 2008.

**ADDRESSES:** You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

#### FOR FURTHER INFORMATION CONTACT:

Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; fax: (816) 329-4090.

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2008-0990; Directorate Identifier 2008-CE-060-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

#### Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued AD No.: 2008-0171, dated September 9, 2008 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

This Airworthiness Directive (AD) is prompted by a potential problem with the freedom of the brake pedals of some PC-6 series aircraft.

The freedom of the brake pedals could be prevented because of an insufficient clearance between the rudder bar lugs on a few aircraft. In such conditions, it is possible that the master brake cylinder is not re-filled with the fluid from the reservoir, which can lead to a degradation of brake effectiveness. Mostly during landing, this can lead to difficulties with the directional control of the aircraft on ground and could cause a runway excursion.

For the reason stated above, the present Airworthiness Directive mandates a check of the brake pedals for full and free movement and, if any damage is found, the modification of the brake pedals to restore their freedom.

You may obtain further information by examining the MCAI in the AD docket.

#### Relevant Service Information

Pilatus Aircraft Ltd. has issued Pilatus PC-6 Service Bulletin No. 32-002, Revision 2, dated April 29, 2008. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

#### FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

#### Differences Between This Proposed AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use

different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a Note within the proposed AD.

#### Costs of Compliance

We estimate that this proposed AD will affect 50 products of U.S. registry. We also estimate that it would take about 2 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$80 per work-hour.

Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$8,000, or \$160 per product.

In addition, we estimate that any necessary follow-on actions would take about 10 work-hours and require parts costing \$100, for a cost of \$900 per product. We have no way of determining the number of products that may need these actions.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and

responsibilities among the various levels of government.

*For the reasons discussed above, I certify this proposed regulation:*

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

#### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

**Pilatus Aircraft Ltd.:** Docket No. FAA-2008-0990; Directorate Identifier 2008-CE-060-AD.

#### Comments Due Date

- (a) We must receive comments by October 17, 2008.

#### Affected ADs

- (b) None.

#### Applicability

- (c) This AD applies to Models PC-6, PC-6-H1, PC-6-H2, PC-6/350, PC-6/350-H1, PC-6/350-H2, PC-6/A, PC-6/A-H1, PC-6/A-H2, PC-6/B-H2, PC-6/B1-H2, PC-6/B2-H2, PC-6/B2-H4, PC-6/C-H2, and PC-6/C1-H2 airplanes, manufacturer serial numbers (MSN) 101 through 950 and MSN 2001 through 2092, certificated in any category.

**Note 1:** These airplanes may also be identified as Fairchild Republic Company PC-6 airplanes, Fairchild Industries PC-6 airplanes, Fairchild Heli Porter PC-6 airplanes, or Fairchild-Hiller Corporation PC-6 airplanes.

#### Subject

- (d) Air Transport Association of America (ATA) Code 32: Landing Gear.

#### Reason

- (e) The mandatory continuing airworthiness information (MCAI) states:

This Airworthiness Directive (AD) is prompted by a potential problem with the freedom of the brake pedals of some PC-6 series aircraft.

The freedom of the brake pedals could be prevented because of an insufficient clearance between the rudder bar lugs on a few aircraft. In such conditions, it is possible that the master brake cylinder is not re-filled with the fluid from the reservoir, which can lead to a degradation of brake effectiveness. Mostly during landing, this can lead to difficulties with the directional control of the aircraft on ground and could cause a runway excursion.

For the reason stated above, the present Airworthiness Directive mandates a check of the brake pedals for full and free movement and, if any damage is found, the modification of the brake pedals to restore their freedom.

#### Actions and Compliance

(f) Unless already done, do the following actions:

- (1) Inspect the brake pedals for full and free movement within 100 hours time-in-service after the effective date of this AD or 12 months after the effective date of this AD, whichever occurs first, following the accomplishment instructions of Pilatus Aircraft Ltd. Pilatus PC-6 Service Bulletin No. 32-002, Revision 2, dated April 29, 2008.

(2) If as a result of the inspection required by paragraph (f)(1) of this AD any stiffness or limited movement of a brake pedal is found, before further flight, perform the corrective actions in accordance with the paragraph 3.C. of the accomplishment instructions of Pilatus Aircraft Ltd. Pilatus PC-6 Service Bulletin No. 32-002, Revision 2, dated April 29, 2008.

(3) As of the effective date of this AD, do not install any pilot or co-pilot rudder pedal assembly Part Number (P/N) 6232.0011.00, P/N 6232.0255.52, P/N 116.35.06.050, P/N 116.35.06.053, or P/N 116.35.06.054 unless it has been inspected and modified as applicable in accordance with paragraphs (f)(1) and (f)(2) of this AD.

#### FAA AD Differences

**Note 2:** This AD differs from the MCAI and/or service information as follows: No differences.

#### Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; fax: (816) 329-4090. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective

actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) **Reporting Requirements:** For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 et seq.), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

#### Related Information

(h) Refer to MCAI European Aviation Safety Agency AD No.: 2008-0171, dated September 9, 2008; and Pilatus Aircraft Ltd. Pilatus PC-6 Service Bulletin No. 32-002, Revision 2, dated April 29, 2008, for related information.

Issued in Kansas City, Missouri, on September 10, 2008.

**James E. Jackson,**

*Acting Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. E8-21691 Filed 9-16-08; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2008-0991; Directorate Identifier 2008-CE-054-AD]

RIN 2120-AA64

#### Airworthiness Directives; Diamond Aircraft Industries GmbH Model DA 42 Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

In-service experience indicates that the powder coating of the rear right hand (RH) engine support bracket degrades over time, leading to a reduced torque of the engine mounting bolts. In some cases, bolts had fully unscrewed and fell into the engine cowling. One case was reported where the pilot had to shut down an engine in flight because of a failed V-belt, the cause of failure assumed to be one of these bolts. This condition, if not corrected, may lead to further cases of loose bolts and subsequent

damage to the engine or accessories in the engine compartment, possibly resulting in in-flight engine shut-down and reduced control of the aircraft.

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

**DATES:** We must receive comments on this proposed AD by October 17, 2008.

**ADDRESSES:** You may send comments by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** (202) 493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Sarjapur Nagarajan, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4145; fax: (816) 329-4090.

#### SUPPLEMENTARY INFORMATION:

#### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2008-0991; Directorate Identifier 2008-CE-054-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to [http://](http://www.regulations.gov)

[www.regulations.gov](http://www.regulations.gov), including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

#### Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued AD No. 2008-0139, dated July 24, 2008 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

In-service experience indicates that the powder coating of the rear right hand (RH) engine support bracket degrades over time, leading to a reduced torque of the engine mounting bolts. In some cases, bolts had fully unscrewed and fell into the engine cowling. One case was reported where the pilot had to shut down an engine in flight because of a failed V-belt, the cause of failure assumed to be one of these bolts. This condition, if not corrected, may lead to further cases of loose bolts and subsequent damage to the engine or accessories in the engine compartment, possibly resulting in in-flight engine shut-down and reduced control of the aircraft.

To address and correct this situation, DAI has published MSB-42-058, providing instructions to accomplish repetitive inspections and correction of the fastening torque of the affected engine mounting bolts and replacement of the bolts with wire-secured bolts Part Number (P/N) D60-9071-26-01, after which the repetitive torque checks are no longer required.

For the reasons described above, this EASA AD requires the accomplishment of repetitive torque checks of the affected engine mounting bolts and replacement of the bolts with wire-secured bolts.

You may obtain further information by examining the MCAI in the AD docket.

#### Relevant Service Information

Diamond Aircraft Industries GmbH has issued Mandatory Service Bulletin No. MSB-42-058, dated May 21, 2008; and Work Instruction WI-MSB-42-058, dated March 12, 2008. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

#### FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe