

Issued in Kansas City, Missouri.

Kim Smith,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-24137 Filed 10-15-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2008-1088; Directorate Identifier 2008-NE-15-AD; Amendment 39-15691; AD 2008-21-07]

RIN 2120-AA64

Airworthiness Directives; Dowty Propellers R408 Series Propellers

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule; request for comments.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

Three in-service propellers have been found to have blades which have lost the bonded metallic leading edge guard. If the leading edge guard comes off as the propeller turns, it could cause secondary damage to aircraft or injury to personnel. For the reasons described above, EASA issued Emergency AD 2007-0223-E to require repetitive inspections of the blade Leading Edge (L/E) guards for correct bonding until they accumulate more than 1,200 flight hours (FH) time in service.

This AD requires actions that are intended to address the unsafe condition described in the MCAI, which could result in the loss of the bonded metallic leading edge guard, and could result in damage to the airplane or injury to personnel.

DATES: This AD becomes effective October 31, 2008.

We must receive comments on this AD by November 17, 2008.

The Director of the Federal Register approved the incorporation by reference of Dowty Propellers Alert Service Bulletin (ASB) D8400-61-A69, dated August 15, 2007, and ASB D8400-61-A69, Revision 1, dated September 18, 2007, listed in the AD as of October 31, 2008.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.
- *Mail:* U.S. Department of Transportation, 1200 New Jersey Avenue, SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001.
- *Hand Delivery:* Deliver to mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.
- *Fax:* (202) 493-2251.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is the same as the mail address provided in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Terry Fahr, Aerospace Engineer, Boston Aircraft Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; e-mail: terry.fahr@faa.gov; telephone (781) 238-7155; fax (781) 238-7170.

SUPPLEMENTARY INFORMATION:

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Airworthiness Directive 2007-0223 R2, dated October 26, 2007, (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

Three in-service propellers have been found to have blades which have lost the bonded metallic leading edge guard. If the leading edge guard comes off as the propeller turns, it could cause secondary damage to aircraft or injury to personnel.

For the reasons described above, EASA issued Emergency AD 2007-0223-E to require repetitive inspections of the blade Leading Edge (L/E) guards for correct bonding until they accumulate more than 1,200 FH time in service. Revision 1 of this AD was issued to clarify the required inspections and follow-up actions depending on findings and to make

reference to the latest Dowty Alert Service Bulletin (ASB) revision.

This AD has been further revised for clarification, specifying that blades repaired at the tip are only allowed to continue up to 500 hours in service after repair. This limitation was already in the Dowty ASB and the Note is added to the AD to avoid the impression that the AD does not require the same limitation.

You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

Dowty Propellers has issued Alert Service Bulletins D8400-61-A69, dated August 15, 2007; and Revision 1, dated September 18, 2007. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of This AD

This product has been approved by the aviation authority of the United Kingdom, and is approved for operation in the United States. Pursuant to our bilateral agreement with the United Kingdom, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are issuing this AD because we evaluated all information provided by the United Kingdom and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

An unsafe condition exists that requires the immediate adoption of this AD. The FAA has found that the risk to the flying public justifies waiving notice and comment prior to adoption of this rule because the required compliance time to detect the unsafe condition is too short for public comment. Therefore, we determined that notice and opportunity for public comment before issuing this AD are impracticable and that good cause exists for making this amendment effective in fewer than 30 days.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety, and we did not precede it by notice and opportunity for public comment. We invite you to send any written relevant data, views, or arguments about this AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2008-1088; Directorate Identifier 2008-NE-15-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of

this AD. We will consider all comments received by the closing date and may amend this AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

2008–21–07 Dowty Propellers (Formerly Dowty Aerospace Propellers):
Amendment 39–15691; Docket No. FAA–2008–1088; Directorate Identifier 2008–NE–15–AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective October 31, 2008.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Dowty Propellers model R408/6–123–F/17 propellers with blades, part numbers (P/Ns) 697071200–18, 697071210–18, 697071227–18, 697071240–18, 697071245–18, or 697071257–18, installed. These propellers are installed on, but not limited to, Bombardier, Inc. (formerly de Havilland Canada) models DHC–8–400, DHC–8–401, and DHC–8–402 series airplanes.

Reason

(d) Three in-service propellers have been found to have blades which have lost the bonded metallic leading edge guard. If the leading edge guard comes off as the propeller turns, it could cause secondary damage to aircraft or injury to personnel. For the reasons described above, EASA issued Emergency AD 2007–0223–E to require repetitive inspections of the blade Leading Edge (L/E) guards for correct bonding until they accumulate more than 1,200 flight hours (FH) time in service.

This AD requires actions that are intended to address the unsafe condition described in the MCAI, which could result in the loss of the bonded metallic leading edge guard, which could result in damage to the airplane or injury to personnel.

Actions and Compliance

(e) Unless already done, do the following actions.

(1) Within the next 50 FH or within 1 month after the effective date of this AD, whichever occurs first, inspect all the concerned blade assemblies where the bonded metallic L/E guard has accumulated 1,200 FH or less since installation, in accordance with the instructions of Dowty Propellers ASB No. D8400–61–A69;

(2) Within 50 FH or 1 month after installing a replacement blade, inspect the

concerned blade assembly where the bonded metallic L/E guard has accumulated 1,200 FH or less since installation, in accordance with the instructions of Dowty Propellers ASB No. D8400–61–A69;

(3) After the inspection as required by paragraph (1) or (2) of this AD, as applicable, at intervals not to exceed 100 FH, repeat the inspection of the concerned blade assemblies in accordance with the instructions of Dowty Propellers ASB No. D8400–61–A69 until the bonded blade L/E guard has accumulated more than 1,200 FH since installation;

(4) When, during any of the inspections as required by paragraphs (1), (2) or (3) of this AD, disbonding is found, apply the criteria as indicated in Appendix A of Dowty Propellers ASB No. D8400–61–A69 Revision 1 and, within the associated time period, repair or replace the affected blade assembly, as necessary, in accordance with the instructions of Dowty Propellers ASB No. D8400–61–A69 Revision 1.

(f) Blades that have been repaired within the first 101.6 mm (4.0 inches) of the tip of the blade as specified in Appendix D of the referenced ASB are allowed to continue in service for another 500 FH after accomplishment of the repair. Repair does not terminate the repetitive inspection requirements of paragraph (e)(3) of this directive.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Boston Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

(2) *Special Flight Permits:* We are prohibiting special flight permits.

Related Information

(h) Refer to MCAI Airworthiness Directive 2007–0223, Revision 2, dated October 26, 2007, and Dowty Propellers Alert Service Bulletin (ASB) D8400–61–A69, dated August 15, 2007 or Revision 1, dated September 18, 2007, for related information.

(i) Contact Terry Fahr, Aerospace Engineer, Boston Aircraft Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; e-mail: terry.fahr@faa.gov; telephone (781) 238–7155; fax (781) 238–7170, for more information about this AD.

Material Incorporated by Reference

(j) You must use the service information specified in Table 1 of this AD to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Dowty Propellers, Anson Business Park, Cheltenham Road East, Gloucester GL2 9QN, UK; Telephone 44 (0) 1452 716000; fax 44 (0) 1452 716001.

(3) You may review copies at the FAA, New England Region, 12 New England Executive Park, Burlington, MA; or at the National Archives and Records

Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: [http://](http://www.archives.gov/federal-register/cfr/ibr-locations.html)

www.archives.gov/federal-register/cfr/ibr-locations.html.

TABLE 1—MATERIAL INCORPORATED BY REFERENCE

Alert Service Bulletin No.	Page	Revision	Date
D8400-61-A69, Total Pages—4	1	1	September 18, 2007.
	2	Original	August 15, 2007.
	3	1	September 18, 2007.
	4	Original	August 15, 2007.
D8400-61-A69, Appendix A, Total Pages—4	1	1	September 18, 2007.
	2 to 4	Original	August 15, 2007.
D8400-61-A69, Appendix B, Total Pages—1	All	Original	August 15, 2007.
D8400-61-A69, Appendix C, Total Pages—3	All	Original	August 15, 2007.
D8400-61-A69, Appendix D, Total Pages—2	All	1	September 18, 2007.

Issued in Burlington, Massachusetts, on October 3, 2008.

Thomas A. Boudreau,

Acting Assistant Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. E8-24252 Filed 10-15-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 97

[Docket No. 30631; Amdt. No 3290]

Standard Instrument Approach Procedures, and Takeoff Minimums and Obstacle Departure Procedures; Miscellaneous Amendments

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs) and associated Takeoff Minimums and Obstacle Departure Procedures for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, adding new obstacles, or changing air traffic requirements. These changes are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

DATES: This rule is effective October 16, 2008. The compliance date for each SIAP, associated Takeoff Minimums, and ODP is specified in the amendatory provisions.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of October 16, 2008.

ADDRESSES: Availability of matters incorporated by reference in the amendment is as follows:

For Examination—

1. FAA Rules Docket, FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591;
2. The FAA Regional Office of the region in which the affected airport is located;
3. The National Flight Procedures Office, 6500 South MacArthur Blvd., Oklahoma City, OK 73169 or,
4. The National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

*Availability—*All SIAPs and Takeoff Minimums and ODPs are available online free of charge. Visit <http://www.nfdc.faa.gov> to register. Additionally, individual SIAP and Takeoff Minimums and ODP copies may be obtained from:

1. FAA Public Inquiry Center (APA-200), FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591; or
2. The FAA Regional Office of the region in which the affected airport is located.

FOR FURTHER INFORMATION CONTACT:

Harry J. Hodges, Flight Procedure Standards Branch (AFS-420), Flight Technologies and Programs Divisions, Flight Standards Service, Federal Aviation Administration, Mike Monroney Aeronautical Center, 6500 South MacArthur Blvd. Oklahoma City, OK 73169 (Mail Address: P.O. Box 25082, Oklahoma City, OK 73125) Telephone: (405) 954-4164.

SUPPLEMENTARY INFORMATION: This rule amends Title 14 of the Code of Federal Regulations, Part 97 (14 CFR part 97), by establishing, amending, suspending, or revoking SIAPs, Takeoff Minimums and/or ODPs. The complete regulators' description of each SIAP and its associated Takeoff Minimums or ODP for an identified airport is listed on FAA form documents which are incorporated by reference in this amendment under 5 U.S.C.552(a), 1 CFR part 51, and 14 CFR part 97.20. The applicable FAA Forms are FAA Forms 8260-3, 8260-4, 8260-5, 8260-15A, and 8260-15B when required by an entry on 8260-15A.

The large number of SIAPs, Takeoff Minimums and ODPs, in addition to their complex nature and the need for a special format make publication in the **Federal Register** expensive and impractical. Furthermore, airmen do not use the regulatory text of the SIAPs, Takeoff Minimums or ODPs, but instead refer to their depiction on charts printed by publishers of aeronautical materials. The advantages of incorporation by reference are realized and publication of the complete description of each SIAP, Takeoff Minimums and ODP listed on FAA forms is unnecessary. This amendment provides the affected CFR sections and specifies the types of SIAPs and the effective dates of the associated Takeoff Minimums and ODPs. This amendment also identifies the airport and its location, the procedure, and the amendment number.

The Rule

This amendment to 14 CFR part 97 is effective upon publication of each separate SIAP, Takeoff Minimums and ODP as contained in the transmittal. Some SIAP and Takeoff Minimums and textual ODP amendments may have been issued previously by the FAA in a Flight Data Center (FDC) Notice to Airmen (NOTAM) as an emergency action of immediate flight safety relating directly to published aeronautical