

McDonnell Douglas DC-10 Service Bulletin —	Revision—	Dated—	For airplanes with—
DC10-53-109	6	July 10, 2008	Extended wing-to-fuselage fillets.
DC10-53-111	5	March 19, 2008	Conventional wing-to-fuselage fillets.

Unsafe Condition

(d) This AD results from fuel system reviews conducted by the manufacturer. We are issuing this AD to reduce the potential of ignition sources inside fuel tanks in the event of a severe lightning strike, which, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Restatement of Requirements of AD 2006-16-03

Installation or Replacement

(f) For airplanes with manufacturer's fuselage numbers identified in the applicable

service bulletin listed in Table 2 of this AD: Within 7,500 flight hours or 60 months after September 7, 2006 (the effective date of AD 2006-16-03), whichever occurs earlier: Install or replace with improved parts, as applicable, the bonding straps between the metallic frame of the fillet and the wing leading edge ribs, on both the left and right sides of the airplane, in accordance with the Accomplishment Instructions of the applicable service bulletin identified in Table 1 or Table 2 of this AD.

TABLE 2—FUSELAGE NUMBERS AFFECTED BY AD 2006-16-03

McDonnell Douglas DC-10 Service Bulletin—	Revision—	Dated—	For airplanes with—
53-109	4	October 7, 1992	Extended wing-to-fuselage fillets.
53-111	3	August 24, 1992	Conventional wing-to-fuselage fillets.

New Requirements of This AD

Installation or Replacement

(g) For airplanes with fuselage numbers not identified in Table 2 of this AD: Within 7,500 flight hours or 60 months, whichever occurs first after the effective date of this AD, install or replace with improved parts, as applicable, the bonding straps between the metallic frame of the fillet and the wing leading edge ribs, on both the left and right sides of the airplane, and reposition two bonding straps. Do the actions in accordance with the Accomplishment Instructions of the applicable service bulletin identified in Table 1 of this AD.

Strap Repositioning for Certain Airplanes

(h) For Configuration 3 airplanes, as identified in McDonnell Douglas DC-10 Service Bulletin DC10-53-109, Revision 6, dated July 10, 2008: Within 7,500 flight hours or 60 months, whichever occurs first after the effective date of this AD, reposition two bonding straps, in accordance with the Accomplishment Instructions of the service bulletin.

Alternative Methods of Compliance (AMOCs)

(i)(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, ATTN: Samuel Lee, Aerospace Engineer, Samuel Lee, Aerospace Engineer, Propulsion Branch, ANM-140L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5262; fax (562) 627-5210; has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector

(PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(3) AMOCs approved previously in accordance with AD 2006-16-03 are approved as AMOCs for the corresponding provisions of this AD. McDonnell Douglas DC-10 Service Bulletins DC10-53-109 and DC10-53-111, both Revision 5, both dated March 19, 2008, and Service Bulletin DC10-53-109, Revision 6, dated July 10, 2008, have been approved by the FAA as an AMOC with the requirements of AD 2006-16-03.

Issued in Renton, Washington, on November 16, 2008.

Stephen P. Boyd,

Assistant Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-28129 Filed 11-25-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2008-1240; Directorate Identifier 2008-NM-098-AD]

RIN 2120-AA64

Airworthiness Directives; Hawker Beechcraft Corporation Model BH.125 Series 600A Airplanes and Model HS.125 Series 700A Airplanes Modified in Accordance With Supplemental Type Certificate (STC) SA2271SW

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Hawker Beechcraft Corporation Model BH.125 series 600A airplanes and Model HS.125 series 700A airplanes. This proposed AD would require inspecting the wiring diagrams containing the cockpit blowers and comparing with the current airplane configuration, and reworking the wiring if necessary. This proposed AD results from a report indicating that a blower motor of the cockpit ventilation and avionics cooling system seized up and gave off smoke. We are proposing this AD to prevent smoke and fumes in the cockpit in the event that a blower motor seizes and overheats due to excessive current draw.

DATES: We must receive comments on this proposed AD by January 12, 2009.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact Hawker Beechcraft Corporation, Department 62, P.O. Box

85, Wichita, Kansas 67201-0085; telephone 316-676-8238; fax 316-676-6706; e-mail tmdc@hawkerbeechcraft.com; Internet https://www.hawkerbeechcraft.com/service_support/pubs.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Andy Shaw, Aerospace Engineer, Special Certification Office, ASW-190, FAA Southwest Regional Office, 2601 Meacham Boulevard, Fort Worth, Texas 76137; telephone (817) 222-5188; fax (817) 222-5785.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2008-1240; Directorate Identifier 2008-NM-098-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We have received a report indicating that a blower motor of the cockpit ventilation and avionics cooling system seized up and gave off smoke on a Raytheon Model Hawker 125-800 airplane. Investigation revealed inadequate short circuit protection on the blower motor electrical circuit. This condition, if not corrected, could result in smoke and fumes in the cockpit in the event that a blower motor seizes and overheats due to excessive current draw.

The cockpit blowers on certain Hawker Beechcraft Corporation Model BH.125 series 600A airplanes and Model HS.125 series 700A airplanes modified in accordance with Supplemental Type Certificate (STC) SA2271SW are identical to those on the affected Raytheon Model Hawker 125-800 airplanes. Therefore, all of these models may be subject to the same unsafe condition.

Other Relevant Rulemaking

We previously issued AD 2005-16-02, amendment 39-14207 (70 FR 44273, August 2, 2005), applicable to certain Raytheon Model HS.125 series 700A airplanes, Model BAe.125 series 800A airplanes, and Model Hawker 800 and Hawker 800XP airplanes. That AD requires inspecting to determine the current rating of the circuit breakers of certain cockpit ventilation and avionics cooling system blowers; and replacing the circuit breakers and modifying the blower wiring, as applicable.

Relevant Service Information

We have reviewed Hawker Beechcraft Mandatory Service Bulletin 24-3850, dated January 2008. The service bulletin describes procedures for inspecting the wiring diagrams containing the cockpit blowers and comparing with the current airplane configuration, and reworking the wiring if necessary.

FAA's Determination and Requirements of This Proposed AD

We are proposing this AD because we evaluated all relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the(se) same type design(s). This proposed AD would require accomplishing the actions specified in the service information described previously, except as discussed under "Differences Between the Proposed AD and Service Bulletin."

Differences Between the Proposed AD and Service Bulletin

Although the NOTE specified in paragraph 3.A. of the Accomplishment Instructions of Hawker Beechcraft Mandatory Service Bulletin 24-3850 specifies that operators should consult the Inspection Authorization, Designated Engineering Representative, FAA, or Hawker Beechcraft Corporation for determination as to the suitability of the service bulletin, this proposed AD would require that the determination be approved by the FAA.

Operators should note that, although the Accomplishment Instructions of the referenced service bulletin describe

procedures for submitting a sheet recording compliance with the service bulletin, this proposed AD would not require that action.

Costs of Compliance

We estimate that this proposed AD would affect 40 airplanes of U.S. registry. We also estimate that it would take about 1 work-hour per product to comply with this inspection proposed by this AD. The average labor rate is \$80 per work-hour. Based on these figures, we estimate the cost of this proposed AD to the U.S. operators to be \$3,200, or \$80 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866,
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979), and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

You can find our regulatory evaluation and the estimated costs of compliance in the AD Docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Arkansas Modification Center, Inc.: Docket No. FAA-2008-1240; Directorate Identifier 2008-NM-098-AD.

Comments Due Date

(a) We must receive comments by January 12, 2009.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Hawker Beechcraft Corporation Model BH.125 series 600A airplanes and Model HS.125 series 700A airplanes, certificated in any category; as identified in Hawker Beechcraft Mandatory Service Bulletin 24-3850, dated January 2008, which have been modified in accordance with Supplemental Type Certificate SA2271SW.

Unsafe Condition

(d) This AD results from a report indicating that a blower motor of the cockpit ventilation and avionics cooling system seized up and gave off smoke. We are issuing this AD to prevent smoke and fumes in the cockpit in the event that a blower motor seizes and overheats due to excessive current draw.

Compliance

(e) Comply with this AD within the compliance times specified, unless already done.

Inspection and Rework

(f) Within 600 flight hours or 6 months after the effective date of this AD, whichever occurs first, inspect the wiring diagrams containing the cockpit blowers and compare with the current airplane configuration, in accordance with the Accomplishment Instructions of Hawker Beechcraft Mandatory Service Bulletin 24-3850, dated January 2008; except as provided by paragraph (g) of this AD.

(1) If the current airplane configuration does not match the applicable cockpit blower wiring diagrams, before further flight, rework the wiring using a method approved by the Manager, Special Certification Office, ASW-190, Rotorcraft Directorate, FAA. For the

determination to be approved by the Manager, Special Certification Office, as required by this paragraph, the Manager's approval letter must specifically refer to this AD.

(2) If the current airplane configuration matches the applicable cockpit blower wiring diagrams, before further flight, rework the wiring in accordance with the Accomplishment Instructions of Hawker Beechcraft Mandatory Service Bulletin 24-3850, dated January 2008.

No Submission of Certain Information

(g) Although Hawker Beechcraft Mandatory Service Bulletin 24-3850, dated January 2008, specifies to submit certain information to the manufacturer, this AD does not include that requirement.

Alternative Methods of Compliance (AMOCs)

(h)(1) The Manager, Special Certification Office, ASW-190, Rotorcraft Directorate, FAA, ATTN: Andy Shaw, Aerospace Engineer, Special Certification Office, ASW-190, FAA, Southwest Regional Office, 2601 Meacham Boulevard, Fort Worth, Texas 76137; telephone (817) 222-5188; fax (817) 222-5785; has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Issued in Renton, Washington, on November 16, 2008.

Stephen P. Boyd,

Assistant Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-28168 Filed 11-25-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2008-1237; Directorate Identifier 2008-NM-125-AD]

RIN 2120-AA64

Airworthiness Directives; ATR Model ATR42-200, ATR42-300, ATR42-320, ATR42-500, ATR72-101, ATR72-201, ATR72-102, ATR72-202, ATR72-211, ATR72-212, and ATR72-212A Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the

products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

[C]hafed wirings were found in the rear baggage zone, closed [close] to the forward side of the aft pressure bulkhead, due to contact with an understructure securing screw. The concerned wiring harness includes rudder trim, pitch trim and stick pusher control wires. Damages on those wires might lead to the loss of fail safe criteria for those critical functions.

The unsafe condition is reduced controllability of the airplane. The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by December 26, 2008.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-40, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION: