

which are the multipliers used to determine the manufacturer selling prices based on manufacturing cost. Chapter 5 of the preliminary TSD discusses the engineering analysis.

2. Energy Use Characterization

The energy use characterization provides estimates of annual energy consumption for the three heating products, which DOE uses in the LCC and PBP analyses and the NIA. DOE developed energy consumption estimates for all of the product classes analyzed in the engineering analysis as the basis for its energy use estimates. Chapter 7 of the preliminary TSD discusses the energy use characterization.

3. Markups To Determine Product Prices

DOE derives consumer prices for products based on manufacturer markups, retailer markups, distributor markups, contractor markups, builder markups, and sales taxes. In deriving these markups, DOE has determined (1) The distribution channels for product sales; (2) the markup associated with each party in the distribution channels; and (3) the existence and magnitude of differences between markups for baseline products (baseline markups) and for more-efficient products (incremental markups). DOE calculates both overall baseline and overall incremental markups based on the product markups at each step in the distribution channel. The overall incremental markup relates the change in the manufacturer sales price of higher-efficiency models (the incremental cost increase) to the change in the retailer or distributor sales price. Chapter 6 of the preliminary TSD discusses the estimation of markups.

4. Life-Cycle Cost and Payback Period Analyses

The LCC and PBP analyses determine the economic impact of potential standards on individual consumers. The LCC is the total consumer expense for a product over the life of the product. The LCC analysis compares the LCCs of products designed to meet possible energy conservation standards with the LCCs of the products likely to be installed in the absence of standards. DOE determines LCCs by considering (1) Total installed cost to the purchaser (which consists of manufacturer selling price, sales taxes, distribution chain markups, and installation cost); (2) the operating expenses of the products (energy use and maintenance); (3) product lifetime; and (4) a discount rate that reflects the real consumer cost of capital and puts the LCC in present-

value terms. The PBP represents the number of years needed to recover the increase in purchase price (including installation cost) of more efficient products through savings in the operating cost of the product. It is the change in total installed cost due to increased efficiency divided by the change in annual operating cost from increased efficiency. Chapter 8 of the preliminary TSD discusses the LCC and PBP analyses.

5. National Impact Analysis

The NIA estimates the national energy savings (NES) and the net present value (NPV) of total consumer costs and savings expected to result from new standards at specific efficiency levels (referred to as candidate standard levels). Examining the three heating products, DOE calculated NES and NPV for each efficiency level as the difference between a base-case forecast (without new standards) and the standards case forecast (with standards). DOE determined national annual energy consumption by multiplying the number of units in use (by vintage, which is expressed in years) by the average unit energy consumption (also by vintage). Cumulative energy savings are the sum of the annual NES determined over a specified time period. The national NPV is the sum over time of the discounted net savings each year, which consists of the difference between total operating cost savings and increases in total installed costs. Critical inputs to this analysis include shipments projections, retirement rates (based on estimated product lifetimes), and estimates of changes in shipments and retirement rates in response to changes in product costs due to standards. Chapter 10 of the preliminary TSD discusses the NIA.

DOE consulted with stakeholders and other interested persons as part of its process for conducting all of the analyses and invites further input from the public on these topics. The preliminary analytical results are subject to revision following review and input from the public. A complete and revised TSD will be made available upon issuance of a NOPR. The final rule will contain the final analysis results and be accompanied by a final rule TSD.

DOE encourages those who wish to participate in the public meeting to obtain the preliminary TSD and to be prepared to discuss its contents. A copy of the preliminary TSD is available at the Web address given in the **SUMMARY** section of this notice. However, public meeting participants need not limit their comments to the topics identified in the preliminary TSD. DOE is also interested

in receiving views concerning other relevant issues that participants believe would affect energy conservation standards for these products or that DOE should address in the NOPR.

Furthermore, DOE welcomes all interested parties, whether or not they participate in the public meeting, to submit in writing by March 16, 2009, comments and information on matters addressed in the preliminary TSD and on other matters relevant to consideration of standards for residential water heaters, direct heating equipment, and pool heaters.

The public meeting will be conducted in an informal, conference style. A court reporter will be present to record the minutes of the meeting. There shall be no discussion of proprietary information, costs or prices, market shares, or other commercial matters regulated by United States antitrust laws.

After the public meeting and the expiration of the period for submitting written statements, DOE will consider all comments and additional information that is obtained from interested parties or through further analyses, and it will prepare a NOPR. The NOPR will include proposed energy conservation standards for the products covered by this rulemaking, and members of the public will be given an opportunity to submit written and oral comments on the proposed standards.

Issued in Washington, DC, on January 5, 2009.

John F. Mizroch,

Acting Assistant Secretary, Energy Efficiency and Renewable Energy.

[FR Doc. E9-476 Filed 1-12-09; 8:45 am]

BILLING CODE 6450-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2009-0004; Directorate Identifier 2008-NM-160-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A318, A319, A320, and A321 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing

airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

One case of elevator servo-control disconnection has been experienced on an aircraft of the A320 family. Failure occurred at the servo-control rod eye-end. Further to this finding, additional inspections have revealed cracking at the same location on a number of other servo-control rod eye-ends. In one case, both actuators of the same elevator surface were affected. * * *

A dual servo-control disconnection on the same elevator could result in an uncontrolled surface, the elevator surface being neither actuated nor damped, which could lead to reduced control of the aircraft.

* * * * *

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by February 12, 2009.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* (202) 493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-40, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Airbus, Airworthiness Office—EAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; fax +33 5 61 93 44 51; e-mail: account.airworth-eas@airbus.com; Internet <http://www.airbus.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments

received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Tim Dulin, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2141; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2009-0004; Directorate Identifier 2008-NM-160-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Airworthiness Directive 2008-0149, dated August 5, 2008 (referred to after this as “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states:

One case of elevator servo-control disconnection has been experienced on an aircraft of the A320 family. Failure occurred at the servo-control rod eye-end. Further to this finding, additional inspections have revealed cracking at the same location on a number of other servo-control rod eye-ends. In one case, both actuators of the same elevator surface were affected. The root cause of the cracking has not yet been determined and tests are ongoing. It is anticipated that further actions will be required.

A dual servo-control disconnection on the same elevator could result in an uncontrolled surface, the elevator surface being neither actuated nor damped, which could lead to reduced control of the aircraft.

For the reason described above, this AD requires a one-time inspection [for cracking] of the elevator servo-control rod eye-ends and, in case of findings, the accomplishment of corrective actions.

The corrective actions include replacing any cracked rod eye end with a serviceable unit and re-adjusting the elevator servo-control. You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

Airbus has issued All Operators Telex A320-27A1186, dated June 23, 2008. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a NOTE within the proposed AD.

Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 730 products of U.S. registry. We also estimate that it would take about 13 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$80 per work-hour. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$759,200, or \$1,040 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I,

section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Airbus: Docket No. FAA-2009-0004; Directorate Identifier 2008-NM-160-AD.

Comments Due Date

(a) We must receive comments by February 12, 2009.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Airbus Model A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-111, -211, -212, -214, -231, -232, -233; and A321-111, -112, -131, -211, -212, -213, -231, and -232 series airplanes; certificated in any category; all manufacturer serial numbers.

Subject

(d) Air Transport Association (ATA) of America Code 27: Flight controls.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

One case of elevator servo-control disconnection has been experienced on an aircraft of the A320 family. Failure occurred at the servo-control rod eye-end. Further to this finding, additional inspections have revealed cracking at the same location on a number of other servo-control rod eye-ends. In one case, both actuators of the same elevator surface were affected. The root cause of the cracking has not yet been determined and tests are ongoing. It is anticipated that further actions will be required.

A dual servo-control disconnection on the same elevator could result in an uncontrolled surface, the elevator surface being neither actuated nor damped, which could lead to reduced control of the aircraft.

For the reason described above, this AD requires a one-time inspection [for cracking] of the elevator servo-control rod eye-ends and, in case of findings, the accomplishment of corrective actions.

The corrective actions include replacing any cracked rod eye-end with a serviceable unit and re-adjusting the elevator servo-control.

Actions and Compliance

(f) Unless already done after the accumulation of 10,000 total flight cycles since first flight of the airplane, do the following actions.

(1) Not before the accumulation of 10,000 total flight cycles since first flight of the airplane, and at the later of the times specified in paragraphs (f)(1)(i) and (f)(1)(ii) of this AD: Inspect both the left-hand and right-hand inboard elevator servo-control rod eye-ends for cracking in accordance with the instructions of Airbus All Operators Telex (AOT) A320-27A1186, dated June 23, 2008.

(i) Within 1,500 flight cycles or 200 days after the effective date of this AD, whichever occurs first.

(ii) Within 1,500 flight cycles or 200 days after accumulating 10,000 total flight cycles since first flight of the airplane, whichever occurs first.

(2) Not before the accumulation of 10,000 total flight cycles since first flight of the airplane, and at the later of the times

specified in paragraphs (f)(2)(i) and (f)(2)(ii) of this AD: Inspect both the left-hand and right-hand outboard elevator servo-control rod eye-ends for cracking, in accordance with the instructions of Airbus AOT A320-27A1186, dated June 23, 2008.

(i) Within 3,000 flight cycles or 400 days after the effective date of this AD, whichever occurs first.

(ii) Within 3,000 flight cycles or 400 days after accumulating 10,000 total flight cycles since first flight of the airplane, whichever occurs first.

(3) If any cracking is found during any inspection required by this AD, before further flight, accomplish all applicable corrective actions in accordance with the instructions of Airbus AOT A320-27A1186, dated June 23, 2008.

(4) Submit a report of the findings of the inspection required by paragraphs (f)(1) and (f)(2) of this AD to Airbus in accordance with the instructions of Airbus AOT A320-27A1186, dated June 23, 2008, at the applicable time specified in paragraph (f)(4)(i) or (f)(4)(ii) of this AD. Under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements contained in this AD and has assigned OMB Control Number 2120-0056.

(i) If the inspection was done after the effective date of this AD: Submit the report within 40 days after the inspection.

(ii) If the inspection was done before the effective date of this AD: Submit the report within 40 days after the effective date of this AD.

(5) As of the effective date of this AD, no person may install on any airplane an elevator servo-control rod eye-end unless it has been inspected in accordance with the instructions of Airbus AOT A320-27A1186, dated June 23, 2008.

FAA AD Differences

Note 1: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Tim Dulin, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2141; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority

(or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) **Reporting Requirements:** For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency Airworthiness Directive 2008-0149, dated August 5, 2008, and Airbus AOT A320-27A1186, dated June 23, 2008, for related information.

Issued in Renton, Washington, on December 29, 2008.

Linda Navarro,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9-456 Filed 1-12-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2009-0003; Directorate Identifier 2007-NM-251-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A330-200 and -300 Series Airplanes, and A340-200, -300, -500 and -600 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as: Several cases of corrosion and damage on the Down Drive Shafts (DDS), between the Down Drive Gear Box (DDGB) and the Input Gear Box (IPGB), on all 10 Flap Tracks (5 per wing), have been reported by AIRBUS Long Range Operators. Investigations have revealed that corrosion and wear due to absence of grease in the spline interfaces could cause [DDS] disconnection which could result in a free movable flap surface, potentially leading to aircraft asymmetry or even flap detachment. The proposed AD would require actions that are intended

to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by February 12, 2009.

ADDRESSES: You may send comments by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- **Fax:** (202) 493-2251.
- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.
- **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-40, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Tim Backman, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425) 227-2797; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2009-0003; Directorate Identifier 2007-NM-251-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Airworthiness Directive 2008-0026, dated February 12, 2008 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

Several cases of corrosion and damage on the Down Drive Shafts (DDS), between the Down Drive Gear Box (DDGB) and the Input Gear Box (IPGB), on all 10 Flap Tracks (5 per wing), have been reported by AIRBUS Long Range Operators.

Investigations have revealed that corrosion and wear due to absence of grease in the spline interfaces could cause [DDS] disconnection which could result in a free movable flap surface, potentially leading to aircraft asymmetry or even flap detachment.

Emergency Airworthiness Directive (EAD) 2007-0222-E mandated on all aircraft older than 6 years since AIRBUS original delivery date of the aircraft, an initial inspection of all DDS and IPGB for corrosion and wear detection in order to replace any damaged part.

Revision 1 of EAD 2007-0222-E aimed for clarifying the compliance instructions.

[EASA AD 2008-0026] supersedes the EAD 2007-0222R1-E and mandates repetitive inspections every 6 years for all the fleet.

The corrective actions include replacing damaged parts before next flight. You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

Airbus has issued Service Bulletins A330-27-3151, A330-27-3152, A340-27-4151, A340-27-4152, and A340-27-5040; all dated August 9, 2007. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in