

compliance time “since date of construction” of the airplane, this AD requires compliance since the date of issuance of the original standard airworthiness certificate or the date of issuance of the original export certificate of airworthiness.

New Requirements of This AD

New Service Bulletin

(k) As of the effective date of this AD: Do the actions required by paragraphs (g) and (h) of this AD in accordance with the Accomplishment Instructions of BAE Systems (Operations) Limited Inspection Service Bulletin ISB.53–182, Revision 1, dated August 6, 2007, except as required by paragraph (n) of this AD.

Additional Inspection Areas

(l) At the applicable compliance time specified in paragraph (g) of this AD, except as provided by paragraph (o) of this AD; or within six months after the effective date of this AD; whichever occurs later: Do an HFEC inspection for corrosion of the outer frame flanges and door hinge bosses of frames 15, 18, 41, and 43, in accordance with the Accomplishment Instructions of BAE Systems (Operations) Limited Inspection Service Bulletin ISB.53–182, Revision 1, dated August 6, 2007 (“the service bulletin”). Repeat the inspection thereafter at the applicable time specified in paragraph 1.D., “Compliance,” of the service bulletin. Application of corrosion-preventive treatment, in accordance with the Accomplishment Instructions of the service bulletin, extends the repetitive inspection interval, as specified in Table 2 in paragraph 1.D., “Compliance,” of the service bulletin.

Corrective Action for Additional Inspection

(m) If any discrepancy is found during any inspection required by paragraph (l) of this AD: Before further flight, perform applicable related investigative/corrective actions in accordance with the Accomplishment Instructions of BAE Systems (Operations) Limited Inspection Service Bulletin ISB.53–182, Revision 1, dated August 6, 2007, except as required by paragraph (n) of this AD.

Exception to BAE Systems (Operations) Limited Inspection Service Bulletin ISB.53–182, Revision 1

(n) If BAE Systems (Operations) Limited Inspection Service Bulletin ISB.53–182, Revision 1, dated August 6, 2007, specifies to contact the manufacturer for appropriate action, before further flight, repair per a method approved by the Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA; or EASA (or its delegated agent).

(o) Where BAE Systems (Operations) Limited Inspection Service Bulletin ISB.53–182, Revision 1, dated August 6, 2007, specifies a compliance time after the issuance of the service bulletin, this AD requires compliance within the specified compliance time after the effective date of this AD. Where BAE Systems (Operations) Limited Inspection Service Bulletin ISB.53–182, Revision 1, dated August 6, 2007, specifies a compliance time “since date of construction” of the airplane, this AD requires compliance

since the date of issuance of the original airworthiness certificate or the date of issuance of the original export certificate of airworthiness.

No Reporting

(p) Although BAE Systems (Operations) Limited Inspection Service Bulletin ISB.53–182, dated March 16, 2005; and Revision 1, dated August 6, 2007; specify to submit information to the manufacturer, this AD does not include such a requirement.

Alternative Methods of Compliance (AMOCs)

(q) The Manager, International Branch, ANM–116, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Todd Thompson, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057–3356; telephone (425) 227–1175; fax (425) 227–1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

Related Information

(r) European Aviation Safety Agency airworthiness directive 2008–0092 R1, dated May 15, 2008, also addresses the subject of this AD.

Issued in Renton, Washington, on February 5, 2009.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9–3400 Filed 2–17–09; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2009–0134; Directorate Identifier 2008–NM–162–AD]

RIN 2120–AA64

Airworthiness Directives; Saab AB, Saab Aerofsystems Model SAAB 340A (SAAB/SF340A) and SAAB 340B Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new Airworthiness Directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of

another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

Two cases of main hydraulic accumulator failure have been reported, one of which was caused by corrosion. Investigation has shown that a severe failure can occur to any of the four hydraulic accumulators which are installed in the hydraulic compartment. Either one of the two end parts on the accumulator may depart from the pressure vessel due to corrosion. This condition, if not corrected, is likely to degrade the functionality of the hydraulic system, possibly resulting in degradation or total loss of control of the landing gear, flap actuation and brakes. A severe failure during flight may even result in debris penetrating and exiting the fuselage outer skin. When such a failure occurs while the aircraft is on the ground, as in the two reported cases, this may cause severe damage to the fuselage and result in injuries to persons nearby.

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by March 20, 2009.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493–2251.

- *Mail:* U.S. Department of

Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–40, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Saab Aircraft AB, SAAB Aerofsystems, SE–581 88, Linköping, Sweden; telephone +46 13 18 5591; fax +46 13 18 4874; e-mail saab2000.techsupport@saabgroup.com; Internet <http://www.saabgroup.com>.

You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425–227–1221 or 425–227–1152.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the

regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Shahram Daneshmandi, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1112; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2009-0134; Directorate Identifier 2008-NM-162-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Airworthiness Directive 2008-0146, dated August 1, 2008 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

Two cases of main hydraulic accumulator failure have been reported, one of which was caused by corrosion. Investigation has shown that a severe failure can occur to any of the four hydraulic accumulators which are installed in the hydraulic compartment. Either one of the two end parts on the accumulator may depart from the pressure vessel due to corrosion. This condition, if not corrected, is likely to degrade the functionality of the hydraulic system, possibly resulting in degradation or total loss of control of the landing gear, flap actuation and brakes. A severe failure during flight may even result in debris penetrating and exiting the fuselage outer skin. When such a failure occurs while the aircraft is on the ground, as in the two reported cases, this may cause severe damage to the fuselage and result in injuries to persons nearby.

To address and correct the unsafe condition, a modified hydraulic accumulator

has been developed, which is sealed between the barrel and the screw cap and between the screw cap and the end cap.

For the reasons described above, this EASA AD requires the replacement of the affected hydraulic accumulators P/N (part number) 08 8423 001 1 and P/N 08 8423 030 1, as identified in Saab SB 340-29-023, with a modified hydraulic accumulator.

You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

Saab has issued Service Bulletin 340-29-023, dated June 10, 2008. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a NOTE within the proposed AD.

Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect 141 products of U.S. registry. We also estimate that it would take 8 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$80 per work-hour. Required parts would cost \$3,582 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no

charge for these costs. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$595,302, or \$4,222 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator,

the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Saab AB, Saab Aerosystems: Docket No. FAA-2009-0134; Directorate Identifier 2008-NM-162-AD.

Comments Due Date

(a) We must receive comments by March 20, 2009.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Saab AB, Saab Aerosystems Model SAAB 340A (SAAB/SF340A) and SAAB 340B airplanes, all serial numbers, certificated in any category; on which hydraulic accumulators with part number (P/N) 08 8423 001 1 or P/N 08 8423 030 1 are installed, except accumulators with serial numbers listed in paragraph 3.B. of Saab Service Bulletin 340-29-023, dated June 10, 2008.

Subject

(d) Air Transport Association (ATA) of America Code 29: Hydraulic power.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

Two cases of main hydraulic accumulator failure have been reported, one of which was caused by corrosion. Investigation has shown that a severe failure can occur to any of the four hydraulic accumulators which are installed in the hydraulic compartment. Either one of the two end parts on the accumulator may depart from the pressure vessel due to corrosion. This condition, if not corrected, is likely to degrade the functionality of the hydraulic system, possibly resulting in degradation or total loss of control of the landing gear, flap actuation and brakes. A severe failure during flight may even result in debris penetrating and exiting the fuselage outer skin. When such a failure occurs while the aircraft is on the ground, as in the two reported cases, this may cause severe damage to the fuselage and result in injuries to persons nearby.

To address and correct the unsafe condition, a modified hydraulic accumulator has been developed, which is sealed between the barrel and the screw cap and between the screw cap and the end cap.

For the reasons described above, [the MCAI] requires the replacement of the affected hydraulic accumulators P/N (part number) 08 8423 001 1 and P/N 08 8423 030 1, as identified in Saab SB 340-29-023, with a modified hydraulic accumulator.

Actions and Compliance

(f) Unless already done, replace the accumulator at the applicable time specified in paragraph (f)(1) or (f)(2) of this AD in accordance with the instructions of Saab Service Bulletin 340-29-023, dated June 10, 2008.

(1) For airplanes on which the manufacturing date of the hydraulic accumulator is June 2000 or earlier: Replace the accumulator with a new or modified accumulator within 24 months after the effective date of this AD.

(2) For airplanes on which the manufacturing date of the accumulator is July 2000 or later: Replace the accumulator with a new or modified accumulator within 10 years after the manufacturing date or within 24 months after the effective date of this AD, whichever occurs later.

(3) As of 24 months after the effective date of this AD, no person may install a hydraulic accumulator, P/N 08 8423 001 1 or P/N 08 8423 030 1 on any airplane, except accumulators with serial numbers listed in paragraph 3.B. of Saab Service Bulletin 340-29-023, dated June 10, 2008.

FAA AD Differences

Note 1: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) **Alternative Methods of Compliance (AMOCs):** The Manager, International Branch, ANM-116, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Shahram Daneshmandi, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1112; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office.

(2) **Airworthy Product:** For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) **Reporting Requirements:** For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency Airworthiness Directive 2008-0146, dated August 1, 2008, and Saab Service

Bulletin 340-29-023, dated June 10, 2008, for related information.

Issued in Renton, Washington, on January 30, 2009.

Stephen P. Boyd,

Assistant Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9-3398 Filed 2-17-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2009-0132; Directorate Identifier 2008-NM-081-AD]

RIN 2120-AA64

Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model EMB-135BJ, -135ER, -135KE, -135KL, -135LR, -145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

During aircraft full scale fatigue test, it has been found the occurrence of cracks in the cockpit windshield post lower eyelet fitting at the attachment of the center post on the forward fuselage (SSI 53-10-19). Further analysis of this cracking resulted in modifications on the aircraft Airworthiness Limitation Items (ALI), to include new inspection tasks and its respective intervals. Undetected fatigue cracking in this area could adversely affect the structural integrity of these airplanes.

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by March 20, 2009.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* (202) 493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-