

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by removing Amendment 39–15820 (74 FR 7810; February 20, 2009), and adding the following new AD:

2009–08–10 Pilatus Aircraft Ltd:

Amendment 39–15883; Docket No. FAA–2009–0347; Directorate Identifier 2009–CE–022–AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective April 20, 2009.

Affected ADs

(b) This AD supersedes AD 2009–04–14, Amendment 39–15820.

Applicability

(c) This AD applies to Models PC–12/47E airplanes, manufacturer serial numbers (MSN) 545 and MSN 1001 and subsequent, certificated in any category.

Subject

(d) Air Transport Association of America (ATA) Code 34: Navigation.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

Field reports have indicated that the possibility exists that both Primary Flight Displays (PFDs) could indicate a roll attitude offset of up to 10 degrees in the same direction if an accelerated turn onto the active runway is performed immediately followed by take-off. This condition has been reported to correct itself after several minutes.

This situation, if not corrected, could result in an undesired bank angle, which would constitute an unsafe condition.

As an interim measure, EASA Emergency AD 2009–0028–E required the introduction of a maximum bank angle during climb. As a result of the ongoing investigation, the problem can be temporarily solved with some limitations in the take-off procedure.

For the reason described above, this AD supersedes EASA AD 2008–0028–E and requires a revision of the operational procedures to be inserted into the POH. This action is still considered to be an interim solution and further AD action is likely to follow.

Actions and Compliance

(f) Unless already done, before further flight as of April 20, 2009 (the effective date of this AD), do the following actions:

(1) Incorporate Pilatus Aircraft Ltd. Temporary Revision No. 11 to PC–12/47E Pilot's Operating Handbook, Report No. 02277, dated March 18, 2009, into the Pilatus PC–12/47E POH.

(2) Remove the information and/or the copy of AD 2009–04–14 required by AD 2009–04–14 to be inserted in the POH.

(3) The owner/operator holding at least a private pilot certificate as authorized by section 43.7 of the Federal Aviation Regulations 14 CFR 43.7 may do the actions required in this AD. Make an entry in the aircraft records showing compliance with this portion of the AD following 14 CFR 43.9.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows:

(1) Since we never allowed incorporating Temporary Revision No. 9, dated January 30, 2009, into the POH, we are not requiring the removal of Temporary Revision No. 9, dated January 30, 2009, as the MCAI requires.

(2) Current regulations (1 CFR 51.7) do not allow us to both incorporate by reference a service document and write the provisions of that document in the AD. We have chosen to incorporate by reference the temporary revision.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to *Attn:* Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; *telephone:* (816) 329–4059; *fax:* (816) 329–4090. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120–0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency (EASA) AD No. 2009–0080–E, dated April 3, 2009, and Pilatus Aircraft Ltd. Temporary Revision No. 11 to PC–12/47E Pilot's Operating Handbook, Report No. 02277, dated March 18, 2009, for related information.

Material Incorporated by Reference

(i) You must use Pilatus Aircraft Ltd. Temporary Revision No. 11 to PC–12/47E Pilot's Operating Handbook, Report No. 02277, dated March 18, 2009, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Pilatus Aircraft Ltd., Customer Service Manager, CH–6371 STANS, Switzerland; *telephone:* +41 (0)41 619 62 08; *fax:* +41 (0)41 619 73 11; *Internet:*

www.pilatus-aircraft.com/, or e-mail: *SupportPC12@pilatus-aircraft.com*. You may get Pilatus Aircraft Ltd. Temporary Revision No. 11 to PC–12/47E Pilot's Operating Handbook, Report No. 02277, dated March 18, 2009, from the Web site of the Swiss Federal Office of Civil Aviation (FOCA): *http://www.bazl.admin.ch/fachleute/lufttechnik/entwicklung/00677/index.html?lang=en*.

(3) You may review copies of the service information incorporated by reference for this AD at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the Central Region, call (816) 329–3768.

(4) You may also review copies of the service information incorporated by reference for this AD at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741–6030, or go to: *http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html*.

Issued in Kansas City, Missouri on April 8, 2009.

John R. Colomy,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9–8516 Filed 4–14–09; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2009–0124 Directorate Identifier 2009–CE–004–AD; Amendment 39–15882; AD 2009–08–09]

RIN 2120–AA64

Airworthiness Directives; EADS SOCATA Model TBM 700 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

A damaged wiring harness which caused the air conditioning system circuit breaker to trip and evidencing a local overheating has been found on an in-service aircraft.

The investigation revealed that the damage (chafed wires) found on the wiring harness resulted from an interference with the under-floor attachment fittings of the cabin partition

net which was due to an incorrect routing of the harness while on the production line.

Such conditions could result in an electrical short and potential loss of several functions essential for the safety of flight.

We are issuing this AD to require actions to correct the unsafe condition on these products.

DATES: This AD becomes effective May 20, 2009.

On May 20, 2009, the Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Albert Mercado, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4119; fax: (816) 329-4090.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on February 13, 2009 (74 FR 7194). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

A damaged wiring harness which caused the air conditioning system circuit breaker to trip and evidencing a local overheating has been found on an in-service aircraft.

The investigation revealed that the damage (chafed wires) found on the wiring harness resulted from an interference with the under-floor attachment fittings of the cabin partition net which was due to an incorrect routing of the harness while on the production line.

Such conditions could result in an electrical short and potential loss of several functions essential for the safety of flight.

For the reason stated above, this AD mandates inspection of the electrical wiring harness, and if necessary a rework of its routing.

Comments

We gave the public the opportunity to participate in developing this AD. We have considered the comment received.

Comment Issue: Number of U.S.-Registered Airplanes

EADS SOCATA requests we change in the Costs of Compliance section the number of products affected on the U.S.

registry from 45 products to 31 products. They state the airplanes listed in the U.S. registry are serial numbers 434, 435, 437 through 439, 441, 443 through 451, 458, 459, 461, 462, 465, 466, 468 through 474, and 476 through 478.

The FAA agrees. We will change the Costs of Compliance section in the final rule AD action to reflect the above comment.

Conclusion

We reviewed the available data, including the comment received, and determined that air safety and the public interest require adopting the AD with the changes described previously. We determined that these changes will not increase the economic burden on any operator or increase the scope of the AD.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have required different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a NOTE within the AD.

Costs of Compliance

Based on the service information, we estimate that this AD will affect 31 products of U.S. registry. We also estimate that it will take about 1 work-hour per product to comply with the basic requirements of this AD. The average labor rate is \$80 per work-hour.

Based on these figures, we estimate the cost of this AD to the U.S. operators to be \$2,480 or \$80 per product.

In addition, we estimate that any necessary follow-on actions would take about 1.5 work-hours for a cost of \$120 per product. We have no way of determining the number of products that may need these actions.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD Docket.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

2009-08-09 EADS SOCATA: Amendment 39-15882; Docket No. FAA-2009-0124; Directorate Identifier 2009-CE-004-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective May 20, 2009.

Affected ADs

(b) None.

Applicability

(c) This AD applies to TBM 700 airplanes, serial numbers 434 through 478, certificated in any category.

Subject

(d) Air Transport Association of America (ATA) Code 92: Wiring Elements.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

A damaged wiring harness which caused the air conditioning system circuit breaker to trip and evidencing a local overheating has been found on an in-service aircraft.

The investigation revealed that the damage (chafed wires) found on the wiring harness resulted from an interference with the under-floor attachment fittings of the cabin partition net which was due to an incorrect routing of the harness while on the production line.

Such conditions could result in an electrical short and potential loss of several functions essential for the safety of flight.

For the reason stated above, this AD mandates inspection of the electrical wiring harness, and if necessary a rework of its routing.

Actions and Compliance

(f) Unless already done, do the following actions:

(1) Within the next 100 hours time-in-service after May 20, 2009 (the effective date of this AD) or within the next 12 months after May 20, 2009 (the effective date of this AD), whichever occurs first, inspect the electrical wiring harness at frame C14 and between frames C16 and C17 for wire chafing and incorrect routing following EADS SOCATA Mandatory Service Bulletin SB 70-163, dated November 2008.

(2) If any wire chafing and/or incorrect routing are found, before further flight, repair and reroute the electrical harness following EADS SOCATA Mandatory Service Bulletin SB 70-163, dated November 2008.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Albert Mercado, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4119; fax: (816) 329-4090. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency (EASA) AD No.: 2009-0006, dated January 13, 2009; and EADS SOCATA Mandatory Service Bulletin SB 70-163, dated November 2008, for related information.

Material Incorporated by Reference

(i) You must use EADS SOCATA Mandatory Service Bulletin SB 70-163, dated November 2008, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact SOCATA AIRCRAFT, INC., North Perry Airport, 7501 South Airport Rd., Pembroke Pines, FL 33023; telephone: (954) 893-1400; fax: (954) 964-4141; Internet: <http://mysocata.com>.

(3) You may review copies of the service information incorporated by reference for this AD at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the Central Region, call (816) 329-3768.

(4) You may also review copies of the service information incorporated by reference for this AD at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Kansas City, Missouri, on April 3, 2009.

John R. Colomy,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9-8527 Filed 4-14-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2008-1140; Airspace Docket No. 08-ASW-24]

Amendment of Class D and Class E Airspace; Corpus Christi NAS/Truax Field, TX

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action amends the geographic coordinates of the Class D and E Airspace areas for Corpus Christi Naval Air Station (NAS)/Truax Field, Corpus Christi, TX. The FAA's National Aeronautical Charting Office is requesting this action to enhance the safety and management of Instrument Flight Rules (IFR) aircraft operations at Corpus Christi NAS/Truax Field.

DATES: *Effective Date:* 0901 UTC, May 7, 2009. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

FOR FURTHER INFORMATION CONTACT: Scott Enander, Central Service Center, Operations Support Group, Federal Aviation Administration, Southwest Region, 2601 Meacham Blvd, Ft Worth, TX 76193-0530; telephone (817) 321-7716.

SUPPLEMENTARY INFORMATION:

History

On November 26, 2008, the FAA published in the **Federal Register** a notice of proposed rulemaking to amend the geographic coordinates of the Class D and E Airspace areas for Corpus Christi Naval Air Station (NAS)/Truax Field, Corpus Christi, TX. (73 FR 71966, Docket No. FAA-2008-1140). Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received. Class D airspace designations are published in paragraph 5000 of FAA Order 7400.9S signed October 3, 2008, and effective October 31, 2008, which is incorporated