

Related Information

(i) Contact James Lawrence, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803, e-mail james.lawrence@faa.gov; telephone (781) 238-7176; fax (781) 238-7199, for more information about this AD.

(j) European Aviation Safety Agency AD 2007-0004, dated January 8, 2007, also addresses the subject of this AD.

(k) Rolls-Royce plc Alert Service Bulletin No. RB.211-72-AE082, Revision 7, dated June 18, 2008, pertains to the subject of this AD. Contact Rolls-Royce plc, P.O. Box 31, Derby, DE24 8BJ, UK, telephone 44 (0) 1332 242424; fax 44 (0) 1332 249936, for a copy of this service information.

(l) Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207, for a copy of the Aircraft Maintenance Manual referenced in this AD.

Issued in Burlington, Massachusetts, on April 17, 2009.

Peter A. White,

Assistant Manager, Engine and Propeller Directorate, Aircraft Certification Service.
[FR Doc. E9-9479 Filed 4-24-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2009-0380; Directorate Identifier 2008-NM-153-AD]

RIN 2120-AA64

Airworthiness Directives; Dassault Model Falcon 2000EX Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

An internal review of design data has shown that the web of the left hand side (LH) stringer 13 near frame 8 might have been improperly trimmed on a few aircraft.

If not corrected, possible crack initiations could occur in the upper stringer web, and therefore could impair the structural strength of the adjacent door stop. This latent failure could ultimately lead to the loss of redundancy of the door stops, thereby affecting the structural integrity of the fuselage.

* * * * *

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by May 27, 2009.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-40, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Dassault Falcon Jet, P.O. Box 2000, South Hackensack, New Jersey 07606; telephone 201-440-6700; Internet <http://www.dassaultfalcon.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:**Comments Invited**

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2009-0380; Directorate Identifier

2008-NM-153-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Airworthiness Directive 2008-0143, dated July 31, 2008 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

An internal review of design data has shown that the web of the left hand side (LH) stringer 13 near frame 8 might have been improperly trimmed on a few aircraft.

If not corrected, possible crack initiations could occur in the upper stringer web, and therefore could impair the structural strength of the adjacent door stop. This latent failure could ultimately lead to the loss of redundancy of the door stops, thereby affecting the structural integrity of the fuselage.

Computational analysis has revealed a substantial reduced fatigue life for the stringer abutting onto the improperly trimmed web and has determined the need for an inspection and repair action no later than the first "C" check.

To address this unsafe condition, the present Airworthiness Directive (AD) mandates an inspection and a conditional rework or replacement of the web of the LH stringer 13 between frames 7 and 8.

Required actions include measuring the trimmed length of the web, inspecting for any sharp and unprotected edges of the web, and doing corrective actions if necessary. Corrective actions include reworking the web, applying protection to the web, and replacing the web, if improperly trimmed. You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

Dassault has issued Mandatory Service Bulletin F2000EX-178, dated July 1, 2008. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a NOTE within the proposed AD.

Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 12 products of U.S. registry. We also estimate that it would take about 1 work-hour per product to comply with the basic requirements of this proposed AD. The average labor rate is \$80 per work-hour. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$960, or \$80 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation

is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Dassault Aviation: Docket No. FAA-2009-0380; Directorate Identifier 2008-NM-153-AD.

Comments Due Date

(a) We must receive comments by May 27, 2009.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Dassault Model Falcon 2000EX airplanes, certificated in any category, serial numbers 102 through 124 inclusive.

Subject

(d) Air Transport Association (ATA) of America Code 53: Fuselage.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

An internal review of design data has shown that the web of the left hand side (LH) stringer 13 near frame 8 might have been improperly trimmed on a few aircraft.

If not corrected, possible crack initiations could occur in the upper stringer web, and therefore could impair the structural strength of the adjacent door stop. This latent failure could ultimately lead to the loss of redundancy of the door stops, thereby affecting the structural integrity of the fuselage.

Computational analysis has revealed a substantial reduced fatigue life for the stringer abutting onto the improperly trimmed web and has determined the need for an inspection and repair action no later than the first "C" check.

To address this unsafe condition, the present Airworthiness Directive (AD) mandates an inspection and a conditional rework or replacement of the web of the LH stringer 13 between frames 7 and 8.

Required actions include measuring the trimmed length of the web, inspecting for any sharp and unprotected edges of the web, and doing corrective actions if necessary. Corrective actions include reworking the web, applying protection to the web, and replacing the web, if improperly trimmed.

Actions and Compliance

(f) Unless already done, do the following actions.

(1) At the later of the times in paragraphs (f)(1)(i) and (f)(1)(ii) of this AD:

Perform a detailed visual inspection to detect any sharp and unprotected edges of the web of the LH stringer 13 between frames 7 and 8, and measure the trimmed length of the web, in accordance with the Accomplishment Instructions of Dassault Mandatory Service Bulletin F2000EX-178, dated July 1, 2008.

(i) Before the accumulation of 3,750 total flight cycles, or within 74 months since the date of issuance of the original French airworthiness certificate or the date of issuance of the original French export certificate of airworthiness, whichever occurs first.

(ii) Within 6 months after the effective date of this AD.

(2) If, during the inspection and measurement required by paragraph (f)(1) of this AD, any sharp or unprotected edge is found, or if the trimmed length is 1.57 inches (40 mm) or greater, before further flight, do all applicable corrective actions, in accordance with the Accomplishment Instructions of Dassault Mandatory Service Bulletin F2000EX-178, dated July 1, 2008.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements*: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency (EASA) Airworthiness Directive 2008-0143, dated July 31, 2008; and Dassault Mandatory Service Bulletin F2000EX-178, dated July 1, 2008; for related information.

Issued in Renton, Washington, on April 15, 2009.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9-9501 Filed 4-24-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 71**

[Docket No. FAA-2009-0187; Airspace Docket No. 09-ACE-3]

Proposed Amendment of Class E Airspace; Ankeny, IA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to amend Class E airspace at Ankeny, IA.

Cancellation of NDB approaches at Ankeny Regional Airport has made it necessary to reconfigure Class E airspace. Controlled airspace is necessary to accommodate Standard Instrument Approach Procedures (SIAPs) at Ankeny Regional Airport, Ankeny, IA. This action also would update the geographic coordinates of the airport to coincide with the FAA's National Aeronautical Charting Office. The FAA is taking this action to enhance the safety and management of Instrument Flight Rules (IFR) aircraft operations at Ankeny Regional Airport.

DATES: Comments must be received on or before June 11, 2009.

ADDRESSES: Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, 1200 New Jersey Avenue, SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001. You must identify the docket number FAA-2009-0187/Airspace Docket No. 09-ACE-3, at the beginning of your comments. You may also submit comments on the Internet at <http://www.regulations.gov>. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone 1-800-647-5527), is on the ground floor of the building at the above address.

FOR FURTHER INFORMATION CONTACT: Scott Enander, Central Service Center, Operations Support Group, Federal Aviation Administration, Southwest Region, 2601 Meacham Blvd., Fort Worth, TX 76193-0530; telephone: (817) 321-7716.

SUPPLEMENTARY INFORMATION:**Comments Invited**

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. Communications should identify both docket numbers and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with those comments a self-addressed, stamped postcard on which the following

statement is made: "Comments to Docket No. FAA-2009-0187/Airspace Docket No. 09-ACE-3." The postcard will be date/time stamped and returned to the commenter.

Availability of NPRMs

An electronic copy of this document may be downloaded through the Internet at <http://www.regulations.gov>. Recently published rulemaking documents can also be accessed through the FAA's Web page at http://www.faa.gov/airports_airtraffic/air_traffic/publications/airspace_amendments/.

Additionally, any person may obtain a copy of this notice by submitting a request to the Federal Aviation Administration (FAA), Office of Air Traffic Airspace Management, ATA-400, 800 Independence Avenue, SW., Washington, DC 20591, or by calling (202) 267-8783. Communications must identify both docket numbers for this notice. Persons interested in being placed on a mailing list for future NPRMs should contact the FAA's Office of Rulemaking (202) 267-9677, to request a copy of Advisory Circular No. 11-2A, Notice of Proposed Rulemaking Distribution System, which describes the application procedure.

The Proposal

This action proposes to amend Title 14, Code of Federal Regulations (14 CFR), Part 71 by amending Class E airspace for SIAPs operations at Ankeny Regional Airport, Ankeny, IA, due to the cancellation of NDB approaches. The area would be depicted on appropriate aeronautical charts. This action also would update the geographic coordinates of the airport to coincide with the FAA's National Aeronautical Charting Office.

Class E airspace areas are published in Paragraph 6005 of FAA Order 7400.9S, dated October 3, 2008, and effective October 31, 2008, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document would be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore, (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal.