

FAA AD Differences

Note 1: This AD differs from the MCAI and/or service information as follows: Although the MCAI/service information allows further flight after cracks are found during compliance with certain actions, this AD requires that you repair the crack(s) before further flight.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2125; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency (EASA) Airworthiness Directive 2008-0181, dated October 1, 2008; and the service bulletins identified in Table 2 of this AD; for related information.

Issued in Renton, Washington, on September 11, 2009.

Stephen P. Boyd,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9-22667 Filed 9-18-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2009-0870; Directorate Identifier 2009-CE-049-AD]

RIN 2120-AA64

Airworthiness Directives; Empresa Brasileira de Aeronáutica S.A. (EMBRAER) Model EMB-500 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as: It has been found the possibility of elevator mass balance fasteners becoming slack under certain conditions. The loose of at least two fasteners may lead to an unbalance condition, which may induce flutter on airplane elevators.

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by November 5, 2009.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* (202) 493-2251.
- *Mail:* U.S. Department of

Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments

received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4146; fax: (816) 329-4090.

SUPPLEMENTARY INFORMATION:**Comments Invited**

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2009-0870; Directorate Identifier 2009-CE-049-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The Agência Nacional de Aviação Civil (ANAC), which is the aviation authority for Brazil, has issued AD No.: 2009-09-01, dated September 3, 2009 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

It has been found the possibility of elevator mass balance fasteners becoming slack under certain conditions. The loose of at least two fasteners may lead to an unbalance condition, which may induce flutter on airplane elevators.

The MCAI requires replacement of the nuts of the right and left elevators mass balance fasteners. You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

Embraer—Empresa Brasileira de Aeronáutica S.A. has issued Phenom by Embraer Service Bulletin No. 500-55-0001, dated July 24, 2009. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Differences Between This Proposed AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a NOTE within the proposed AD.

Costs of Compliance

We estimate that this proposed AD will affect 25 products of U.S. registry. We also estimate that it would take about 4 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$80 per work-hour. Required parts would cost about \$150 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these costs. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here.

Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$11,750, or \$470 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Empresa Brasileira de Aeronáutica S.A. (EMBRAER): Docket No. FAA-2009-0870; Directorate Identifier 2009-CE-049-AD.

Comments Due Date

- (a) We must receive comments by November 5, 2009.

Affected ADs

- (b) None.

Applicability

- (c) This AD applies to EMB-500 airplanes, serial numbers 50000005, 50000006, 50000008 through 50000036, 50000038 through 50000041, 50000043 through 50000046, 50000048, and 50000053, certificated in any category.

Subject

- (d) Air Transport Association of America (ATA) Code 27: Flight Controls.

Reason

- (e) The mandatory continuing airworthiness information (MCAI) states:

It has been found the possibility of elevator mass balance fasteners becoming slack under certain conditions. The loss of at least two fasteners may lead to an unbalance condition, which may induce flutter on airplane elevators.

The MCAI requires replacement of the nuts of the right and left elevators mass balance fasteners.

Actions and Compliance

- (f) Unless already done, do the following actions:

- (1) Within the next 30 days after the effective date of this AD, replace the nuts of the right-hand (RH) and left-hand (LH) elevators' mass balance fasteners with new ones of self-locking type bearing part number (P/N) MS21043-4. Do the replacements following Phenom by Embraer Service Bulletin No. 500-55-0001, dated July 24, 2009.

- (2) As of 30 days after the effective date of this AD, only install self-locking type nuts, P/N MS21043-4, on the RH and LH elevators mass balance fasteners.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

- (g) The following provisions also apply to this AD:

- (1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4146; fax: (816) 329-4090. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

- (2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective

actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) **Reporting Requirements:** For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 et seq.), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI Agência Nacional de Aviação Civil (ANAC) Brazilian Airworthiness Directive AD No.: 2009-09-01, dated September 3, 2009, and Phenom by Embraer Service Bulletin No. 500-55-0001, dated July 24, 2009, for related information.

Issued in Kansas City, Missouri, on September 15, 2009.

Scott A. Horn,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9-22642 Filed 9-18-09; 8:45 am]

BILLING CODE 4910-13-P

JOINT BOARD FOR THE ENROLLMENT OF ACTUARIES

20 CFR Part 901

[REG-159704-03]

RIN 1545-BC82

Performance of Actuarial Services Under the Employee Retirement Income Security Act of 1974

AGENCY: Joint Board for the Enrollment of Actuaries.

ACTION: Notice of proposed rulemaking.

SUMMARY: This document contains proposed amendments to 20 CFR part 901 relating to the enrollment of actuaries under section 3042 of the Employee Retirement Income Security Act of 1974 (ERISA). The proposed amendments would update the eligibility requirements for performing actuarial services for ERISA-covered employee pension benefit plans, including the continuing education requirements, and the standards for performing such actuarial services. The proposed amendments would affect employee pension benefit plans and the actuaries providing actuarial services to those plans.

DATES: Written or electronic comments must be received by November 20, 2009.

ADDRESSES: Send written comments to: CC:PA:LPD:PR (REG-159704-03), Room 5203, Internal Revenue Service, PO Box 7604, Ben Franklin Station, Washington, DC 20044. Submissions may be hand-

delivered Monday through Friday between the hours of 8 a.m. and 4 p.m. to CC:PA:LPD:PR (REG-159704-03), Courier's Desk, Internal Revenue Service, 1111 Constitution Avenue, NW., Washington, DC or sent electronically via the Federal eRulemaking Portal at <http://www.regulations.gov> (IRS REG-159704-03).

FOR FURTHER INFORMATION CONTACT: Patrick McDonough, Executive Director, Joint Board for the Enrollment of Actuaries, (202) 622-8229 (not a toll-free number).

SUPPLEMENTARY INFORMATION:

Paperwork Reduction Act

The collections of information referenced in this notice of proposed rulemaking were previously reviewed and approved by the Office of Management and Budget in accordance with the Paperwork Reduction Act of 1995 (44 U.S.C. 3507(d)) under control number 1545-0951, relating to Enrolled Actuaries under Employee Retirement Income Security Act of 1974, published on September 7, 1988, in the **Federal Register** (53 FR 34484). There are no proposals for substantive changes to this collection of information.

An agency may not conduct or sponsor, and a person is not required to respond to, a collection of information unless it displays a valid control number assigned by the Office of Management and Budget.

Books or records relating to a collection of information must be retained as long as their contents may become material in the administration of any internal revenue law. Generally, tax returns and tax return information are confidential, as required by 26 U.S.C. 6103.

Background

This document contains proposed amendments to 20 CFR Part 901 under section 3042 of the Employee Retirement Income Security Act of 1974 (88 Stat. 829), Public Law 93-406 (ERISA). Section 3042 of ERISA provides that the Joint Board for the Enrollment of Actuaries (Joint Board) shall, by regulations, establish reasonable standards and qualifications for persons performing actuarial services with respect to plans subject to ERISA and, upon application by any individual, shall enroll such individual if the Joint Board finds that such individual satisfies such standards and qualifications. Section 3042 also provides that the Joint Board may, after notice and an opportunity for a hearing, suspend or terminate the enrollment of

an individual who fails to discharge his duties under ERISA or who does not satisfy the requirements for enrollment.

Consistent with section 3042, the Joint Board has promulgated regulations at 20 CFR part 901, addressing eligibility for enrollment, requirements for continuing education of enrolled actuaries, professional standards for performance of actuarial services under ERISA, bases for disciplinary actions and the procedures to be followed in taking those actions. Comprehensive regulations regarding section 3042 were last issued in 1988 (53 FR 34484). The Joint Board has determined that the regulations need to be updated to reflect changes in the law and in industry practice. In addition to these proposed regulations, final regulations relating to user fees for the initial enrollment and reenrollment as an enrolled actuary were published in the **Federal Register** on December 21, 2007 (72 FR 72606).

In anticipation of amending the Joint Board regulations, the Joint Board issued a Request for Information (RFI) which was published in the **Federal Register** on June 30, 2004 (69 FR 39376). The RFI specifically requested comments as to whether, and to what extent, changes should be made to the regulations in the following five areas:

1. Procedures and conditions for enrollment and reenrollments;
2. Continuing professional education (CPE) requirements;
3. Waivers of the CPE requirements;
4. Types of enrollment statuses (active, inactive, and retired); and
5. Standards of conduct.

Eight comments were received. The current regulations prescribe various rules regarding the enrollment and reenrollment of actuaries. Section 901.13 of the regulations provides that an individual applying for enrollment must satisfy requirements for: (1) Qualifying experience; (2) basic actuarial knowledge; and (3) pension actuarial knowledge. Basic actuarial knowledge may be demonstrated by passing a Joint Board examination (or an examination acceptable to the Joint Board) regarding basic actuarial mathematics and methodology, or by earning a degree pertaining to actuarial mathematics from an accredited college. Pension actuarial knowledge must be demonstrated by passing a Joint Board examination (or an examination acceptable to the Joint Board) in actuarial mathematics related to pension plans.

Under section 901.11, an enrolled actuary must reenroll once every three years. To qualify for reenrollment an actuary must complete a minimum of 36