

effective date of this AD, replace the existing rail pressure control valve with a rail pressure control valve part number (P/N) 05-7320-E000702, and modify the Vrail plug to make it compatible with the replacement rail pressure control valve.

(2) Guidance on the valve replacement and rail modification specified in paragraph (e)(1) of this AD can be found in Thielert Repair Manual RM-02-02, Chapter 73-10.08, and Chapter 39-40.08, respectively.

TAE 125-01 Reciprocating Engines

(3) For TAE 125-01 reciprocating engines, within 100 flight hours after the effective date of this AD, replace the existing rail pressure control valve with a rail pressure control valve, P/N 02-7320-04100R3.

(4) Guidance on the valve replacement specified in paragraph (e)(3) of this AD can be found in Thielert Repair Manual RM-02-01, Chapter 29.0.

TAE 125-02-99 and TAE 125-01 Engines, Repetitive Replacements of Rail Pressure Control Valves

(5) Thereafter, for affected TAE 125-02-99 and TAE 125-01 engines, replace the rail pressure control valve with the same P/N valve within every 600 flight hours.

FAA AD Differences

(f) This AD differs from the Mandatory Continuing Airworthiness Information (MCAI) and/or service information as follows:

(1) We reduced the initial compliance time for TAE 125-02-99 reciprocating engines from within 110 flight hours to within 100 flight hours, and for TAE 125-01 reciprocating engines from within the next 3 months to within 100 flight hours.

(2) We require a repetitive replacement compliance time for the rail pressure control valve of within every 600 flight hours. The MCAIs instruct the operators to follow Thielert Maintenance Manual, Chapter 5, Airworthiness Limitations, for the repetitive compliance time.

(3) We exclude the repetitive inspections of the alternator on TAE 125-01 engines, as we consider these inspections as maintenance actions.

Alternative Methods of Compliance (AMOCs)

(g) The Manager, Engine Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

Related Information

(h) Refer to MCAI European Aviation Safety Agency (EASA) AD 2008-0128, dated July 9, 2008, EASA AD 2008-0215, dated December 5, 2008, Thielert Service Bulletin No. TAE 125-1008 P1, Revision 1, dated September 29, 2008, and Thielert Repair Manual RM-02-02, for related information. Contact Thielert Aircraft Engines GmbH, Platanenstrasse 14 D-09350, Lichtenstein, Germany, telephone: +49-37204-696-0; fax: +49-37204-696-55; e-mail: info@centurion-engines.com, for a copy of this service information.

(i) Contact Jason Yang, Aerospace Engineer, Engine Certification Office, FAA,

Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; e-mail: jason.yang@faa.gov; telephone (781) 238-7747; fax (781) 238-7199, for more information about this AD.

Issued in Burlington, Massachusetts, on October 13, 2009.

Carlos Pestana,

Acting Assistant Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. E9-25035 Filed 10-16-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2009-0914; Directorate Identifier 2009-NM-122-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A330-200 and -300, and Model A340-300 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

In the door 2 area, the hat-racks are supplied with a basic wire harness which includes "Oxygen Masks" activation.

In case of a monument installation, the respective non-used hat-rack connections between monument and outer skin are put on stow. It was noticed in production, that the distance between the stowed wire harness and the monument could be too small. This condition, if not corrected, could lead to the short circuit of wires dedicated to oxygen, which, in case of emergency, could result in a large number of passenger oxygen masks not being supplied with oxygen, possibly causing personal injuries.

* * * * *

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by December 3, 2009.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-40, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Airbus SAS—Airworthiness Office—EAL, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; fax +33 5 61 93 45 80, e-mail airworthiness.A330-A340@airbus.com; Internet <http://www.airbus.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1138; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2009-0914; Directorate Identifier 2009-NM-122-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We have lengthened the 30-day comment period for proposed ADs that address MCAI originated by aviation authorities of other countries to provide adequate time for interested parties to submit comments. The comment period for these proposed ADs is now typically 45 days, which is consistent with the comment period for domestic transport ADs.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Airworthiness Directive 2009-0077, dated April 6, 2009 (referred to after this as “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states:

In the door 2 area, the hat-racks are supplied with a basic wire harness which includes “Oxygen Masks” activation.

In case of a monument installation, the respective non-used hat-rack connections between monument and outer skin are put on stow. It was noticed in production, that the distance between the stowed wire harness and the monument could be too small. This condition, if not corrected, could lead to the short circuit of wires dedicated to oxygen, which, in case of emergency, could result in a large number of passenger oxygen masks not being supplied with oxygen, possibly causing personal injuries.

For the reasons described above, this AD requires the modification of the hat rack connectors on stow, and the rerouting of the associated wire harness in case of monument installed in door 2 area.

You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

Airbus has issued Mandatory Service Bulletins A330-92-3070, Revision 01, dated January 12, 2009; and A340-92-4073, Revision 01, dated January 13, 2009. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA’s Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the

MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a note within the proposed AD.

Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 43 products of U.S. registry. We also estimate that it would take about 3 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$80 per work-hour. Required parts costs are negligible. Where the service information lists required parts costs that are uncovered under warranty, we have assumed that there will be no charge for these costs. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$10,320, or \$240 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority

because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Airbus: Docket No. FAA-2009-0914; Directorate Identifier 2009-NM-122-AD.

Comments Due Date

- (a) We must receive comments by December 3, 2009.

Affected ADs

- (b) None.

Applicability

- (c) This AD applies to Airbus Model A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, and -343 series airplanes; and Airbus Model A340-311, -312, and -313 series airplanes; certificated in any category, all manufacturer

serial numbers on which Airbus modification 48825 has been embodied in production, except those on which Airbus modification 57409 has been embodied in production.

Subject

(d) Air Transport Association (ATA) of America Code 92.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

In the door 2 area, the hat-racks are supplied with a basic wire harness which includes "Oxygen Masks" activation.

In case of a monument installation, the respective non-used hat-rack connections between monument and outer skin are put on stow. It was noticed in production, that the distance between the stowed wire harness and the monument could be too small. This condition, if not corrected, could lead to the short circuit of wires dedicated to oxygen, which, in case of emergency, could result in a large number of passenger oxygen masks not being supplied with oxygen, possibly causing personal injuries.

For the reasons described above, this AD requires the modification of the hat rack connectors on stow, and the rerouting of the associated wire harness in case of monument installed in door 2 area.

Actions and Compliance

(f) Unless already done, do the following actions.

(1) Within 24 months after the effective date of this AD, modify both the left-hand (L/H) and right-hand (R/H) hat-rack connectors in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A330-92-3070, Revision 01, dated January 12, 2009; or Airbus Mandatory Service Bulletin A340-92-4073, Revision 01, dated January 13, 2009; as applicable, except as provided by paragraph (f)(2) of this AD.

(2) Modifications done before the effective date of this AD, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A330-92-3070 or A340-92-4073, both dated July 10, 2008, as applicable, are acceptable for compliance with the applicable requirements of paragraph (f)(1) of this AD, provided that within 24 months after the effective date of this AD, the "ADDITIONAL WORK" specified in Airbus Mandatory Service Bulletin A330-92-3070, Revision 01, dated January 12, 2009; or Airbus Mandatory Service Bulletin A340-92-4073, Revision 01, dated January 13, 2009; as applicable; is accomplished in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A330-92-3070, Revision 01, dated January 12, 2009; or Airbus Mandatory Service Bulletin A340-92-4073, Revision 01, dated January 13, 2009; as applicable.

FAA AD Differences

Note 1: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1138; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency Airworthiness Directive 2009-0077, dated April 6, 2009; Airbus Mandatory Service Bulletin A330-92-3070, Revision 01, dated January 12, 2009; and Airbus Mandatory Service Bulletin A340-92-4073, Revision 01, dated January 13, 2009; for related information.

Issued in Renton, Washington, on October 5, 2009.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9-24988 Filed 10-16-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2009-0913; Directorate Identifier 2009-NM-101-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 737-600, -700, -700C, -800, and -900 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Boeing Model 737-600, -700, -700C, -800, and -900 series airplanes. This proposed AD would require inspections for scribe lines in the fuselage skin at lap joints, the splice strap at certain butt joints, the skin or doubler at certain approved repair doublers, and the skin at decal locations; and related investigative and corrective actions if necessary. This proposed AD results from reports of scribe line damage found adjacent to the skin lap joints, decals, and wing-to-body fairings. We are proposing this AD to detect and correct scribe lines, which can develop into fatigue cracks in the skin. Undetected fatigue cracks can grow and cause sudden decompression of the airplane.

DATES: We must receive comments on this proposed AD by December 3, 2009.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; e-mail me.boecom@boeing.com; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office