

for separation of the drive arm following Scheibe Aircraft GmbH Service Bulletin No. 104-24/1; No. 232-6/1; and No. 653-91/1 (same document), dated June 25, 2009. If any looseness is found, before further flight, repair the drive arm of the mechanical elevator trim tab following Scheibe Aircraft GmbH Work Instruction No. 104-24; No. 232-6; and No. 653-91 (same document), dated March 23, 2009.

(2) Repetitively thereafter, at intervals not to exceed every 12 months, inspect the drive arm of the mechanical elevator trim tab and do all corrective actions following Scheibe Aircraft GmbH Service Bulletin No. 104-24/1; No. 232-6/1; and No. 653-91/1 (same document), dated June 25, 2009; and Scheibe Aircraft GmbH Work Instruction No. 104-24; No. 232-6; and No. 653-91 (same document), dated March 23, 2009.

**Note 1:** The service information references four documents: 104-24 (104-24/1), 232-6 (232-6/1), 653-91 (653-91/1), and 770-30 (770-30/1). This AD does not reference 770-30 (770-30/1) because the Model SF28A Tandem Falke is not type certificated in the United States. 14 CFR part 39 only allows the FAA to issue ADs against type certificated products.

FAA AD Differences

**Note 2:** This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Greg Davison, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4130; fax: (816) 329-4090. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency (EASA) AD No.: 2009-0132, dated June 23, 2009; Scheibe Aircraft GmbH Service Bulletin No. 104-24/1; No. 232-6/1; and No. 653-91/1 (same document), dated

June 25, 2009; and Scheibe Aircraft GmbH Work Instruction No. 104-24; No. 232-6; and No. 653-91 (same document), dated March 23, 2009, for related information.

Material Incorporated by Reference

(i) You must use the service information specified in Table 1 of this AD to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact SCHEIBE AIRCRAFT GMBH/Customer Service, Am Flugplatz 5, 73540 Heubach, Federal Republic of Germany; telephone: + 49 (0) 7173-184286; fax: + 49 (0) 7173-185587; E-mail: [info@scheibe-aircraft.de](mailto:info@scheibe-aircraft.de); Internet: <http://www.scheibe-aircraft.de/>.

(3) You may review copies of the service information incorporated by reference for this AD at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the Central Region, call (816) 329-3768.

(4) You may also review copies of the service information incorporated by reference for this AD at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

TABLE 1—MATERIAL INCORPORATED BY REFERENCE

Service information	Pages	Revision	Date
Scheibe Aircraft GmbH Service Bulletin No. 104-24/1; No. 232-6/1; and No. 653-91/1 (same document).	1 and 2 .....	Not Applicable .....	June 25, 2009.
Scheibe Aircraft GmbH Work Instruction No. 104-24; No. 232-6; and No. 653-91 (same document).	1 and 2 .....	Not Applicable .....	March 23, 2009.

Issued in Kansas City, Missouri, on November 10, 2009.  
**Kim Smith,**  
*Manager, Small Airplane Directorate, Aircraft Certification Service.*  
[FR Doc. E9-27777 Filed 11-25-09; 8:45 am]  
BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION  
Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2009-1075; Directorate Identifier 2009-NM-181-AD; Amendment 39-16107; AD 2008-09-23 R1]

RIN 2120-AA64

**Airworthiness Directives; Bombardier Inc. Model CL-600-2C10 (Regional Jet Series 700, 701 & 702), CL-600-2D15 (Regional Jet Series 705), and CL-600-2D24 (Regional Jet Series 900) Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule; request for comments.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for the products listed above that would revise an existing AD. This AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

Bombardier Aerospace has completed a system safety review of the aircraft fuel system against fuel tank safety standards introduced in Chapter 525 of the Airworthiness Manual through Notice of Proposed Amendment (NPA) 2002-043. The identified non-compliances were then assessed using Transport Canada Policy Letter No. 525-001, to determine if mandatory corrective action is required.

The assessment showed that it is necessary to introduce Critical Design Configuration Control Limitations (CDCCL), in order to preserve critical fuel tank system ignition source prevention features during configuration changes such as modifications and repairs, or during maintenance actions. Failure to preserve critical fuel tank system ignition source prevention features could result in a fuel tank explosion. \* \* \*

We are issuing this AD to require actions to correct the unsafe condition on these products. This AD requires actions that are intended to address the unsafe condition described in the MCAI.

**DATES:** This AD becomes effective December 14, 2009.

On June 6, 2008 (73 FR 24145, May 2, 2008), the Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD.

We must receive comments on this AD by January 11, 2010.

**ADDRESSES:** You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* (202) 493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-40, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; e-mail [thd.crj@aero.bombardier.com](mailto:thd.crj@aero.bombardier.com); Internet <http://www.bombardier.com>.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Mazdak Hobbi, Aerospace Engineer, Airframe and Mechanical Systems Branch, ANE-171, FAA, New York Aircraft Certification Office, 1600

Stewart Avenue, Suite 410, Westbury, New York 11590; telephone (516) 228-7330; fax (516) 794-5531.

#### SUPPLEMENTARY INFORMATION:

##### Discussion

On April 24, 2008, we issued AD 2008-09-23, Amendment 39-15504 (73 FR 24145, May 2, 2008). That AD applied to all Bombardier Model CL-600-2C10 (Regional Jet Series 700, 701 & 702), CL-600-2D15 (Regional Jet Series 705), and CL-600-2D24 (Regional Jet Series 900) airplanes. That AD required revising the Airworthiness Limitations Section (ALS) of the Instructions for Continued Airworthiness to include the critical design configuration control limitations (CDCCL) data.

CDCCLs are limitation requirements to preserve a critical ignition source prevention feature of the fuel tank system design that is necessary to prevent the occurrence of an unsafe condition. The purpose of a CDCCL is to provide instruction to retain the critical ignition source prevention feature during configuration change that may be caused by alterations, repairs, or maintenance actions. A CDCCL is not a periodic inspection.

Since we issued that AD, we have determined that it is necessary to clarify the AD's intended effect on spare and on-airplane fuel tank system components, regarding the use of maintenance manuals and instructions for continued airworthiness.

Section 91.403(c) of the Federal Aviation Regulations (14 CFR 91.403(c)) specifies the following:

No person may operate an aircraft for which a manufacturer's maintenance manual or instructions for continued airworthiness has been issued that contains an airworthiness limitation section unless the mandatory \* \* \* procedures \* \* \* have been complied with.

Some operators have questioned whether existing components affected by the new CDCCLs must be reworked. We did not intend for the AD to retroactively require rework of components that had been maintained using acceptable methods before the effective date of the AD. Owners and operators of the affected airplanes therefore are not required to rework affected components identified as airworthy or installed on the affected airplanes before the required revisions of the ALS of the Instructions for Continued Airworthiness. But once the CDCCLs are incorporated into the ALS of the Instructions for Continued Airworthiness, future maintenance actions on components must be done in accordance with those CDCCLs.

#### FAA's Determination

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. This new AD retains the requirements of the existing AD, and adds a new note to clarify the intended effect of the AD on spare and on-airplane fuel tank system components. We have renumbered subsequent notes accordingly.

#### Explanation of Additional Change to AD

AD 2008-09-23 allowed the use of alternative CDCCLs if they are part of a "later revision" of the ALS of the Instructions for Continued Airworthiness. That provision has been removed from this AD. Allowing the use of "later revisions" of specific service documents violates Office of the Federal Register policies for approving materials that are incorporated by reference. Affected operators, however, may request approval to use an alternative CDCCL that is part of a later revision of the referenced service document as an alternative method of compliance, under the provisions of paragraph (g) of this AD.

#### Differences Between the AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have required different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a **Note** within the AD.

#### Costs of Compliance

This revision imposes no additional economic burden. The current costs for this AD are repeated for the convenience of affected operators, as follows:

We estimate that this AD will affect about 297 products of U.S. registry. We also estimate that it will take about 1 work-hour per product to comply with the basic requirements of this AD. The average labor rate is \$80 per work-hour. Based on these figures, we estimate the cost of this AD to the U.S. operators to be \$23,760, or \$80 per product.

### FAA's Justification and Determination of the Effective Date

This revision merely clarifies the intended effect on spare and on-airplane fuel tank system components, and makes no substantive change to the AD's requirements. For this reason, it is found that notice and opportunity for prior public comment for this action are unnecessary, and good cause exists for making this amendment effective in less than 30 days.

### Comments Invited

This AD is a final rule that involves requirements affecting flight safety, and we did not precede it by notice and opportunity for public comment. We invite you to send any written relevant data, views, or arguments about this AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2009-1075; Directorate Identifier 2009-NM-181-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this AD. We will consider all comments received by the closing date and may amend this AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this AD.

### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will

not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

*For the reasons discussed above, I certify this AD:*

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing amendment 39-15504 (73 FR 24145, May 2, 2008) and adding the following new AD:

**2008-09-23 R1 Bombardier, Inc. (Formerly Bombardier Aerospace, Inc.; Canadair):** Amendment 39-16107. Docket No. FAA-2009-1075; Directorate Identifier 2009-NM-181-AD.

#### Effective Date

- (a) This airworthiness directive (AD) becomes effective December 14, 2009.

#### Affected ADs

- (b) This AD revises AD 2008-09-23, Amendment 39-15504.

#### Applicability

- (c) This AD applies to all Bombardier Inc. Model CL-600-2C10 (Regional Jet Series 700, 701 & 702), CL-600-2D15 (Regional Jet Series 705), and CL-600-2D24 (Regional Jet Series 900) airplanes, certificated in any category, all serial numbers.

#### Subject

- (d) Air Transport Association (ATA) of America Code 28: Fuel.

### Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

Bombardier Aerospace has completed a system safety review of the aircraft fuel system against fuel tank safety standards introduced in Chapter 525 of the Airworthiness Manual through Notice of Proposed Amendment (NPA) 2002-043. The identified non-compliances were then assessed using Transport Canada Policy Letter No. 525-001, to determine if mandatory corrective action is required.

The assessment showed that it is necessary to introduce Critical Design Configuration Control Limitations (CDCCL), in order to preserve critical fuel tank system ignition source prevention features during configuration changes such as modifications and repairs, or during maintenance actions. Failure to preserve critical fuel tank system ignition source prevention features could result in a fuel tank explosion. Revision has been made to Bombardier CL-600-2C10, CL-600-2D15, CL-600-2D24 Maintenance Requirements Manual, CSP B-053, Part 2, Section 3, "Fuel System Limitations" to introduce the required CDCCL.

The corrective action is revising the Airworthiness Limitations Section (ALS) of the Instructions for Continued Airworthiness to include the CDCCL data.

### Restatement of AD 2008-09-23, With Changes to Compliance Method: Actions and Compliance

(f) Unless already done, do the following actions.

(1) Within 60 days after June 6, 2008 (the effective date of AD 2008-09-23), revise the ALS of the Instructions for Continued Airworthiness to incorporate the CDCCL data specified in CRJ 700/900 Series Regional Jet (Bombardier) Temporary Revision (TR) 2-222, dated March 30, 2006, to Section 3, "Fuel System Limitations," of Part 2 of Bombardier CL-600-2C10, CL-600-2D15 and CL-600-2D24 Maintenance Requirements Manual CSP B-053.

**Note 1:** The actions required by paragraph (f)(1) of this AD may be done by inserting a copy of the TR into the maintenance requirements manual. When the TR has been included in the general revision of the maintenance program, the general revision may be inserted into the maintenance requirements manual, provided the relevant information in the general revision is identical to that in the TR, and the temporary revision may be removed.

(2) After accomplishing the actions specified in paragraph (f)(1) of this AD, no alternative CDCCLs may be used unless the CDCCLs are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (g)(1) of this AD.

### NEW INFORMATION

#### Explanation of CDCCL Requirements

**Note 2:** Notwithstanding any other maintenance or operational requirements, components that have been identified as airworthy or installed on the affected airplanes before the revision of the ALS of

the Instructions for Continued Airworthiness, as required by paragraph (f) of this AD, do not need to be reworked in accordance with the CDCCLs. However, once the ALS of the Instructions for Continued Airworthiness has been revised, future maintenance actions on these components must be done in accordance with the CDCCLs.

#### FAA AD Differences

**Note 3:** This AD differs from the MCAI and/or service information as follows: No differences.

#### Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York ACO, ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, New York, 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to ensure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3502 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

#### Related Information

(h) Refer to MCAI Canadian Airworthiness Directive CF-2008-07, dated January 25, 2008; and CRJ 700/900 Series Regional Jet (Bombardier) Temporary Revision 2-222, dated March 30, 2006; for related information.

#### Material Incorporated by Reference

(i) You must use CRJ 700/900 Series Regional Jet (Bombardier) Temporary Revision 2-222, dated March 30, 2006, to Section 3, "Fuel System Limitations," of Part 2 of Bombardier CL-600-2C10, CL-600-2D15 and CL-600-2D24 Maintenance Requirements Manual CSP B-053, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register previously approved the incorporation by reference of CRJ 700/900 Series Regional Jet (Bombardier) Temporary Revision 2-222, dated March 30, 2006, to Section 3, "Fuel

System Limitations," of Part 2 of Bombardier CL-600-2C10, CL-600-2D15, and CL-600-2D24 Maintenance Requirements Manual CSP B-053, on June 6, 2008 (73 FR 24145, May 2, 2008).

(2) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; e-mail [thd.crj@aero.bombardier.com](mailto:thd.crj@aero.bombardier.com); Internet <http://www.bombardier.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

Issued in Renton, Washington, on November 18, 2009.

**Stephen P. Boyd,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. E9-28297 Filed 11-25-09; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2009-0317; Directorate Identifier 79-ANE-18; Amendment 39-16087; AD 2009-24-01]

**RIN 2120-AA64**

#### Airworthiness Directives; Pratt & Whitney JT8D-7, -7A, -7B, -9, -9A, -11, -15, and -17 Turbofan Engines

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** The FAA is superseding an existing airworthiness directive (AD) for Pratt & Whitney JT8D-1, -1A, -1B, -7, -7A, -7B, -9, -9A, -11, -15, and -17 turbofan engines with 2nd stage fan blades, part number (P/N) 433802, 645902, 759902, 695932, 678102, or 746402, installed. That AD currently requires initial and repetitive ultrasonic inspection (UI) and fluorescent penetrant inspection (FPI) of those P/N 2nd stage fan blades. This AD replaces the required FPI with eddy current inspection (ECI) on all affected 2nd stage fan blades and maintains the requirement of UI of the blade root

attachment on some of the affected 2nd stage fan blades. This AD also introduces an optional terminating action to the repetitive blade inspections for certain engine models. This AD results from reports of 10 fractures of 2nd stage fan blades since AD 87-14-01R1 became effective. We are issuing this AD to prevent uncontained failure of 2nd stage fan blades, which could result in damage to the airplane.

**DATES:** This AD becomes effective January 4, 2010. The Director of the Federal Register approved the incorporation by reference of certain publications listed in the regulations as of January 4, 2010.

**ADDRESSES:** You can get the service information identified in this AD from Pratt & Whitney, 400 Main St., East Hartford, CT 06108; telephone (860) 565-8770; fax (860) 565-4503.

The Docket Operations office is located at Docket Management Facility, U.S. Department of Transportation, 1200 New Jersey Avenue, SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001.

#### FOR FURTHER INFORMATION CONTACT:

Kevin Dickert, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; e-mail: [kevin.dickert@faa.gov](mailto:kevin.dickert@faa.gov); telephone (781) 238-7117, fax (781) 238-7199.

**SUPPLEMENTARY INFORMATION:** The FAA proposed to amend 14 CFR part 39 by superseding AD 87-14-01 R1, Amendment 39-6359 (54 FR 43954, October 30, 1989), with a proposed AD. The proposed AD applies to JT8D-7, -7A, -7B, -9, -9A, -11, -15, and -17 turbofan engines with 2nd stage fan blades, P/N 433802, 645902, 759902, 695932, 678102, or 746402 installed. We published the proposed AD in the **Federal Register** on August 7, 2009 (74 FR 39582). That action proposed to replace the required FPI with ECI on all affected 2nd stage fan blades and would maintain the requirement of UI of the blade root attachment on some of the affected 2nd stage fan blades. That action also proposed to introduce an optional terminating action to the repetitive blade inspections for certain engine models.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory