

**Material Incorporated by Reference**

(k) You must use Appendix 1 of Honeywell International Inc. Service Bulletin LT 101-71-00-0002, Revision 26, dated April 2, 2008, to determine the gas generator turbine disc serial numbers affected by this AD. The Director of the Federal Register approved the incorporation by reference of this service bulletin in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Honeywell International Inc., P.O. Box 52181, Phoenix, AZ 85072-2181; telephone (800) 601-3099 (U.S.A.) or (602) 365-3099 (International); or go to: <https://portal.honeywell.com/wps/portal/aero>, for a copy of this service information. You may review copies at the FAA, New England Region, 12 New England Executive Park, Burlington, MA; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on November 18, 2009.

**Peter A. White,**

*Assistant Manager, Engine and Propeller Directorate, Aircraft Certification Service.*

[FR Doc. E9-28235 Filed 11-27-09; 8:45 am]

BILLING CODE 4910-13-P

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

**[Docket No. FAA-2009-0870 Directorate Identifier 2009-CE-049-AD; Amendment 39-16108; AD 2009-24-14]**

**RIN 2120-AA64**

**Airworthiness Directives; Empresa Brasileira de Aeronáutica S.A. (EMBRAER) Model EMB-500 Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

It has been found the possibility of elevator mass balance fasteners becoming slack under certain conditions. The loose of at least two fasteners may lead to an unbalance condition, which may induce flutter on airplane elevators.

We are issuing this AD to require actions to correct the unsafe condition on these products.

**DATES:** This AD becomes effective January 4, 2010.

On January 4, 2010, the Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD.

**ADDRESSES:** You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4146; fax: (816) 329-4090.

**SUPPLEMENTARY INFORMATION:****Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on September 21, 2009 (74 FR 48028). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

It has been found the possibility of elevator mass balance fasteners becoming slack under certain conditions. The loose of at least two fasteners may lead to an unbalance condition, which may induce flutter on airplane elevators.

The MCAI requires replacement of the nuts of the right and left elevators mass balance fasteners.

**Comments**

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

**Conclusion**

We reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

**Differences Between This AD and the MCAI or Service Information**

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have required different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a note within the AD.

**Costs of Compliance**

We estimate that this AD will affect 25 products of U.S. registry. We also estimate that it will take about 2 work-hours per product to comply with the basic requirements of this AD. The average labor rate is \$80 per work-hour. Required parts will cost about \$150 per product.

Based on these figures, we estimate the cost of this AD to the U.S. operators to be \$7,750 or \$310 per product.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

*For the reasons discussed above, I certify this AD:*

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD Docket.

## Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

## List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

## Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

**2009-24-14 Empresa Brasileira de Aeronáutica S.A. (EMBRAER):** Amendment 39-16108; Docket No. FAA-2009-0870; Directorate Identifier 2009-CE-049-AD.

### Effective Date

(a) This airworthiness directive (AD) becomes effective January 4, 2010.

### Affected ADs

(b) None.

### Applicability

(c) This AD applies to EMB-500 airplanes, serial numbers 50000005, 50000006, 50000008 through 50000036, 50000038 through 50000041, 50000043 through 50000046, 50000048, and 50000053, certificated in any category.

### Subject

(d) Air Transport Association of America (ATA) Code 27: Flight Controls.

### Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

It has been found the possibility of elevator mass balance fasteners becoming slack under certain conditions. The loose of at least two fasteners may lead to an unbalance condition, which may induce flutter on airplane elevators.

The MCAI requires replacement of the nuts of the right and left elevators mass balance fasteners.

### Actions and Compliance

(f) Unless already done, do the following actions:

(1) Within the next 30 days after January 4, 2010 (the effective date of this AD), replace the nuts of the right-hand (RH) and left-hand (LH) elevators' mass balance fasteners with new ones of self-locking type bearing part number (P/N) MS21043-4. Do the replacements following Phenom by Embraer Service Bulletin No. 500-55-0001, dated July 24, 2009.

(2) As of 30 days after January 4, 2010 (the effective date of this AD), only install self-locking type nuts, P/N MS21043-4, on the RH and LH elevators' mass balance fasteners.

### FAA AD Differences

**Note:** This AD differs from the MCAI and/or service information as follows: No differences.

### Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to *Attn: Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4146; fax: (816) 329-4090.* Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

### Related Information

(h) Refer to MCAI Agência Nacional de Aviação Civil (ANAC) Brazilian Airworthiness Directive AD No.: 2009-09-01, dated September 3, 2009, and Phenom by Embraer Service Bulletin No. 500-55-0001, dated July 24, 2009, for related information.

### Material Incorporated by Reference

(i) You must use Phenom by Embraer Service Bulletin No. 500-55-0001, dated July 24, 2009, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of

this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact EMBRAER Empresa Brasileira de Aeronáutica S.A., Phenom Maintenance Support, Av. Brig. Farina Lima, 2170, São José dos Campos—SP, CEP: 12227-901—PO Box: 38/2, BRASIL, telephone: +55 12 3927-5383; fax: +55 12 3927-2610; E-mail: [reliability.executive@embraer.com.br](mailto:reliability.executive@embraer.com.br); Internet: <http://www.embraer.com.br>.

(3) You may review copies of the service information incorporated by reference for this AD at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the Central Region, call (816) 329-3768.

(4) You may also review copies of the service information incorporated by reference for this AD at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

Issued in Kansas City, Missouri, on November 19, 2009.

**Patrick R. Mullen,**

*Acting Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. E9-28306 Filed 11-27-09; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF HEALTH AND HUMAN SERVICES

### Food and Drug Administration

## 21 CFR Part 520

**Docket No. FDA-2009-N-0665]**

### Oral Dosage Form New Animal Drugs; Chlortetracycline Powder

**AGENCY:** Food and Drug Administration, HHS.

**ACTION:** Final rule.

**SUMMARY:** The Food and Drug Administration (FDA) is amending the animal drug regulations to reflect approval of an abbreviated new animal drug application (ANADA) filed by Alpharma Inc. The ANADA provides for use of generic chlortetracycline soluble powder to make medicated drinking water for cattle, swine, chickens, and turkeys for the treatment of several bacterial diseases.

**DATES:** This rule is effective November 30, 2009.

**FOR FURTHER INFORMATION CONTACT:** John K. Harshman, Center for Veterinary Medicine (HFV-104), Food and Drug Administration, 7500 Standish Pl., Rockville, MD 20855, 240-276-8197, e-mail: [john.harshman@fda.hhs.gov](mailto:john.harshman@fda.hhs.gov).